



## SERVICE BULLETIN

**SUBJECT:** ELECTRICAL POWER – Static Inverter AI<sup>2</sup> Model 1G1000-1A-2170, Part Number 1-002-0102-2170 – Modification.

**TRANSMITTAL:** Service Bulletin 1-002-0102-2170-24-47 Initial Release (Revision 0).

### **I. Planning Information**

#### **A. Effectivity**

Applies to Static Inverters, AI<sup>2</sup> Part Number 1-002-0102-2170, Boeing P/N: S281W204-1 marked as “MOD LVL –”. Existing units that are labeled as “MOD LVL A” already contain the product improvement.

#### **B. Concurrent Requirements**

None.

#### **C. Reason**

Avionic Instruments has investigated and tested numerous scenarios that could cause a no fault found (NFF) return of the static inverter. The root cause of the NFF returns has been identified as unspecified power interruption to the unit. The power interrupt limits defined by the specification do not cause this problem. However, a power interrupt of a certain duration may cause a race condition within the bias supply leading to a latching fault condition. The latch can only be cleared by recycling power to the unit. At the aircraft level, this unexpected latching fault is falsely interpreted as a static inverter hard failure.

#### **D. Description**

Updating the Inverter Control Assembly will prevent the false alarm due to power interruptions beyond the levels identified in the specification. This will greatly improve availability of the static inverter by eliminating NFF returns attributed to this false alarm condition. This upgrade will require partial disassembly of the static inverter and changing four resistors.

#### **E. Compliance Recommendation**

Recommended – Service Bulletin recommended to be accomplished when manpower and facilities are available to prevent operational impact.

#### **F. Approval**

This Service Bulletin has been reviewed by Boeing and the FAA. The repairs and modifications herein comply with the applicable regulations and are on record with the Supplier as FAA-approved for installation.

#### **G. Manpower**

The estimated time required to accomplish the task of disassembly, inspection and/or rework, and reassembly of the unit in relation to this service bulletin is four and a half (4.5) hours. Activity related to product return to service is included in this time estimate.

The technical data in this document (or file) is controlled for export under the Export Administration Regulations (EAR), 15 CFR Parts 730 - 774, ECCN: EAR99. Violations of these laws may be subject to fines and penalties under the Export Administration Act.



## SERVICE BULLETIN

### **H. Weight and Balance**

Subject change has no significant impact on balance and weight.

### **I. Electrical Load Data**

Subject change has no effect on electrical performance or connections.

### **J. Software Accomplishment Summary**

Subject change has no effect on Software.

### **K. References**

- Component Maintenance Manual 24-20-52 (1-001-4902-0052)

### **L. Other Publications Affected**

- Component Maintenance Manual 24-20-52 (1-001-4902-0052) Rev "14"

### **M. Interchangeability of Parts**

Refer to Paragraph 2.E., Re-identified Parts/Existing Parts Accountability for interchangeability information.



## SERVICE BULLETIN

### II. Material Information

#### A. Material

Customers may contact Avionic Instruments customer service at 732-388-3500. Products upgraded by Avionic Instruments. Avionic Instruments will not perform any repair beyond that which is specified in this document without first notifying the customer of any associated charges and receiving customer consent. The price may be subject to escalation one year after the release of this service bulletin.

<u>Part Number</u>	<u>Name</u>	<u>Price</u>
1-001-6301-0030	1-002-0102-2170-24-47 SB Kit	\$2,849.00

It is highly recommended that any units in need of modification be returned to Avionic Instruments however if field upgrades are performed by operators or operator designees, it is requested that they notify AI<sup>2</sup> Repair Department, within 30 days, at: 732-388-3500, [repair@avionicinstruments.com](mailto:repair@avionicinstruments.com) or FAX (732) 382-4996 prior to performing the work to report unit S/N so we can provide the new label and kit. Any units received in-house for service bulletin upgrade will be subjected to the ATP prior to the upgrade being completed. AI<sup>2</sup> will notify the Airline Operator of any out-of-specification condition noted during performance of the ATP. The unit would need to be repaired prior to the upgrade being initiated and the repair will be quoted in accordance with AI<sup>2</sup>'s published catalog.

#### B. Industry Support Information

This modification is a chargeable event and is not an under warranty condition.

#### C. Material Necessary for Each Component

1-001-6301-0030 Kit Contents	
Quantity	Material
1	Resistor R130
1	Resistor R131
1	Resistor R162
1	Resistor R163
1	Label

#### D. Material Necessary for Each Spare

Not Applicable.

#### E. Re-identified Parts/Existing Parts Accountability

The part shown below is changed as shown in this Service Bulletin.

<u>New P/N</u>	<u>Keyword</u>	<u>Old P/N</u>	<u>Quantity</u>	<u>Disposition</u>
1-002-0102-2170 Mod A	Static Inverter	1-002-0102-2170 Mod -	1	Replacement

THIS DOCUMENT IS SUBJECTED TO THE CONTROLS AND RESTRICTIONS SET FORTH ON THE FIRST PAGE.



**AVIONIC INSTRUMENTS LLC** AEROSPACE FOR INDUSTRY™  
1414 Randolph Avenue, Avenel, New Jersey 07001 Tel. 732-388-3500  
FAX: (732) 382-4996 Email: [Techsupp@avionicinstruments.com](mailto:Techsupp@avionicinstruments.com)

## SERVICE BULLETIN

### F. Special Tooling

1. SMT Rework Station
2. Standard Tools
3. Safety glasses
4. Solder iron

THIS DOCUMENT IS SUBJECTED TO THE CONTROLS AND RESTRICTIONS SET FORTH ON THE FIRST PAGE.



## SERVICE BULLETIN

### III. Accomplishment Instructions

#### A. Instructions for Part Number for Installation of Kit Part Number 1-001-6301-0030

1. Remove (23) screws (8x 0404CPP188, 15x MS51957-13) from the left side of the top cover. (Figure 1).
2. Remove (22) screws (8x 0404CPP188, 14x MS51957-13) from the right side of the top cover. (Figure 2).
3. Remove (8) screws (4x 0404CPP188, 4x MS51957-13) from the top of the top cover. (Figure 3).
4. Remove (10) screws (10x MS51957-14) from the front panel. (Figure 4).
5. Remove (2) screws (2x MS51957-13) from the rear panel. (Figure 5).
6. Carefully lift the top cover to remove it from the unit. (Figure 6).
7. Remove (2) screws (2x 0605CPP188) from output (cable assembly). (Figure 6).
8. Remove (1) cable tie (1x MS3367-4-9). (Figure 7).
9. Carefully disconnect the connector. This step may require removing the shrink tubing (1.5"±.06 M23053/5-108-0 (Black)) and tie with lacing from the connector. (Figure 7, 8).
10. Remove (2) screws (2x MS51957-13) from (top) lugs on the bus assembly. Ensure that the top two lugs are removed before the bottom two. (Figure 7).
11. Remove (2) lower screws (2x 0405CPP188). (Figure 7).
12. Tilt the unit so that it is resting on its right side.
13. Remove (4) screws (4x MS51959-13) from bottom of unit. (Figure 9).
14. Remove the Inverter Module Assembly (1-002-0107-1653) and Inverter Control Link Cap Assembly (1-002-0107-1707). (Figure 10).
15. Remove (5) screws (5x MS51959-12) from shield. (Figure 10, 11).
16. Remove (2) screws (2x 0404CPP188) from inverter control. (Figure 12).
17. Locate resistors R130, R131 R162 and R163 on the inverter board. (Figure 13). (IPL Figure 26 items 225, 210 and 235).
18. Use solder tool to remove and replace resistors as follows:

Reference #	Original Part #	Replace with Part #
R130	1-001-0662-0023 (7.32k Ohm)	1-001-0662-0025 (7.68k Ohm)
R131	1-001-0662-0023 (7.32k Ohm)	1-001-0662-0013 (2k Ohm)
R162	1-001-0662-0007 (1k Ohm)	1-001-0662-0029 (10k Ohm)
R163	1-001-0662-0040 (68.1k Ohm)	1-001-0662-0129 (182k Ohm)

THIS DOCUMENT IS SUBJECTED TO THE CONTROLS AND RESTRICTIONS SET FORTH ON THE FIRST PAGE.



## SERVICE BULLETIN

Re-assemble the unit as follows:


19. Bring the cable through the panel and attach the cable to the connector on the front of the inverter control.
20. Insert (2) screws (2x 0404CPP188) into the inverter control. (Figure 12).
21. Attach shield to inverter control using (5) screws (5x MS51959-12). (Figure 10, 11)
22. Tilt unit so it is resting on one side.
23. Insert (4) screws (4x MS51959-13) into the bottom of the unit. (Figure 9).
24. Insert (2) bottom screws (2x 0405CPP188) to the bus assembly. (Figure 7).
25. Attach (2) top screws (2x MS51957-13) to the bus assembly. (Figure 7).
26. Reconnect the connector to the DC-AC power supply. This step may require attaching shrink tubing (1.5"±.06 M23053/5-108-0 (Black)), and tie with lacing. (Figure 7, 8).
27. Attach (1) new cable tie (1x MS3367-4-9). (Figure 7).
28. Insert (2) screws (2x 0605CPP188) into lugs to attach output (cable assembly). (Figure 6).
29. Place cover onto the unit.
30. Insert (2) screws (2x MS51957-13) into the rear panel. (Figure 5).
31. Insert (10) screws (10x MS51957-14) into the front panel. (Figure 4).
32. Insert (8) screws (4x 0404CPP188, 4x MS51957-13) into the top of the top cover. (Figure 3).
33. Insert (22) screws (8x 0404CPP188, 15x MS51957-13) into the right side of the top cover. (Figure 2).
34. Insert (23) screws (8x 0404CPP188, 15x MS51957-13) into the left side of the top cover. (Figure 1).



## SERVICE BULLETIN

### B. Completion

Upon completion of the modification, the label on the cover will be changed to indicate the model/part number change. Units that have completed the modification described in this service bulletin are to be changed to part number 1-002-0102-2170 MOD "A".



**Note:** The new label has the same AI2 part number as the old label (1-001-2501-0131). The content of the label is determined by the outline drawing.

### C. Testing

Upon completion of the modification and re-labeling of the unit, the unit shall complete and pass the testing shown in the "Testing and Troubleshooting" section of CMM 24-20-52 (1-001-4902-0052) before returning to service.





## SERVICE BULLETIN



**Figure 1 – Left Side of Unit (Top Cover) Screw Locations**

THIS DOCUMENT IS SUBJECTED TO THE CONTROLS AND RESTRICTIONS SET FORTH ON THE FIRST PAGE.





**AVIONIC INSTRUMENTS LLC** AEROSPACE FOR INDUSTRY™  
1414 Randolph Avenue, Avenel, New Jersey 07001 Tel. 732-388-3500  
FAX: (732) 382-4996 Email: [Techsupp@avionicsinstruments.com](mailto:Techsupp@avionicsinstruments.com)

## SERVICE BULLETIN




**Figure 2 – Right Side of Unit (Top Cover) Screw Locations**

THIS DOCUMENT IS SUBJECTED TO THE CONTROLS AND RESTRICTIONS SET FORTH ON THE FIRST PAGE.



## SERVICE BULLETIN




**Figure 3 – Top of Unit (Top Cover) Screw Locations**

THIS DOCUMENT IS SUBJECTED TO THE CONTROLS AND RESTRICTIONS SET FORTH ON THE FIRST PAGE.





## SERVICE BULLETIN




**Figure 4 – Front Panel Screw Locations**

THIS DOCUMENT IS SUBJECTED TO THE CONTROLS AND RESTRICTIONS SET FORTH ON THE FIRST PAGE.



**AVIONIC INSTRUMENTS LLC** AEROSPACE FOR INDUSTRY™  
1414 Randolph Avenue, Avenel, New Jersey 07001 Tel. 732-388-3500  
FAX: (732) 382-4996 Email: [Techsupp@avionicinstruments.com](mailto:Techsupp@avionicinstruments.com)

## SERVICE BULLETIN




**Figure 5 - Rear Panel Screw Locations**

THIS DOCUMENT IS SUBJECTED TO THE CONTROLS AND RESTRICTIONS SET FORTH ON THE FIRST PAGE.



## SERVICE BULLETIN




**Figure 6 – Output Cable Assembly Screw Locations**

THIS DOCUMENT IS SUBJECTED TO THE CONTROLS AND RESTRICTIONS SET FORTH ON THE FIRST PAGE.



**AVIONIC INSTRUMENTS LLC** AEROSPACE FOR INDUSTRY TM  
1414 Randolph Avenue, Avenel, New Jersey 07001 Tel. 732-388-3500  
FAX: (732) 382-4996 Email: [Techsupp@avionicinstruments.com](mailto:Techsupp@avionicinstruments.com)

## SERVICE BULLETIN




**Figure 7 – Bus Assembly Screw, Connector, and Cable Tie Locations**

THIS DOCUMENT IS SUBJECTED TO THE CONTROLS AND RESTRICTIONS SET FORTH ON THE FIRST PAGE.



## SERVICE BULLETIN




**Figure 8 – Connector Disconnected and Cable Tie Removed**

THIS DOCUMENT IS SUBJECTED TO THE CONTROLS AND RESTRICTIONS SET FORTH ON THE FIRST PAGE.



## SERVICE BULLETIN



**Figure 9 - Bottom of Unit Screw Locations**


THIS DOCUMENT IS SUBJECTED TO THE CONTROLS AND RESTRICTIONS SET FORTH ON THE FIRST PAGE.





**AVIONIC INSTRUMENTS LLC** AEROSPACE FOR INDUSTRY TM  
1414 Randolph Avenue, Avenel, New Jersey 07001 Tel. 732-388-3500  
FAX: (732) 382-4996 Email: [Techsupp@avionicinstruments.com](mailto:Techsupp@avionicinstruments.com)


## SERVICE BULLETIN



**Figure 10 - Inverter Module Assembly and Inverter Control Link Cap Assembly Removed**

THIS DOCUMENT IS SUBJECTED TO THE CONTROLS AND RESTRICTIONS SET FORTH ON THE FIRST PAGE.

**AVIONIC INSTRUMENTS LLC** AEROSPACE FOR INDUSTRY TM  
 1414 Randolph Avenue, Avenel, New Jersey 07001 Tel. 732-388-3500  
 FAX: (732) 382-4996 Email: [Techsupp@avionicinstruments.com](mailto:Techsupp@avionicinstruments.com)  
**SERVICE BULLETIN**




**Figure 11 – Inverter Control Shield Screw Locations**

THIS DOCUMENT IS SUBJECTED TO THE CONTROLS AND RESTRICTIONS SET FORTH ON THE FIRST PAGE.



## SERVICE BULLETIN



**Figure 12 – Inverter Control Screw, and Connector Locations**

THIS DOCUMENT IS SUBJECTED TO THE CONTROLS AND RESTRICTIONS SET FORTH ON THE FIRST PAGE.



## SERVICE BULLETIN




Figure 13 – Inverter board removed

THIS DOCUMENT IS SUBJECTED TO THE CONTROLS AND RESTRICTIONS SET FORTH ON THE FIRST PAGE.