

issues

NOTIFICATION BULLETIN No. RTC-060b R1

**TECHNICAL CONTENT OF THIS DOCUMENT IS APPROVED ON
THE BASIS OF AUTHORIZATION DOA NO. EASA.21J.057.**

- 1. CONCERNING TO:** All SPORTSTAR RTC aircraft equipped with Woodcomp Klassic 170/3/R propeller.
- 2. REASON:** Installation of DUC SWIRL-3-L propeller according to EASA Major Change Approval 10080106 instead of standard installed propeller Woodcomp Klassic 170/3/R
- 3. REQUIRED ACTIONS:**
 1. Replace the Woodcomp Klassic 170/3/R propeller with the DUC SWIRL -3-L propeller according to work procedure.
 2. Record the bulletin implementation in the Logbook.
- 4. LATEST DAY OF THE ACTION:** None.
- 5. CARRIED OUT BY:** Owner/operator of the airplane.
- 6. COSTS COVERED BY:** Owner/operator of the airplane.
- 7. NECESSARY MATERIAL:** In accordance with the text of the bulletin.
- 8. WORK PROCEDURE:** In accordance with the text of the bulletin.
- 9. APPENDICES:** POH Supplement No 37 (doc. No. ERTC020-10-AS-037)

Valid from: July 18th, 2023

**1. Work procedure****1.1 Necessary tools**

See Airplane Maintenance Manual for SportStar RTC (doc. No. ERTC022-10-AS), Section 61-10.

1.2 Necessary material

Name	Marking	Nomencl.	Quantity
<hr/>			
DUC SWIRL-3-L installation		S6 00-87 01	1 pc
	or		
DUC SWIRL-3-L installation		S6 00-88 01	1 pc

Material shall be supplied by the airplane manufacturer.

1.3 Work procedure**1.3.1 Woodcomp Klassic 170/3/R propeller removal**

Remove the Woodcomp Klassic 170/3/R propeller according the procedure mentioned in the Airplane Maintenance Manual for SportStar RTC (doc. No. ERTC022-10-AS), Section 61-10, par. 2 A. (1).

1.3.2 DUC SWIRL-3-L propeller installation

Install the DUC SWIRL-3-L according the procedure mentioned in the Airplane Maintenance Manual for SportStar RTC (doc. No. ERTC022-10-AS), Section 61-10, par. 2 C. (2).

2. Influence on airplane documentation**2.1 Accompanying technical documentation****2.1.1 Pilot's Operating Handbook for SportStar RTC (doc. No. ERTC020-10-AS)**

Owner/operator will insert Supplement No. 37 (doc. No. ERTC020-10-AS-037), which is enclosed to this bulletin, into POH. Owner/operator will mark Supplements incorporated into the POH into table on page 9-4.

2.2 Operation technical documentation

The authorized person will carry out this record in the Aircraft Logbook after bulletin implementation: „**The removal of the existing Woodcomp Klassic 170/3/R propeller and the installation of the new DUC SWIRL-3-L propeller were carried out according to the Information Bulletin No. RTC-060b R1**“ and they will add the date and his signature.

3. Influence on weight and balancing

Not affected.