

*issues***SERVICE BULLETIN No. RTC-072a SR**

**TECHNICAL CONTENT OF THIS DOCUMENT IS APPROVED ON
THE BASIS OF AUTHORIZATION DOA NO. EASA.21J.057.**

THIS SB COULD BE AFFECTED BY AD.

- 1. CONCERNING TO:** All SPORTSTAR RTC aircraft equipped with ROTAX ULS engine according to ROTAX Service Bulletin SB -912-078UL.
- 2. REASON:** The ROTAX engine manufacturer has issued Service Bulletin SB-912-078UL ordering the replacement of the propeller shaft and its accessories.
- 3. REQUIRED ACTIONS:**
1. Check and replace if necessary according to ROTAX Service Bulletin 912-078UL.
 2. Record the replacement into Engine Log Book.
- 4. LATEST DAY OF THE ACTION:** According to ROTAX Service Bulletin 912-078UL.
- 5. CARRIED OUT BY:** Organizations authorized for maintenance / repairs of this type of airplane.
- 6. COSTS COVERED BY:** According to ROTAX Service Bulletin 912-078UL.
- 7. NECESSARY MATERIAL:**

Name	Marking	Nomencl. (EVE)	ROTAX P/N	Quantity
Propeller shaft	Version 2	766260	937047	1 pc
Ball bearing	35-72-17	765227	832587	1 pc
Oil seal	40x55x7	766261	950470	1 pc
Roller bearing		766228	232246	1 pc
Oil seal	30x52x7	766262	950228	1 pc
Isolating flange		766229	950228	1 pc

The material marking and nomenclature is in accordance with the material defined in ROTAX Service Bulletin SB-912-078UL. Material shall be supplied by the airplane manufacturer.

- 8. WORK PROCEDURE:** According to ROTAX Service Bulletin 912-078UL.
- 9. APPENDICES:** None.

Valid from: September 1st, 2023.