JET AVIATION
A GENERAL DYNAMICS COMPANY

Status Detail Report

Report Created On: 16 Nov 2022

Phone: +1-912-298-1318
Fax: 1-912-963-0265/1-800-944-1775
Analyst: Michael Dyess

Gulfstream Aerospace Corporation
G450
N450LP
S/N: 4123
Regulation: BMU-BCAA
Airworthiness Date: 28 Apr 2008

Airframe & Component Times					Total Time	
Logbook	Position	Description	Serial No.	Log Date	Hours	Cycles
Airframe		GULFSTREAM AEROSPACE CORPORATION G450	4123	14 Nov 2022	5530.4	2599
Engine	1	ROLLS-ROYCE DERBY PLC TAY611-8C (G450)	85245	14 Nov 2022	5452.4	2550
Engine	2	ROLLS-ROYCE DERBY PLC TAY611-8C (G450)	85244	14 Nov 2022	5452.4	2550
APU		HONEYWELL GTCP36-150(GIV)	P-238	31 Oct 2022	5230.5	5452

ATA / U=Custom	Description / Part Number / HW / MM Ref / Ops Number(s)	Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
00 - General											
000500U	Jbja Airplane Maintenance Program		HRS		5530.4			0			0
			AFL		2599			0			0
			MOS		174.6			28 Apr 2008			
Airframe			MSC				-				
009000U	Placards and Markings Survey		HRS		107.2			5423.2			0
			AFL		39			2560			0
			MOS		3		12	16 Aug 2022	16 Aug 2023		
Airframe	200005										
Notes: INDEXED FROM C OF A RENEWAL AT REQUEST OF OPERATOR.											
009010U	FDR / Cvr Download (Reasonable Test & Analysis of Data)		HRS		6.5			5523.9			0
			AFL		2			2597			0
			MOS		.2		12	11 Nov 2022	11 Nov 2023		
Airframe	200005										
Notes: INDEXED FROM C OF A RENEWAL AT REQUEST OF OPERATOR.											
01 - Watch List											

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
010010	Service Center Maintenance Induction Checklist	HRS AFL MOS MSC		190.2 71 5.8		 O/C	5340.2 2528 23 May 2022			0 0
Airframe										
05 - Time Limits/Maintenance Checks										
055001	Aircraft Residual Deicing / Anti-Icing Fluid - Inspection / Cleaning	HRS AFL MOS MSC		3538.7 1590 114.7		 O/C	1991.7 1009 25 Apr 2013			0 0
Airframe										
055201	No. 1 Engine - Inspection of the Engine after Surge	HRS ENC MOS MSC		5452.4 2550 175.7		 O/C	0 0 24 Mar 2008			0 0
Engine										
055201 (056201)	No. 2 Engine - Inspection of the Engine after Surge	HRS ENC MOS MSC		5452.4 2550 176.2		 O/C	0 0 11 Mar 2008			0 0
Engine										
055202	No. 1 Engine - Inspection of the Engine after Shock Loading	HRS ENC MOS MSC		5452.4 2550 175.7		 O/C	0 0 24 Mar 2008			0 0
Engine										
055202 (056202)	No. 2 Engine - Inspection of the Engine after Shock Loading	HRS ENC MOS MSC		5452.4 2550 176.2		 O/C	0 0 11 Mar 2008			0 0
Engine										
055203	No. 1 Engine - Inspection of the Engine after Lightning Strike	HRS ENC MOS MSC		5452.4 2550 175.7		 O/C	0 0 24 Mar 2008			0 0
Engine										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
055203 (056203)	No. 2 Engine - Inspection of the Engine after Lightning Strike	HRS ENC MOS MSC		5452.4 2550 176.2		 O/C	0 0 11 Mar 2008			0 0
Engine										
055204	No. 1 Engine - Inspection of the Engine after Ingestion of Volcanic ASH	HRS ENC MOS MSC		5452.4 2550 175.7		 O/C	0 0 24 Mar 2008			0 0
Engine										
055204 (056204)	No. 2 Engine - Inspection of the Engine after Ingestion of Volcanic ASH	HRS ENC MOS MSC		5452.4 2550 176.2		 O/C	0 0 11 Mar 2008			0 0
Engine										
055205	No. 1 Engine - Inspection of the Engine after Bird Strike or Slush Ingestion	HRS ENC MOS MSC		5452.4 2550 175.7		 O/C	0 0 24 Mar 2008			0 0
Engine										
055205 (056205)	No. 2 Engine - Inspection of the Engine after Bird Strike or Slush Ingestion	HRS ENC MOS MSC		5452.4 2550 176.2		 O/C	0 0 11 Mar 2008			0 0
Engine										
055207	No. 1 Engine - Inspection of the Engine for Snow and Ice before Starting	HRS ENC MOS MSC		5452.4 2550 175.7		 O/C	0 0 24 Mar 2008			0 0
Engine										
055207 (056207)	No. 2 Engine - Inspection of the Engine for Snow and Ice before Starting	HRS ENC MOS MSC		5452.4 2550 176.2		 O/C	0 0 11 Mar 2008			0 0
Engine										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
055208	No. 1 Engine - Inspection of the Engine after Bypass Duct Blockage	HRS		5452.4			0			0
		ENC		2550			0			0
		MOS		175.7			24 Mar 2008			
		MSC				O/C				
Engine										
055208 (056208)	No. 2 Engine - Inspection of the Engine after Bypass Duct Blockage	HRS		5452.4			0			0
		ENC		2550			0			0
		MOS		176.2			11 Mar 2008			
		MSC				O/C				
Engine										
055209	No. 1 Engine - Inspection of the Engine after Vibration	HRS		5452.4			0			0
		ENC		2550			0			0
		MOS		175.7			24 Mar 2008			
		MSC				O/C				
Engine										
055209 (056209)	No. 2 Engine - Inspection of the Engine after Vibration	HRS		5452.4			0			0
		ENC		2550			0			0
		MOS		176.2			11 Mar 2008			
		MSC				O/C				
Engine										
055301	No. 1 Engine - N1 Overspeed Inspection Requirements	HRS		5452.4			0			0
		ENC		2550			0			0
		MOS		175.7			24 Mar 2008			
		MSC				O/C				
Engine										
055301 (056301)	No. 2 Engine - N1 Overspeed Inspection Requirements	HRS		5452.4			0			0
		ENC		2550			0			0
		MOS		176.2			11 Mar 2008			
		MSC				O/C				
Engine										
055302	No. 1 Engine - N2 Overspeed Inspection Requirements	HRS		5452.4			0			0
		ENC		2550			0			0
		MOS		175.7			24 Mar 2008			
		MSC				O/C				
Engine										
055302 (056302)	No. 2 Engine - N2 Overspeed Inspection Requirements	HRS		5452.4			0			0
		ENC		2550			0			0
		MOS		176.2			11 Mar 2008			
		MSC				O/C				
Engine										

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Description: Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
055303	No. 1 Engine - Tgt Exceedance Inspection Requirements		HRS ENC MOS MSC		5452.4 2550 175.7		 O/C	0 0 24 Mar 2008			0 0
Engine											
055303 (056303)	No. 2 Engine - Tgt Exceedance Inspection Requirements		HRS ENC MOS MSC		5452.4 2550 176.2		 O/C	0 0 11 Mar 2008			0 0
Engine											
055304	No. 1 Engine - Combined Tgt Exceedance (Other Than Engine Starting and Relighting) and N1 Overspeed or N2 Overspeed (Other Than Reverse Thrust) Inspection Requiremen		HRS ENC MOS MSC		5452.4 2550 175.7		 O/C	0 0 24 Mar 2008			0 0
Engine											
055304 (056304)	No. 2 Engine - Combined Tgt Exceedance (Other Than Engine Starting and Relighting) and N1 Overspeed or N2 Overspeed (Other Than Reverse Thrust) Inspection Requiremen		HRS ENC MOS MSC		5452.4 2550 176.2		 O/C	0 0 11 Mar 2008			0 0
Engine											
055401	No. 1 Engine - Accident, Incident, Event - Special Inspections		HRS ENC MOS MSC		5452.4 2550 175.7		 O/C	0 0 24 Mar 2008			0 0
Engine											
055401 (056401)	No. 2 Engine - Accident, Incident, Event - Special Inspections		HRS ENC MOS MSC		5452.4 2550 176.2		 O/C	0 0 11 Mar 2008			0 0
Engine											

08 - Leveling and Weighing

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Description: Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
080001	Weight and Balance of Aircraft		HRS		1620.3			3910.1			0
			AFL		629			1970			0
			MOS		49.4		60	05 Oct 2018	05 Oct 2023		
Airframe											
11 - Placards and Markings											
111010	Exterior Paint 1		HRS		5525.5			4.9			0
			AFL		2597			2			0
			MOS		171.5			01 Aug 2008			
			MSC				O/C				
Airframe											
Notes: PN: CA8800/I1050 SN: MATTERHORN WHITE.											
111015	Exterior Paint 2		HRS		5525.5			4.9			0
			AFL		2597			2			0
			MOS		171.5			01 Aug 2008			
			MSC				O/C				
Airframe											
Notes: PN: 808751ES SN: PANTONE 289C.											
111020	Exterior Paint 3		HRS		5525.5			4.9			0
			AFL		2597			2			0
			MOS		171.5			01 Aug 2008			
			MSC				O/C				
Airframe											
Notes: PN: 808667ES SN: COOL GRAY.											
111025	Exterior Paint 4		HRS		5525.5			4.9			0
			AFL		2597			2			0
			MOS		171.5			01 Aug 2008			
			MSC				O/C				
Airframe											
Notes: PN: P6180ES SN: GRAY.											
111030	Exterior Paint 5		HRS		5525.5			4.9			0
			AFL		2597			2			0
			MOS		171.5			01 Aug 2008			
			MSC				O/C				
Airframe											
Notes: PN: P1203 SN: SUNFAST RED.											

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Description: Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
111035	Exterior Paint 6		HRS		5525.5			4.9			0
			AFL		2597			2			0
			MOS		171.5			01 Aug 2008			
Airframe			MSC				O/C				
Notes: PN: AF740 SN: CLEAR COAT.											
111040	Exterior Paint 7		HRS		5525.5			4.9			0
			AFL		2597			2			0
			MOS		171.5			01 Aug 2008			
Airframe			MSC				O/C				
Notes: PN: 9719 SN: FIRE RED (INK).											
111111	Exterior Strip and Paint		HRS		5530.4			0			0
			AFL		2599			0			0
			MOS		174.6			28 Apr 2008			
Airframe			MSC				O/C				
12 - Servicing											
122401	Integrated Drive Generator (Left) - Servicing		HRS		1691.5			3838.9			0
			AFL		668			1931			0
			MOS		51.8			22 Jul 2018			
Airframe			MSC				O/C				
122402	Integrated Drive Generator (Right) - Servicing		HRS		1691.5			3838.9			0
			AFL		668			1931			0
			MOS		51.8			22 Jul 2018			
Airframe			MSC				O/C				
122403	Integrated Drive Generator (Left) - Oil System Draining		HRS		5530.4			0			0
			AFL		2599			0			0
			MOS		174.6			28 Apr 2008			
Airframe			MSC				O/C				
122404	Integrated Drive Generator (Right) - Oil System Draining		HRS		5530.4			0			0
			AFL		2599			0			0
			MOS		174.6			28 Apr 2008			
Airframe			MSC				O/C				

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
122701 Airframe	Aileron Trim Tab Actuator - Service / Lubrication	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0
122703 Airframe	Aileron Load Relief Bungee (Left) - Lubrication	HRS AFL MOS MSC		882.2 304 24.1		O/C	4648.2 2295 12 Nov 2020			0 0
122704 Airframe	Aileron Load Relief Bungee (Right) - Lubrication	HRS AFL MOS MSC		882.2 304 24.1		O/C	4648.2 2295 12 Nov 2020			0 0
122707 Airframe	Rudder Pedals - Lubrication 052000-4A,200104	HRS AFL MOS		1769.5 717 54.7		2000 96	3760.9 1882 26 Apr 2018	5760.9 30 Apr 2026	5810.9 31 May 2026	0 0 [End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]
122708 Airframe	Rudder Torque Tube Bearing - Lubrication 052000-2A,200102	HRS AFL MOS		6.5 2 .2	49.3	1000 48	5523.9 2597 11 Nov 2022	6573.2* 30 Nov 2026	6623.2 31 Dec 2026	0 0 [End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]
122711 Airframe	Wing Flap (Left) - Lubrication 052000-1A,200101	HRS AFL MOS		6.5 2 .2		500 24	5523.9 2597 11 Nov 2022	6023.9 30 Nov 2024	6073.9 31 Dec 2024	0 0 [End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]
122712 Airframe	Wing Flap (Right) - Lubrication 052000-1A,200101	HRS AFL MOS		6.5 2 .2		500 24	5523.9 2597 11 Nov 2022	6023.9 30 Nov 2024	6073.9 31 Dec 2024	0 0 [End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]
122713 Airframe	Flap Actuator Bushing (Left) - Lubrication	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
122714	Flap Actuator Bushing (Right) - Lubrication		HRS		5530.4			0			0
			AFL		2599			0			0
			MOS		174.6			28 Apr 2008			
Airframe			MSC				O/C				
122715	Wing Flap Traveling Nut (Left) - Lubrication		HRS		6.5		500	5523.9	6023.9	6073.9	0
			AFL		2			2597			0
			MOS		.2		24	11 Nov 2022	30 Nov 2024	31 Dec 2024	
Airframe	052000-1A,200101		[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
122716	Wing Flap Traveling Nut (Right) - Lubrication		HRS		6.5		500	5523.9	6023.9	6073.9	0
			AFL		2			2597			0
			MOS		.2		24	11 Nov 2022	30 Nov 2024	31 Dec 2024	
Airframe	052000-1A,200101		[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
122717	Spoiler Hinges (Left) Inboard / Middle / Outboard - Lubrication		HRS		190.2			5340.2			0
			AFL		71			2528			0
			MOS		6.1	2	12	12 May 2022	31 May 2023*	30 Jun 2023	
Airframe	052000-1C,200201		[End Of Month Item] [MOS: +1m/-1m]								
122718	Spoiler Hinges (Right) Inboard / Middle / Outboard - Lubrication		HRS		190.2			5340.2			0
			AFL		71			2528			0
			MOS		6.1	2	12	12 May 2022	31 May 2023*	30 Jun 2023	
Airframe	052000-1C,200201		[End Of Month Item] [MOS: +1m/-1m]								
122719	Spoiler Load Relief Bungee (Left) - Lubrication		HRS		882.2			4648.2			0
			AFL		304			2295			0
			MOS		24.1			12 Nov 2020			
Airframe			MSC				O/C				
122720	Spoiler Load Relief Bungee (Right) - Lubrication		HRS		882.2			4648.2			0
			AFL		304			2295			0
			MOS		24.1			12 Nov 2020			
Airframe			MSC				O/C				
122721	Control Surface Hinge Joints - Lubrication		HRS		5530.4			0			0
			AFL		2599			0			0
			MOS		174.6			28 Apr 2008			
Airframe			MSC				O/C				

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
122722 Airframe	Lube, R Cont Surface Hng Joint	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
122901 Airframe	Hydraulic System Reservoir (Left) - Servicing	HRS AFL MOS MSC		181 68 5.7		 O/C	5349.4 2531 26 May 2022			0 0
122902 Airframe	Hydraulic System Reservoir (Right) - Servicing	HRS AFL MOS MSC		130.9 49 2.6		 O/C	5399.5 2550 27 Aug 2022			0 0
122903 Airframe	Hydraulic System Accumulator (Left) - Servicing	HRS AFL MOS MSC		4900.8 2429 151.3		 O/C	629.6 170 06 Apr 2010			0 0
122904 Airframe	Hydraulic System Accumulator (Right) - Servicing	HRS AFL MOS MSC		4900.8 2429 151.3		 O/C	629.6 170 06 Apr 2010			0 0
123201 Airframe	Main Landing Gear (Left) - Lubrication 052000-4M,200194	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		6.5 2 .2		 4	5523.9 2597 11 Nov 2022	31 Mar 2023	30 Apr 2023	0 0
123202 Airframe	Main Landing Gear (Right) - Lubrication 052000-4M,200194	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		6.5 2 .2		 4	5523.9 2597 11 Nov 2022	31 Mar 2023	30 Apr 2023	0 0
123203 Airframe	Main Landing Gear Door Hinges (Left) - Lubrication 052000-1A,200101	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]		6.5 2 .2		500 24	5523.9 2597 11 Nov 2022	6023.9 30 Nov 2024	6073.9 31 Dec 2024	0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
123204	Main Landing Gear Door Hinges (Right) - Lubrication	HRS		6.5		500	5523.9	6023.9	6073.9	0
		AFL		2			2597			0
		MOS		.2		24	11 Nov 2022	30 Nov 2024	31 Dec 2024	
Airframe	052000-1A,200101	[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
123205	Nose Landing Gear - Lubrication	HRS		6.5			5523.9			0
		AFL		2			2597			0
		MOS		.2		4	11 Nov 2022	31 Mar 2023	30 Apr 2023	
Airframe	052000-4M,200194	[End Of Month Item] [MOS: +1m/-1m]								
123206	Nose Landing Gear Door Hinges - Lubrication	HRS		6.5		500	5523.9	6023.9	6073.9	0
		AFL		2			2597			0
		MOS		.2		24	11 Nov 2022	30 Nov 2024	31 Dec 2024	
Airframe	052000-1A,200101	[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
123207	Landing Gear Emergency Extension Nitrogen Blow-Down Bottle - Servicing	HRS		439.3			5091.1			0
		AFL		157			2442			0
		MOS		12.1			14 Nov 2021			
		MSC				O/C				
Airframe										
123208	Parking / Emergency Brake Accumulator - Servicing	HRS		882.2			4648.2			0
		AFL		304			2295			0
		MOS		23			15 Dec 2020			
		MSC				O/C				
Airframe										
123209	Main Tire Assembly - Servicing	HRS		17			5513.4			0
		AFL		5			2594			0
		MOS		.9			18 Oct 2022			
		MSC				O/C				
Airframe										
Notes: PN: 1159L47003-5 SN: FEB09-1112. PRESSURE GAGE: 569151CAL: 03/17										
123210	Nose Tire Assembly - Servicing	HRS		190.2			5340.2			0
		AFL		71			2528			0
		MOS		6.1			14 May 2022			
		MSC				O/C				
Airframe										
Notes: PN: 1159L50400-37 SN: 5045GC. PRESSURE GAGE: 569151CAL: 03/17										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
123211	Landing Gear Shock Struts and Actuating Cylinders (Left Main) - Cleaning	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										
123212	Landing Gear Shock Struts and Actuating Cylinders (Right Main) - Cleaning	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										
123213	Landing Gear Shock Struts and Actuating Cylinders (Nose) - Cleaning	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										
123501	Oxygen Cylinder - Servicing	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										
123502	Oxygen - Servicing	HRS AFL MOS MSC		957.2 362 29.1		 O/C	4573.2 2237 12 Jun 2020			0 0
Airframe										
124901	Auxiliary Power Unit Oil - Servicing	HRS AFL MOS MSC		882.2 304 26.5		 O/C	4648.2 2295 31 Aug 2020			0 0
Airframe										
124902	Auxiliary Power Unit Manual Oil Level - Check	HRS AFL MOS MSC		4593.3 2210 139.9		 O/C	937.1 389 19 Mar 2011			0 0
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
127901 Airframe	Fill Engine Oil System - Servicing	HRS AFL MOS MSC		1691.5 668 51.7		 O/C	3838.9 1931 24 Jul 2018			0 0
Notes: EXXON 2380										
127902 Airframe	Engine Oil Level Check (Left) - Servicing	HRS AFL MOS MSC		882.2 304 26.5		 O/C	4648.2 2295 31 Aug 2020			0 0
Notes: EXXON 2380										
127903 Airframe	Engine Oil Level Check (Right) - Servicing	HRS AFL MOS MSC		882.2 304 26.5		 O/C	4648.2 2295 31 Aug 2020			0 0
Notes: EXXON 2380										
127904 Airframe	Engine Oil System (Left) - Servicing	HRS AFL MOS MSC		4912.2 2432 151.7		 O/C	618.2 167 24 Mar 2010			0 0
Notes: EXXON 2380										
127905 Airframe	Engine Oil System (Right) - Servicing	HRS AFL MOS MSC		4912.2 2432 151.7		 O/C	618.2 167 24 Mar 2010			0 0
Notes: EXXON 2380										
127906 Airframe	APU Oil System - Servicing (Using Oil Replenish System)	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
128001 Airframe	Engine Starter (Left) - Oil Level Check 052000-1A,200100	HRS AFL MOS [HRS: +50/-50]		6.5 2 .2		500 	5523.9 2597 11 Nov 2022	6023.9	6073.9	0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
128002 Airframe	Engine Starter (Right) - Oil Level Check 052000-1A,200100	HRS AFL MOS [HRS: +50/-50]		6.5 2 .2		500	5523.9 2597 11 Nov 2022	6023.9	6073.9	0 0
128003 Airframe	AIR Turbine Starter Oil Drain (Left) - Servicing	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
128004 Airframe	AIR Turbine Starter Oil Drain (Right) - Servicing	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
20 - Standard Practices - Airframe										
200093 Airframe	Post Maintenance Servicing	HRS AFL DATE MSC				 O/C				0 0
200098[U] Engine	No. 1 Engine - 2A (1000 Hrs) Engine 1 Check	HRS ENC MOS [HRS: +50/-50]		6.5 2 .2		1000	5445.9 2548 11 Nov 2022	6445.9	6495.9	0 0
200099[U] Engine	No. 2 Engine - 2A (1000 Hrs) Engine 2 Check	HRS ENC MOS [HRS: +50/-50]		6.5 2 .2		1000	5445.9 2548 11 Nov 2022	6445.9	6495.9	0 0
200100[U] Airframe	1A (500 Hrs) Check	HRS AFL MOS [HRS: +50/-50]		6.5 2 .2		500	5523.9 2597 11 Nov 2022	6023.9	6073.9	0 0
200101[U] Airframe	1A (500 Hrs/24MOS) Check	HRS AFL MOS [MOS: +1m/-1m] [HRS: +50/-50]		6.5 2 .2		500 24	5523.9 2597 11 Nov 2022	6023.9 11 Nov 2024	6073.9 11 Dec 2024	0 0

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
200102U	2A (1000 Hrs) Check		HRS		6.5	49.3	1000	5523.9	6573.2*	6623.2	0
			AFL		2			2597			0
			MOS		.2			11 Nov 2022			
Airframe			[HRS: +50/-50]								
200103U	3A (1500 Hrs) Check		HRS		1129.5	-11	1500	4400.9	5889.9*	5939.9	0
			AFL		441			2158			0
			MOS		36.6			29 Oct 2019			
Airframe			[HRS: +50/-50]								
200104U	4A (2000 Hrs) Check		HRS		1769.5		2000	3760.9	5760.9	5810.9	0
			AFL		717			1882			0
			MOS		54.4			04 May 2018			
Airframe			[HRS: +50/-50]								
200105U	5A (2500 Hrs) Check		HRS		190.2		2500	5340.2	7840.2	7890.2	0
			AFL		71			2528			0
			MOS		6			15 May 2022			
Airframe			[HRS: +50/-5]								
200106U	6A (3000 Hrs) Check		HRS		5530.4	2889.9	3000	0	5889.9*	5939.9	0
			AFL		2599			0			0
			MOS		174.6			28 Apr 2008			
Airframe			[HRS: +50/-50]								
200110U	10A (5000 Hrs) Check		HRS		560.5	30.1	5000	4969.9	10000*	10050	0
			AFL		185			2414			0
			MOS		14.1			14 Sep 2021			
Airframe			[HRS: +50/-50]								
200201U	1C (12 Mos) Check		HRS		190.2			5340.2			0
			AFL		71			2528			0
			MOS		5.8	-9	12	23 May 2022	31 May 2023*	30 Jun 2023	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
200202U	2C (24 Mos) Check		HRS		190.2			5340.2			0
			AFL		71			2528			0
			MOS		5.8		24	23 May 2022	31 May 2024	30 Jun 2024	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
200203U	3C (36 Mos) Check		HRS		957.2			4573.2			0
			AFL		362			2237			0
			MOS		29.1	4	36	12 Jun 2020	30 Jun 2023*	31 Jul 2023	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
200204U	4C (48 Mos) Check		HRS		882.2			4648.2			0
			AFL		304			2295			0
			MOS		23.2	-40	48	10 Dec 2020	31 Oct 2024*	30 Nov 2024	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
200205U	5C (60 Mos) Check		HRS		190.2			5340.2			0
			AFL		71			2528			0
			MOS		6.1		60	14 May 2022	31 May 2027	30 Jun 2027	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
200206U	6C (72 Mos) Check		HRS		957.2			4573.2			0
			AFL		362			2237			0
			MOS		29.1		72	12 Jun 2020	30 Jun 2026	31 Jul 2026	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
200301U	24 Month Check		HRS		697.6			4832.8			0
			AFL		234			2365			0
			MOS		18.5		24	30 Apr 2021	30 Apr 2023	31 May 2023	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
200302U	48 Month Check		HRS		882.2			4648.2			0
			AFL		304			2295			0
			MOS		23.2	-40	48	10 Dec 2020	31 Oct 2024*	30 Nov 2024	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
200303U	72 Month Check		HRS		957.2			4573.2			0
			AFL		362			2237			0
			MOS		29.1	-20	72	12 Jun 2020	31 May 2026*	30 Jun 2026	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
200304U	96 Month Check		HRS		2367			3163.4			0
			AFL		954			1645			0
			MOS		72.3	-68	96	07 Nov 2016	31 Aug 2024*	30 Sep 2024	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
200305[U]	144 / 96 Month Check		HRS		882.2			4648.2			0
			AFL		304			2295			0
			MOS		23.2	-101	96	10 Dec 2020	31 Aug 2028*	30 Sep 2028	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
200306[U]	144 Month Check		HRS		882.2			4648.2			0
			AFL		304			2295			0
			MOS		23.2	-101	144	10 Dec 2020	31 Aug 2032*	30 Sep 2032	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
200307[U]	192 / 144 Month Check		HRS		5530.4			0			0
			AFL		2599			0			0
			MOS		174.6	125	192**	28 Apr 2008	31 Aug 2024*	30 Sep 2024	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
200308[U]	192 Month Check		HRS		5530.4			0			0
			AFL		2599			0			0
			MOS		174.6	125	192	28 Apr 2008	31 Aug 2024*	30 Sep 2024	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
21 - AIR Conditioning											
210001	AIR Conditioning System - Functional Check		HRS		439.3			5091.1			0
			AFL		157			2442			0
			MOS		12.1			12 Nov 2021			
Airframe			MSC				O/C				
212101	Cabin Silencer - Removal / Installation		HRS		5530.4			0			0
	1159AC50153-5	SN-UNKNOWN	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			
Airframe			MSC				O/C				
212102	Cockpit Silencer - Removal / Installation		HRS		5530.4			0			0
	1159AC50153-7	SN-UNKNOWN	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			
Airframe			MSC				O/C				

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
212103 Logbook Position	Pack Inlet Valve (Left) - Removal / Installation 396610-6 474C	HRS AFL MOS MSC		4138.4 1939 129.8		 O/C	1392 660 22 Jan 2012			0 0 HONEYWELL ENGINES SYSTEMS & SERVICE
Airframe										
Notes: VER BY Q307597										
212104 Logbook Position	Pack Inlet Valve (Right) - Removal / Installation 396610-6 1241	HRS AFL MOS MSC		4343.4 2048 134.5		 O/C	1187 551 30 Aug 2011			0 0 HONEYWELL ENGINES SYSTEMS & SERVICE
Airframe										
Notes: VER BY Q307597										
212201 Logbook Position	Ram AIR Check Valve - Removal / Installation 3202776-1 SN-UNKNOWN	HRS AFL MOS MSC	TSN:4969.9 TSN:2414 TSN:161	560.5 185 14.1		 O/C	4969.9 2414 14 Sep 2021			0 0
Airframe										
212202 Logbook Position	Ram AIR Check Valve - Detailed Inspection	HRS AFL MOS		560.5 185 14.1	30.1	5000	4969.9 2414 14 Sep 2021	10000*	10050	0 0
Airframe	052000-10A,200110	[HRS: +50/-50]								
Notes: PN: 320276-1 SN: <NONE>.										
212501 Logbook Position	Electronic Equipment Rack Cooling FANS (Left) - Removal / Installation 011989500 C08050220	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 AMETEK
Airframe										
212502 Logbook Position	Electronic Equipment Rack Cooling FANS (Right) - Removal / Installation 011989500 C07460058	HRS AFL MOS MSC	TSN:13 TSN:4	5517.4 2595 171.3		 O/C	13 4 06 Aug 2008			0 0 AMETEK
Airframe										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
212509	Personal Services Unit Cooling Fan - Removal / Installation 011990500 C10170126	HRS AFL MOS MSC		439.3 157 12.2		 O/C	5091.1 2442 10 Nov 2021			0 0 N/A
Airframe										
212510	Aft Equipment Cooling Fan - Removal / Installation 011586501 108043816	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 AMETEK
Airframe										
212513	Electronic Equipment Rack Cooling FANS (Left) - Operational Test	HRS AFL MOS MSC		5525.5 2597 173		 O/C	4.9 2 17 Jun 2008			0 0
Airframe										
212514	Electronic Equipment Rack Cooling FANS (Right) - Operational Test	HRS AFL MOS MSC		5525.5 2597 173		 O/C	4.9 2 17 Jun 2008			0 0
Airframe										
212517	Detector, Aft Eer Low Speed 035640501 E07512522	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										
212534	Modular Avionics Unit Cooling Fan (No. 2) - Removal / Installation PN SN-UNKNOWN	HRS AFL MOS MSC		4882.7 2421 149.5		 O/C	647.7 178 31 May 2010			0 0
Airframe										
213001	Cabin Pressurization Control - System Check	HRS AFL MOS MSC		2640.5 1094 89.4		 O/C	2889.9 1505 04 Jun 2015			0 0
Airframe										

Notes: PERFORMED CABIN PRESSURIZATION CONTROL OPERATIONAL TEST IAW CMP 213001. FOUND SATIS.

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
213006	Cabin Pressure Controller - Removal / Installation 2119146-4 18-F0204	HRS AFL MOS MSC	TSN:2284.2 TSN:1167 TSN:67	3246.2 1432 107.9		 O/C	2284.2 1167 20 Nov 2013			0 0 HONEYWELL
Airframe										
213007	Cabin Pressurization Selector Panel - Removal / Installation 2118936-1 28-B0465	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 HONEYWELL
Airframe										
Notes: SERIES:2										
213008	Cabin Pressurization Control Panel - Removal / Installation 2119144-1 27-A0275	HRS AFL MOS MSC		1164.6 455 37.5		 O/C	4365.8 2144 02 Oct 2019			0 0
Airframe										
213009	Cabin Pressurization Controller - System Check	HRS AFL MOS MSC		3246.2 1432 107.6		 O/C	2284.2 1167 28 Nov 2013			0 0
Airframe										
213011	Thrust Recovery Outflow Valve - Removal / Installation 103878-1 38-A0367	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 HONEYWELL AVIATION AFTERMARKET SERVICES
Airframe										
213015	Pressure Relief Valve - Removal / Installation 103832-3 28-F0133	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 HONEYWELL AVIATION AFTERMARKET SERVICES
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
213302	Differential Pressure Limiter Valve (Primary) - Functional Check	HRS AFL MOS [HRS: +50/-50]		190.2 71 6	49.7	2500	5340.2 2528 15 May 2022	7889.9*	7939.9	0 0
Airframe	052000-5A,200105									
213303	Differential Pressure Limiter Valve (Secondary) - Functional Check	HRS AFL MOS [HRS: +50/-50]		190.2 71 6		2500	5340.2 2528 17 May 2022	7840.2	7890.2	0 0
Airframe	052000-5A,200105									
213304	Differential Pressure Limiter Valve (Negative) - Functional Check	HRS AFL MOS [HRS: +50/-50]		190.2 71 6	49.7	2500	5340.2 2528 15 May 2022	7889.9*	7939.9	0 0
Airframe	052000-5A,200105									
213308	Pressure Relief Valve Remote AIR Filter - Detailed Inspection	HRS AFL MOS [HRS: +50/-50]		190.2 71 6.1		2500	5340.2 2528 13 May 2022	7840.2	7890.2	0 0
Airframe	052000-5A,200105									
213309	Remote AIR Filter - Removal / Installation 147240-1 N/A	HRS AFL MOS MSC	TSN:692 TSN:233 TSN:20	190.2 71 6.1		 O/C	5340.2 2528 13 May 2022			0 0 N/A
Airframe										
213401	Cabin Pressure Indicator (No. 1) - Removal / Installation 789537-2-2 0700	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 INTERTECHNIQUE
Airframe										
Notes: VERIFIED BY PQ246										
213403	Cabin Pressure Acquisition Module - Removal / Installation 714984-1-1 0223	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 AUTO VALVE INC
Airframe										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
215101	AIR Conditioning Controller (Left) - Removal / Installation 1152564-3 1152564-00636	HRS AFL MOS MSC		1416.9 561 42.7		 O/C	4113.5 2038 24 Apr 2019			0 0 HONEYWELL ENGINES SYSTEMS & SERVICE
Airframe										
215102	AIR Conditioning Controller (Right) - Removal / Installation 1152564-3 1152564-00597	HRS AFL MOS MSC		1416.9 561 42.7		 O/C	4113.5 2038 24 Apr 2019			0 0 HONEYWELL ENGINES SYSTEMS & SERVICE
Airframe										
215103	Pack Outlet Temperature Sensor (Left) - Removal / Installation 1151834-1 05398	HRS AFL MOS MSC	TSN:886.1 TSN:355 TSN:32	4644.3 2244 142.6		 O/C	886.1 355 27 Dec 2010			0 0 HONEYWELL ASCA INC.
Airframe										
Notes: VERIFIED BY Q302557										
215104	Pack Outlet Temperature Sensor (Right) - Removal / Installation 1151834-1 05400	HRS AFL MOS MSC	TSN:886.2 TSN:355 TSN:32	4644.2 2244 142.6		 O/C	886.2 355 27 Dec 2010			0 0 HONEYWELL ASCA INC.
Airframe										
Notes: VERIFIED BY Q302557										
215105	Compressor Outlet Temperature Sensor (Left) - Removal / Installation 1150124-2 1150124-07430	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 HONEYWELL ASCA INC.
Airframe										
Notes: Q306859										
215106	Compressor Outlet Temperature Sensor (Right) - Removal / Installation 1150124-2 1150124-07338	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 HONEYWELL ASCA INC.
Airframe										
Notes: Q306859										

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
Logbook Position	HW	SW									
	MM Ref										
	Ops Number(s)										
215201	AIR Conditioning Pack (Left) - Removal / Installation		HRS		5530.4			0			0
	2215080-3	1156	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			
			MSC				O/C				
Airframe											
Notes: Q302557											
215202	AIR Conditioning Pack (Right) - Removal / Installation		HRS		5530.4			0			0
	2215080-3	1160	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			
			MSC				O/C				
Airframe											
Notes: Q302557											
215203	Primary / Secondary Heat Exchangers (Left) - Removal / Installation		HRS		3246.1			2284.3			0
			AFL		1432			1167			0
	70210-2215080-3	1156	MOS		107.8			21 Nov 2013			
			MSC				O/C				
Airframe											
Notes: Q302557P/N REMOVED: 70210-2215080-3, S/N REMOVED: 1156											
215204	Primary / Secondary Heat Exchangers (Right) - Removal / Installation		HRS		5530.4			0			0
			AFL		2599			0			0
	70210-2341680-1	1908	MOS		174.6			28 Apr 2008			
			MSC				O/C				
Airframe											
Notes: Q302557											
215205	AIR Cycle Machine (Left) - Removal / Installation		HRS		5530.4			0			0
	2205590-1	1143	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			HONEYWELL ENGINES SYSTEMS & SERVICE
			MSC				O/C				
Airframe											
Notes: Q302557											

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
215206	AIR Cycle Machine (Right) - Removal / Installation 2205590-1 1136	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0 HONEYWELL ENGINES SYSTEMS & SERVICE
Airframe										
Notes: Q302557										
215207	Low Limit Valve (Left) - Removal / Installation 3291284-1 354	HRS AFL MOS MSC		4644.2 2244 142.6		O/C	886.2 355 27 Dec 2010			0 0
Airframe										
215208	Low Limit Valve (Right) - Removal / Installation 3291284-1 1174	HRS AFL MOS MSC	TSN:886.2 TSN:355 TSN:32	4644.2 2244 142.6		O/C	886.2 355 27 Dec 2010			0 0
Airframe										
215213	Turbine Inlet Temperature Sensor (Left) - Removal / Installation 1150124-2 07360	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0 HONEYWELL ASCA INC.
Airframe										
Notes: Q302557										
215214	Turbine Inlet Temperature Sensor (Right) - Removal / Installation 1150124-2 07374	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0 HONEYWELL ASCA INC.
Airframe										
Notes: Q302557										
215215	Reheater / Condenser (Left) - Removal / Installation 70210-2341142-1 SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0
Airframe										
215216	Reheater / Condenser (Right) - Removal / Installation X SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0
Airframe										

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Description: Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
215225	Heat Exchanger, Lh Secondary 70210-2341682-1	1866	HRS AFL MOS MSC		5530.4 2599 174.6			0 0 28 Apr 2008			0 0
Airframe							O/C				
Notes: Q302557											
215226	Heat Exchanger, Rh Secondary 70210-2341682-1	1870	HRS AFL MOS MSC		5530.4 2599 174.6			0 0 28 Apr 2008			0 0
Airframe							O/C				
Notes: Q302557											
216101	Zone Trim AIR Valve (Cockpit) - Removal / Installation 3291688-3	573	HRS AFL MOS MSC		1416.9 561 42.6			4113.5 2038 29 Apr 2019			0 0 HONEYWELL ENGINES SYSTEMS & SERVICE
Airframe							O/C				
Notes: VERFIED BY Q124019											
216102	Zone Trim AIR Valve (Forward Cabin) - Removal / Installation 3291688-3	235	HRS AFL MOS MSC		1416.9 561 42.6			4113.5 2038 29 Apr 2019			0 0 HONEYWELL ENGINES SYSTEMS & SERVICE
Airframe							O/C				
216103	Zone Trim AIR Valve (Aft Cabin) - Removal / Installation 3291688-3	1326	HRS AFL MOS MSC		1416.9 561 42.6			4113.5 2038 29 Apr 2019			0 0 HONEYWELL ENGINES SYSTEMS & SERVICE
Airframe							O/C				

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
216105	Overheat Thermostat Zone Supply (Zone No. 1) - Removal / Installation 129740-1-1 1151834-05372	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 HONEYWELL ENGINES SYSTEMS & SERVICE
Airframe										
216106	Overheat Thermostat Zone Supply (Zone No. 2) - Removal / Installation 129740-1-1 1151834-05380	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 HONEYWELL ENGINES SYSTEMS & SERVICE
Airframe										
216107	AIR Supply / Zone Trim AIR Check Valve (Left, Cold) - Detailed Inspection	HRS AFL MOS		957.2 362 29.1	 -12	 72	4573.2 2237 12 Jun 2020	 31 May 2026*	 30 Jun 2026	0 0
	[End Of Month Item] [MOS: +1m/-1m]									
Airframe										
216108	AIR Supply / Zone Trim AIR Check Valve (Right, Cold) - Detailed Inspection	HRS AFL MOS		957.2 362 29.1	 -12	 72	4573.2 2237 12 Jun 2020	 31 May 2026*	 30 Jun 2026	0 0
	[End Of Month Item] [MOS: +1m/-1m]									
Airframe										
216113	AIR Supply and Zone Trim AIR Check Valves (Left, Hot) - Removal / Installation 3202760-2 2130	HRS AFL MOS MSC		957.2 362 29.1		 O/C	4573.2 2237 12 Jun 2020			0 0
Airframe										
Notes: VERFIED BY Q124019										
216114	AIR Supply and Zone Trim AIR Check Valves (Right, Hot) - Removal / Installation 123190-1 SN-UNKNOWN	HRS AFL MOS MSC		957.2 362 29.1		 O/C	4573.2 2237 12 Jun 2020			0 0
Airframe										
Notes: VERFIED BY Q124019										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
216115 Airframe	AIR Supply and Zone Trim AIR Check Valves (Left, Cold) - Removal / Installation 3202760-2 1175	HRS AFL MOS MSC		957.2 362 29.1		 O/C	4573.2 2237 12 Jun 2020			0 0
216116 Airframe	AIR Supply and Zone Trim AIR Check Valves (Right, Cold) - Removal / Installation 123190-1 SN-UNKNOWN	HRS AFL MOS MSC	TSN:4573.2 TSN:2237	957.2 362 29.1		 O/C	4573.2 2237 12 Jun 2020			0 0
216117 Airframe	AIR Supply / Zone Trim AIR Check Valve (Left, Hot) - Detailed Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		957.2 362 29.1	-12	 72	4573.2 2237 12 Jun 2020	31 May 2026*	30 Jun 2026	0 0
216118 Airframe	AIR Supply / Zone Trim AIR Check Valve (Right, Hot) - Detailed Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		957.2 362 29.1	-12	 72	4573.2 2237 12 Jun 2020	31 May 2026*	30 Jun 2026	0 0
216120 Airframe	Low Speed Warning Detector (Zone No. 1) - Removal / Installation 035640501 E08050166	HRS AFL MOS MSC	TSN:4.9 TSN:2 TSN:1	5525.5 2597 174.5		 O/C	4.9 2 02 May 2008			0 0
216121 Airframe	Low Speed Warning Detector (Zone No. 2) - Removal / Installation 035640501 E08050158	HRS AFL MOS MSC	TSN:4.9 TSN:2 TSN:1	5525.5 2597 174.5		 O/C	4.9 2 02 May 2008			0 0
216201 Airframe	Cabin / Cockpit Temperature Indication - Functional Test	HRS AFL MOS MSC		4644.3 2244 142.6		 O/C	886.1 355 27 Dec 2010			0 0

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
216401	Cabin / Cockpit Temperature Indicator (Cockpit) - Removal / Installation		HRS		5530.4			0			0
			AFL		2599			0			0
	789575-2-1	0656	MOS		174.6			28 Apr 2008			VOUGHT AIRCRAFT INDUSTRIES INC.
			MSC				O/C				
Airframe											
Notes: VERIFIED BY PQ246											
216402	Cabin / Cockpit Temperature Indicator (Zone No.1) - Removal / Installation		HRS		5530.4			0			0
			AFL		2599			0			0
	789575-1	SN-UNKNOWN	MOS		174.6			28 Apr 2008			VOUGHT AIRCRAFT INDUSTRIES INC.
			MSC				O/C				
Airframe											
216403	Cabin / Cockpit Temperature Indicator (Zone No. 2) - Removal / Installation		HRS		5530.4			0			0
			AFL		2599			0			0
	789575-1	SN-UNKNOWN	MOS		174.6			28 Apr 2008			VOUGHT AIRCRAFT INDUSTRIES INC.
			MSC				O/C				
Airframe											
216404	Zone Supply Temperature Sensor (Cockpit) - Removal / Installation		HRS		5530.4			0			0
			AFL		2599			0			0
	1151834-1	1151834-05411	MOS		174.6			28 Apr 2008			HONEYWELL ASCA INC.
			MSC				O/C				
Airframe											
216405	Zone Supply Temperature Sensor (Forward Cabin) - Removal / Installation		HRS	TSN:4.9	5525.5			4.9			0
			AFL	TSN:2	2597			2			0
	1151834-1	1151834-05373	MOS	TSN:1	174.5			02 May 2008			HONEYWELL ASCA INC.
			MSC				O/C				
Airframe											
216406	Zone Supply Temperature Sensor (Aft Cabin) - Removal / Installation		HRS	TSN:4.9	5525.5			4.9			0
			AFL	TSN:2	2597			2			0
	1151834-1	1151834-05371	MOS	TSN:1	174.5			02 May 2008			HONEYWELL ASCA INC.
			MSC				O/C				
Airframe											

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
216407	Zone Temperature Sensor (Cockpit) - Removal / Installation 129740-1-1 2817	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 HONEYWELL ENGINES SYSTEMS & SERVICE
Airframe										
216408	Zone Temperature Sensor (Forward Cabin) - Removal / Installation 1151834-1 108067894	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 HONEYWELL ASCA INC.
Airframe										
216409	Zone Temperature Sensor (Aft Cabin) - Removal / Installation 1151834-1 108067900	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 HONEYWELL ASCA INC.
Airframe										
216411	Zone Temperature Sensor Fan (Forward Cabin) - Removal / Installation 011590500 108067894	HRS AFL MOS MSC	TSN:4.9 TSN:2 TSN:1	5525.5 2597 174.5		 O/C	4.9 2 02 May 2008			0 0 MPC PRODUCTS
Airframe										
216412	Zone Temperature Sensor Fan (Aft Cabin) - Removal / Installation 011590500 108067900	HRS AFL MOS MSC	TSN:4.9 TSN:2 TSN:1	5525.5 2597 174.5		 O/C	4.9 2 02 May 2008			0 0 MPC PRODUCTS
Airframe										
217001	Ozone Converter (Left) - Removal / Installation 1159SCAC501-1 7025	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 COX & COMPANY INC
Airframe										

Notes: VER BY Q307597

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
217002 Airframe	Ozone Converter (Right) - Removal / Installation 1159SCAC501-1 7027	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 COX & COMPANY INC
Notes: VER BY Q307597										
217003 Airframe	Ozone Converter (Left) - Functional Test	HRS AFL MOS [HRS: +50/-50]		5530.4 2599 174.6		10000	0 0 28 Apr 2008	10000	10050	0 0
Notes: PN: 1159SCAC501-1 SN: <NONE>. SET TO MASTER										
217004 Airframe	Ozone Converter (Right) - Functional Test	HRS AFL MOS [HRS: +50/-50]		5530.4 2599 174.6		10000	0 0 28 Apr 2008	10000	10050	0 0
Notes: PN: 1159SCAC501-1 SN: <NONE>.										
22 - Auto Flight										
221001 Airframe	Flight Guidance Panel - Removal / Installation 7021852-901 00120250	HRS AFL MOS MSC		1300.7 510 40.4		 O/C	4229.7 2089 05 Jul 2019			0 0 HONEYWELL
221002 Airframe	Autopilot - Operational Check	HRS AFL MOS MSC		1300.7 510 40.4		 O/C	4229.7 2089 05 Jul 2019			0 0
221200 Airframe	Aileron Servo - Operational Test	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
221202 Airframe	Aileron Servo No. 2 - Removal / Installation 6264-164 024	HRS AFL MOS MSC		1008.2 397 33.5		 O/C	4522.2 2202 02 Feb 2020			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
221204 Airframe	Aileron Servo Bracket Assembly No. 2 - Removal / Installation 4-6264-151 158	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0
221205 Airframe	Module,Proc 7 Afcs Cont 1-Mau 7029305-1902 13062266	HRS AFL MOS MSC		3246.2 1432 107.9		O/C	2284.2 1167 18 Nov 2013			0 0 HONEYWELL
221206 Airframe	Module,Proc 9 Afcs Cont 2-Mau 7029305-1902 13072338	HRS AFL MOS MSC		3246.2 1432 107.9		O/C	2284.2 1167 20 Nov 2013			0 0 HONEYWELL
221207 Airframe	Module,Proc#8 Afcs Mon#1-Mau#1 7028432-1902 1305G364	HRS AFL MOS MSC		3246.2 1432 107.9		O/C	2284.2 1167 18 Nov 2013			0 0 HONEYWELL
221208 Airframe	Module,PROC10 Afcs Mon 2-Mau 2 7028432-1902 1307G705	HRS AFL MOS MSC		3246.2 1432 107.9		O/C	2284.2 1167 20 Nov 2013			0 0 HONEYWELL
221209 Airframe	Aileron Servo Bracket Assembly - Rigging	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0
221301 Airframe	Elevator Autopilot Servo Bracket - Removal / Installation 6264-162 177	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0

Notes: VERFIED BY PQ211

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
221303	Elevator Autopilot Servo - Removal / Installation 2-6264-151 172	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										
Notes: VERFIED BY PQ211										
221305	Elevator Trim Servo - Removal / Installation 7000260-503 1408H653	HRS AFL MOS MSC		844.4 290 22.2		 O/C	4686 2309 11 Jan 2021			0 0 N/A
Airframe										
221306	Elevator Trim Servo Bracket - Removal / Installation 7000261-604 0802H145	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 HONEYWELL
Airframe										
221307	Elevator Trim Servo Bracket Assembly - Rigging	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										
221308	Elevator Trim Servo - Operational Test	HRS AFL MOS MSC		844.4 290 22.2		 O/C	4686 2309 11 Jan 2021			0 0
Airframe										
223005	Auto Throttle - Operational Check	HRS AFL MOS MSC		957.2 362 29.1		 O/C	4573.2 2237 12 Jun 2020			0 0
Airframe										
23 - Communications										
231003	VHF Communication Antenna No. 1 - Removal / Installation DMC50-22-1 4659	HRS AFL MOS MSC	TSN:1	957.2 362 29.1		 O/C	4573.2 2237 12 Jun 2020			0 0
Airframe										
Notes: PQ162										

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Description: Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
231004	VHF Communication Antenna No. 2 - Removal / Installation		HRS		957.2			4573.2			0
			AFL		362			2237			0
	DMC50-22-1	1879	MOS		29.1			12 Jun 2020			
			MSC				O/C				
Airframe											
231005	Transceiver, #3 VHF Comm		HRS		957.2			4573.2			0
	7026203-813	07080348	AFL		362			2237			0
			MOS		29.1			12 Jun 2020			
			MSC				O/C				
Airframe											
Notes: VERFIED BY:PQ005											
231006	VHF Communication Antenna No. 3 - Removal / Installation		HRS		957.2			4573.2			0
			AFL		362			2237			0
	DMC50-22-1	1903	MOS		29.1			12 Jun 2020			
			MSC				O/C				
Airframe											
231010	VHF Voice Communications - Operational Test		HRS		882.2			4648.2			0
			AFL		304			2295			0
			MOS		23			15 Dec 2020			
			MSC				O/C				
Airframe											
231015	VHF Data Radio - Return to Service Test		HRS		2643.1			2887.3			0
			AFL		1095			1504			0
			MOS		90.6			29 Apr 2015			
			MSC				O/C				
Airframe											
231101	High Frequency Receiver / Transmitter No. 1 - Removal / Installation		HRS		659.7			4870.7			0
			AFL		220			2379			0
	822-0102-001	1750	MOS		17.2			09 Jun 2021			
			MSC				O/C				
Airframe											
231102	High Frequency Receiver / Transmitter No. 2 - Removal / Installation		HRS		659.7			4870.7			0
			AFL		220			2379			0
	822-0102-001	6142	MOS		17.2			09 Jun 2021			
			MSC				O/C				
Airframe											

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
231105 Airframe	Antenna Coupler Unit No. 1 - Removal / Installation 622-8114-002 6159	HRS AFL MOS MSC		882.2 304 25.8		 O/C	4648.2 2295 21 Sep 2020			0 0
231110 Airframe	HF Antenna - Removal / Installation 1159CS40160-802-25 1662	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 GULFSTREAM SAV PROD-IPT
Notes: PQ211										
231112 Airframe	HF Shunt Antenna - Continuity Check	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
231120 Airframe	High Frequency Voice Communications - Operational Check	HRS AFL MOS MSC		659.7 220 17.2		 O/C	4870.7 2379 09 Jun 2021			0 0
231121 Airframe	High Frequency Antenna Adapter - Removal / Installation 822-0089-001 1088	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 ROCKWELL COLLINS
231203 Airframe	Radio Telecommunications Antenna - Removal / Installation UNK UNK	HRS AFL MOS MSC		3021.1 1338 102.2		 O/C	2509.3 1261 09 May 2014			0 0 MATRIX AVIATION INC
231241 Airframe	Voice / Data Radio Module No. 1 - Removal / Installation 7026201-813 08034343	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 FINISHMASTER INC.
Notes: MOD: E,F,K,M (VERFIED BY:PQ005)										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
231244	Voice / Data Radio Module No. 2 - Removal / Installation 7026201-813 08034368	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 FINISHMASTER INC.
Airframe										
Notes: MOD:E,F,K,M (VERFIED BY:PQ005)										
231301	Antenna Coupler Unit No. 1 - Servicing	HRS AFL MOS MSC		882.2 304 25.8		 O/C	4648.2 2295 21 Sep 2020			0 0
Airframe										
231400	Aircell In-Flight Telecommunications System - Operational Check	HRS AFL MOS MSC		957.2 362 29.1		 O/C	4573.2 2237 12 Jun 2020			0 0
Airframe										
231401	Antenna, Wireless LAN Access Point-Primary PERMANENT REMOVAL PERMANENT REMOVAL	HRS AFL MOS MSC		2367 954 73.4		 O/C	3163.4 1645 05 Oct 2016			0 0 CISCO SYSTEMS
Airframe										
Notes: CE41 4280164 REV -										
231405	In-Flight Telecommunications System - Operational Check	HRS AFL MOS MSC		3021.1 1338 102		 O/C	2509.3 1261 15 May 2014			0 0
Airframe										
231481	Aircell Satellite Transceiver - Removal / Installation P12023 1202311230	HRS AFL MOS MSC		5512.4 2593 171.1		 O/C	18 6 12 Aug 2008			0 0
Airframe										
231491	Handset-(L/H Seat #4) Aircell/Iridium WIP-330 MSL8108200177	HRS AFL MOS MSC		5525.5 2597 172		 O/C	4.9 2 17 Jul 2008			0 0
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
231493 Airframe	Handset-(R/H Vip Seat) Aircell/Iridium WIP-330 MLS8108200180	HRS AFL MOS MSC		5525.5 2597 172		 O/C	4.9 2 17 Jul 2008			0 0
231494 Airframe	Handset-(Conf Table) Aircell/Iridium WIP-330 AL816H400648	HRS AFL MOS MSC		5525.5 2597 172		 O/C	4.9 2 17 Jul 2008			0 0
231499 Airframe	Aircell Call Alerter - Removal / Installation P12924 1292410059	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
231502 Airframe	Aircell Dual Channel Satellite Antenna - Removal / Installation S67-1575-165 449-2618	HRS AFL MOS MSC		957.2 362 29.1		 O/C	4573.2 2237 12 Jun 2020			0 0
231510 Airframe Notes: REV.B	Aircell Handset Interface Unit - Removal / Installation P12346 1234611986	HRS AFL MOS MSC		2698.6 1124 92.3		 O/C	2831.8 1475 07 Mar 2015			0 0
231513 Airframe Notes: REV.C	Aircell Satellite Interface Unit - Removal / Installation P12777 1277711376	HRS AFL MOS MSC		2623.3 1084 82.1		 O/C	2907.1 1515 14 Jan 2016			0 0 AIRCELL
231514 Airframe	Aircell Cabin Telecommunication Router (Ctr) - Removal / Installation P12083-001 1208370862	HRS AFL MOS MSC		2256 928 69.8		 O/C	3274.4 1671 22 Jan 2017			0 0 Aircell

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
Logbook Position	HW	SW									
	MM Ref										
	Ops Number(s)										
231543	Programmable Switch Panel 441-0010-102	44VC1X	HRS AFL MOS MSC	TSN:1	2367 954 72.3		O/C	3163.4 1645 07 Nov 2016			0 0 GAC
Airframe											
Notes: CE415710058 REV. -											
232101	Antenna Tray, SATCOM (Vert) 806-10-1001-5 A	OPOOO306 B	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0
Airframe											
232102	Satellite Data Unit - Removal / Installation 7516118-27011	6700082	HRS AFL MOS MSC	TSN:2284.3 TSN:1167 TSN:67	3246.1 1432 107.7		O/C	2284.3 1167 26 Nov 2013			0 0 HONEYWELL
Airframe											
Notes: VERFIED BY:PQ005											
232103	High Power Amplifier - Removal / Installation 1252-A-3600-02	1372	HRS AFL MOS MSC		2896 1249 97.6		O/C	2634.4 1350 28 Sep 2014			0 0 HONEYWELL
Airframe											
Notes: VERFIED BY:PQ005											
232113	Diplexer, Lna 804-10-0025	1043-0576	HRS AFL MOS MSC	TSN:4	4593.3 2210 139.9		O/C	937.1 389 19 Mar 2011			0 0
Airframe											
232133	Satellite Communications System - Operational Check		HRS AFL MOS MSC		2623.3 1084 82.1		O/C	2907.1 1515 14 Jan 2016			0 0
Airframe											
232210	Facsimile Machine No. 1 - Final Phase Removal / Installation MFC-440CN	G7F418688	HRS AFL MOS MSC		5525.5 2597 174.1		O/C	4.9 2 13 May 2008			0 0 CHELTON INC
Airframe											

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
Logbook Position	HW	SW									
	MM Ref										
	Ops Number(s)										
232263	Router, Bbml PERMANENT REMOVAL	PERMANENT REMOVAL	HRS AFL MOS MSC	2367 954 72.7			O/C	3163.4 1645 24 Oct 2016			0 0 ZyXEL
Airframe											
Notes: CE41 4290147 REV -											
232280	Storage Drive-Cabin LAN PERMANENT REMOVAL	PERMANENT REMOVAL	HRS AFL MOS MSC	2367 954 72.7			O/C	3163.4 1645 24 Oct 2016			0 0
Airframe											
Notes: CE41 4290147 REV -											
233002	Speaker, Galley Call System DT-PA2N	064596059	HRS AFL MOS MSC	5525.5 2597 174.6			O/C	4.9 2 29 Apr 2008			0 0
Airframe											
233011	Speaker, Cabin Paging DT-PA2N	080484016	HRS AFL MOS MSC	5525.5 2597 173.6			O/C	4.9 2 27 May 2008			0 0 CYTEC ENGINEERED MATERIALS
Airframe											
233012	Speaker, Cabin Paging DT-PA2N	080483010	HRS AFL MOS MSC	5525.5 2597 173.6			O/C	4.9 2 27 May 2008			0 0 CYTEC ENGINEERED MATERIALS
Airframe											
233013	Speaker, Cabin Paging DT-PA2N	080483014	HRS AFL MOS MSC	5525.5 2597 173.6			O/C	4.9 2 27 May 2008			0 0 CYTEC ENGINEERED MATERIALS
Airframe											

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
Logbook Position	HW	SW									
	MM Ref										
	Ops Number(s)										
233014	Speaker, Cabin Paging DT-PA2N	080483029	HRS AFL MOS MSC		5525.5 2597 173.6		 O/C	4.9 2 27 May 2008			0 0 CYTEC ENGINEERED MATERIALS
Airframe											
233019	Speaker, Cabin Paging DT-PA2N	080483019	HRS AFL MOS MSC		5525.5 2597 174.5		 O/C	4.9 2 02 May 2008			0 0 CYTEC ENGINEERED MATERIALS
Airframe											
233028	Switch Panel, Fwd Vip 2501-2-434Q551A	317GB	HRS AFL MOS MSC		2367 954 73		 O/C	3163.4 1645 17 Oct 2016			0 0
Airframe											
233030	Switch Panel, Aft Vip 2501-2-096	3175C	HRS AFL MOS MSC		5525.5 2597 174.6		 O/C	4.9 2 29 Apr 2008			0 0
Airframe											
233031	Panel, #1 Entertainment Switch 2501-2-074Q551A	3178M	HRS AFL MOS MSC		2367 954 72.9		 O/C	3163.4 1645 20 Oct 2016			0 0
Airframe											
233032	Panel, #2 Entertainment Switch 2501-2-075	3175K	HRS AFL MOS MSC		5525.5 2597 174.6		 O/C	4.9 2 29 Apr 2008			0 0 AIRSHOW INC.
Airframe											
233033	Panel, #3 Entertainment Switch 2501-2-538	3179V	HRS AFL MOS MSC		5525.5 2597 174.6		 O/C	4.9 2 29 Apr 2008			0 0 AIRSHOW INC.
Airframe											

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
233034	Panel, #4 Entertainment Switch 2501-2-539	3179R	HRS AFL MOS MSC		5525.5 2597 174.6		O/C	4.9 2 29 Apr 2008			0 0 AIRSHOW INC.
Airframe											
233035	Panel, #5 Entertainment Switch 2501-2-002	316XF	HRS AFL MOS MSC		5525.5 2597 174.6		O/C	4.9 2 29 Apr 2008			0 0 AIRSHOW INC.
Airframe											
233036	Panel, #6 Entertainment Switch 2501-2-0029	316NC	HRS AFL MOS MSC		5525.5 2597 172		O/C	4.9 2 16 Jul 2008			0 0 AIRSHOW INC.
Airframe											
233037	Panel, #7 Entertainment Switch 2501-2-030	3175B	HRS AFL MOS MSC		5525.5 2597 172		O/C	4.9 2 16 Jul 2008			0 0 AIRSHOW INC.
Airframe											
233038	Panel, #8 Entertainment Switch 2501-2-004	3178K	HRS AFL MOS MSC		5525.5 2597 174.6		O/C	4.9 2 29 Apr 2008			0 0 AIRSHOW INC.
Airframe											
233039	Panel, #9 Entertainment Switch 2501-2-075	3175L	HRS AFL MOS MSC		5525.5 2597 174.6		O/C	4.9 2 29 Apr 2008			0 0 AIRSHOW INC.
Airframe											
233040	Panel,#10 Entertainment Switch 2501-2-002	316XD	HRS AFL MOS MSC		5525.5 2597 172		O/C	4.9 2 16 Jul 2008			0 0 AIRSHOW INC.
Airframe											
233041	Panel, #11 Entertainment Sw 2501-2-004	3178L	HRS AFL MOS MSC		5525.5 2597 174.6		O/C	4.9 2 29 Apr 2008			0 0 AIRSHOW INC.
Airframe											

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Description: Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
233042	Panel, #12 Entertainment Sw 2501-2-002-Q551A	316XF	HRS AFL MOS MSC	TSN:9.1 TSN:2 TSN:4	5512.4 2593 171.1		 O/C	18 6 12 Aug 2008			0 0 AIRSHOW INC.
Airframe											
233043	Panel, #13 Entertainment Sw 2501-2-002	316XG	HRS AFL MOS MSC		5525.5 2597 172		 O/C	4.9 2 16 Jul 2008			0 0 AIRSHOW INC.
Airframe											
233044	Panel, #14 Entertainment Sw 2501-2-004	3178K	HRS AFL MOS MSC		5525.5 2597 172		 O/C	4.9 2 16 Jul 2008			0 0 AIRSHOW INC.
Airframe											
233045	Panel, #15 Entertainment Sw 2501-2-044	31790	HRS AFL MOS MSC		5525.5 2597 171.7		 O/C	4.9 2 25 Jul 2008			0 0
Airframe											
233046	Panel, #16 Entertainment Sw 2501-2-045	3177F	HRS AFL MOS MSC		5525.5 2597 171.7		 O/C	4.9 2 25 Jul 2008			0 0
Airframe											
233047	Panel, #17 Entertainment Sw 2501-4-008	3174Y	HRS AFL MOS MSC		5525.5 2597 174.3		 O/C	4.9 2 08 May 2008			0 0
Airframe											
233052	Video Control Unit 100-2415-01	0808726	HRS AFL MOS MSC		5525.5 2597 174.3		 O/C	4.9 2 06 May 2008			0 0 INSIGHT DIRECT,INC
Airframe											
233089	DVD Player #2 866-0027-005	725-0715	HRS AFL MOS MSC		4480 2140 137		 O/C	1050.4 459 17 Jun 2011			0 0 GULFSTREAM - APPLETON
Airframe											

Notes: UNIT TESTED - APRIL 19, 2011. FL015198. (S/NO. 725-0083 TAKEN OFF @ 1050:23 HRS, 459 CYCLES FL015198).

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
233096	Player, CD 3210-1-1	207460024	HRS AFL MOS MSC		5525.5 2597 174.6		 O/C	4.9 2 29 Apr 2008			0 0 GULFSTREAM DALLAS
Airframe											
233102	Monitor, #1 R/H Seat 7002-061	0805J047	HRS AFL MOS MSC		5525.5 2597 171.8		 O/C	4.9 2 22 Jul 2008			0 0 ROSEN AVIATION DISPLAYS, LLC
Airframe											
233103	Monitor, #2 L/H Seat 7002-060	0805J077	HRS AFL MOS MSC		5525.5 2597 171.8		 O/C	4.9 2 22 Jul 2008			0 0 ROSEN AVIATION DISPLAYS, LLC
Airframe											
233104	Monitor, #2 R/H Seat 7002-060	0805J075	HRS AFL MOS MSC		5522.5 2597 171.8		 O/C	7.9 2 22 Jul 2008			0 0 ROSEN AVIATION DISPLAYS, LLC
Airframe											
233105	Monitor, #3 L/H Seat 7002-061	0805J052	HRS AFL MOS MSC		5525.6 2597 171.8		 O/C	4.8 2 22 Jul 2008			0 0 ROSEN AVIATION DISPLAYS, LLC
Airframe											
233106	Monitor, #3 R/H Seat 7002-060	0805J074	HRS AFL MOS MSC		5525.5 2597 171.8		 O/C	4.9 2 22 Jul 2008			0 0 ROSEN AVIATION DISPLAYS, LLC
Airframe											
233107	Monitor, #4 L/H Seat 7002-061	0805J045	HRS AFL MOS MSC		5525.5 2597 171.8		 O/C	4.9 2 22 Jul 2008			0 0 ROSEN AVIATION DISPLAYS, LLC
Airframe											

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Description: Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
233112	Monitor, Credenza 1700-002	0707T006	HRS AFL MOS MSC		5525.5 2597 172		O/C	4.9 2 16 Jul 2008			0 0 GULFSTREAM DALLAS
Airframe											
233118	Monitor, Lcd (Right Forward) 1700-002	0708T020	HRS AFL MOS MSC		2367 954 72.3		O/C	3163.4 1645 07 Nov 2016			0 0
Airframe											
Notes: GC41 5020348 REV -											
233119	Monitor, Lcd (Left Aft) 2002-002	0805N013	HRS AFL MOS MSC		5525.5 2597 172.2		O/C	4.9 2 10 Jul 2008			0 0
Airframe											
233134	Panel, Credenza Control 2501-2-380	3176N	HRS AFL MOS MSC	TSN:3	5525.5 2597 172.2		O/C	4.9 2 09 Jul 2008			0 0
Airframe											
233166	Dcu 4088467-902	35546041	HRS AFL MOS MSC		2549.1 1053 80.4		O/C	2981.3 1546 05 Mar 2016			0 0
Airframe											
233167	Antenna Control Unit, SAT Tv 4088470-901	32622894	HRS AFL MOS MSC		2367 954 72.5		O/C	3163.4 1645 02 Nov 2016			0 0
Airframe											
Notes: GC41 5070064 REV C											
233168	Multi Switch Controller, SAT Tv 4088479-901	32640390	HRS AFL MOS MSC		2367 954 72.5		O/C	3163.4 1645 02 Nov 2016			0 0
Airframe											
Notes: GC41 5070064 REV C											

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Description: Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
233169	Receiver Module, SAT Tv #1		HRS		2367			3163.4			0
	4088477-902	32601749	AFL		954			1645			0
			MOS		72.5			02 Nov 2016			
			MSC				O/C				
Airframe											
Notes: GC41 5070064 REV C											
233170	Power Supply, SAT Tv -Rack Fan		HRS		2367			3163.4			0
	4088485-901	32655762	AFL		954			1645			0
			MOS		72.5			02 Nov 2016			
			MSC				O/C				
Airframe											
Notes: GC41 5070064 REV C											
233172	MR500 Card Cage		HRS		2367			3163.4			0
	4088500	32614425-901	AFL		954			1645			0
			MOS		72.5			02 Nov 2016			
			MSC				O/C				
Airframe											
Notes: GC41 5070064 REV C											
233173	High Speed Data Router		HRS		2367			3163.4			0
	PERMANENT REMOVAL	PERMANENT REMOVAL	AFL		954			1645			0
			MOS		72.4			04 Nov 2016			
			MSC				O/C				
Airframe											
Notes: CE41 3030177 REV -											
233185	Remote, Cabin #1 Touch Screen		HRS		5525.5			4.9			0
	2507-1-003	207460158	AFL		2597			2			0
			MOS		172			15 Jul 2008			AIRSHOW INC.
			MSC				O/C				
Airframe											
233186	Remote, Cabin #2 Touch Screen		HRS		5525.5			4.9			0
	2507-1-003	207350144	AFL		2597			2			0
			MOS		172			15 Jul 2008			AIRSHOW INC.
			MSC				O/C				
Airframe											
233201	Camera, Vertical Stab		HRS		882.2			4648.2			0
	100-1054-02	1232	AFL		304			2295			0
			MOS		24.8			22 Oct 2020			
			MSC				O/C				
Airframe											

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
233202	Camera, Fwd Looking 100-1056-02	0808739	HRS AFL MOS MSC		957.2 362 29.1		 O/C	4573.2 2237 12 Jun 2020			0 0
Airframe											
233203	Camera, Aft Looking 100-1056-02	0809833	HRS AFL MOS MSC		5525.5 2597 171.8		 O/C	4.9 2 23 Jul 2008			0 0 SECURAPLANE TECHNOLOGIES, LLC
Airframe											
233215	Unit, Airshow Data Management 925000-100	D01002605	HRS AFL MOS MSC		4480 2140 136.1		 O/C	1050.4 459 12 Jul 2011			0 0 ROCKWELL COLLINS
Airframe											
233222	Computer, Airshow Display 926000-100	D01002606	HRS AFL MOS MSC	TSN:2284.2 TSN:1167 TSN:67	3246.2 1432 107.6		 O/C	2284.2 1167 27 Nov 2013			0 0 UNISON INDUSTRIES
Airframe											
233223	Controller, Airshow 922000-2	H01002548	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 ELECTRO ENTERPRISES INC
Airframe											
233251	Subwoofer, #1 DT-AUS-4MSGA	0704474002	HRS AFL MOS MSC		5525.5 2597 172		 O/C	4.9 2 17 Jul 2008			0 0 GULFSTREAM DALLAS
Airframe											
233252	Subwoofer, #2 DT-AUS-4MSGA	080474004	HRS AFL MOS MSC		5525.5 2597 172		 O/C	4.9 2 17 Jul 2008			0 0 GULFSTREAM DALLAS
Airframe											

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
233253	Subwoofer, #3 DT-AUS-4MSGA	0804474007	HRS AFL MOS MSC		5525.5 2597 172		O/C	4.9 2 17 Jul 2008			0 0 GULFSTREAM DALLAS
Airframe											
233254	Subwoofer, #4 DT-AUS-4MSGA	080402005	HRS AFL MOS MSC		5525.5 2597 172		O/C	4.9 2 17 Jul 2008			0 0 GULFSTREAM DALLAS
Airframe											
233261	Module, Cabin Management 1944-1-8/1944-512-20	4CT2F	HRS AFL MOS MSC		922.4 336 27.8		O/C	4608 2263 21 Jul 2020			0 0
Airframe											
233301	Speaker, #1 Cbn Entertainment DT-A8GAK	080491001	HRS AFL MOS MSC		5525.5 2597 173.4		O/C	4.9 2 05 Jun 2008			0 0 D T SYSTEMS CORP.
Airframe											
233302	Speaker, #2 Cbn Entertainment DT-A8GAK	080491003	HRS AFL MOS MSC		5525.5 2597 173.4		O/C	4.9 2 05 Jun 2008			0 0 D T SYSTEMS CORP.
Airframe											
233303	Speaker, #3 Cbn Entertainment DT-A8GAK	080491005	HRS AFL MOS MSC		5525.5 2597 173.4		O/C	4.9 2 05 Jun 2008			0 0 D T SYSTEMS CORP.
Airframe											
233304	Speaker, #4 Cbn Entertainment DT-A8GAK	080491006	HRS AFL MOS MSC		5525.5 2597 173.4		O/C	4.9 2 05 Jun 2008			0 0 D T SYSTEMS CORP.
Airframe											

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
Logbook Position	HW	SW									
	MM Ref										
	Ops Number(s)										
233305	Speaker, #5 Cbn Entertainment DT-A8GAK	080491010	HRS AFL MOS MSC		5525.5 2597 173.4		 O/C	4.9 2 03 Jun 2008			0 0 D T SYSTEMS CORP.
Airframe											
233306	Speaker, #6 Cbn Entertainment DT-A8GAK	080491011	HRS AFL MOS MSC		5525.5 2597 173.4		 O/C	4.9 2 03 Jun 2008			0 0 D T SYSTEMS CORP.
Airframe											
233307	Speaker, #7 Cbn Entertainment DT-A8GAK	080491016	HRS AFL MOS MSC		5525.5 2597 173.4		 O/C	4.9 2 03 Jun 2008			0 0 D T SYSTEMS CORP.
Airframe											
233309	Speaker, #9 Cbn Entertainment DT-A8GAK	080491020	HRS AFL MOS MSC		5525.5 2597 173.2		 O/C	4.9 2 09 Jun 2008			0 0 D T SYSTEMS CORP.
Airframe											
233310	Speaker, #10 Cbn Entertainment DT-A8GAK	080491021	HRS AFL MOS MSC		5525.5 2597 173.2		 O/C	4.9 2 09 Jun 2008			0 0 D T SYSTEMS CORP.
Airframe											
233311	Speaker, #11 Cbn Entertainment DT-A8GAK	080491024	HRS AFL MOS MSC		5525.5 2597 173.4		 O/C	4.9 2 03 Jun 2008			0 0
Airframe											
233312	Speaker, #12 Cbn Entertainment DT-A8GAK	080491029	HRS AFL MOS MSC		5525.5 2597 173.4		 O/C	4.9 2 03 Jun 2008			0 0
Airframe											

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
233318	Forward Lavatory Passenger Address Speaker - Final Phase Removal / Installation	HRS		5525.5			4.9			0
		AFL		2597			2			0
	DT-PA2N 080484028	MOS		171.9			18 Jul 2008			
		MSC				O/C				
Airframe										
233320	Speaker, Public Address	HRS		5525.5			4.9			0
	DT-PA2N 064596005	AFL		2597			2			0
		MOS		174.6			29 Apr 2008			
		MSC				O/C				
Airframe										
233406	Controller, Audio/Video #6	HRS		5525.5			4.9			0
	2023-1-1 208070031	AFL		2597			2			0
		MOS		174.3			06 May 2008			
		MSC				O/C				
Airframe										
233407	Controller, Audio/Video #7	HRS		5525.5			4.9			0
	2023-1-1 208070031	AFL		2597			2			0
		MOS		174.3			06 May 2008			
		MSC				O/C				
Airframe										
233440	Dual Digital Video Disc Player(S) No. 1 and No. 2 - Final Phase Removal / Installation	HRS		2367			3163.4			0
		AFL		954			1645			0
	866-0027-005 725-0278	MOS		72.2			10 Nov 2016			
		MSC				O/C				
Airframe										
Notes: COMPLIED WITH CMP G450 233440 DUAL DIGITAL VIDEO DISC PLAYER(S) NO. 1 AND NO. 2 - FINAL PHASE REMOVAL / INSTALLATION										
233441	Dual Digital Video Disc Player(S) No. 3 and No. 4 - Final Phase Removal / Installation	HRS		882.2			4648.2			0
		AFL		304			2295			0
	866-0027-005 725-0486	MOS		23			15 Dec 2020			
		MSC				O/C				
Airframe										
233484	Cabin Entertainment Audio - Operational Test (Elite)	HRS		882.2			4648.2			0
		AFL		304			2295			0
		MOS		23			15 Dec 2020			
		MSC				O/C				
Airframe										

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
Logbook Position	HW	SW									
	MM Ref										
	Ops Number(s)										
233511	Receptacle, Monitor Lh #1 0100-002	0803K130	HRS AFL MOS MSC		5525.5 2597 171.8		 O/C	4.9 2 22 Jul 2008			0 0 ROSEN AVIATION DISPLAYS, LLC
Airframe											
233512	Receptacle, Monitor Rh #1 0100-002	0803K134	HRS AFL MOS MSC		5525.5 2597 171.8		 O/C	4.9 2 22 Jul 2008			0 0 ROSEN AVIATION DISPLAYS, LLC
Airframe											
233513	Receptacle, Monitor Lh #2 0100-002	0803K131	HRS AFL MOS MSC		5525.5 2597 171.8		 O/C	4.9 2 22 Jul 2008			0 0 ROSEN AVIATION DISPLAYS, LLC
Airframe											
233514	Receptacle, Monitor Rh #2 0100-002	0804K106	HRS AFL MOS MSC		5525.5 2597 171.8		 O/C	4.9 2 22 Jul 2008			0 0 ROSEN AVIATION DISPLAYS, LLC
Airframe											
233515	Receptacle, Monitor Lh #3 0100-002	0803K133	HRS AFL MOS MSC		5525.5 2597 171.8		 O/C	4.9 2 22 Jul 2008			0 0 ROSEN AVIATION DISPLAYS, LLC
Airframe											
233517	Receptacle, Monitor Lh #4 0100-002	0803K136	HRS AFL MOS MSC		5525.5 2597 171.8		 O/C	4.9 2 22 Jul 2008			0 0 ROSEN AVIATION DISPLAYS, LLC
Airframe											
233541	Cabin Entertainment Video - Operational Test (Elite)		HRS AFL MOS MSC		882.2 304 23		 O/C	4648.2 2295 15 Dec 2020			0 0
Airframe											

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
233741	External Camera - Operational Test (Elite)	HRS		957.2			4573.2			0
		AFL		362			2237			0
		MOS		29.1			12 Jun 2020			
		MSC				O/C				
Airframe										
234302	Call System - Operational Test (Elite)	HRS		882.2			4648.2			0
		AFL		304			2295			0
		MOS		23.2			09 Dec 2020			
		MSC				O/C				
Airframe										
235003	Network / Audio Interface Module No. 1 - Removal / Installation 7517964-918 08094793	HRS		2465.4			3065			0
		AFL		1011			1588			0
		MOS		77.5			01 Jun 2016			FINISHMASTER INC.
		MSC				O/C				
Airframe										
Notes: MOD:AK,AL,AM,AN,AT (VERFIED BY:PQ005)										
235004	Network / Audio Interface Module No. 2 - Removal / Installation 7517964-918 08024043	HRS		5530.4			0			0
		AFL		2599			0			0
		MOS		174.6			28 Apr 2008			FINISHMASTER INC.
		MSC				O/C				
Airframe										
Notes: MOD:AK,AL,AM,AN,AT (VERFIED BY:PQ005)										
235005	Audio Control Panel No. 1 - Removal / Installation 7511900-90302 06032342	HRS		3546.6			1983.8			0
		AFL		1600			999			0
		MOS		115.2			09 Apr 2013			HONEYWELL
		MSC				O/C				
Airframe										
Notes: MODS:A,C,G,H,J,N,V,W,AB, AG, AP & AS										
235006	Audio Control Panel No. 2 - Removal / Installation 7511900-90302 07053629	HRS		2640.5			2889.9			0
		AFL		1094			1505			0
		MOS		89.6			29 May 2015			HONEYWELL
		MSC				O/C				
Airframe										
235007	Audio Control Panel No. 3 - Removal / Installation 7511900-90302 08034861	HRS		5530.4			0			0
		AFL		2599			0			0
		MOS		174.6			28 Apr 2008			HONEYWELL
		MSC				O/C				
Airframe										
Notes: MODS:A,C,G,H,J,N,V,W,AB & AG										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
235010 Airframe	Audio Integrating: I/O Devices - Operational Test	HRS AFL MOS MSC		957.2 362 29.1		O/C	4573.2 2237 12 Jun 2020			0 0
235012 Airframe	Modular Radio System - Return to Service Test	HRS AFL MOS MSC		2643.1 1095 90.6		O/C	2887.3 1504 29 Apr 2015			0 0
235013 Airframe	Modular Radio Cabinet No. 1 - Removal / Installation 7517959-904 08033659	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0 HONEYWELL
Notes: VERFIED BY:PQ005										
235016 Airframe	Modular Radio Cabinet No. 2 - Removal / Installation 7517959-904 08033636	HRS AFL MOS MSC	TSN:2284.2 TSN:1167 TSN:67	3246.2 1432 107.8		O/C	2284.2 1167 22 Nov 2013			0 0 HONEYWELL
235030 Airframe	Audio Integrating System - Operational Check	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0
235301 Airframe	Pilot Oxygen Mask Microphone - Operational Check	HRS AFL MOS MSC		1416.9 561 42.8		O/C	4113.5 2038 23 Apr 2019			0 0
235302 Airframe	Copilot Oxygen Mask Microphone - Operational Check	HRS AFL MOS MSC		2643.1 1095 90.5		O/C	2887.3 1504 30 Apr 2015			0 0
235303 Airframe	Observer Oxygen Mask Microphone - Operational Check	HRS AFL MOS MSC		1416.9 561 42.8		O/C	4113.5 2038 23 Apr 2019			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
236001	Static Discharging (Left Wing Static Wicks / Bonding) - Functional Test	HRS		882.2			4648.2			0
		AFL		304			2295			0
		MOS		26	14	48	16 Sep 2020	30 Sep 2024*	31 Oct 2024	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-4C,200204									
Notes: FLUKE 1587 CN 557026 DUE 2/17										
236002	Static Discharging (Right Wing Static Wicks / Bonding) - Functional Test	HRS		882.2			4648.2			0
		AFL		304			2295			0
		MOS		26	-16	48	16 Sep 2020	31 Aug 2024*	30 Sep 2024	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-4C,200204									
Notes: FLUKE 1587 CN 557026 DUE 2/17										
236003	Static Discharging (Left Horizontal Stabilizer Static Wick / Bonding) - Functional Test	HRS		882.2			4648.2			0
		AFL		304			2295			0
		MOS		26	-16	48	16 Sep 2020	31 Aug 2024*	30 Sep 2024	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-4C,200204									
Notes: REF METER 554975 DATE CAL"D: 03/23/16 DATE DUE: 03/17										
236004	Static Discharging (Right Horizontal Stabilizer Static Wick / Bonding) - Functional Test	HRS		882.2			4648.2			0
		AFL		304			2295			0
		MOS		26	-16	48	16 Sep 2020	31 Aug 2024*	30 Sep 2024	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-4C,200204									
Notes: REF METER 554975 DATE CAL"D: 03/23/16 DATE DUE: 03/17										
236005	Static Discharging (Vertical Stabilizer Static Wick / Bonding) - Functional Test	HRS		882.2			4648.2			0
		AFL		304			2295			0
		MOS		26	-16	48	16 Sep 2020	31 Aug 2024*	30 Sep 2024	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-4C,200204									
236006	Static Discharging (Tail Cone Static Wick / Bonding) - Functional Test	HRS		882.2			4648.2			0
		AFL		304			2295			0
		MOS		26	-16	48	16 Sep 2020	31 Aug 2024*	30 Sep 2024	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-4C,200204									

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
237001	Cockpit Voice Recorder - Removal / Installation 980-6023-002 ARCVR-11002	HRS AFL MOS MSC		439.3 157 12		 O/C	5091.1 2442 16 Nov 2021			0 0
Airframe										
237003	Cockpit Voice Recorder AREA Microphone - Removal / Installation 16301-02 SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										
237004	Cockpit Voice Recorder - Operational Test	HRS AFL MOS		190.2 71 6.1		 12	5340.2 2528 12 May 2022	31 May 2023	30 Jun 2023	0 0
Airframe	052000-1C,200201	[End Of Month Item] [MOS: +1m/-1m]								
237012	Cockpit Voice Recorder Underwater Locator Beacon Battery (DK120 DK120/90) - Discard DK120/90 AT117995	HRS AFL MOS [End Of Month Item]	 TSN:3	1641.7 641 49.1		 84	3888.7 1958 13 Oct 2018	 01 Sep 2025		0 0 SPINNEYBECK EXPIRATION
Airframe										
Notes: CODE:C REPLACE WITH NEW DK120/90, PP COVERAGE										
237013	Cockpit Voice Recorder Underwater Locator Beacon - Removal / Installation DK120/90 AT117995	HRS AFL MOS MSC	 TSN:3	1641.7 641 49.1		 O/C	3888.7 1958 13 Oct 2018			0 0
Airframe										
237014	Cockpit Voice Recorder Underwater Locator Beacon Battery (DK120 or DK120/90) - Replacement DK120/90 AT117995	HRS AFL MOS MSC	 TSN:3	1641.7 641 49.1		 O/C	3888.7 1958 13 Oct 2018			0 0
Airframe										
237016	Cockpit Voice Recorder Underwater Locator Beacon - Operational Test	HRS AFL MOS		882.2 304 26		 84	4648.2 2295 16 Sep 2020	16 Sep 2027	16 Oct 2027	0 0
Airframe	052000-72M,200303	[MOS: +1m/-1m]								

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
237018	Cockpit Voice Recorder Underwater Locator Beacon - Cleaning	HRS AFL MOS MSC		1641.7 641 49.1		 O/C	3888.7 1958 13 Oct 2018			0 0
Airframe										
237020	Cockpit Voice Recorder Impact Switch - Functional Check	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										
237021	Cockpit Voice Recorder Impact Switch - Removal / Installation 1159SCAV402-2 2685	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 DAVTRON INC
Airframe										
237022	Cockpit Voice Recorder Underwater Locator Beacon - Battery Voltage Check	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										
237051	Micro QAR (Quick Access Recorder) QAR200-03-04 000509412	HRS AFL MOS MSC	 TSN:3	5525.9 2597 171.5		 O/C	4.5 2 31 Jul 2008			0 0 L3 Communications
Airframe										
237201	Security System Battery Pack No. 1 - Final Phase Restore 100-1032-01 1021434	HRS AFL MOS		957.2 362 29.1		 48	4573.2 2237 12 Jun 2020	30 Jun 2024		0 0
Airframe	[End Of Month Item]									
237202	Display Unit, Security Sys.Con 100-0106-01 0809010	HRS AFL MOS MSC		5525.5 2597 173.8		 O/C	4.9 2 21 May 2008			0 0 SECURAPLANE TECHNOLOGIES, LLC
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
237203 Airframe	Ultra High Frequency Antenna - Final Phase Removal / Installation DMC57-1 9110	HRS AFL MOS MSC		957.2 362 29.1		 O/C	4573.2 2237 12 Jun 2020			0 0
237204 Airframe	Indicator, Security Sys Alarm 100-0651-01 0808686	HRS AFL MOS MSC		5525.5 2597 174.1		 O/C	4.9 2 13 May 2008			0 0 SECURAPLANE TECHNOLOGIES, LLC
237207 Airframe	Passive Infrared Sensor (Fwd Nose Wheel Well) - Final Phase Removal / Installation 100-0401-11 0808790	HRS AFL MOS MSC		5525.5 2597 174.3		 O/C	4.9 2 08 May 2008			0 0 GULFSTREAM DALLAS
237208 Airframe	Passive Infrared Sensor (Aft Nose Wheel Well) - Final Phase Removal / Installation 100-0401-11 0808782	HRS AFL MOS MSC		5525.5 2597 174.3		 O/C	4.9 2 08 May 2008			0 0 GULFSTREAM DALLAS
237209 Airframe	Passive Infrared Sensor (Left Main Gear Wheel Well) - Final Phase Removal / Installation 100-0401-11 0808789	HRS AFL MOS MSC		5525.5 2597 174.1		 O/C	4.9 2 12 May 2008			0 0 GULFSTREAM DALLAS
237210 Airframe	Passive Infrared Sensor (Right Main Gear Wheel Well) - Final Phase Removal / Installation 100-0401-11 0808873	HRS AFL MOS MSC		5525.5 2597 174.1		 O/C	4.9 2 12 May 2008			0 0 GULFSTREAM DALLAS
237222 Airframe	Aircraft Security System - Final Phase Operational Test	HRS AFL MOS MSC		957.2 362 29.1		 O/C	4573.2 2237 12 Jun 2020			0 0

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
237250	Securaplane 500 Security System Wiring and Components-Inspection		HRS		5530.4			0			0
			AFL		2599			0			0
			MOS		171.1		192	12 Aug 2008	31 Aug 2024	30 Sep 2024	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
237310	Unit, Video Distribution MSM2925-01-1	030801001	HRS		5525.5			4.9			0
			AFL		2597			2			0
			MOS		174.3			06 May 2008			
			MSC				O/C				
Airframe											
239199	Satellite Data Unit-Software Update		HRS		5530.4			0			0
			AFL		2599			0			0
			MOS		174.6			28 Apr 2008			
			MSC				O/C				
Airframe											
239201[U]	Usb Adapter 441-0091-100	477YMF	HRS		2367			3163.4			0
			AFL		954			1645			0
			MOS	TSN:1	72.3			07 Nov 2016			GAC
			MSC				O/C				
Airframe											
Notes: CMP G450 239201 USB ADAPTERCE415710058 REV. -											
239202[U]	Hsd Router (SATCOM Direct) 1233-F-2191-10 E	976	HRS		2367			3163.4			0
			AFL		954			1645			0
			MOS	TSN:4	72.5			30 Oct 2016			SATCOM DIRECT
			MSC				O/C				
Airframe											
Notes: CMP G450 239202 HSD ROUTER (SATCOM DIRECT)CE414290148 REV. -											
24 - Electrical Power											
240101	Emergency Battery (Left) - Removal / Installation 1159SCAV524-3	P5797	HRS		39.1			5491.3			0
			AFL		12			2587			0
			MOS		1.4			04 Oct 2022			
			MSC				O/C				
Airframe											
240102	Emergency Battery (Right) - Removal / Installation 1159SCAV524-3	P1908	HRS		1080.9			4449.5			0
			AFL		416			2183			0
			MOS		34.4			03 Jan 2020			
			MSC				O/C				
Airframe											

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
240103 Airframe	Emergency Battery (Fwd) - Removal / Installation 1159SCAV524-3 P3436	HRS AFL MOS MSC		958.4 364 31.9		 O/C	4572 2235 19 Mar 2020			0 0
240104 Airframe	Emergency Battery (Aft) - Removal / Installation 1159SCAV524-3 P3343	HRS AFL MOS MSC		1416.9 561 43		 O/C	4113.5 2038 17 Apr 2019			0 0 SECURAPLANE TECHNOLOGIES, LLC
Notes: VERFIED BY:PQ005										
240106 Airframe	Emergency Battery - Battery Level Test / Built-In Test Equipment (Left)	HRS AFL MOS MSC		39.1 12 1.4		 O/C	5491.3 2587 04 Oct 2022			0 0
240107 Airframe	Emergency Battery - Battery Level Test / Built-In Test Equipment (Right)	HRS AFL MOS MSC		2367 954 73.5		 O/C	3163.4 1645 30 Sep 2016			0 0
240108 Airframe	Emergency Battery - Battery Level Test / Built-In Test Equipment (Forward)	HRS AFL MOS MSC		958.4 364 31.9		 O/C	4572 2235 19 Mar 2020			0 0
240109 Airframe	Emergency Battery - Battery Level Test / Built-In Test Equipment (Aft)	HRS AFL MOS MSC		1416.9 561 43		 O/C	4113.5 2038 17 Apr 2019			0 0
240111 Airframe	Emergency Battery (Left) - Restore 102-1103-01 2200113-40	HRS AFL MOS [End Of Month Item]		39.1 12 1.4		 48	5491.3 2587 04 Oct 2022	 31 Oct 2026		0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
240112 Airframe	Emergency Battery (Right) - Restore 100-0302-01 P2753	HRS AFL MOS [End Of Month Item]	TSN:4	6.5 2 .2		48	5523.9 2597 11 Nov 2022	31 Jul 2026		0 0
240113 Airframe	Emergency Battery (Forward) - Restore 1159SCAV524-3 P3436	HRS AFL MOS [End Of Month Item]		958.4 364 31.9		48	4572 2235 19 Mar 2020	29 Feb 2024		0 0
240114 Airframe	Emergency Battery (Aft) - Restore 1159SCAV524-3 P3343	HRS AFL MOS [End Of Month Item]		1416.9 561 43		48	4113.5 2038 17 Apr 2019	30 Apr 2023		0 0 SECURAPLANE TECHNOLOGIES, LLC
240121 Airframe	Emergency Battery Power System (Left) - Operational Test 052000-1C,200201	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		39.1 12 1.4		12	5491.3 2587 04 Oct 2022	31 Oct 2023	30 Nov 2023	0 0
240122 Airframe	Emergency Battery Power System (Right) - Operational Test 052000-1C,200201	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		190.2 71 6.2	34	12	5340.2 2528 09 May 2022	30 Jun 2023*	31 Jul 2023	0 0
240123 Airframe	Emergency Battery Power System (Forward) - Operational Test 052000-1C,200201	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		190.2 71 6.2	34	12	5340.2 2528 09 May 2022	30 Jun 2023*	31 Jul 2023	0 0
240124 Airframe	Emergency Battery Power System (Aft) - Operational Test 052000-1C,200201	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		190.2 71 6.2	34	12	5340.2 2528 09 May 2022	30 Jun 2023*	31 Jul 2023	0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
242001	Tail Compartment AC Power Feeder Cables - Detailed Inspection	HRS		2367			3163.4			0
		AFL		954			1645			0
		MOS		73	-47	96	17 Oct 2016	31 Aug 2024*	30 Sep 2024	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-8C									
242005	Standby Electrical Power System - Operational Test	HRS		181			5349.4			0
		AFL		68			2531			0
		MOS		5.7		24	26 May 2022	31 May 2024	30 Jun 2024	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe	200202									
242100	Engine AC Generation - Operational Check	HRS		49.9			5480.5			0
		AFL		16			2583			0
		MOS		1.8			23 Sep 2022			
		MSC				O/C				
Airframe										
242103	Integrated Drive Generator (Left) - Removal / Installation	HRS	TSN:3838.9	1691.5			3838.9			0
	1702785 AADH000253	AFL	TSN:1931	668			1931			0
		MOS	TSN:123	51.9			20 Jul 2018			HAMILTON
		MSC				O/C				SUNDSTRAND
Airframe										
242104	Integrated Drive Generator (Right) - Removal / Installation	HRS	TSN:3838.9	1691.5			3838.9			0
	1702785 AADH000250	AFL	TSN:1931	668			1931			0
		MOS	TSN:123	51.9			18 Jul 2018			HAMILTON
		MSC				O/C				SUNDSTRAND
Airframe										
242109	Integrated Drive Generator (Left) - Oil Level Check	HRS		439.3			5091.1			0
		AFL		157			2442			0
		MOS		12.3			08 Nov 2021			
		MSC				O/C				
Airframe										
242110	Integrated Drive Generator (Right) - Oil Level Check	HRS		439.3			5091.1			0
		AFL		157			2442			0
		MOS		12.3			08 Nov 2021			
		MSC				O/C				
Airframe										
242111	Integrated Drive Generator (Left) - Detailed Inspection	HRS		6.5		500	5523.9	6023.9	6073.9	0
		AFL		2			2597			0
		MOS		.2			11 Nov 2022			
		[HRS: +50/-50]								
Airframe	052000-1A,200100									

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
242112 Airframe	Integrated Drive Generator (Right) - Detailed Inspection 052000-1A	HRS AFL MOS [HRS: +50/-50]		6.5 2 .2		500	5523.9 2597 11 Nov 2022	6023.9	6073.9	0 0
242113 Airframe	L Idg Disconnect System - Operational Test	HRS AFL MOS [MOS: +1m/-1m]		49.9 16 1.8	1	50	5480.5 2583 23 Sep 2022	24 Nov 2026*	24 Dec 2026	0 0
242114 Airframe	R Idg Disconnect System - Operational Test	HRS AFL MOS [MOS: +1m/-1m]		49.9 16 1.8	1	50	5480.5 2583 23 Sep 2022	24 Nov 2026*	24 Dec 2026	0 0
242115 Airframe	Idg Oil, L - Service	HRS AFL MOS MSC		957.2 362 29.1		O/C	4573.2 2237 12 Jun 2020			0 0
242116 Airframe	Idg Oil, R - Service	HRS AFL MOS MSC		957.2 362 29.1		O/C	4573.2 2237 12 Jun 2020			0 0
242123 Airframe	Integrated Drive Generator (Left) - Oil System Filling	HRS AFL MOS MSC		1769.5 717 54.5		O/C	3760.9 1882 02 May 2018			0 0
242126 Airframe	Integrated Drive Generator (Right) - Oil System Filling	HRS AFL MOS MSC		1769.5 717 54.5		O/C	3760.9 1882 02 May 2018			0 0
242143 Airframe	Integrated Drive Generator Oil Scavenger Filter Differential Pressure Indicator (Left) - Inspection	HRS AFL MOS MSC		439.3 157 12.3		O/C	5091.1 2442 08 Nov 2021			0 0

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
242144	Integrated Drive Generator Oil Scavenger Filter Differential Pressure Indicator (Right) - Inspection		HRS AFL MOS MSC		439.3 157 12.3		O/C	5091.1 2442 08 Nov 2021			0 0
Airframe											
242201	APU Generator - Removal / Installation 1159SCAV501-1	0645	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0 HAMILTON SUNDSTRAND
Airframe											
242202	APU Generator Control Unit - Removal / Installation 1702787B	0994	HRS AFL MOS MSC	TSN:2284.2 TSN:1167 TSN:67	3246.2 1432 107.9		O/C	2284.2 1167 20 Nov 2013			0 0 GULFSTREAM SAV PROD-IPT
Airframe											
Notes: VERFIED BY:PQ005											
242206	APU AC Generation System - Operational Check		HRS AFL MOS MSC		3246.2 1432 107.6		O/C	2284.2 1167 28 Nov 2013			0 0
Airframe											
242301	E-Inverter - Removal / Installation 1-002-0102-1346	GC001670	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0 AVIONIC INSTRUMENTS INC
Airframe											
242401	Hmg - Removal / Installation 3022018-000	G0720579	HRS AFL MOS MSC		181 68 5.7		O/C	5349.4 2531 26 May 2022			0 0 N/A
Airframe											
Notes: Q306918											
242402	Hydraulic Motor Generator Generator Control Unit - Removal / Installation 1159SCAV523-1	G0810445	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0 EATON AEROSPACE
Airframe											

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
242404	Hydraulic Motor Generator Current Transformer Assembly - Removal / Installation 307-1 207500213	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 GULFSTREAM DALLAS
Airframe										
242406	Standby Junction and Relay Panel - Removal / Installation PN SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										
242603	Integrated Drive Generator: Generator Control Unit (Left) - Removal / Installation 1702785 AADH000253	HRS AFL MOS MSC		1691.5 668 51.7		 O/C	3838.9 1931 24 Jul 2018			0 0 GULFSTREAM SAV PROD-IPT
Airframe										
Notes: VERFIED BY:PQ005										
242604	Integrated Drive Generator: Generator Control Unit (Right) - Removal / Installation 1702785 AADH000250	HRS AFL MOS MSC		1691.5 668 51.7		 O/C	3838.9 1931 24 Jul 2018			0 0 GULFSTREAM SAV PROD-IPT
Airframe										
Notes: VERFIED BY:PQ005										
242700	60 Hertz Power Generation System - Functional Test	HRS AFL MOS MSC		2947.8 1288 98.5		 O/C	2582.6 1311 30 Aug 2014			0 0
Airframe										
242701	Converter (400 HZ - 60 HZ) {Left} - Removal / Installation 1-002-0102-2052 HT000939	HRS AFL MOS MSC		2947.8 1288 98.5		 O/C	2582.6 1311 30 Aug 2014			0 0 AVIONIC INSTRUMENTS INC
Airframe										
Notes: VERFIED BY:PQ005										
243001	Main Battery (Left) - Removal / Installation 9750W0380-1 15153W0001	HRS AFL MOS MSC		190.2 71 6		 O/C	5340.2 2528 17 May 2022			0 0 N/A
Airframe										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
243002	Main Battery (Right) - Removal / Installation 9750W0380-1 7025W0001	HRS AFL MOS MSC		190.2 71 6		 O/C	5340.2 2528 17 May 2022			0 0 N/A
Airframe										
243003	Main Battery Charger (Left) - Removal / Installation 100-1104-01 0702128	HRS AFL MOS MSC		1323.9 522 40.9		 O/C	4206.5 2077 20 Jun 2019			0 0 SECURAPLANE TECHNOLOGIES, LLC
Airframe										
243004	Main Battery Charger (Right) - Removal / Installation 100-1104-01 1047	HRS AFL MOS MSC		1905.6 769 58.1		 O/C	3624.8 1830 12 Jan 2018			0 0 SECURAPLANE TECHNOLOGIES, LLC
Airframe										
243011	Main Battery (Left) - Capacity Check (Aircraft Not Having ASC 069)	HRS AFL MOS		190.2 71 6	 26	 12	5340.2 2528 17 May 2022	 30 Jun 2023*	 31 Jul 2023	0 0
	[End Of Month Item] [MOS: +1m/-1m]									
Airframe	052000-1C,200201									
Notes: PN: 9750W0380-1 SN: <NONE>. GAINJET REQUIRES AT LEAST 90% CAPACITY AS A SATISFACTORY RESULT. IF NOT CELLES REPLACEMENT MUST BE DONE IN ORDER TO HAVE AT LEAST 90%.										
243012	Main Battery (Right) - Capacity Check (Aircraft Not Having ASC 069)	HRS AFL MOS		190.2 71 6	 26	 12	5340.2 2528 17 May 2022	 30 Jun 2023*	 31 Jul 2023	0 0
	[End Of Month Item] [MOS: +1m/-1m]									
Airframe	052000-1C,200201									
Notes: PN: 9750W0380-1 SN: <NONE>. GAINJET REQUIRES AT LEAST 90% CAPACITY AS A SATISFACTORY RESULT. IF NOT CELLES REPLACEMENT MUST BE DONE IN ORDER TO HAVE AT LEAST 90%.										
243015	Main Battery - Operational Check	HRS AFL MOS MSC		5214.6 2493 157.9		 O/C	315.8 106 18 Sep 2009			0 0
Airframe										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
243020	Tail Compartment Dc Feeder Cables - Detailed Inspection	HRS		2367			3163.4			0
		AFL		954			1645			0
		MOS		73	-47	96	17 Oct 2016	31 Aug 2024*	30 Sep 2024	
Airframe	052000-8C	[End Of Month Item] [MOS: +1m/-1m]								
243100	L Main Transformer Rectifier Unit - Removal / Installation	HRS		5530.4			0			0
	1159SCAV508-3 B2702	AFL		2599			0			0
		MOS		174.6			28 Apr 2008			INTERTECHNIQUE
Airframe		MSC				O/C				
243101	L Essential Transformer Rectifier Unit - Removal / Installation	HRS		5530.4			0			0
	1159SCAV508-3 B2701	AFL		2599			0			0
		MOS		174.6			28 Apr 2008			INTERTECHNIQUE
Airframe		MSC				O/C				
243102	R Main Transformer Rectifier Unit - Removal / Installation	HRS		5530.4			0			0
	1159SCAV508-3 B2742	AFL		2599			0			0
		MOS		174.6			28 Apr 2008			INTERTECHNIQUE
Airframe		MSC				O/C				
243103	R Essential Transformer Rectifier Unit - Removal / Installation	HRS		5530.4			0			0
	1159SCAV508-3 B2743	AFL		2599			0			0
		MOS		174.6			28 Apr 2008			INTERTECHNIQUE
Airframe		MSC				O/C				
243104	Auxiliary Transformer Rectifier Unit - Removal / Installation	HRS		5530.4			0			0
	1159SCAV508-3 B2703	AFL		2599			0			0
		MOS		174.6			28 Apr 2008			INTERTECHNIQUE
Airframe		MSC				O/C				
243400	Main Battery (Left) - Return to Service Test	HRS		685.5			4844.9			0
		AFL		230			2369			0
		MOS		18.1			14 May 2021			
Airframe		MSC				O/C				

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
243401 Airframe	Main Battery (Right) - Return to Service Test	HRS AFL MOS MSC		685.5 230 18.1		 O/C	4844.9 2369 14 May 2021			0 0
243402 Airframe	Main Battery Charger - Operational Check	HRS AFL MOS MSC		1905.6 769 58.1		 O/C	3624.8 1830 12 Jan 2018			0 0
243801 Airframe	Battery Volts / Amps Display Indicator - Removal / Installation 789550-2-1 0653	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 PEERLESS ELECTRONICS INC
Notes: VERIFIED BY PQ246										
244200 Airframe	External AC Power System - Operational Test	HRS AFL MOS MSC		5525.5 2597 174.6		 O/C	4.9 2 29 Apr 2008			0 0
244201 Airframe	External Alternating Current Power Current Transformer Assembly - Removal / Installation 1159SCAV504-1 1353	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 ECE
244203 Airframe	External AC Power Receptacle - Removal / Installation PN SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
244300 Airframe	External Dc Power System - Operational Check	HRS AFL MOS MSC		5525.5 2597 174.6		 O/C	4.9 2 29 Apr 2008			0 0

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Description: Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
244414	60 HZ Power Outlet (Fwd Lavatory) - Final Phase Removal / Installation		HRS		2367			3163.4			0
			AFL		954			1645			0
	106186-2	70370416	MOS		72.6			28 Oct 2016			MID CONT.
			MSC				O/C				
Airframe											
Notes: CMP G450 244414 60HZ OUTLET (FWD LAV)CE414940200 REV. -											
244424	60 HZ Power Outlet (Left Galley) - Final Phase Removal / Installation		HRS		5525.5			4.9			0
			AFL		2597			2			0
	106186-2	24010408	MOS		174.3			08 May 2008			
			MSC				O/C				
Airframe											
244429	60 HZ Power Outlet (Aft Lavatory Vanity) - Final Phase Removal / Installation		HRS		5525.5			4.9			0
			AFL		2597			2			0
	106186-2	24040408	MOS		174.5			02 May 2008			
			MSC				O/C				
Airframe											
244430	60HZ Outlet (Credenza)		HRS		2367			3163.4			0
	106186-2	70530416	AFL		954			1645			0
			MOS		72.6			28 Oct 2016			MID CONT.
			MSC				O/C				
Airframe											
Notes: CMP G450 244430 60HZ OUTLET (CREDENZA)CE414940200 REV. -											
244434	60 HZ Power Outlet (Left Seat No. 2) - Final Phase Removal / Installation		HRS		5525.5			4.9			0
			AFL		2597			2			0
	106186-2	23960408	MOS		171.9			18 Jul 2008			
			MSC				O/C				
Airframe											
244442	60HZ Universal Outlet (Conference Group #1)		HRS		5525.5			4.9			0
	106084-1	4310508	AFL		2597			2			0
			MOS		171.8			22 Jul 2008			
			MSC				O/C				
Airframe											
244445	60HZ Universal Outlet		HRS		5525.5			4.9			0
	106084-1	4320508	AFL		2597			2			0
			MOS		171.8			22 Jul 2008			
			MSC				O/C				
Airframe											

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Description: Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
244449	60HZ Universal Outlet 106186-2	24000408	HRS AFL MOS MSC	5525.5 2597 174.2			O/C	4.9 2 09 May 2008			0 0
Airframe											
244450	60HZ Universal Outlet 106186-2	23970408	HRS AFL MOS MSC	5525.5 2597 174.2			O/C	4.9 2 09 May 2008			0 0
Airframe											
244452	60HZ Universal Outlet 106186-2	23950408	HRS AFL MOS MSC	5525.5 2597 171.8			O/C	4.9 2 22 Jul 2008			0 0
Airframe											
244453	60HZ Universal Outlet 106186-2	24060408	HRS AFL MOS MSC	5525.5 2597 171.9			O/C	4.9 2 18 Jul 2008			0 0
Airframe											
244454	60 HZ AC Power Controller (#1) 106075-1	31240408	HRS AFL MOS MSC	5525.5 2597 174.1			O/C	4.9 2 12 May 2008			0 0
Airframe											
244455	60 HZ AC Power Controller (#2) 106075-1	32050408	HRS AFL MOS MSC	5525.5 2597 171.9			O/C	4.9 2 18 Jul 2008			0 0
Airframe											
244456	60 HZ AC Power Controller (#3) 106075-1	25290907	HRS AFL MOS MSC	5525.5 2597 171.8			O/C	4.9 2 22 Jul 2008			0 0
Airframe											
244457	60 HZ AC Power Controller (#4) 106075-1	24030408	HRS AFL MOS MSC	5525.5 2597 171.8			O/C	4.9 2 22 Jul 2008			0 0
Airframe											

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
Logbook Position	HW	SW									
	MM Ref										
	Ops Number(s)										
244464	60 HZ AC Power Controller (#11)		HRS		5525.5			4.9			0
	106075-1	31920408	AFL		2597			2			0
			MOS		171.8			22 Jul 2008			
			MSC				O/C				
Airframe											
244465	AC Gfi, Lh Cabin 60HZ		HRS		5530.4			0			0
	106072-1	22220308	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			
			MSC				O/C				
Airframe											
244466	AC Gfi, Rh Cabin 60HZ		HRS		5530.4			0			0
	106072-1	22650308	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			
			MSC				O/C				
Airframe											
244467	AC Gfi, Lavs 60HZ		HRS		5530.4			0			0
	106072-1	22490308	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			
			MSC				O/C				
Airframe											
244468	AC Gfi, Galley 60HZ		HRS		1494.9			4035.5			0
	106072-1	10970107	AFL		610			1989			0
			MOS		42.5			30 Apr 2019			
			MSC				O/C				
Airframe											
244476	60 HZ AC Power Controller (#13)		HRS		5525.5			4.9			0
	106075-1	29910308	AFL		2597			2			0
			MOS		174.2			09 May 2008			
			MSC				O/C				
Airframe											
244477	60 HZ AC Power Controller (#14)		HRS		5525.5			4.9			0
	106075-1	30890308	AFL		2597			2			0
			MOS		174.2			09 May 2008			
			MSC				O/C				
Airframe											
244478	60 HZ AC Power Controller (#15)		HRS		5525.5			4.9			0
	106075-1	31770408	AFL		2597			2			0
			MOS		173.9			19 May 2008			
			MSC				O/C				
Airframe											

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
244479	60 HZ AC Power Controller (#16)		HRS		5525.5			4.9			0
	106075-1	31650408	AFL		2597			2			0
			MOS		173.9			19 May 2008			
			MSC				O/C				
Airframe											
244480	60 HZ AC Power Controller (#17)		HRS		5525.5			4.9			0
	106075-1	31130308	AFL		2597			2			0
			MOS		173.8			21 May 2008			
			MSC				O/C				
Airframe											
244481	60 HZ AC Power Controller (#18)		HRS		5525.5			4.9			0
	106075-1	31890408	AFL		2597			2			0
			MOS		171.9			18 Jul 2008			
			MSC				O/C				
Airframe											
244482	60 HZ AC Power Controller (#19)		HRS		5525.5			4.9			0
	106075-1	31990408	AFL		2597			2			0
			MOS		171.8			22 Jul 2008			
			MSC				O/C				
Airframe											
244483	60 HZ AC Power Controller (#20)		HRS		5525.5			4.9			0
	106075-1	30780308	AFL		2597			2			0
			MOS		174.5			02 May 2008			
			MSC				O/C				
Airframe											
244495	Overlay, Gfi Remote Switch		HRS		5525.5			4.9			0
	GC544930019-211	20136	AFL		2597			2			0
			MOS		174.5			01 May 2008			
			MSC				O/C				
Airframe											
245005	AC Load Distributing System - Operational Test		HRS		4882.7			647.7			0
			AFL		2421			178			0
			MOS		149.5			31 May 2010			
			MSC				O/C				
Airframe											
Notes: AC LOAD DISTRIBUTION TEST PERFORMED SATIS											
245101	Left Power Distribution Box - Removal / Installation		HRS	TSN:209	5321.4			209			0
	1703230	0344	AFL	TSN:65	2534			65			0
			MOS	TSN:9	165.5			30 Jan 2009			HAMILTON SUNDSTRAND
			MSC				O/C				
Airframe											
Notes: REMOVED AND REINSTALLED TO ACCOMPLISH TASK # 05008 FROM WO # 52448. OPS CHECK PERFORMED SATIS.											

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
245102	Right Power Distribution Box - Removal / Installation 1703232 0344	HRS AFL MOS MSC	TSN:4.9 TSN:2 TSN:1	5525.5 2597 173.9		 O/C	4.9 2 19 May 2008			0 0 HAMILTON SUNDSTRAND
Airframe										
Notes: SEE R&I LOG. PQ211										
245121	Tray, Left Pdb 1703237A 0334	HRS AFL MOS MSC	TSN:4.9 TSN:2 TSN:1	5525.5 2597 173.9		 O/C	4.9 2 19 May 2008			0 0
Airframe										
Notes: PQ246										
245122	Tray, Right Pdb 1703239A 0331	HRS AFL MOS MSC	TSN:4.9 TSN:2 TSN:1	5525.5 2597 173.9		 O/C	4.9 2 19 May 2008			0 0
Airframe										
246001	L Bpcu - Removal / Installation 1702789A 0664	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 HAMILTON SUNDSTRAND
Airframe										
246002	R Bpcu - Removal / Installation 1702789A 0665	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 HAMILTON SUNDSTRAND
Airframe										
Notes: VERFIED BY:PQ005										
246005	Dc Load Distribution System - Operational Check	HRS AFL MOS MSC		4882.7 2421 149.6		 O/C	647.7 178 28 May 2010			0 0
Airframe										
246010	Ground Service Bus - Operational Check	HRS AFL MOS MSC		5525.5 2597 174.6		 O/C	4.9 2 29 Apr 2008			0 0
Airframe										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
246517	Cockpit Main Dc Current Circuit Breaker - Removal / Installation	HRS		5530.4			0			0
	PN SN-UNKNOWN	AFL		2599			0			0
		MOS		174.6			28 Apr 2008			
		MSC				O/C				
Airframe										
249201U	AC Power Controller (Credenza)	HRS		2367			3163.4			0
	106075-1 139081115	AFL		954			1645			0
		MOS	TSN:11	72.6			28 Oct 2016			MID CONT.
		MSC				O/C				
Airframe										
Notes: CMP G450 249201 AC POWER CONTROLLER (CREDENZA)CE414940200 REV. -										
249202U	AC Power Controller (Fwd Lav)	HRS		2367			3163.4			0
	106075-1 140451215	AFL		954			1645			0
		MOS	TSN:9	72.6			28 Oct 2016			MID CONT.
		MSC				O/C				
Airframe										
Notes: CMP G450 249202 AC POWER CONTROLLER (FWD LAV)										
25 - Equipment/Furnishings										
250010	Tow Bar	HRS		5530.4			0			0
	WYG45XLT 4433	AFL		2599			0			0
		MOS		174.6			28 Apr 2008			WELKER-YOUNG INDUSTRIES
		MSC				O/C				
Airframe										
250015	Ladder	HRS		5516.4			14			0
	1159SCB750-1 00239D	AFL		2594			5			0
		MOS		171.3			07 Aug 2008			
		MSC				O/C				
Airframe										
251001	Pilot Seat - Removal / Installation	HRS		882.2			4648.2			0
	1159SCF513-23 54099	AFL		304			2295			0
		MOS		23.7			25 Nov 2020			
		MSC				O/C				
Airframe										
251002	Copilot Seat - Removal / Installation	HRS		882.2			4648.2			0
	1159SCF513-24 52359	AFL		304			2295			0
		MOS		24.5			02 Nov 2020			
		MSC				O/C				
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
251003 Airframe	Observer Seat - Removal / Installation 1159SCF501-1 325-1425	HRS AFL MOS MSC		882.2 304 24.5		O/C	4648.2 2295 02 Nov 2020			0 0
251006 Airframe	Crew Seat Inertia Reels (Pilot) - Operational Test 200202	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		190.2 71 6.2	34	24	5340.2 2528 09 May 2022	30 Jun 2024*	31 Jul 2024	0 0
251007 Airframe	Crew Seat Inertia Reels (Copilot) - Operational Test 200202	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		190.2 71 6.2	34	24	5340.2 2528 09 May 2022	30 Jun 2024*	31 Jul 2024	0 0
251008 Airframe	Observer Seat Inertia Reel - Operational Test 200202	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		190.2 71 6.2	34	24	5340.2 2528 09 May 2022	30 Jun 2024*	31 Jul 2024	0 0
251016 Airframe	Crew Seat Restraints (Pilot) - Detailed Inspection 200202	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		190.2 71 6.2	34	24	5340.2 2528 09 May 2022	30 Jun 2024*	31 Jul 2024	0 0
251017 Airframe	Crew Seat Restraints (Copilot) - Detailed Inspection 200202	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		190.2 71 6.2	34	24	5340.2 2528 09 May 2022	30 Jun 2024*	31 Jul 2024	0 0
251018 Airframe	Crew Seat Restraints (Observer) - Detailed Inspection 200202	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		190.2 71 6.2	38	24	5340.2 2528 09 May 2022	30 Jun 2024*	31 Jul 2024	0 0
251021 Airframe	Crew Seats Locking Mechanism and Seat Tracks (Pilot) - Detailed Inspection 052000-4C,200204	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		882.2 304 26	-15	48	4648.2 2295 15 Sep 2020	31 Aug 2024*	30 Sep 2024	0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
251022	Crew Seats Locking Mechanism and Seat Tracks (Copilot) - Detailed Inspection	HRS		882.2			4648.2			0
		AFL		304			2295			0
		MOS		26	-15	48	15 Sep 2020	31 Aug 2024*	30 Sep 2024	
	[End Of Month Item] [MOS: +1m/-1m]									
Airframe	052000-4C,200204									
251023	Crew Seats Locking Mechanism and Seat Tracks (Observer) - Detailed Inspection	HRS		882.2			4648.2			0
		AFL		304			2295			0
		MOS		26	-15	48	15 Sep 2020	31 Aug 2024*	30 Sep 2024	
	[End Of Month Item] [MOS: +1m/-1m]									
Airframe	052000-4C,200204									
252001	Cabin Full Size Single Seat (Left, No. 1) - Final Phase Removal / Installation	HRS	TSN:3158.5	2367			3163.4			0
		AFL	TSN:1643	954			1645			0
	GC422080565-15-4123 080403-10	MOS	TSN:100	72.3			07 Nov 2016			
		MSC				O/C				
Airframe										
Notes: TW S/N 561051 TO 140 IN LBS.PER GC422080566 REV. -										
252002	Cabin Full Size Single Seat (Left, No. 2) - Final Phase Removal / Installation	HRS	TSN:3158.5	2367			3163.4			0
		AFL	TSN:1643	954			1645			0
	GC422080565-17-4123 080403-06	MOS	TSN:100	72.3			07 Nov 2016			
		MSC				O/C				
Airframe										
Notes: TW S/N 561051 TO 140 IN LBS.PER GC422080566 REV. -										
252006	Cabin Full Size Single Seat (Right, No. 1) - Final Phase Removal / Installation	HRS	TSN:3158.5	2367			3163.4			0
		AFL	TSN:1643	954			1645			0
	GC422080565-117-4123 080403-05	MOS	TSN:100	72.3			07 Nov 2016			
		MSC				O/C				
Airframe										
Notes: TW S/N 561051 TO 140 IN LBS.PER GC422080566 REV. -										
252007	Cabin Full Size Single Seat (Right, No. 2) - Final Phase Removal / Installation	HRS	TSN:3158.5	2367			3163.4			0
		AFL	TSN:1643	954			1645			0
	GC422080565-13-4123 080403-09	MOS	TSN:100	72.3			07 Nov 2016			
		MSC				O/C				
Airframe										
Notes: TW 561051 PER. 140 INCH LBSGC422080566 REV -.										

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
Logbook Position	HW	SW									
	MM Ref										
	Ops Number(s)										
252017	Divan (Left No. 1, Two Place) - Final Phase Removal / Installation		HRS		2367			3163.4			0
			AFL		954			1645			0
	2523.700.01-03	080403-04	MOS		72.3			08 Nov 2016			
			MSC				O/C				
Airframe											
252018	Divan (Left No. 2, Two Place) - Final Phase Removal / Installation		HRS		2367			3163.4			0
			AFL		954			1645			0
	2523.700.01-03	080403-03	MOS		72.3			08 Nov 2016			
			MSC				O/C				
Airframe											
252019	Divan (Right No. 1, Two Place) - Final Phase Removal / Installation		HRS		2367			3163.4			0
			AFL		954			1645			0
	2523.700.01-04	080403-01	MOS		72.3			08 Nov 2016			
			MSC				O/C				
Airframe											
252020	Divan (Right No. 2, Two Place) - Final Phase Removal / Installation		HRS		2367			3163.4			0
			AFL		954			1645			0
	2523.700.01-04	080403-02	MOS		72.3			08 Nov 2016			
			MSC				O/C				
Airframe											
252021	Shade, #1 L.H. Window		HRS		5525.5			4.9			0
	ATG-WS-2002	0607-901	AFL		2597			2			0
			MOS		173.9			19 May 2008			AEROSPACE TECHNOLOGIES GROUP INC.
			MSC				O/C				
Airframe											
252022	Shade, #1 R.H. Window		HRS		5525.5			4.9			0
	ATG-WS-2002	0607-902	AFL		2597			2			0
			MOS		173.9			19 May 2008			AEROSPACE TECHNOLOGIES GROUP INC.
			MSC				O/C				
Airframe											

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Description: Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
252023	Shade, #2 L.H. Window WSFA-20-008	0607-101	HRS AFL MOS MSC		2367 954 72.6		O/C	3163.4 1645 29 Oct 2016			0 0
Airframe											
Notes: PER GP522160016 REV. C											
252024	Shade, #2 R.H. Window WSFA-20-008	0607-102	HRS AFL MOS MSC		2367 954 72.6		O/C	3163.4 1645 29 Oct 2016			0 0
Airframe											
Notes: PER GP522160016 REV. C											
252025	Shade, #3 L.H. Window WSFA-20-008	0607-103	HRS AFL MOS MSC		2367 954 72.6		O/C	3163.4 1645 29 Oct 2016			0 0
Airframe											
Notes: PER GP522160016 REV. C											
252026	Shade, #3 R.H. Window WSFA-20-008	0607-104	HRS AFL MOS MSC	TSN:3158.5 TSN:1643 TSN:99	2367 954 72.6		O/C	3163.4 1645 29 Oct 2016			0 0
Airframe											
Notes: PER GP522160016 REV. C											
252027	Shade, #4 L.H. Window WSFA-20-008	0607-105	HRS AFL MOS MSC		2367 954 72.6		O/C	3163.4 1645 29 Oct 2016			0 0
Airframe											
Notes: PER GP522160016 REV. C											
252028	Shade, #4 R.H. Window WSFA-20-008	0607-106	HRS AFL MOS MSC		2367 954 72.6		O/C	3163.4 1645 29 Oct 2016			0 0
Airframe											
Notes: PER GP522160016 REV.C											
252029	Shade, #5 L.H. Window WSFA-20-007	0607-501	HRS AFL MOS MSC		2367 954 72.2		O/C	3163.4 1645 11 Nov 2016			0 0
Airframe											
Notes: INSTALLED PER GP522160016 REV B											

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Description: Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
252030	Shade, #5 R.H. Window WSFA-20-007	0607-502	HRS AFL MOS MSC		2367 954 72.5		 O/C	3163.4 1645 30 Oct 2016			0 0
Airframe											
Notes: PER GP522160016 REV.C											
252031	Shade, #6 L.H. Window WSFA-20-007	0607-503	HRS AFL MOS MSC		1164.6 455 37.5		 O/C	4365.8 2144 02 Oct 2019			0 0
Airframe											
Notes: PER GP522160016 REV.C											
252032	Shade, #6 R.H. Window WSFA-20-007	0607-504	HRS AFL MOS MSC		2367 954 72.5		 O/C	3163.4 1645 30 Oct 2016			0 0
Airframe											
Notes: PER GP522160016 REV.C											
252051	Supplemental Heating - Removal / Installation 80WS042	NSN	HRS AFL MOS MSC		429.8 153 11.9		 O/C	5100.6 2446 18 Nov 2021			0 0
Airframe											
252101	Passenger Seats Attachments and Locking - Detailed Inspection		HRS AFL MOS		882.2 304 25.2	 27	 48	4648.2 2295 09 Oct 2020	 30 Nov 2024*	 31 Dec 2024	0 0
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-4C,200204										
252102	Passenger Seats Restraints - Detailed Inspection		HRS AFL MOS		190.2 71 6.2	 34	 24	5340.2 2528 09 May 2022	 30 Jun 2024*	 31 Jul 2024	0 0
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe	200202										
Notes: REFERENCE ICA DOCUMENT GC42801A344 REV - FOR STC ST03579AT-D											
252104	Passenger Seats Inertia Reels - Operational Test		HRS AFL MOS		190.2 71 6.2	 34	 24	5340.2 2528 09 May 2022	 30 Jun 2024*	 31 Jul 2024	0 0
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe	200202										
Notes: REFERENCE ICA DOCUMENT GC42801A344 REV - FOR STC ST03579AT-D											

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Description: Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
252131	Cabin Double Seat (Left, No. 1) - Final Phase Removal / Installation		HRS	TSN:3158.5	2367			3163.4			0
			AFL	TSN:1643	954			1645			0
	GC422080565-19-4123	080403-07	MOS	TSN:100	72.3			07 Nov 2016			
			MSC				O/C				
Airframe											
Notes: TW 561051 TO 140 INCH LBSPER GC422080566 REV -.											
252132	Cabin Double Seat (Left, No. 2) - Final Phase Removal / Installation		HRS	TSN:3158.5	2367			3163.4			0
			AFL	TSN:1643	954			1645			0
	GC422080565-21-4123	080403-08	MOS	TSN:100	72.3			07 Nov 2016			
			MSC				O/C				
Airframe											
Notes: TW 561051 TO 140 INCH LBSPER GC422080566 REV -.											
252300[U]	Forward Pocket Door (Lh)		HRS		5525.5			4.9			0
	42100-210L-016	31518	AFL		2597			2			0
			MOS		174.6			29 Apr 2008			
			MSC				O/C				
Airframe											
252301	Right Door, Pocket (Forward Cabin)		HRS		5525.5			4.9			0
	42100-210R-038	31436	AFL		2597			2			0
			MOS		173.3			07 Jun 2008			
			MSC				O/C				
Airframe											
252302	Door, Pocket (Mid Cabin)		HRS		5525.5			4.9			0
	42300-230R-024	31650	AFL		2597			2			0
			MOS		172.9			19 Jun 2008			
			MSC				O/C				
Airframe											
252501	Table, #1		HRS	TSN:3158.5	2367			3163.4			0
	53775-25	33117	AFL	TSN:1643	954			1645			0
			MOS	TSN:102	72.6			29 Oct 2016			
			MSC				O/C				
Airframe											
Notes: PER. GPM272001013-501 REV.-											
252502	Table, #2		HRS	TSN:3158.5	2367			3163.4			0
	53775-25	33118	AFL	TSN:1643	954			1645			0
			MOS	TSN:102	72.6			29 Oct 2016			
			MSC				O/C				
Airframe											
Notes: PER. GPM272001013-501 REV.-											

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
252602 Airframe	Toilet Seat, Aft Lav TS-141450-005-AL TS1748	HRS AFL MOS MSC		5525.5 2597 172.7		 O/C	4.9 2 25 Jun 2008			0 0
253010 Airframe	Microwave Oven - Final Phase Removal / Installation R-21LTF 36171	HRS AFL MOS MSC	 TSN:1	2367 954 72.5		 O/C	3163.4 1645 01 Nov 2016			0 0
253012 Airframe	High Temperature Oven - Final Phase Removal / Installation 91107-037-2 61535	HRS AFL MOS MSC	 TSN:25	2367 954 72.5		 O/C	3163.4 1645 01 Nov 2016			0 0
Notes: CE424360022 REV.B										
253017 Airframe	Coffeemaker No. 1 - Final Phase Removal / Installation 400-1794-02 07-05-41014	HRS AFL MOS MSC		5525.5 2597 174.1		 O/C	4.9 2 12 May 2008			0 0 GULFSTREAM SAV COMPLETION IPTS
253051 Airframe	60HZ Outlet Monitor Panel Overlay GC544930009-209 21939	HRS AFL MOS MSC		2367 954 72.4		 O/C	3163.4 1645 04 Nov 2016			0 0 EDN
Notes: CE414940200 REV. -										
253201 Airframe	Espresso Machine AL-EX15-200E-29 661	HRS AFL MOS MSC		1416.9 561 42.7		 O/C	4113.5 2038 26 Apr 2019			0 0
254101 Airframe	Lavatory Compartment - Inspection	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0

ATA / U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Description: Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
256011	Crew Smoke Goggles (Pilot) - Inspection		HRS		957.2			4573.2			0
			AFL		362			2237			0
			MOS		29.1		36	12 Jun 2020	30 Jun 2023	31 Jul 2023	
Airframe	052000-3C,200203		[End Of Month Item] [MOS: +1m/-1m]								
256012	Crew Smoke Goggles (Copilot) - Inspection		HRS		957.2			4573.2			0
			AFL		362			2237			0
			MOS		29.1		36	12 Jun 2020	30 Jun 2023	31 Jul 2023	
Airframe	052000-3C,200203		[End Of Month Item] [MOS: +1m/-1m]								
256013	Crew Smoke Goggles (Observer) - Inspection		HRS		957.2			4573.2			0
			AFL		362			2237			0
			MOS		29.1		36	12 Jun 2020	30 Jun 2023	31 Jul 2023	
Airframe	052000-3C,200203		[End Of Month Item] [MOS: +1m/-1m]								
256016	Axe, Crash		HRS		5530.4			0			0
	D-42	NSN	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			
Airframe			MSC				O/C				
256017	FIRE / Crash Axe - Inspection		HRS		190.2			5340.2			0
			AFL		71			2528			0
			MOS		6.2		12	09 May 2022	31 May 2023	30 Jun 2023	
Airframe	052000-1C		[End Of Month Item] [MOS: +1m/-1m]								
256025	Ditching Line - Detailed Inspection		HRS		882.2			4648.2			0
			AFL		304			2295			0
			MOS		25.5	15	48	02 Oct 2020	31 Oct 2024*	30 Nov 2024	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
256041	First AID Kit, #1		HRS	TSN:249.1	190.2			5340.2			0
	AFAK 1.0	110821004	AFL	TSN:86	71			2528			0
			MOS	TSN:6	6			17 May 2022			N/A
Airframe			MSC				O/C				
256043	First AID / Medical Kits (No. 1) - Detailed Inspection		HRS		190.2			5340.2			0
			AFL		71			2528			0
			MOS		6	26	12	17 May 2022	30 Jun 2023*	31 Jul 2023	
Airframe	052000-1C,200201		[End Of Month Item] [MOS: +1m/-1m]								

Notes: PN: AFAK E ES SN: <NONE>. REFERENCE ICA DOCUMENT GC42801A344 REV - FOR STC ST03579AT-D

ATA / U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
256045	First AID / Medical Kit(S) Time Limited Supply - Discard AFAK 1.0 091721024	HRS AFL MOS		6.5 2 .2		 12	5523.9 2597 11 Nov 2022	 31 Oct 2023		0 0
Airframe		[End Of Month Item]								EXPIRATION
Notes: REFERENCE ICA DOCUMENT GC42801A344 REV - FOR STC ST03579AT-D										
256061	Flashlight (No. 1) RX1019 32938352	HRS AFL MOS MSC		4593.3 2210 139.9		 O/C	937.1 389 19 Mar 2011			0 0
Airframe										
256062	Flashlight (No. 2) 106-000-646 32714440	HRS AFL MOS MSC	TSN:1050.4 TSN:459 TSN:38	4480 2140 137		 O/C	1050.4 459 17 Jun 2011			0 0
Airframe										
256063	Flashlight (No. 3) 106-000-646 32710594	HRS AFL MOS MSC	TSN:1050.4 TSN:459 TSN:38	4480 2140 137		 O/C	1050.4 459 17 Jun 2011			0 0
Airframe										
256071	Flashlight (No. 1) - Operational Test	HRS AFL MOS		190.2 71 6.2	 34	 12	5340.2 2528 09 May 2022	 30 Jun 2023*	 31 Jul 2023	0 0
Airframe	052000-1C,200201	[End Of Month Item] [MOS: +1m/-1m]								
256072	Flashlight (No. 2) - Operational Test	HRS AFL MOS		190.2 71 6.2	 34	 12	5340.2 2528 09 May 2022	 30 Jun 2023*	 31 Jul 2023	0 0
Airframe	052000-1C,200201	[End Of Month Item] [MOS: +1m/-1m]								
256073	Flashlight (No. 3) - Operational Test	HRS AFL MOS		190.2 71 6.2	 34	 12	5340.2 2528 09 May 2022	 30 Jun 2023*	 31 Jul 2023	0 0
Airframe	052000-1C,200201	[End Of Month Item] [MOS: +1m/-1m]								
256201	Life Vest(S) - Detailed Inspection	HRS AFL MOS		190.2 71 6.1	 29	 12	5340.2 2528 14 May 2022	 30 Jun 2023*	 31 Jul 2023	0 0
Airframe	052000-1C,200201	[End Of Month Item] [MOS: +1m/-1m]								
Notes: REFERENCE ICA DOCUMENT GC42801A344 REV - FOR STC ST03579AT-D										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
256202 Logbook Position	Life Raft(S) {No. 1} - Detailed Inspection	HRS		190.2			5340.2			0
		AFL		71			2528			0
		MOS		6	-3	12	17 May 2022	31 May 2023*	30 Jun 2023	
Airframe	052000-1C,200201	[End Of Month Item] [MOS: +1m/-1m]								
Notes: PN: 1421FAUL-6KO-1-100 SN: <NONE>. REFERENCE ICA DOCUMENT GC42801A344 REV - FOR STC ST03579AT-D										
256203 Logbook Position	Life Raft(S) {No. 2} - Detailed Inspection	HRS		190.2			5340.2			0
		AFL		71			2528			0
		MOS		6	-3	12	17 May 2022	31 May 2023*	30 Jun 2023	
Airframe	052000-1C,200201	[End Of Month Item] [MOS: +1m/-1m]								
Notes: REFERENCE ICA DOCUMENT GC42801A344 REV - FOR STC ST03579AT-D										
256205 Logbook Position	Life Vest(S) - Restore	HRS		934.8			4595.6			0
		AFL		346			2253			0
		MOS		28.3		120	08 Jul 2020	29 Mar 2028		
Airframe		[End Of Month Item]								OVERHAUL
Notes: REF. FAA FORM 8130-3 AG45198 FOR WORK PERFORMED										
256211 Logbook Position	Life Vest (No. 1) - Removal / Installation 63600-105 L1001998	HRS		685.5			4844.9			0
		AFL		230			2369			0
		MOS		18.1			14 May 2021			
Airframe		MSC				O/C				
256212 Logbook Position	Life Vest (No. 2) - Removal / Installation 63600-105 L1001999	HRS		685.5			4844.9			0
		AFL		230			2369			0
		MOS		18.1			14 May 2021			
Airframe		MSC				O/C				
256213 Logbook Position	Life Vest (No. 3) - Removal / Installation 63600-105 L1016939	HRS		685.5			4844.9			0
		AFL		230			2369			0
		MOS		18.1			14 May 2021			
Airframe		MSC				O/C				
256214 Logbook Position	Life Vest (No. 4) - Removal / Installation 63600-105 L1016953	HRS		685.5			4844.9			0
		AFL		230			2369			0
		MOS		18.1			14 May 2021			
Airframe		MSC				O/C				

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
256215 Airframe	Life Vest (No. 5) - Removal / Installation 63600-105 L1016954	HRS AFL MOS MSC		685.5 230 18.1		O/C	4844.9 2369 14 May 2021			0 0
256216 Airframe	Life Vest (No. 6) - Removal / Installation 63600-105 L1016955	HRS AFL MOS MSC		685.5 230 18.1		O/C	4844.9 2369 14 May 2021			0 0
256217 Airframe	Life Vest (No. 7) - Removal / Installation 63600-105 L1016956	HRS AFL MOS MSC		685.5 230 18.1		O/C	4844.9 2369 14 May 2021			0 0
256218 Airframe	Life Vest (No. 8) - Removal / Installation 63600-105 L2018100	HRS AFL MOS MSC		685.5 230 18.1		O/C	4844.9 2369 14 May 2021			0 0
256219 Airframe	Life Vest (No. 9) - Removal / Installation 63600-105 L1002001	HRS AFL MOS MSC		685.5 230 18.1		O/C	4844.9 2369 14 May 2021			0 0
256220 Airframe	Life Vest (No. 10) - Removal / Installation 63600-105 L1002002	HRS AFL MOS MSC		685.5 230 18.1		O/C	4844.9 2369 14 May 2021			0 0
256221 Airframe	Life Vest (No. 11) - Removal / Installation 63600-105 L1002003	HRS AFL MOS MSC		685.5 230 18.1		O/C	4844.9 2369 14 May 2021			0 0
256222 Airframe	Life Vest (No. 12) - Removal / Installation 63600-105 L1002006	HRS AFL MOS MSC		685.5 230 18.1		O/C	4844.9 2369 14 May 2021			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
256223 Airframe	Life Vest (No. 13) - Removal / Installation 63600-105 L1002005	HRS AFL MOS MSC		685.5 230 18.1		 O/C	4844.9 2369 14 May 2021			0 0
256224 Airframe	Life Vest (No. 14) - Removal / Installation 63600-105 L1002004	HRS AFL MOS MSC		685.5 230 18.1		 O/C	4844.9 2369 14 May 2021			0 0
256225 Airframe	Life Vest (No. 15) - Removal / Installation 63600-105 L1002007	HRS AFL MOS MSC		685.5 230 18.1		 O/C	4844.9 2369 14 May 2021			0 0
256226 Airframe	Life Vest (No. 16) - Removal / Installation 63600-105 L1002008	HRS AFL MOS MSC		685.5 230 18.1		 O/C	4844.9 2369 14 May 2021			0 0
256250 Airframe	Life Vest (Pilot) - Removal / Installation 63600-505 L785676	HRS AFL MOS MSC		685.5 230 18.1		 O/C	4844.9 2369 14 May 2021			0 0
256251 Airframe	Life Vest (Copilot) - Removal / Installation 63600-505 L786832	HRS AFL MOS MSC		685.5 230 18.1		 O/C	4844.9 2369 14 May 2021			0 0
256252 Airframe	Life Vest (Observer) - Removal / Installation 63600-505 L786868	HRS AFL MOS MSC		685.5 230 18.1		 O/C	4844.9 2369 14 May 2021			0 0
256260 Airframe	Life Raft (No. 1) - Final Phase Removal / Installation 1421FAUL-6KO-1-100 14UL-00292	HRS AFL MOS MSC		190.2 71 6		 O/C	5340.2 2528 17 May 2022			0 0 N/A

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
256261	Life Raft (No. 2) - Final Phase Removal / Installation 1421FAUL-6K0-1-100 14UL-00291	HRS AFL MOS MSC		190.2 71 6		 O/C	5340.2 2528 17 May 2022			0 0 N/A
Airframe										
256270	Life Rafts (No. 1) - Restore 1421FAUL-6KO-1-100 14UL-00292	HRS AFL MOS		190.2 71 6		 36	5340.2 2528 17 May 2022	 31 May 2025		0 0
Airframe		[End Of Month Item]								OVERHAUL
Notes: REF. FAA FORM 8130-3 AG458184 FOR WORK PERFORM.CURRENT HYDRO: 10/2016NEXT HYDRO DUE: 10/2022CYL. DOM: 02/2008CYL. EXP: N/AELT S/N: 133686ELT BATT EXP: 02/2020HEX ID: A6CDD0910083215										
256271	Life Rafts (No. 2) - Restore 1421FAUL-6K0-1-100 14UL-00291	HRS AFL MOS		190.2 71 6		 36	5340.2 2528 17 May 2022	 31 May 2025		0 0
Airframe		[End Of Month Item]								OVERHAUL
Notes: REF. FAA FORM 8130-3 AG45185 FOR WORK PERFORMEDCURRENT HYDRO: 10/2016NEXT HYDRO DUE: 10/2022CYL. DOM: 02/2008CYL EXP: N/AELT S/N: 133013ELT BATT EXP: 07/2022HEX ID: A6CDD0910082215										
256281	Protective Breathing Equipment (No. 1) - Removal / Installation MR-10039N E1608537	HRS AFL MOS MSC	TSN:1717.7 TSN:736 TSN:50	439.3 157 12.3		 O/C	5091.1 2442 08 Nov 2021			0 0 N/A
Airframe										
256282	Protective Breathing Equipment (No. 1) - Detailed Inspection	HRS AFL MOS		6.5 2 .2	 -3	500 12	5523.9 2597 11 Nov 2022	6023.9 30 Nov 2023*	6073.9 31 Dec 2023	0 0
Airframe	052000-1A,200100	[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
Notes: TO BE REPLACED NOV/2018.REFERENCE ICA DOCUMENT GC42801A344 REV - FOR STC ST03579AT-D										
256283	Protective Breathing Equipment (No. 1) - Discard MR-10039N E1608537	HRS AFL MOS		2157 893 66.2		 120	3373.4 1706 09 May 2017	 30 Apr 2027		0 0
Airframe		[End Of Month Item]								EXPIRATION
Notes: REFERENCE ICA DOCUMENT GC42801A344 REV - FOR STC ST03579AT-D										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
256284 Logbook Position	Protective Breathing Equipment (No. 2) - Removal / Installation MR-10039N E1707845	HRS AFL MOS MSC	TSN:1330.2 TSN:560 TSN:40	439.3 157 12.3		 O/C	5091.1 2442 08 Nov 2021			0 0 N/A
Airframe										
256285 Airframe	Protective Breathing Equipment (No. 2) - Detailed Inspection 052000-1A,200100	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]		6.5 2 .2	 -3	500 12	5523.9 2597 11 Nov 2022	6023.9 30 Nov 2023*	6073.9 31 Dec 2023	0 0
Notes: REFERENCE ICA DOCUMENT GC42801A344 REV - FOR STC ST03579AT-D										
256286 Airframe	Protective Breathing Equipment (No. 2) - Discard MR-10039N E1707845	HRS AFL MOS [End Of Month Item]		1769.5 717 54.9		 120	3760.9 1882 20 Apr 2018	 01 Aug 2028		0 0 EXPIRATION
Notes: REFERENCE ICA DOCUMENT GC42801A344 REV - FOR STC ST03579AT-D										
256301 Airframe	Emergency Locator Transmitter - Removal / Installation 453-5060 13899	HRS AFL MOS MSC		190.2 71 6.2		 O/C	5340.2 2528 10 May 2022			0 0 N/A
256302 Airframe	Emergency Locator Transmitter Batteries - Discard 452-0133 392333-010	HRS AFL MOS [End Of Month Item]	 TSN:9	190.2 71 6.2		 60	5340.2 2528 10 May 2022	 02 Nov 2026		0 0 N/A EXPIRATION
256303 Airframe	Emergency Locator Transmitter Antenna - Removal / Installation 110-341 50421	HRS AFL MOS MSC	TSN:2063.9 TSN:976 TSN:71	957.2 362 29.1		 O/C	4573.2 2237 12 Jun 2020			0 0
Notes: PQ162										
256306 Airframe	Emergency Locator Transmitter - Operational Test (FAR 91.207) 052000-1C,200201	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		190.2 71 6.2	 3	 12	5340.2 2528 11 May 2022	 31 May 2023*	 30 Jun 2023	0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
256401 Airframe	Defibrillator 861304 B11E-00328	HRS AFL MOS MSC	TSN:2	4448.1 2114 136.3		 O/C	1082.3 485 06 Jul 2011			0 0 Philips Medical Systems
256402 Airframe	Defibrillator - General Visual Insp	HRS AFL MOS [End Of Month Item]		6.5 2 .2		 4	5523.9 2597 11 Nov 2022	31 Mar 2023		0 0
256403 Airframe	Battery, Defibrillator 989803139301 NSN	HRS AFL MOS MSC		190.2 71 6.2		 DUE	5340.2 2528 09 May 2022	31 Jul 2027		0 0 N/A EXPIRATION
256404 Airframe	Electrode PAD, Defibrillator SET #1 989803139261 201214-0953	HRS AFL MOS MSC		697.6 234 18.5		 DUE	4832.8 2365 30 Apr 2021	14 Jun 2023		0 0 EXPIRATION
256405 Airframe	Electrode PAD, Defibrillator SET #2 989803139261 989803139261	HRS AFL MOS MSC		697.6 234 18.5		 DUE	4832.8 2365 30 Apr 2021	14 Jun 2023		0 0 EXPIRATION
256406 Airframe	Battery, Defibrillator (Spare) 989803139301 NSN	HRS AFL MOS MSC		190.2 71 6.2		 DUE	5340.2 2528 09 May 2022	31 Jul 2027		0 0 N/A EXPIRATION
256501 Airframe	Switch Panel, Fwd Lav # 1 2501-1-029 316YV	HRS AFL MOS MSC		5525.5 2597 174.1		 O/C	4.9 2 12 May 2008			0 0
256502 Airframe	Switch Panel, Aft Lav #1 2501-1-031 316RF	HRS AFL MOS MSC		5525.5 2597 171.9		 O/C	4.9 2 18 Jul 2008			0 0

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Description: Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
256503	Switch Panel, Aft Lav #2		HRS		5525.5			4.9			0
	2501-1-032	316NH	AFL		2597			2			0
			MOS		174.2			09 May 2008			
			MSC				O/C				
Airframe											
256504	Switch Panel, Fwd Lav Flush		HRS		5525.5			4.9			0
	2501-1-134	316NF	AFL		2597			2			0
			MOS		174.1			12 May 2008			
			MSC				O/C				
Airframe											
256505	Switch Panel, Aft Lav Flush		HRS		5525.5			4.9			0
	2501-1-321	3179W	AFL		2597			2			0
			MOS		174.1			12 May 2008			
			MSC				O/C				
Airframe											
256506	Switch Panel, Galley #1		HRS		5525.5			4.9			0
	2501-3-047	206250211	AFL		2597			2			0
			MOS		174.3			07 May 2008			
			MSC				O/C				
Airframe											
256507	Switch Panel, Galley #2		HRS		5525.5			4.9			0
	2501-3-126	3178G	AFL		2597			2			0
			MOS		174.3			07 May 2008			
			MSC				O/C				
Airframe											
26 - FIRE Protection											
260301	Baggage Compartment Smoke Evacuation Valve - Operational Test		HRS		957.2			4573.2			0
			AFL		362			2237			0
			MOS		29.1		72	12 Jun 2020	30 Jun 2026	31 Jul 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-6C,200206										
261109	Equipment Overheat Thermal Switch (Left) - Operational Check		HRS		5530.4			0			0
			AFL		2599			0			0
			MOS		174.6			28 Apr 2008			
			MSC				O/C				
Airframe											

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
261110 Airframe	Equipment Overheat Thermal Switch (Right) - Operational Check	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
261125 Airframe	Forward Fixed Cowl FIRE Detection RAIL Assembly - Removal / Installation PN SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
261126 Airframe	R/H FIRE Detection Fwd Fix Cowl RAIL	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
261127 Airframe	Aft Fixed Cowl FIRE Detection RAIL Assembly (Left) - Removal / Installation PN SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
261128 Airframe	Aft Fixed Cowl FIRE Detection RAIL Assembly (Right) - Removal / Installation PN SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
261145 Airframe	Engine FIRE and Heat Sensing (Left) - Functional Test	HRS AFL MOS MSC		1769.5 717 54.5		 O/C	3760.9 1882 02 May 2018			0 0
261146 Airframe	Engine FIRE and Heat Sensing (Right) - Functional Test	HRS AFL MOS MSC		1769.5 717 54.5		 O/C	3760.9 1882 02 May 2018			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
261149 Airframe	FIRE Detection Link Harness (from Aft Fixed Cowl RAIL to Forward Fixed Cowl Disconnect) {Right} - Removal / Installation 51291-226 08-02-9747	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0
261150 Airframe	FIRE Detection Link Harness (from Aft Fixed Cowl RAIL to Forward Fixed Cowl Disconnect) {Right} - Removal / Installation 51291-224 08-02-9790	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0
261151 Airframe	FIRE Detection Link Harness (from Fwd Fixed Cowl RAIL to Fwd Fixed Cowl Disconnect) {Left} - Removal / Installation 51291-220 08-02-9825	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0
261153 Airframe	FIRE Detection RAIL Assembly No. 1 (Left) - Removal / Installation 51291-225 07-10-9451	HRS AFL MOS MSC	TSN:3838.9 TSN:1931 TSN:123	1691.5 668 51.9		O/C	3838.9 1931 19 Jul 2018			0 0
261154 Airframe	FIRE Detection RAIL Assembly No. 1 (Right) - Removal / Installation 51291-227 06-10-8378	HRS AFL MOS MSC	TSN:3838.9 TSN:1931 TSN:123	1691.5 668 51.9		O/C	3838.9 1931 19 Jul 2018			0 0
261155 Airframe	FIRE Detection RAIL Assembly No. 2 (Left) - Removal / Installation 51291-222 07-10-9454	HRS AFL MOS MSC	TSN:3838.9 TSN:1931 TSN:123	1691.5 668 51.9		O/C	3838.9 1931 20 Jul 2018			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
261156 Airframe	FIRE Detection RAIL Assembly No. 2 (Right) - Removal / Installation 51291-222 07-10-9457	HRS AFL MOS MSC	TSN:3838.9 TSN:1931 TSN:123	1691.5 668 51.9		 O/C	3838.9 1931 19 Jul 2018			0 0
261157 Airframe	FIRE Detection RAIL Assembly No. 3 (Left) - Removal / Installation 51291-223 07-10-9447	HRS AFL MOS MSC	TSN:3838.9 TSN:1931 TSN:123	1691.5 668 51.9		 O/C	3838.9 1931 19 Jul 2018			0 0 ARROW BELL
261158 Airframe	FIRE Detection RAIL Assembly No. 3 (Right) - Removal / Installation 51291-228 07-10-9444	HRS AFL MOS MSC		1691.5 668 51.9		 O/C	3838.9 1931 19 Jul 2018			0 0
261201 Airframe	FIRE Detection Control Unit (Left) - Removal / Installation 51653-274 1208	HRS AFL MOS MSC		957.2 362 29.1		 O/C	4573.2 2237 12 Jun 2020			0 0
261202 Airframe	FIRE Detection Control Unit (Right) - Removal / Installation 51653-154 2544	HRS AFL MOS MSC		957.2 362 29.1		 O/C	4573.2 2237 12 Jun 2020			0 0
261209 Airframe	Pylon Thermal Switches (Left) - Functional Test	HRS AFL MOS MSC		5530.4 2599 171.1		 O/C	0 0 12 Aug 2008			0 0
261210 Airframe	Pylon Thermal Switches (Right) - Functional Test	HRS AFL MOS MSC		5530.4 2599 171.1		 O/C	0 0 12 Aug 2008			0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
261211	FIRE Detection Control Unit (Left) - Functional Test	HRS		957.2			4573.2			0
		AFL		362			2237			0
		MOS		29.1			12 Jun 2020			
		MSC				O/C				
Airframe										
261212	FIRE Detection Control Unit (Right) - Functional Test	HRS		957.2			4573.2			0
		AFL		362			2237			0
		MOS		29.1			12 Jun 2020			
		MSC				O/C				
Airframe										
261213	Pylon Hot Indication Circuit and Thermal Switches (Left) - Operational Check	HRS		882.2			4648.2			0
		AFL		304			2295			0
		MOS		23.3		72	08 Dec 2020	31 Dec 2026	31 Jan 2027	
	[End Of Month Item] [MOS: +1m/-1m]									
Airframe	052000-4C,200206									
261214	Pylon Hot Indication Circuit and Thermal Switches (Right) - Operational Check	HRS		882.2			4648.2			0
		AFL		304			2295			0
		MOS		23.3		72	08 Dec 2020	31 Dec 2026	31 Jan 2027	
	[End Of Month Item] [MOS: +1m/-1m]									
Airframe	052000-4C,200206									
261301	Auxiliary Power Unit FIRE Detection Loop - Removal / Installation	HRS		5530.4			0			0
		AFL		2599			0			0
	6360-12-1000/450-7 201492	MOS		174.6			28 Apr 2008			MEGGITT SAFETY SYSTEMS
		MSC				O/C				
Airframe										
261302	APU (FIRE) Shutdown Circuit - Operational Test	HRS		190.2			5340.2			0
		AFL		71			2528			0
		MOS		6	43	24	17 May 2022	30 Jun 2024*	31 Jul 2024	
	[End Of Month Item] [MOS: +1m/-1m]									
Airframe	200202									
261303	Auxiliary Power Unit FIRE Detection Loop - Temperature Trip Point Check	HRS		1769.5			3760.9			0
		AFL		717			1882			0
		MOS		54.7			26 Apr 2018			
		MSC				O/C				
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
261305	APU Compartment FIRE Detection Loop - Operational Test	HRS		1769.5		2000	3760.9	5760.9	5810.9	0
		AFL		717			1882			0
		MOS		54.7			26 Apr 2018			
		[HRS: +50/-50]								
Airframe	052000-4A,200104									
261418	Aft Equipment Overheat Thermal Switch - Operational Check	HRS		882.2			4648.2			0
		AFL		304			2295			0
		MOS		26	-16	48	16 Sep 2020	31 Aug 2024*	30 Sep 2024	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-4C,200204									
261419	Baggage Compartment Below Floor Overheat Thermal Switch - Operational Check	HRS		2367			3163.4			0
		AFL		954			1645			0
		MOS		73.1	-44	96	14 Oct 2016	31 Aug 2024*	30 Sep 2024	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-8C									
261601	FIRE Detection and Indication - Functional Test	HRS		882.2			4648.2			0
		AFL		304			2295			0
		MOS		23.3			08 Dec 2020			
		MSC				O/C				
Airframe										
262020	Engine FIRE Bottle (Left) - Removal / Installation 33800100-1 55259D1	HRS		697.6			4832.8			0
		AFL		234			2365			0
		MOS		18.5			30 Apr 2021			
		MSC				O/C				
Airframe										
Notes: VERIFIED BY Q306918										
262021	Engine FIRE Bottle (Left) - (Hydrostatic) Functional Test	HRS		2157			3373.4			0
		AFL		893			1706			0
		MOS		66.2			09 May 2017			
		MSC				O/C				HYDRO CHECK
Airframe										
Notes: PN: 33800100-1 SN: <NONE>. VERIFIED BY Q306918										
262025	Engine FIRE Bottle (Right) - Removal / Installation 33800100-1 A3074D1	HRS		697.6			4832.8			0
		AFL		234			2365			0
		MOS		18.5			30 Apr 2021			
		MSC				O/C				
Airframe										
Notes: VERIFIED BY Q306918										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
262026 Logbook Position	Engine FIRE Bottle (Right) - (Hydrostatic) Functional Test	HRS AFL MOS MSC		2157 893 66.2		O/C	3373.4 1706 09 May 2017			0 0 HYDRO CHECK
Airframe										
Notes: PN: 33800100-1 SN: <NONE>. VERIFIED BY Q306918										
262105 Airframe	Engine FIRE Extinguishing Shuttle Valve (Double Check Valve Tee) (Left) - Detailed Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		1416.9 561 43	13	120	4113.5 2038 17 Apr 2019	30 Apr 2029*	31 May 2029	0 0
Notes: LATEST DUE ON 30.08.2019, NEW REQUIREMENT IAW AMM REV. 27. J.BLUMER										
262106 Airframe	Engine FIRE Extinguishing Shuttle Valve (Double Check Valve Tee) (Right) - Functional Test	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		1416.9 561 43	13	120	4113.5 2038 17 Apr 2019	30 Apr 2029*	31 May 2029	0 0
Notes: LATEST DUE ON 30.08.2019, NEW REQUIREMENT IAW AMM REV. 27. J.BLUMER										
262108 Airframe	Engine FIRE Bottle Cartridge (Squib) {Left Bottle, Left Squib, Service Life} - Discard 30903876 1366TE	HRS AFL MOS [End Of Month Item]	TSN:16	2157 893 66.2		120	3373.4 1706 09 May 2017	31 Jan 2026		0 0
Notes: VERIFIED BY Q306918										
262109 Airframe	Engine FIRE Bottle Cartridge (Squib) {Left Bottle, Left Squib, Manufacturers Life} - Discard M30903959 00093	HRS AFL MOS [End Of Month Item]		6.5 2 .2		180	5523.9 2597 11 Nov 2022	31 Oct 2037		0 0 MANUFACTURE
Notes: VERIFIED BY Q306918										
262110 Airframe	Engine FIRE Bottle Cartridge (Squib) {Left Bottle, Right Squib, Service Life} - Discard 30903931 0722RL	HRS AFL MOS [End Of Month Item]	TSN:27	2157 893 66.2		120	3373.4 1706 09 May 2017	28 Feb 2025		0 0
Notes: VERIFIED BY Q306918										

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
262111	Engine FIRE Bottle Cartridge (Squib) {Left Bottle, Right Squib, Manufacturers Life} - Discard		HRS		6.5			5523.9			0
			AFL		2			2597			0
	M30903931	00169	MOS		.2		180	11 Nov 2022	31 Oct 2037		
			[End Of Month Item]								MANUFACTURE
Airframe											
Notes: VERIFIED BY Q306918											
262112	Engine FIRE Bottle Cartridge (Squib) {Left Bottle, APU Squib, Service Life} - Discard		HRS		2157			3373.4			0
			AFL		893			1706			0
	30903933	0775RL	MOS	TSN:27	66.2		120	09 May 2017	28 Feb 2025		
			[End Of Month Item]								
Airframe											
Notes: VERIFIED BY Q306918											
262113	Engine FIRE Bottle Cartridge (Squib) {Left Bottle, APU Squib, Manufacturers Life} - Discard		HRS		6.5			5523.9			0
			AFL		2			2597			0
	30903931	0199	MOS		.2		180	11 Nov 2022	30 Sep 2037		
			[End Of Month Item]								MANUFACTURE
Airframe											
Notes: VERIFIED BY Q306918											
262114	Engine FIRE Bottle Cartridge (Squib) {Right Bottle, Left Squib, Service Life} - Discard		HRS		2157			3373.4			0
			AFL		893			1706			0
	30903876	0316TK	MOS	TSN:14	66.2		120	09 May 2017	31 Mar 2026		
			[End Of Month Item]								
Airframe											
Notes: VERIFIED BY Q306918											
262115	Engine FIRE Bottle Cartridge (Squib) {Right Bottle, Left Squib, Manufacturers Life} - Discard		HRS		6.5			5523.9			0
			AFL		2			2597			0
	M30903959	00091	MOS		.2		180	11 Nov 2022	31 Oct 2037		
			[End Of Month Item]								MANUFACTURE
Airframe											
Notes: VERIFIED BY Q306918											
262116	Engine FIRE Bottle Cartridge (Squib) {Right Bottle, Right Squib, Service Life} - Discard		HRS		190.2			5340.2			0
			AFL		71			2528			0
	30903828	1125CB	MOS	TSN:2	6.1		120	14 May 2022	31 Mar 2032		N/A
			[End Of Month Item]								
Airframe											
Notes: VERIFIED BY Q306918											

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
262117	Engine FIRE Bottle Cartridge (Squib) {Right Bottle, Right Squib, Manufacturers Life} - Discard		HRS		6.5			5523.9			0
			AFL		2			2597			0
	M30903931	1210CG	MOS		.2		180	11 Nov 2022	30 Sep 2037		
			[End Of Month Item]								MANUFACTURE
Airframe											
Notes: VERIFIED BY Q306918											
262118	Engine FIRE Bottle Cartridge (Squib) {Right Bottle, Spare Squib, Service Life} - Discard		HRS		2157			3373.4			0
			AFL		893			1706			0
	30903852	1790UB	MOS	TSN:12	66.2		120	09 May 2017	31 May 2026		
			[End Of Month Item]								
Airframe											
Notes: VERIFIED BY Q306918											
262119	Engine FIRE Bottle Cartridge (Squib) {Right Bottle, Spare Squib, Manufacturers Life} - Discard		HRS		5530.4			0			0
			AFL		2599			0			0
	30903933	2003HL	MOS		174.6		180	28 Apr 2008	30 Nov 2022		
			[End Of Month Item]								MANUFACTURE
Airframe											
Notes: VERIFIED BY Q306918											
262120	Engine FIRE Pull Handle (Left) - Removal / Installation		HRS		5530.4			0			0
	24293-1	359	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			ESTERLINE
			MSC				O/C				MASON
Airframe											
262121	Engine FIRE Pull Handle (Right) - Removal / Installation		HRS		5530.4			0			0
	24293-2	331	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			JANCO
			MSC				O/C				CORPORATION
Airframe											
262122	Engine and Auxiliary Power Unit FIRE Extinguishing Firing Circuitry (Left Engine) - Functional Check		HRS		957.2			4573.2			0
			AFL		362			2237			0
			MOS		29.1		36	12 Jun 2020	30 Jun 2023	31 Jul 2023	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe	200203										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
262123	Engine and Auxiliary Power Unit FIRE Extinguishing Firing Circuitry (Right Engine) - Functional Check	HRS		957.2			4573.2			0
		AFL		362			2237			0
		MOS		29.1		36	12 Jun 2020	30 Jun 2023	31 Jul 2023	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe	200203									
262124	Engine FIRE Bottle Pressure Switch (Left) - Operational Test	HRS		190.2			5340.2			0
		AFL		71			2528			0
		MOS		6.1	17	60	14 May 2022	31 May 2027*	30 Jun 2027	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe	200205									
262125	Engine FIRE Bottle Pressure Switch (Right) - Operational Test	HRS		190.2			5340.2			0
		AFL		71			2528			0
		MOS		6.1	17	60	14 May 2022	31 May 2027*	30 Jun 2027	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe	200205									
262126	Engine and Auxiliary Power Unit FIRE Extinguishing Firing Circuitry (APU) - Functional Check	HRS		697.6			4832.8			0
		AFL		234			2365			0
		MOS		18.5	-18	36	30 Apr 2021	30 Apr 2024*	31 May 2024	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe										
Notes: REF C/N 556311 CAL"D 09/06/2016 DUE 09/2017										
262128	Engine FIRE Bottle Cartridge (Squib) (Left Bottle, Left Squib) - Removal / Installation	HRS		2157			3373.4			0
		AFL		893			1706			0
	30903876 1366TE	MOS		66.2			09 May 2017			
		MSC				O/C				
Airframe										
262129	Engine FIRE Bottle Cartridge (Squib) (Left Bottle, Right Squib) - Removal / Installation	HRS		2157			3373.4			0
		AFL		893			1706			0
	30903931 0722RL	MOS		66.2			09 May 2017			
		MSC				O/C				
Airframe										
262130	Engine FIRE Bottle Cartridge (Squib) (Left Bottle, APU Squib) - Removal / Installation	HRS		2157			3373.4			0
		AFL		893			1706			0
	30903933 0775RL	MOS		66.2			09 May 2017			
		MSC				O/C				
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
262131 Logbook Position	Engine FIRE Bottle Cartridge (Squib) (Right Bottle, Left Squib) - Removal / Installation 30903876 0316TK	HRS AFL MOS MSC		2157 893 66.2		O/C	3373.4 1706 09 May 2017			0 0
Airframe										
262132 Logbook Position	Engine FIRE Bottle Cartridge (Squib) (Right Bottle, Right Squib) - Removal / Installation 30903828 1125CB	HRS AFL MOS MSC	TSN:2	190.2 71 6.1		O/C	5340.2 2528 14 May 2022			0 0 N/A
Airframe										
262133 Logbook Position	Engine FIRE Bottle Cartridge (Squib) (Right Bottle, Spare Squib) - Removal / Installation 30903852 1790UB	HRS AFL MOS MSC		2157 893 66.2		O/C	3373.4 1706 09 May 2017			0 0
Airframe										
262135 Logbook Position	Engine FIRE Pull Handle (Left) - Functional Test	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0
Airframe										
262136 Logbook Position	Engine FIRE Pull Handle (Right) - Functional Test	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0
Airframe										
262138 Logbook Position	FIRE Bottle (Left) - Weight Check	HRS AFL MOS		697.6 234 18.5	31	60	4832.8 2365 30 Apr 2021	31 May 2026*	30 Jun 2026	0 0
Airframe	[End Of Month Item] [MOS: +1m/-1m]									
262141 Logbook Position	FIRE Bottle (Right) - Weight Check	HRS AFL MOS		697.6 234 18.5	31	60	4832.8 2365 30 Apr 2021	31 May 2026*	30 Jun 2026	0 0
Airframe	[End Of Month Item] [MOS: +1m/-1m]									

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
262510 Logbook Position	Portable Water FIRE Extinguisher (Forward Cabin) - Removal / Installation 892480 25508	HRS AFL MOS MSC		190.2 71 5.8		 O/C	5340.2 2528 23 May 2022			0 0 N/A
Airframe										
262512	Portable Water FIRE Extinguisher (Forward Cabin) - (Proof Pressure Test) Functional Test	HRS AFL MOS [End Of Month Item]		190.2 71 6		 60	5340.2 2528 17 May 2022	 31 May 2027		0 0 HYDRO CHECK
Airframe										
Notes: PN: 892480 SN: <NONE>. REFERENCE ICA DOCUMENT GC42801A344 REV - FOR STC ST03579AT-D										
262515	Portable Water FIRE Extinguisher (Aft Cabin) - Removal / Installation 892480 SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 AV OX INC
Airframe										
262550	Extinguish, Aft Lav Trash FIRE 474276 NSN	HRS AFL MOS MSC		190.2 71 6.1		 O/C	5340.2 2528 13 May 2022			0 0 N/A
Airframe										
262551	Extinguish, Fwd Lav Trash FIRE 474276 NSN	HRS AFL MOS MSC	TSN:5335.3 TSN:2526 TSN:168	190.2 71 6.2		 O/C	5340.2 2528 09 May 2022			0 0 N/A
Airframe										
262553	Ext, Fwd Galley/Annex Trash 474276 NSN	HRS AFL MOS MSC		190.2 71 5.8		 O/C	5340.2 2528 23 May 2022			0 0 N/A
Airframe										
262560	Trash Receptacle Enclosure (Aft Lavatory) - Detailed Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		190.2 71 6.2		 12	5340.2 2528 09 May 2022	 31 May 2023	30 Jun 2023	0 0
Airframe	052000-1C									

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
262561 Logbook Position	Trash Receptacle Enclosure (Forward Lavatory) - Detailed Inspection	HRS AFL MOS		190.2 71 6.2		 12	5340.2 2528 09 May 2022	 31 May 2023	 30 Jun 2023	0 0
	[End Of Month Item] [MOS: +1m/-1m]									
Airframe	052000-1C									
262563 Logbook Position	Trash Receptacle Enclosure (Forward Galley / Annex) - Detailed Inspection	HRS AFL MOS		190.2 71 6.2		 12	5340.2 2528 09 May 2022	 31 May 2023	 30 Jun 2023	0 0
	[End Of Month Item] [MOS: +1m/-1m]									
Airframe	052000-1C									
262570 Logbook Position	Trash Receptacle FIRE Extinguishing Bottle (Weight Check, Aft Lavatory) - Functional Test	HRS AFL MOS		190.2 71 6.2		 60	5340.2 2528 09 May 2022	 31 May 2027	 30 Jun 2027	0 0
	[End Of Month Item] [MOS: +1m/-1m]									WEIGHT CHECK
Airframe	052000-5C									
Notes: PN: 474276 SN: <NONE>. REFERENCE ICA DOCUMENT GC42801A344 REV - FOR STC ST03579AT-D										
262571 Logbook Position	Trash Receptacle FIRE Extinguishing Bottle (Weight Check, Forward Lavatory) - Functional Test	HRS AFL MOS		190.2 71 6.2		 60	5340.2 2528 09 May 2022	 31 May 2027	 30 Jun 2027	0 0
	[End Of Month Item] [MOS: +1m/-1m]									WEIGHT CHECK
Airframe	052000-5C									
Notes: PN: 474276 SN: <NONE>. REFERENCE ICA DOCUMENT GC42801A344 REV - FOR STC ST03579AT-D										
262573 Logbook Position	Trash Receptacle FIRE Extinguishing Bottle (Weight Check, Forward Galley / Annex) - Functional Test	HRS AFL MOS		190.2 71 6.2		 60	5340.2 2528 09 May 2022	 31 May 2027	 30 Jun 2027	0 0
	[End Of Month Item] [MOS: +1m/-1m]									WEIGHT CHECK
Airframe	052000-5C									
Notes: PN: 474276 SN: <NONE>. REFERENCE ICA DOCUMENT GC42801A344 REV - FOR STC ST03579AT-D										
262583 Logbook Position	Trash Receptacle FIRE Extinguisher Nozzles (Aft Lavatory) - Detailed Inspection	HRS AFL MOS		190.2 71 6.2		 12	5340.2 2528 09 May 2022	 31 May 2023	 30 Jun 2023	0 0
	[End Of Month Item] [MOS: +1m/-1m]									
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
262584	Trash Receptacle FIRE Extinguisher Nozzles (Forward Lavatory) - Detailed Inspection	HRS		190.2			5340.2			0
		AFL		71			2528			0
		MOS		6.2		12	09 May 2022	31 May 2023	30 Jun 2023	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe										
262586	Trash Receptacle FIRE Extinguisher Nozzles (Forward Galley / Annex) - Detailed Inspection	HRS		190.2			5340.2			0
		AFL		71			2528			0
		MOS		6.2		12	09 May 2022	31 May 2023	30 Jun 2023	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe										
262600	Portable Halon FIRE Extinguisher (Cockpit) - Removal / Installation 898052 X-988851	HRS		190.2			5340.2			0
		AFL		71			2528			0
		MOS		6.2			09 May 2022			N/A
		MSC				O/C				
Airframe										
262601	Portable Halon FIRE Extinguisher (Cockpit) - Detailed Inspection	HRS		190.2			5340.2			0
		AFL		71			2528			0
		MOS		6.2		12	09 May 2022	31 May 2023	30 Jun 2023	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-1C,200201									
Notes: PN: 898052 SN: <NONE>. UNIT REPLACED PER 262600										
262602	Portable Halon FIRE Extinguisher (Cockpit) - Weight Check	HRS		190.2			5340.2			0
		AFL		71			2528			0
		MOS		6.2		12	09 May 2022	31 May 2023	30 Jun 2023	
		[End Of Month Item] [MOS: +1m/-1m]								WEIGHT CHECK
Airframe										
262610	Portable Halon FIRE Extinguisher (Forward Cabin) - Removal / Installation C354 F-68185115	HRS		190.2			5340.2			0
		AFL		71			2528			0
		MOS		6.2			09 May 2022			N/A
		MSC				O/C				
Airframe										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
262611	Portable Halon FIRE Extinguisher (Forward Cabin) - Detailed Inspection	HRS		190.2			5340.2			0
		AFL		71			2528			0
		MOS		6.2		12	09 May 2022	31 May 2023	30 Jun 2023	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-1C,200201									
Notes: REFERENCE ICA DOCUMENT GC42801A344 REV - FOR STC ST03579AT-D										
262612	Portable Halon FIRE Extinguisher (Forward Cabin) - Weight Check	HRS		190.2			5340.2			0
		AFL		71			2528			0
		MOS		6.2		12	09 May 2022	31 May 2023	30 Jun 2023	
		[End Of Month Item] [MOS: +1m/-1m]								WEIGHT CHECK
Airframe										
262615	Portable Halon FIRE Extinguisher (Forward Cabin) - Final Phase Restore	HRS		1022.2			4508.2			0
		AFL		401			2198			0
	30H673 F-68185115	MOS		33.8		72	21 Jan 2020	30 Jun 2026		
		[End Of Month Item]								OVERHAUL
Airframe										
Notes: REFERENCE ICA DOCUMENT GC42801A344 REV - FOR STC ST03579AT-D										
262630	Portable Halon FIRE Extinguisher (Aft Lavatory) - Removal / Installation	HRS	TSN:1226.7	190.2			5340.2			0
		AFL	TSN:490	71			2528			0
	C354 D-05889499	MOS	TSN:45	6.2			09 May 2022			N/A
		MSC				O/C				
Airframe										
Notes: S/NO. X-192913 OFF AND ON - FL015198.										
262631	Portable Halon FIRE Extinguisher (Aft Lavatory) - Detailed Inspection	HRS		190.2			5340.2			0
		AFL		71			2528			0
		MOS		6.2		12	09 May 2022	31 May 2023	30 Jun 2023	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-1C,200201									
Notes: REFERENCE ICA DOCUMENT GC42801A344 REV - FOR STC ST03579AT-D										
262632	Portable Halon FIRE Extinguisher (Aft Lavatory) - Weight Check	HRS		190.2			5340.2			0
		AFL		71			2528			0
		MOS		6.2		12	09 May 2022	31 May 2023	30 Jun 2023	
		[End Of Month Item] [MOS: +1m/-1m]								WEIGHT CHECK
Airframe										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
262635	Portable Halon FIRE Extinguisher (Aft Lavatory) - Final Phase Restore	HRS		1416.9			4113.5			0
		AFL		561			2038			0
	C354TS D-05889499	MOS	TSN:13	42.7		72	24 Apr 2019	31 Aug 2023		
		[End Of Month Item]								OVERHAUL
Airframe										
Notes: REFERENCE ICA DOCUMENT GC42801A344 REV - FOR STC ST03579AT-D										
27 - Flight Controls										
270005	Rudder and Aileron Trim Control Head - Removal / Installation	HRS		5525.5			4.9			0
		AFL		2597			2			0
	528401-13 194	MOS		172.7			25 Jun 2008			
		MSC				O/C				
Airframe										
Notes: VERIFIED BY PQ211										
270021	Flight Control System Force Sensors - Operational Test	HRS		5530.4			0			0
		AFL		2599			0			0
		MOS		174.6			28 Apr 2008			
		MSC				O/C				
Airframe										
270032	Rudder Primary Cable Pressure Seals - Removal / Installation	HRS		3021.1			2509.3			0
		AFL		1338			1261			0
	1159CH7020-5 NSN	MOS		102.1			14 May 2014			
		MSC				O/C				
Airframe										
270033	Elevator Primary Cable Pressure Seals - Removal / Installation	HRS	TSN:2907.1	2623.3			2907.1			0
		AFL	TSN:1515	1084			1515			0
	1159C47020-7 N/A	MOS	TSN:92	82.6			29 Dec 2015			
		MSC				O/C				
Airframe										
270101	Angle of Attack Transducer (Left) - Removal / Installation	HRS		439.3			5091.1			0
	SLZ7600 FT0250	AFL		157			2442			0
		MOS		12.2			11 Nov 2021			N/A
		MSC				O/C				
Airframe										
Notes: VERF Q307597										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
270102	Angle of Attack Transducer (Right) - Removal / Installation SLZ7600 FT0231	HRS AFL MOS MSC		4304.6 2029 133.8		 O/C	1225.8 570 21 Sep 2011			0 0 PROFESSIONAL AIRCRAFT ACCESSORIES
Airframe										
Notes: S/NO. FT0158 CAME OFF - FL015758.										
271001	Aileron Trim Tab - Removal / Installation 1159SCH20600-69 4123	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										
271002	Aileron Trim Tab Actuator - Removal / Installation 1159SCC201-7 00538	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 GOODRICH SENSOR SYSTEMS
Airframe										
271003	Aileron Trim Cable Assembly FS 452 - Rbs 345 (Upper) - Removal / Installation X SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										
271008	Aileron Trim Tab Actuator / Linkage - General Visual Inspection	HRS AFL MOS		2367 954 73.4	 -34	 96	3163.4 1645 04 Oct 2016	 31 Aug 2024*	 30 Sep 2024	0 0
Airframe	[End Of Month Item] [MOS: +1m/-1m] 052000-8C									
271009	Lateral Control System - Operational Check	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
271010 Airframe	Aileron Control and Trim Cables In Pressurized Areas of Fuselage and Overwing to Aft Wing Links - Detailed Inspection 052000-8C	HRS AFL MOS		2367 954 72.9	-50	96	3163.4 1645 20 Oct 2016	31 Aug 2024*	30 Sep 2024	0 0
	[End Of Month Item] [MOS: +1m/-1m]									
Notes: TENSIOMETER: 66852 DATE DUE: 02/17										
271011 Airframe	Aileron Control and Trim Cables In Main Wheel Wells and Wing Rear Beam - Detailed Inspection 200202	HRS AFL MOS		190.2 71 6.2	50	24	5340.2 2528 11 May 2022	30 Jun 2024*	31 Jul 2024	0 0
	[End Of Month Item] [MOS: +1m/-1m]									
271012 Airframe	Lateral Control System - Friction Test	HRS AFL MOS MSC		4882.7 2421 149.6		O/C	647.7 178 28 May 2010			0 0
271017 Airframe	Lateral Control System (Power) - Operational Test	HRS AFL MOS MSC		4882.7 2421 149.6		O/C	647.7 178 28 May 2010			0 0
271018 Airframe	Lateral Control System (Manual) - Operational Test	HRS AFL MOS MSC		882.2 304 23.1		O/C	4648.2 2295 14 Dec 2020			0 0
271019 Airframe	Aileron Balancing - Adjustment / Test	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0
271020 Airframe	Upper Surface of Ailerons and Left Trim Tab - General Visual Inspection 052000-4C,200204	HRS AFL MOS		882.2 304 26.5	-2	48	4648.2 2295 02 Sep 2020	31 Aug 2024*	30 Sep 2024	0 0
	[End Of Month Item] [MOS: +1m/-1m]									

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
271021 Airframe	Aileron (Left) - Removal / Installation 1159CS20006-800-47 4123	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0
271022 Airframe	Aileron (Right) - Removal / Installation 1159CS20006-800-44 4123	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0
271030 Airframe	Aileron and Trim Control System - Operational Test	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0
271101 Airframe	Control Column Wheel (Left) - Removal / Installation 1159SCF410-55 0148	HRS AFL MOS MSC		5525.5 2597 171.5		O/C	4.9 2 31 Jul 2008			0 0 ESTERLINE MASON
271102 Airframe	Control Column Wheel (Right) - Removal / Installation 1159SCF410-55 SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0 ESTERLINE MASON
271103 Airframe	Aileron Control - Rigging Check	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0
271105 Airframe	Aileron Actuator Load Relief Bungee Assembly (Left) - Removal / Installation 1159C20014-7 NSN	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0 GULFSTREAM - APPLETON

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
271106 Airframe	Aileron Actuator Load Relief Bungee Assembly (Right) - Removal / Installation 1159C20014-7 NSN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 GULFSTREAM - APPLETON
271107 Airframe	Aileron Actuator Load Relief Bungee Assembly (Left) - Inspection	HRS AFL MOS MSC		439.3 157 12.3		 O/C	5091.1 2442 08 Nov 2021			0 0
271108 Airframe	Aileron Actuator Load Relief Bungee Assembly (Right) - Inspection	HRS AFL MOS MSC		439.3 157 12.3		 O/C	5091.1 2442 08 Nov 2021			0 0
271127 Airframe	Aileron Primary Cable Assembly FS 280 - FS 475 (Right) - Removal / Installation PN SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
271131 Airframe	Aileron Cable Assembly Forward Rbs 109 - Rbs 143 (Left Inboard) - Removal / Installation GAC576FC111-871P4P1 NSN	HRS AFL MOS MSC	 TSN:14	957.2 362 29.1		 O/C	4573.2 2237 12 Jun 2020			0 0
271132 Airframe	Aileron Cable Assembly Forward Rbs 143 - Rbs 279 (Left Outboard) - Removal / Installation GAC576FC052-800P2P3 NSN	HRS AFL MOS MSC	 TSN:1	957.2 362 29.1		 O/C	4573.2 2237 12 Jun 2020			0 0
271133 Airframe	Aileron Cable Assembly Aft Rbs 109 - Rbs 200 (Left Inboard) - Removal / Installation GAC576FC081-332P3P2 NSN	HRS AFL MOS MSC	 TSN:24	957.2 362 29.1		 O/C	4573.2 2237 12 Jun 2020			0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
271134	Aileron Cable Assembly Aft Rbs 200 - Rbs 279 (Left Outboard) - Removal / Installation GAC576FC078-263P2P4 NSN	HRS AFL MOS MSC	TSN:3	957.2 362 29.1		O/C	4573.2 2237 12 Jun 2020			0 0
Airframe										
271135	Aileron Cable Assembly Forward Rbs 109 - Rbs 143 (Right Inboard) - Removal / Installation GAC576FC111-871P4P1 NSN	HRS AFL MOS MSC		957.2 362 29.1		O/C	4573.2 2237 12 Jun 2020			0 0
Airframe										
271136	Aileron Cable Assembly Forward Rbs 143 - Rbs 279 (Right Outboard) - Removal / Installation GAC576FC052-800P2P3 NSN	HRS AFL MOS MSC		957.2 362 29.1		O/C	4573.2 2237 12 Jun 2020			0 0
Airframe										
271137	Aileron Cable Assembly Aft Rbs 109 - Rbs 200 (Right Inboard) - Removal / Installation GAC576FC081-332P3P2 NSN	HRS AFL MOS MSC		957.2 362 29.1		O/C	4573.2 2237 12 Jun 2020			0 0
Airframe										
271138	Aileron Cable Assembly Aft Rbs 200 - Rbs 279 (Right Outboard) - Removal / Installation GAC576FC078-263P2P4 NSN	HRS AFL MOS MSC		957.2 362 29.1		O/C	4573.2 2237 12 Jun 2020			0 0
Airframe										
271204	Aileron Trim System - Rigging	HRS AFL MOS MSC		882.2 304 23.4		O/C	4648.2 2295 04 Dec 2020			0 0
Airframe										
271219	Aileron Force Sensor (Left) - Removal / Installation 1159SCC473-7 TY-00889	HRS AFL MOS MSC		5525.5 2597 174.4		O/C	4.9 2 05 May 2008			0 0 TYEE AIRCRAFT INC
Airframe										

Notes: N/A BY P/N

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
271222 Airframe	Aileron Force Sensor (Right) - Removal / Installation 1159SCC473-7 TY-00890	HRS AFL MOS MSC		5525.5 2597 174.4		 O/C	4.9 2 05 May 2008			0 0 TYEE AIRCRAFT INC
Notes: N/A BY P/N										
271301 Airframe	Aileron Force Link Assembly (Left) - Removal / Installation 1159C50258-9 SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 LEONARD'S METAL INC.
271302 Airframe	Aileron Force Link Assembly (Right) - Removal / Installation 1159C50258-10 SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 VOUGHT AIRCRAFT INDUSTRIES INC.
271303 Airframe	Aileron Hardover Prevention System - Operational Check 052000-2A,200102	HRS AFL MOS [HRS: +50/-50]	6.5 2 .2		49.3	1000	5523.9 2597 11 Nov 2022	6573.2*	6623.2	0 0
271309 Airframe	Aileron Actuator (Left) - Removal / Installation 1159H47230-5 5536	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 PARKER HANNIFIN CORPORATION
Notes: VERIFIED BY Q301450										
271310 Airframe	Aileron Actuator (Right) - Removal / Installation 1159H47230-7 5535	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 CRESTVIEW AEROSPACE CORPORATION
Notes: VERIFIED BY Q301450										

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
271401	Aileron Position Transducer (Left) - Removal / Installation		HRS		5530.4			0			0
	3A1316A	A2338	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			IPECO INC
			MSC				O/C				
Airframe											
271402	Aileron Position Transducer (Right) - Removal / Installation		HRS		5530.4			0			0
	3A1316A	A2340	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			IPECO INC
			MSC				O/C				
Airframe											
271404	Sensor, R Cont Wheel Pos Rvdt		HRS		5525.5			4.9			0
	1159SCF452-5	A1547	AFL		2597			2			0
			MOS		174.3			07 May 2008			
			MSC				O/C				
Airframe											
271410	Sensor, Aileron Trim - FDR		HRS		5525.5			4.9			0
	1159SCF452-5	A1472	AFL		2597			2			0
			MOS		174.3			08 May 2008			
			MSC				O/C				
Airframe											
272001	Rudder - Removal / Installation		HRS	TSN:3163.4	2367			3163.4			0
	1159CS52204-803	GB2660	AFL	TSN:1645	954			1645			0
			MOS	TSN:102	72.8			22 Oct 2016			
			MSC				O/C				
Airframe											
Notes: TW #558150 CAL 1/17TW #558097 CAL 11/16											
272002	Rudder Power Actuator - Removal / Installation		HRS		5530.4			0			0
	1159SCH428-7	0141	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			PARKER HANNIFIN CORPORATION
			MSC				O/C				
Airframe											
Notes: VERIFIED BY PQ211											
272003	Rudder Trim Actuator - Removal / Installation		HRS		5530.4			0			0
	159SCC100-23	1373	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			GOODRICH SENSOR SYSTEMS
			MSC				O/C				
Airframe											

ATA / U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
272005	Rudder Torque Tube - Removal / Installation 1159B221605-27 NSN	HRS AFL MOS MSC	TSN:3163.4 TSN:1645 TSN:102	2367 954 73.1		 O/C	3163.4 1645 14 Oct 2016			0 0
Airframe										
Notes: TORQUE WRENCH # 558136 CAL DUE 8/17.										
272006	Rudder Deactivation Valve (Left) - Removal / Installation 1159SCH501-17 EFS3047	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 EFS AEROSPACE, INC
Airframe										
Notes: Q306918										
272007	Rudder Deactivation Valve (Right) - Removal / Installation 1159SCH501-17 EFS3054	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 EFS AEROSPACE, INC
Airframe										
Notes: Q306918										
272012	Rudder Torque Tube - Detailed Inspection	HRS AFL MOS		2367 954 73.1	 -44	 96	3163.4 1645 14 Oct 2016	 31 Aug 2024*	 30 Sep 2024	0 0
Airframe	052000-8C	[End Of Month Item] [MOS: +1m/-1m]								
Notes: TORQUE WRENCH # 558136 CAL DUE 08/17.										
272013	Rudder System - Functional Test	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										
272014	Rudder Hardover Prevention System - Operational Check	HRS AFL MOS		6.5 2 .2	49.3	1000	5523.9 2597 11 Nov 2022	6573.2*	6623.2	0 0
Airframe	052000-2A,200102	[HRS: +50/-50]								
272033	Rudder Control System - Operational Test	HRS AFL MOS MSC		957.2 362 29.1		 O/C	4573.2 2237 12 Jun 2020			0 0
Airframe										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
272103	Rudder Cable Assembly FS 470 - FS 760 (Inboard) - Removal / Installation GAC576FC305-632P3P4 NSN	HRS AFL MOS MSC	TSN:12	957.2 362 29.1		O/C	4573.2 2237 12 Jun 2020			0 0
Airframe										
272104	Rudder Cable Assembly FS 470 - FS 760 (Outboard) - Removal / Installation GAC576FC242-119P4P3 NSN	HRS AFL MOS MSC	TSN:7	957.2 362 29.1		O/C	4573.2 2237 12 Jun 2020			0 0
Airframe										
272107	Rudder Control and Trim Cables In Pressurized Areas of Fuselage and Overwing to Aft Wing Links - Detailed Inspection	HRS AFL MOS		2367 954 72.9	-50	96	3163.4 1645 20 Oct 2016	31 Aug 2024*	30 Sep 2024	0 0
	[End Of Month Item] [MOS: +1m/-1m]									
Airframe	052000-8C									
Notes: TENSIOMETER: 66852 DATE DUE: 02/17										
272108	Rudder Control and Trim Cables In Main Wheel Well and Tail Compartment - Detailed Inspection	HRS AFL MOS		190.2 71 6.2	51	24	5340.2 2528 10 May 2022	30 Jun 2024*	31 Jul 2024	0 0
	[End Of Month Item] [MOS: +1m/-1m]									
Airframe	200202									
272113	Rudder and Trim Control System - Operational Test	HRS AFL MOS MSC		2367 954 72.4		O/C	3163.4 1645 05 Nov 2016			0 0
Airframe										
272202	Rudder Trim Feel Bungee - Removal / Installation 1159C20350-23 FAH0623	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0 FRISBY AEROSPACE LLC.
Airframe										
Notes: VERFIED BY PQ211										
272203	Rudder Trim Control System-Fc	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0
Airframe										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
272204	Rudder Trim System - Rigging	HRS		5530.4			0			0
		AFL		2599			0			0
		MOS		174.6			28 Apr 2008			
Airframe		MSC				O/C				
272303	Standby Rudder System--OPS Ck	HRS		5530.4			0			0
		AFL		2599			0			0
		MOS		174.6			28 Apr 2008			
Airframe		MSC				O/C				
272401	Rudder Position Transducer - Removal / Installation 3A1316A A2370	HRS		5530.4			0			0
		AFL		2599			0			0
		MOS		174.6			28 Apr 2008			
Airframe		MSC				O/C				
Notes: VERFIED BY PQ211										
272402	Potentiometer, Rudder NWS 1159SCL500-17 1500	HRS		5530.4			0			0
		AFL		2599			0			0
		MOS		174.6			28 Apr 2008			EATON AEROSPACE
Airframe		MSC				O/C				
Notes: VERF PQ162										
272420	Rudder Force Sensor - Removal / Installation 1159SCC473-9 TY-1249	HRS		5525.5			4.9			0
		AFL		2597			2			0
		MOS		174.4			05 May 2008			JAMAICA BEARINGS CO. INC.
Airframe		MSC				O/C				
Notes: N/A BY P/N										
272701	Sensor, Rudder Control - FDR 1159SCF452-5 SN-UNKNOWN	HRS		5530.4			0			0
		AFL		2599			0			0
		MOS		174.6			28 Apr 2008			
Airframe		MSC				O/C				
273001	Elevator (Left) - Removal / Installation 1159CS20002-59 4123	HRS	TSN:4648.2	882.2			4648.2			0
		AFL	TSN:2295	304			2295			0
		MOS	TSN:151	23.7			25 Nov 2020			
Airframe		MSC				O/C				

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
273002 Airframe	Elevator (Right) - Removal / Installation 1159CS20002-60 4123	HRS AFL MOS MSC	TSN:4648.2 TSN:2295 TSN:152	882.2 304 23.4		O/C	4648.2 2295 05 Dec 2020			0 0
273003 Airframe	Elevator Free Play - Inspection	HRS AFL MOS MSC		882.2 304 26.5		O/C	4648.2 2295 02 Sep 2020			0 0
273005 Airframe	Elevator Control System - Operational Test	HRS AFL MOS MSC		882.2 304 23.3		O/C	4648.2 2295 08 Dec 2020			0 0
273006 Airframe	Elevator Control System - Rigging Check	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0
273007 Airframe	Elevator Actuator Load Relief Bungee Assembly - Removal / Installation 1159C20014-7 NSN	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0
273009 Airframe	Elevator Control System - Rigging Check	HRS AFL MOS MSC		882.2 304 23.3		O/C	4648.2 2295 08 Dec 2020			0 0
273023 Airframe	Elevator Trim Tab (Left) - Removal / Installation 1159CSH20500-39 4117	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0

Notes: VER BY PQ627

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
273024 Airframe	Elevator Trim Tab (Right) - Removal / Installation 1159CSH20500-40 4112	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0
Notes: VERIFIED BY PQ627										
273025 Airframe	Elevator Trim Tab Actuator (Left) - Removal / Installation 159SCC100-25 208	HRS AFL MOS MSC		882.2 304 23.4		O/C	4648.2 2295 05 Dec 2020			0 0
Notes: PQ600										
273026 Airframe	Elevator Trim Tab Actuator (Right) - Removal / Installation 159SCC100-25 01922	HRS AFL MOS MSC	TSN:4648.2 TSN:2295 TSN:152	882.2 304 23.4		O/C	4648.2 2295 05 Dec 2020			0 0
Notes: PQ600										
273099 Airframe	Elevator Control and Trim Cables In Pressurized Areas of the Fuselage and Overwing to Aft Wing Links - Detailed Inspection 052000-8C	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		2367 954 73	-47	96	3163.4 1645 17 Oct 2016	31 Aug 2024*	30 Sep 2024	0 0
Notes: TENSIOMETER: 57480 DATE DUE: 11/16										
273100 Airframe	Elevator Control and Trim Cables In Main Wheel Wells and Tail Compartment - Detailed Inspection 200202	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		190.2 71 6.2	51	24	5340.2 2528 10 May 2022	30 Jun 2024*	31 Jul 2024	0 0
273102 Airframe	Elevator Cable Assembly (Inboard) FS 467.50 - FS 741.80 - Removal / Installation GAC576FC298-215P3P4 NSN	HRS AFL MOS MSC		957.2 362 29.1		O/C	4573.2 2237 12 Jun 2020			0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
273104	Elevator Cable Assembly (Upper Outboard) FS 126.00 - FS 482.00 - Removal / Installation	HRS		5530.4			0			0
		AFL		2599			0			0
	PN SN-UNKNOWN	MOS		174.6			28 Apr 2008			
		MSC				O/C				
Airframe										
273105	Elevator Cable Assembly (Outboard) FS 482.00 - FS 725.34 - Removal / Installation	HRS		957.2			4573.2			0
		AFL		362			2237			0
	GAC576FC269-184P4P3 NSN	MOS	TSN:7	29.1			12 Jun 2020			
		MSC				O/C				
Airframe										
273109	Eddy Current Damper (Left) - Removal / Installation	HRS		5530.4			0			0
		AFL		2599			0			0
	1159SCC202-1 A1031	MOS		174.6			28 Apr 2008			MOOG INCORPORATED
		MSC				O/C				
Airframe										
Notes: VERF PQ162										
273115	Valve, Elevator Fwd Deactivate	HRS		5530.4			0			0
		AFL		2599			0			0
	1159SCH501-17 EFS3048	MOS		174.6			28 Apr 2008			EFS AEROSPACE, INC
		MSC				O/C				
Airframe										
Notes: Q306918										
273116	Valve, Elevator Aft Deactivate	HRS		5530.4			0			0
		AFL		2599			0			0
	1159SCH501-17 EFS3058	MOS		174.6			28 Apr 2008			EFS AEROSPACE, INC
		MSC				O/C				
Airframe										
Notes: Q306918										
273125	Elevator Hardover Protection System Switches-Adjustment / Test	HRS		5530.4			0			0
		AFL		2599			0			0
		MOS		174.6			28 Apr 2008			
		MSC				O/C				
Airframe										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
Logbook Position	Part Number	Serial Number									
	HW	SW									
	MM Ref										
	Ops Number(s)										
273203	Control Column Shaker (Pilot) - Removal / Installation		HRS		5530.4			0			0
	C36602	7346	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			SAFE FLIGHT INSTRUMENT CORPORATION
Airframe			MSC				O/C				
Notes: VERF PQ164											
273204	Control Column Shaker (Copilot) - Removal / Installation		HRS		5530.4			0			0
	C-36602	7345	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			ASC INTERNATIONAL INC
Airframe			MSC				O/C				
273206	Stall Barrier Actuator - Removal / Installation		HRS		5530.4			0			0
	1159SCH503-55	0524	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			EATON AEROSPACE
Airframe			MSC				O/C				
Notes: VERIFIED BY PQ103											
273210	Stall Barrier - Functional Test		HRS		190.2			5340.2			0
			AFL		71			2528			0
			MOS		6		24	15 May 2022	31 May 2024	30 Jun 2024	
Airframe	200202		[End Of Month Item] [MOS: +1m/-1m]								
273215	Elevator Hardover Protection System - Operational Check		HRS		6.5	49.3	1000	5523.9	6573.2*	6623.2	0
			AFL		2			2597			0
			MOS		.2			11 Nov 2022			
Airframe	052000-2A,200102		[HRS: +50/-50]								
273217	Elevator Trim Tab Control System - Functional Test		HRS		882.2			4648.2			0
			AFL		304			2295			0
			MOS		23.3			08 Dec 2020			
Airframe			MSC				O/C				
273218	Elevator Manual Control System - Operational Check		HRS		190.2			5340.2			0
			AFL		71			2528			0
			MOS		6.1	47	24	14 May 2022	30 Jun 2024*	31 Jul 2024	
Airframe	200202		[End Of Month Item] [MOS: +1m/-1m]								

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
273302	Elevator Trim Wheel Dial (Right) - Removal / Installation 43083-406-6 060135	HRS AFL MOS MSC		5525.5 2597 172.2		 O/C	4.9 2 09 Jul 2008			0 0
Airframe										
273321	Elevator Trim (Rvdt) - Adjustment/Test	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										
273401	Elevator Actuator - Removal / Installation 1159SCH452-7 5545	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 KAISER FLUID TECHNOLOGIES
Airframe										
Notes: VERIFIED BY PQ211										
273503	Elevator Trim Tab Rotary Variable Displacement Transducer (Left) - Removal / Installation 3A2266B B0899	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 IPECO INC
Airframe										
Notes: PQ606										
273504	Elevator Trim Tab Rotary Variable Displacement Transducer (Right) - Removal / Installation 3A2266B B1098	HRS AFL MOS MSC		439.3 157 12		 O/C	5091.1 2442 16 Nov 2021			0 0
Airframe										
Notes: PQ606										
273505	Elevator Rotary Variable Differential Transducer (ASC 001) - Adjustment	HRS AFL MOS MSC		5525.5 2597 174.2		 O/C	4.9 2 09 May 2008			0 0
Airframe										
Notes: PN: 1159SCF452-5 SN: H1828. PQ619										
273506	Rvdt, R Elv Cont Column Posit 3A2266A SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 IPECO INC
Airframe										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
273507	Elevator Rotary Variable Differential Transducer - Adjustment	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										
273508	Elevator Position Transducer (Lvdt)-Right 1159SCC614-3 0249	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										
273509	Elevator Position Transducer (Lvdt)-Left 1159SCC614-3 0311	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										
273519	Elevator Force Sensor - Removal / Installation 1159SCC473-1 TY-01016	HRS AFL MOS MSC		5525.5 2597 174.4		 O/C	4.9 2 05 May 2008			0 0 GULFSTREAM SAV PROD-IPT
Airframe										
Notes: N/A BY P/N										
273701	Sensor, Elevator Control - FDR 1159SCF452-5 SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										
274104	Horizontal Stabilizer Back-Up MODE - Operational Check	HRS AFL MOS MSC		5525.5 2597 172.9		 O/C	4.9 2 19 Jun 2008			0 0
Airframe										
274105	Flap Control System - Operational Test	HRS AFL MOS MSC		4157.9 1948 130.2		 O/C	1372.5 651 11 Jan 2012			0 0
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
274106	Emergency Stabilizer Back-Up MODE - Operational Check	HRS		6.5	49.3	1000	5523.9	6573.2*	6623.2	0
		AFL		2			2597			0
		MOS		.2		48	11 Nov 2022	30 Nov 2026	31 Dec 2026	
	[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]									
Airframe	052000-2A,200102									
274107	Horizontal Stabilizer Electric Motor Unit - Removal / Installation	HRS	TSN:2889.9	2640.5			2889.9			0
		AFL	TSN:1505	1094			1505			0
	1159SCC610-13 0144	MOS		89.9			18 May 2015			
		MSC				O/C				
Airframe										
274108	Horizontal Stabilizer Electric Motor Control Unit - Removal / Installation	HRS		5530.4			0			0
		AFL		2599			0			0
	1159SCC611-1 136	MOS		174.6			28 Apr 2008			
		MSC				O/C				
Airframe										
274109	Horizontal Stabilizer Electric Motor Unit - Discard	HRS	TSN:2889.9	2640.5		24000	2889.9	24000		0
	1159SCC610-13 0144	AFL	TSN:1505	1094			1505			0
		MOS		89.9			18 May 2015			
Airframe										
274201	Horizontal Stabilizer Actuator - Removal / Installation	HRS		5530.4			0			0
	1159SCC200-45 1618	AFL		2599			0			0
		MOS		174.6			28 Apr 2008			GOODRICH
		MSC				O/C				SENSOR
Airframe										SYSTEMS
Notes: PQ093										
274203	Horizontal Stabilizer Control System - Rigging / Adjustment	HRS		5530.4			0			0
		AFL		2599			0			0
		MOS		174.6			28 Apr 2008			
		MSC				O/C				
Airframe										
275001	Flap (Left) - Removal / Installation	HRS	TSN:4648.2	882.2			4648.2			0
	1159CS20005-59 4123	AFL	TSN:2295	304			2295			0
		MOS	TSN:151	23.7			25 Nov 2020			
		MSC				O/C				
Airframe										
Notes: Q305969										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
275002	Flap (Right) - Removal / Installation 1159CS20005-60 4123	HRS AFL MOS MSC	TSN:4648.2 TSN:2295 TSN:151	882.2 304 23.7		 O/C	4648.2 2295 25 Nov 2020			0 0
Airframe										
Notes: Q305969										
275003	Flap System - Operational Test	HRS AFL MOS MSC		882.2 304 23.7		 O/C	4648.2 2295 25 Nov 2020			0 0
Airframe										
275004	Emerg Flap System - OPS Test	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										
275005	Flap - Rigging	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										
275006	Alternate Flap System - Operational Test	HRS AFL MOS MSC		5525.5 2597 172.9		 O/C	4.9 2 19 Jun 2008			0 0
Airframe										
275009	Flap / Stabilizer - Autorig	HRS AFL MOS MSC		2640.5 1094 89.6		 O/C	2889.9 1505 28 May 2015			0 0
Airframe										
275015	Inboard Flap Actuator (Left) - Removal / Installation 1159SCC615-5 0326	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 MOOG INCORPORATED
Airframe										
Notes: VERIFIED BY PQ154										

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
Logbook Position	HW	SW									
	MM Ref										
	Ops Number(s)										
275016	Inboard Flap Actuator (Right) - Removal / Installation		HRS		5530.4			0			0
	1159SCC615-5	0328	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			MOOG
			MSC				O/C				INCORPORATED
Airframe											
Notes: VERIFIED BY PQ154											
275017	Outboard Flap Actuator (Left) - Removal / Installation		HRS		5530.4			0			0
	1159SCC616-7	0141	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			MOOG
			MSC				O/C				INCORPORATED
Airframe											
Notes: VERIFIED BY PQ154											
275018	Outboard Flap Actuator (Right) - Removal / Installation		HRS		5530.4			0			0
	1159SCC616-8	0133	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			MOOG
			MSC				O/C				INCORPORATED
Airframe											
Notes: VERIFIED BY PQ154											
275021	Wing Flap Roller (Left Inboard A Track A-1) - Removal / Installation		HRS		5530.4			0			0
			AFL		2599			0			0
	PN	SN-UNKNOWN	MOS		174.6			28 Apr 2008			
			MSC				O/C				
Airframe											
275022	Wing Flap Roller (Right Inboard A Track A-1) - Removal / Installation		HRS		5530.4			0			0
			AFL		2599			0			0
	PN	SN-UNKNOWN	MOS		174.6			28 Apr 2008			
			MSC				O/C				
Airframe											
275023	Wing Flap Roller (Left Outboard A Track A-2) - Removal / Installation		HRS		5530.4			0			0
			AFL		2599			0			0
	PN	SN-UNKNOWN	MOS		174.6			28 Apr 2008			
			MSC				O/C				
Airframe											

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
275024	Wing Flap Roller (Right Outboard A Track A-2) - Removal / Installation		HRS		5530.4			0			0
			AFL		2599			0			0
	PN	SN-UNKNOWN	MOS		174.6			28 Apr 2008			
			MSC				O/C				
Airframe											
275059	Wing Flap Roller (Left Inboard D Track D-20) - Removal / Installation		HRS		5530.4			0			0
			AFL		2599			0			0
	PN	SN-UNKNOWN	MOS		174.6			28 Apr 2008			
			MSC				O/C				
Airframe											
275060	Wing Flap Roller (Right Inboard D Track D-20) - Removal / Installation		HRS		5530.4			0			0
			AFL		2599			0			0
	PN	SN-UNKNOWN	MOS		174.6			28 Apr 2008			
			MSC				O/C				
Airframe											
275061	Wing Flap Roller (Left Outboard D Track D-21) - Removal / Installation		HRS		5530.4			0			0
			AFL		2599			0			0
	PN	SN-UNKNOWN	MOS		174.6			28 Apr 2008			
			MSC				O/C				
Airframe											
275062	Wing Flap Roller (Right Outboard D Track D-21) - Removal / Installation		HRS		5530.4			0			0
			AFL		2599			0			0
	PN	SN-UNKNOWN	MOS		174.6			28 Apr 2008			
			MSC				O/C				
Airframe											
275103	Switch, Flap Follow-Up		HRS		5530.4			0			0
	D508-7	A1834	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			PIC WIRE &
			MSC				O/C				CABLE SUPPLY
Airframe											INC

Notes: VERIFIED BY PQ618

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
275104 Airframe	Flap and Stabilizer Electronic Control Unit - Removal / Installation 1159SCC612-17 276	HRS AFL MOS MSC		2640.5 1094 89.6		 O/C	2889.9 1505 28 May 2015			0 0
275108 Airframe	Flap Control Handle - Removal / Installation 4260-0045-1 SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 MPC PRODUCTS
275120 Airframe	Module, Flap Hydraulic Control 1159SCH600-1 095	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 HYDRA CORP. - USA
275201 Airframe	Flap Hydraulic Drive Motor - Removal / Installation 1159SCH212-1 MX710777B	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 HYDRA-ELECTRIC COMPANY
Notes: VERIFIED BY PQ618										
275301 Airframe	Flap Drive Gearbox - Removal / Installation 1159SCC210-3 0139	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 MOOG INCORPORATED
Notes: VERIFIED BY PQ618										
275305 Airframe	Flap Torque Shaft (Left No. 1, Rbs 5 - Rbs 37) - Removal / Installation PN SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
275306 Airframe	Flap Torque Shaft (Right No. 1, Rbs 5 - Rbs 37) - Removal / Installation PN SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
275307 Airframe	Flap Torque Shaft (Left No. 2, Rbs 38 - Rbs 65) - Removal / Installation 1159SCC213-3 SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 MOOG INCORPORATED
275308 Airframe	Flap Torque Shaft (Right No. 2, Rbs 38 - Rbs 65) - Removal / Installation 1159SCC213-3 SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 MOOG INCORPORATED
275309 Airframe	Flap Torque Shaft (Left No. 3, Rbs 66 - Rbs 89) - Removal / Installation 1159SCC213-5 SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 MOOG INCORPORATED
275310 Airframe	Flap Torque Shaft (Right No. 3, Rbs 66 - Rbs 89) - Removal / Installation 1159SCC213-5 SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 MOOG INCORPORATED
275311 Airframe	Flap Torque Shaft (Left No. 4, Rbs 90 - Rbs 122) - Removal / Installation 1159SCC213-61 SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 MOOG INCORPORATED
275312 Airframe	Flap Torque Shaft (Right No. 4, Rbs 90 - Rbs 122) - Removal / Installation 1159SCC213-61 SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 MOOG INCORPORATED

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
275313 Logbook Position	Flap Torque Shaft (Left No. 5, Rbs 123 - Rbs 151) - Removal / Installation 1159SCC213-63 SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 MOOG INCORPORATED
Airframe										
275314	Flap Torque Shaft (Right No. 5, Rbs 123 - Rbs 151) - Removal / Installation 1159SCC213-63 SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 MOOG INCORPORATED
Airframe										
275315	Flap Torque Shaft (Left No. 6, Rbs 155 - Rbs 180) - Removal / Installation 1159SCC213-9 SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 MOOG INCORPORATED
Airframe										
275316	Flap Torque Shaft (Right No. 6, Rbs 155 - Rbs 180) - Removal / Installation 1159SCC213-11 SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 MOOG INCORPORATED
Airframe										
275317	Flap Torque Shaft (Left No. 7, Rbs 184 - Rbs 216) - Removal / Installation 1159SCC213-13 SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 MOOG INCORPORATED
Airframe										
275318	Flap Torque Shaft (Right No. 7, Rbs 184 - Rbs 216) - Removal / Installation 1159SCC213-15 SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 MOOG INCORPORATED
Airframe										
275319	Flap Torque Shaft (Left No. 8, Rbs 217 - Rbs 253) - Removal / Installation 1159SCC213-17 SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 MOOG INCORPORATED
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
275320 Airframe	Flap Torque Shaft (Right No. 8, Rbs 217 - Rbs 253) - Removal / Installation 1159SCC213-17 SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 MOOG INCORPORATED
276001 Airframe Notes: Q305969	Ground Spoiler (Left) - Removal / Installation 1159CS40700-9 M653900	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 HUREL-HISPANO U.K. LTD.
276002 Airframe Notes: Q305969	Ground Spoiler (Right) - Removal / Installation 1159CS40700-10 M646070	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 HUREL-HISPANO U.K. LTD.
276003 Airframe Notes: Q305969	Inboard Flight Spoiler (Left) - Removal / Installation 1159CS40701-9 M653890	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 HUREL-HISPANO U.K. LTD.
276004 Airframe Notes: Q305969	Outboard Flight Spoiler (Left) - Removal / Installation 1159CS40702-9 M665640	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 VERSAFORM CORPORATION
276005 Airframe Notes: Q305969	Inboard Flight Spoiler (Right) - Removal / Installation 1159CS40701-10 M665630	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 HUREL-HISPANO U.K. LTD.

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
276006	Outboard Flight Spoiler (Right) - Removal / Installation 1159CS40702-10 M686260	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 HUREL-HISPANO U.K. LTD.
Airframe										
Notes: Q305969										
276007	Ground Spoiler Actuator (Left) - Removal / Installation 1159SCH305-23 2567	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 PARKER HANNIFIN CORPORATION
Airframe										
Notes: VERIFIED BY Q301450										
276008	Ground Spoiler Actuator (Right) - Removal / Installation 1159SCH305-24 2569	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 GULFSTREAM BRN SPARES IPT
Airframe										
Notes: VERIFIED BY Q301450										
276009	Flight Spoiler Actuator (Left) - Removal / Installation 1159SCH250-29 3310	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 PARKER HANNIFIN CORPORATION
Airframe										
Notes: VERIFIED BY Q301450										
276010	Flight Spoiler Actuator (Right) - Removal / Installation 1159SCH250-30 3306	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 PARKER HANNIFIN CORPORATION
Airframe										
Notes: VERIFIED BY Q301450										

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
276015	Selector Hydraulic, Spoiler (Left)		HRS		5530.4			0			0
	1159SCH501-15	SN-UNKNOWN	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			EFS AEROSPACE, INC
Airframe			MSC				O/C				
276016	Selector Hydraulic, Spoiler (Right)		HRS		5530.4			0			0
	1159SCH501-15	SN-UNKNOWN	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			EFS AEROSPACE, INC
Airframe			MSC				O/C				
276017	Switch, Ground Spoiler Pressure		HRS		5530.4			0			0
	1159SCH213-5	6757	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			GULFSTREAM BRN SPARES IPT
Airframe			MSC				O/C				
276104	Speed Brake Cable Assemblies In Fuselage and Overwing AREA to Aft Links - Detailed Inspection		HRS		2367			3163.4			0
			AFL		954			1645			0
			MOS		72.9	-50	96	20 Oct 2016	31 Aug 2024*	30 Sep 2024	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-8C										
Notes: TENSIOMETER: 66852 DATE DUE: 02/17											
276105	Speed Brake Cables In Main Wheel Well / Wing Rear Beam - Detailed Inspection		HRS		190.2			5340.2			0
			AFL		71			2528			0
			MOS		6.2	50	24	11 May 2022	30 Jun 2024*	31 Jul 2024	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe	200202										
276108	Speed Brake Handle Assembly - Removal / Installation		HRS		5525.5			4.9			0
	4111-0048-1	064479	AFL		2597			2			0
			MOS		172.3			07 Jul 2008			
Airframe			MSC				O/C				
276109	Speed Brake - Operational Test		HRS		882.2			4648.2			0
			AFL		304			2295			0
			MOS		23.1			14 Dec 2020			
Airframe			MSC				O/C				

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
276110 Airframe	Speed Brake Handle - Rigging	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
276201 Airframe	Ground Spoiler Auto Deploy (Rto Operation) - Operational Check	HRS AFL MOS MSC		957.2 362 29.1		 O/C	4573.2 2237 12 Jun 2020			0 0
276203 Airframe	Ground Spoiler System - Operational Test	HRS AFL MOS MSC		957.2 362 29.1		 O/C	4573.2 2237 12 Jun 2020			0 0
276213 Airframe	Ground Spoiler - Rigging	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
276218 Airframe	Ground Spoiler System - Rigging Check	HRS AFL MOS MSC		882.2 304 23.1		 O/C	4648.2 2295 14 Dec 2020			0 0
276301 Airframe	Inboard Flight Spoiler Bellcrank Assembly (Left) - Removal / Installation 1159CM20208-17 N/A	HRS AFL MOS MSC		4882.7 2421 149.6		 O/C	647.7 178 28 May 2010			0 0
276302 Airframe	Inboard Flight Spoiler Bellcrank Assembly (Right) - Removal / Installation 1159CM20208-18 N/A	HRS AFL MOS MSC		4882.7 2421 149.6		 O/C	647.7 178 28 May 2010			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
276303 Airframe	Outboard Flight Spoiler Bellcrank Assembly (Left) - Removal / Installation 1159CM20209-21 N/A	HRS AFL MOS MSC		4882.7 2421 149.6		 O/C	647.7 178 28 May 2010			0 0
276304 Airframe	Outboard Flight Spoiler Bellcrank Assembly (Right) - Removal / Installation 1159CM20209-22 N/A	HRS AFL MOS MSC		4882.7 2421 149.6		 O/C	647.7 178 28 May 2010			0 0
276401 Airframe	Ground Spoiler Primary Solenoid Valve - Removal / Installation 1159SCH257-9 2563	HRS AFL MOS MSC		957.2 362 29.1		 O/C	4573.2 2237 12 Jun 2020			0 0
276402 Airframe	Ground Spoiler Secondary Solenoid Valve - Removal / Installation 1159SCH257-9 4111	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 PARKER HANNIFIN CORPORATION
276500 Airframe	Spoiler Position Transducer - Adjustment	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
276505 Airframe	Ground Spoiler Position Transducer (Left) - Removal / Installation 3A1316A A2326	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 IPECO INC
276506 Airframe	Ground Spoiler Position Transducer (Right) - Removal / Installation 3A1316A A2334	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 IPECO INC

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
276507	Flight Spoiler Position Transducer (Left) - Removal / Installation 3A1316A A2368	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 IPECO INC
Airframe										
276508	Flight Spoiler Position Transducer (Right) - Removal / Installation 3A1316A A2368	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 IPECO INC
Airframe										
276513	Ground Spoiler Indication Switch (Left) - Adjustment	HRS AFL MOS MSC		882.2 304 23.1		 O/C	4648.2 2295 14 Dec 2020			0 0
Airframe										
276514	Ground Spoiler Indication Switch (Right) - Adjustment	HRS AFL MOS MSC		882.2 304 23.1		 O/C	4648.2 2295 14 Dec 2020			0 0
Airframe										
277002	Gust Lock System - Functional Test	HRS AFL MOS		882.2 304 23.3		1000 	4648.2 2295 08 Dec 2020	5648.2	5698.2	0 0
Airframe	200102	[HRS: +50/-50]								
28 - Fuel										
280001	Fuel System-- Inspection/Check	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										
280002	Complete Fuel System Bleed Procedure - Adjustment Test	HRS AFL MOS MSC		2367 954 72.3		 O/C	3163.4 1645 08 Nov 2016			0 0
Airframe										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
280003	Fuel Tank Vapor Hazard - Reduction	HRS		2367			3163.4			0
		AFL		954			1645			0
		MOS		72.9			18 Oct 2016			
		MSC				O/C				
Airframe										
280004	Fuel System - Engine Bleed	HRS		1691.5			3838.9			0
		AFL		668			1931			0
		MOS		51.8			23 Jul 2018			
		MSC				O/C				
Airframe										
280005	Fuel System - Upstream (Tank) Side Bleed	HRS		5530.4			0			0
		AFL		2599			0			0
		MOS		174.6			28 Apr 2008			
		MSC				O/C				
Airframe										
280006	APU Fuel System - Bleeding	HRS		882.2			4648.2			0
		AFL		304			2295			0
		MOS		23.3			07 Dec 2020			
		MSC				O/C				
Airframe										
280008	Microbiological Contamination Test of Fuel Tank - Special Detailed Inspection	HRS		957.2			4573.2			0
		AFL		362			2237			0
		MOS		29.1	-114	4	12 Jun 2020	31 Dec 2020*	31 Jan 2021	
		[MOS: +1m/-1m]								
Airframe	200194									
280010	Defueling Procedures - Servicing	HRS		68.4			5462			0
		AFL		24			2575			0
		MOS		2.2			09 Sep 2022			
		MSC				O/C				
Airframe										
281001	Fuel Tank (Left) - Leak Check	HRS		882.2			4648.2			0
		AFL		304			2295			0
		MOS		23.8			23 Nov 2020			
		MSC				O/C				
Airframe										

Notes: PRESSURE GAUGE: 562071CAL DUE: 11/16

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
281002 Airframe	Fuel Tank (Right) - Leak Check	HRS AFL MOS MSC		882.2 304 23.8		 O/C	4648.2 2295 23 Nov 2020			0 0
Notes: PRESSURE GAGE #562071CAL DATE 5/3/16CAL DUE 11/16										
281401 Airframe	Gravity Water / Fuel Drain Valve - Operational Test	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
281405 Airframe	Allen Type Gravity Water / Fuel Drain Valves (Left) - Removal / Installation 775C-80NW 4438	HRS AFL MOS MSC		3804 1763 123		 O/C	1726.4 836 16 Aug 2012			0 0 AUTO VALVE INC
Notes: Q302557										
281406 Airframe	Allen Type Gravity Water / Fuel Drain Valves (Right) - Removal / Installation 775C-80NW 3808	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 AUTO VALVE INC
Notes: Q302557										
281409 Airframe	Flapper Check Valve (Left) - Inspection	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
281505 Airframe	Vent Float / Non-Reliefing Valve (AIR Passage) {Left Forward} - Removal / Installation 1159SCP003-3 3301	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 VOUGHT AIRCRAFT INDUSTRIES INC.

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
281506 Logbook Position	Vent Float / Non-Reliefing Valve (AIR Passage) {Right Forward} - Removal / Installation 1159SCP003-3 3309	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 VOUGHT AIRCRAFT INDUSTRIES INC.
Airframe										
281507 Logbook Position	Vent Float / Non-Reliefing Valve (AIR Passage) {Left Aft} - Removal / Installation 1159SCP004 2580	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 SHAW AERO DEVICES
Airframe										
281508 Logbook Position	Vent Float / Non-Reliefing Valve (AIR Passage) {Right Aft} - Removal / Installation 1159SCP004 2610	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 SHAW AERO DEVICES
Airframe										
281509 Logbook Position	L Fwd Vent Float / Non-Reliefing Valve (Vent Duct) - Removal / Installation 1159SCP006-1 3329	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 AAR COMPOSITES
Airframe										
Notes: PQ093										
281510 Logbook Position	R Fwd Vent Float / Non-Reliefing Valve (Vent Duct) - Removal / Installation 1159SCP006-1 3294	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 AAR COMPOSITES
Airframe										
Notes: PQ093										
281519 Logbook Position	Forward Outboard Vent Float Drain (Vent Duct) Valve (Left) - Removal / Installation 1159SCP007-3 4800	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 GULFSTREAM BRN SPARES IPT
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
281520 Airframe	Forward Outboard Vent Float Drain (Vent Duct) Valve (Right) - Removal / Installation 1159SCP007-3 4786	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 GULFSTREAM BRN SPARES IPT
281521 Airframe	Aft Outboard Vent Float Drain (Vent Duct) Valve (Left) - Removal / Installation 1159SCP007-3 4794	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 GULFSTREAM BRN SPARES IPT
281522 Airframe	Aft Outboard Vent Float Drain (Vent Duct) Valve (Right) - Removal / Installation 1159SCP007-3 4784	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 GULFSTREAM BRN SPARES IPT
282001 Airframe Notes: Q300135	Main Fuel Boost Pump (Left) - Removal / Installation 1159SCP011-7 9911-0655	HRS AFL MOS MSC		5293.5 2527 164.8		 O/C	236.9 72 23 Feb 2009			0 0 CORPORATE SERVICE SUPPLY & MANU INC
282002 Airframe Notes: Q300135	Main Fuel Boost Pump (Right) - Removal / Installation 1159SCP011-7 SN01745	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 CORPORATE SERVICE SUPPLY & MANU INC
282003 Airframe Notes: Q300135	Alternate Fuel Boost Pump (Left) - Removal / Installation 1159SCP011-7 SN01686	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 CORPORATE SERVICE SUPPLY & MANU INC

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
282004 Airframe	Alternate Fuel Boost Pump (Right) - Removal / Installation 1159SCP011-7 SN01746	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 CORPORATE SERVICE SUPPLY & MANU INC
Notes: Q300135										
282005 Airframe	Fuel Boost Pump Electromagnetic Interference Filter (Left) - Removal / Installation 1159SCP011-13 00787	HRS AFL MOS MSC		5293.5 2527 164.8		 O/C	236.9 72 23 Feb 2009			0 0 ONTIC ENGINEERING AND MANUFACTURING INC
282006 Airframe	Fuel Boost Pump Electromagnetic Interference Filter (Right) - Removal / Installation 1159SCP011-13 SN01085	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 ONTIC ENGINEERING AND MANUFACTURING INC
282011 Airframe	Fuel Boost Pump Control Systems - Operational Check	HRS AFL MOS MSC		2643.1 1095 90.5		 O/C	2887.3 1504 30 Apr 2015			0 0
282029 Airframe	Outboard Boost Pump Contactor (Left) - Removal / Installation SM100D23 3874	HRS AFL MOS MSC		2652.9 1097 90.8		 O/C	2877.5 1502 22 Apr 2015			0 0
282103 Airframe	Pressure Fueling - Operational Check	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
282110	Pressure Fueling / Defueling Adapter - Removal / Installation 61255 1205	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 GULFSTREAM SAV PROD-IPT
Airframe										
282112	Engine Suction Fuel Feed (Left) - Operational Test	HRS AFL MOS MSC		1691.5 668 51.7		 O/C	3838.9 1931 24 Jul 2018			0 0
Airframe										
282113	Engine Suction Fuel Feed (Right) - Operational Test	HRS AFL MOS MSC		1691.5 668 51.7		 O/C	3838.9 1931 24 Jul 2018			0 0
Airframe										
282205	Pressure Fueling Shut-Off Valve (Left) - Removal / Installation AV1A1614 AA146813	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 GULFSTREAM SAV PROD-IPT
Airframe										
Notes: Q300135										
282206	Pressure Fueling Shut-Off Valve (Right) - Removal / Installation AV1A1614 AA146814	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 GULFSTREAM SAV PROD-IPT
Airframe										
Notes: Q300135										
282213	High-Level Pilot Valve (Left, Inboard) - Removal / Installation 17-155-301 7649	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 PARKER HANNIFIN CORP-USE S03721 A2 ADDR
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
282214 Airframe	High-Level Pilot Valve (Left, Outboard) - Removal / Installation 17-155-301 7650	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 PARKER HANNIFIN CORP-USE S03721 A2 ADDR
282215 Airframe	High-Level Pilot Valve (Right, Inboard) - Removal / Installation 17-155-301 7758	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 PARKER HANNIFIN CORP-USE S03721 A2 ADDR
282216 Airframe	High-Level Pilot Valve (Right, Outboard) - Removal / Installation 17-155-301 7660	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 PARKER HANNIFIN CORP-USE S03721 A2 ADDR
282219 Airframe	Fuel Tank High-Level Shutoff (Automatic MODE) - Operational Check	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
282220 Airframe	Remote Fueling Shut-Off Control Valve - Operational Check	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
282221 Airframe	Remote Fueling Solenoid Shut-Off Valve (Left) - Removal / Installation 14-155-201 2555	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 PARKER HANNIFIN CORPORATION

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
282222 Airframe	Remote Fueling Solenoid Shut-Off Valve (Right) - Removal / Installation 14-155-201 2590	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0 PARKER HANNIFIN CORPORATION
282223 Airframe Notes: Q300135	Fueling / Defueling Precheck Selector Valve (No. 1) - Removal / Installation 6BS100 2759	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0 ALLEN AIRCRAFT PRODUCTS INC
282224 Airframe Notes: Q300135	Fueling / Defueling Precheck Selector Valve (No. 2) - Removal / Installation 6BS100 2761	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0 ALLEN AIRCRAFT PRODUCTS INC
282402 Airframe Notes: PN: 6999-4 SN: <NONE>.	Fuel Cross-Flow / Intertank System - Operational Check	HRS AFL MOS MSC		231.4 84 7.2		O/C	5299 2515 11 Apr 2022			0 0
282403 Airframe Notes: PQ093	Intertank Shut-Off Valve Motor - Removal / Installation 40565-4 1404A	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0
282406 Airframe Notes: PQ093	Cross-Flow Shut-Off Valve Motor - Removal / Installation 40565-4 884A	HRS AFL MOS MSC		231.4 84 7.2		O/C	5299 2515 11 Apr 2022			0 0

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
282410	Fuel Intertank Valve / Cross-Flow Valve Electromagnetic Interference Filter - Removal / Installation		HRS		5530.4			0			0
			AFL		2599			0			0
	61586-1	1053	MOS		174.6			28 Apr 2008			ARGO-TECH CORPORATION
			MSC				O/C				
Airframe											
282411	Filter, Crossfeed Emi		HRS		5530.4			0			0
			AFL		2599			0			0
	61586-1	1056	MOS		174.6			28 Apr 2008			
			MSC				O/C				
Airframe											
282507	Fuel Boost Pump, Forward Inlet Assembly Screen (Left) - Detailed Inspection		HRS		2367			3163.4			0
			AFL		954			1645			0
			MOS		73.4	-34	96	04 Oct 2016	31 Aug 2024*	30 Sep 2024	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-8C										
282508	Fuel Boost Pump, Forward Inlet Assembly Screen (Right) - Detailed Inspection		HRS		2367			3163.4			0
			AFL		954			1645			0
			MOS		73.4	-35	96	05 Oct 2016	31 Aug 2024*	30 Sep 2024	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-8C										
282509	Fuel Boost Pump, Aft Inlet Assembly Screen (Left) - Detailed Inspection		HRS		2367			3163.4			0
			AFL		954			1645			0
			MOS		73.4	-34	96	04 Oct 2016	31 Aug 2024*	30 Sep 2024	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-8C										
282510	Fuel Boost Pump, Aft Inlet Assembly Screen (Right) - Detailed Inspection		HRS		2367			3163.4			0
			AFL		954			1645			0
			MOS		73.4	-35	96	05 Oct 2016	31 Aug 2024*	30 Sep 2024	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-8C										
282601	Engine Fuel Distribution System (Fuel Flow) - Functional Test		HRS		2640.5			2889.9			0
			AFL		1094			1505			0
			MOS		89.4			04 Jun 2015			
			MSC				O/C				
Airframe											

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
282603	Engine Dual Wall Fuel Feed Line Shroud (Left) - Functional Test	HRS		2367			3163.4			0
		AFL		954			1645			0
		MOS		73.5	-30	96	30 Sep 2016	31 Aug 2024*	30 Sep 2024	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-8C									
282604	Engine Dual Wall Fuel Feed Line Shroud (Right) - Functional Test	HRS		2367			3163.4			0
		AFL		954			1645			0
		MOS		73.5	-30	96	30 Sep 2016	31 Aug 2024*	30 Sep 2024	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-8C									
282605	APU Dual Wall Fuel Feed Line Shroud - Functional Test	HRS		2367			3163.4			0
		AFL		954			1645			0
		MOS		73.5	-30	96	30 Sep 2016	31 Aug 2024*	30 Sep 2024	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-8C									
282606	Engine Dual Wall Fuel Feed Line (Left) - Detailed Inspection	HRS		190.2			5340.2			0
		AFL		71			2528			0
		MOS		6.2	28	24	10 May 2022	30 Jun 2024*	31 Jul 2024	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe	200202									
282607	Engine Dual Wall Fuel Feed Line (Right) - Detailed Inspection	HRS		190.2			5340.2			0
		AFL		71			2528			0
		MOS		6.2	28	24	10 May 2022	30 Jun 2024*	31 Jul 2024	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe	200202									
282608	APU Dual Wall Fuel Feed Line - Detailed Inspection	HRS		190.2			5340.2			0
		AFL		71			2528			0
		MOS		6.2	28	24	10 May 2022	30 Jun 2024*	31 Jul 2024	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe	200202									
282619	Fuel Ejector Pump (Left) - Remvoal / Installation	HRS		5530.4			0			0
	1159SCP002-5 2260	AFL		2599			0			0
		MOS		174.6			28 Apr 2008			ALLEN AIRCRAFT
		MSC				O/C				PRODUCTS INC
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
282620 Airframe	Fuel Ejector Pump (Right) - Remvoal / Installation 1159SCP002-5 2259	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 ALLEN AIRCRAFT PRODUCTS INC
282625 Airframe	Fuel Ejector Pump Flapper Check Valve (Left) - Removal / Installation 1159SCP002-5 SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 ALLEN AIRCRAFT PRODUCTS INC
282626 Airframe	Fuel Ejector Pump Flapper Check Valve (Right) - Removal / Installation 1159SCP002-5 SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 ALLEN AIRCRAFT PRODUCTS INC
282627 Airframe	Ejector Pump Flapper Valve (Left) - Leak Check	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
282628 Airframe	Ejector Pump Flapper Valve (Right) - Leak Check	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
282629 Airframe	Engine (Installed) Fuel Shut-Off Valve (Left) - Operational Check 200202	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		190.2 71 6.1	46	 24	5340.2 2528 14 May 2022	30 Jun 2024*	31 Jul 2024	0 0
282630 Airframe	Engine (Installed) Fuel Shut-Off Valve (Right) - Operational Check 200202	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		190.2 71 6.1	46	 24	5340.2 2528 14 May 2022	30 Jun 2024*	31 Jul 2024	0 0

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
282631	Engine Fuel Shut-Off Valve (Left) - Removal / Installation AV16B1453B4	AA143964	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 ITT AEROSPACE CONTROLS
Airframe											
Notes: Q300135											
282632	Engine Fuel Shut-Off Valve (Right) - Removal / Installation AV16B1453B4	AA143966	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 ITT AEROSPACE CONTROLS
Airframe											
Notes: Q300135											
282640	APU Fuel Shut-Off Valve - Removal / Installation V4700-108-2	0289	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe											
Notes: Q300135											
282641	APU Fuel Shut-Off Valve - Functional Test		HRS AFL MOS		190.2 71 5.8	 36	 24	5340.2 2528 23 May 2022	 30 Jun 2024*	 31 Jul 2024	0 0
Airframe	200202		[End Of Month Item] [MOS: +1m/-1m]								
284100	Fuel Quantity System (Left) - Capacitance / Insulation Resistance Check		HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe											
284101	Fuel Quantity System (Right) - Capacitance / Insulation Resistance Check		HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe											

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
284102 Airframe	Fuel Quantity Signal Conditioner - Removal / Installation 367-936-001 1131 2 F	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 PARKER HANNIFIN CORPORATION
284103 Airframe	Fuel System Interface to Aircraft Systems - Operational Check	HRS AFL MOS MSC		2643.1 1095 90.5		 O/C	2887.3 1504 30 Apr 2015			0 0
284107 Airframe	Fuel Ground Service Control Panel - Removal / Installation 366-212-001 1125	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 PARKER HANNIFIN CORPORATION
284108 Airframe	Fuel Ground Service Control Panel - Operational Check	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
284114 Airframe	Refueling Door Fuel High-Level Warning Light - Operational Check	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
284121 Airframe	Fuel Quantity Probe (Left No. 1) - Removal / Installation 1159SCP460-1 1574	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
284122 Airframe	Fuel Quantity Probe (Left No. 2) - Removal / Installation 1159SCP460-2 1555	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 PARKER HANNIFIN CORPORATION

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
284123	Fuel Quantity Probe (Left No. 3) - Removal / Installation		HRS		5530.4			0			0
	1159SCP460-3	1576	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			PARKER
			MSC				O/C				HANNIFIN
Airframe											CORPORATION
284124	Fuel Quantity Probe (Left No. 4) - Removal / Installation		HRS		5530.4			0			0
	1159SCP460-4	1543	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			
			MSC				O/C				
Airframe											
284125	Fuel Quantity Probe (Left No. 5) - Removal / Installation		HRS		5530.4			0			0
	1159SCP460-5	1623	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			PARKER
			MSC				O/C				HANNIFIN
Airframe											CORPORATION
284126	Fuel Quantity Probe (Left No. 6) - Removal / Installation		HRS		5530.4			0			0
	1159SCP460-6	1674	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			PARKER
			MSC				O/C				HANNIFIN
Airframe											CORPORATION
284127	Fuel Quantity Probe (Left No. 7) - Removal / Installation		HRS		5530.4			0			0
	1159SCP460-7	1582	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			PARKER
			MSC				O/C				HANNIFIN
Airframe											CORPORATION
284128	Fuel Quantity Probe (Left No. 8) - Removal / Installation		HRS		5530.4			0			0
	1159SCP460-8	1655	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			PARKER
			MSC				O/C				HANNIFIN
Airframe											CORPORATION

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
284129 Airframe	Fuel Quantity Probe (Left No. 9) - Removal / Installation 1159SCP460-9 1617	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 HI-TEMP INSULATION INC
284130 Airframe	Fuel Quantity Probe (Left No. 10) - Removal / Installation 1159SCP460-10 1550	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 PARKER HANNIFIN CORPORATION
284131 Airframe	Fuel Quantity Probe (Left No. 11) - Removal / Installation 1159SCP460-11 1638	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 PARKER HANNIFIN CORPORATION
284132 Airframe	Fuel Quantity Probe (Left No. 12) - Removal / Installation 1159SCP460-12 1687	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 PARKER HANNIFIN CORPORATION
284133 Airframe	Fuel Quantity Probe (Left No. 13) - Removal / Installation 1159SCP460-13 1565	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 PARKER HANNIFIN CORPORATION
284134 Airframe	Fuel Quantity Probe (Left No. 14) - Removal / Installation 1159SCP460-14 1559	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 PARKER HANNIFIN CORPORATION

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
284135 Airframe	Fuel Quantity Probe (Left No. 15) - Removal / Installation 1159SCP460-15 1540	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 PARKER HANNIFIN CORPORATION
284136 Airframe	Fuel Quantity Probe (Left No. 16) - Removal / Installation 1159SCP460-16 1595	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 PARKER HANNIFIN CORPORATION
284137 Airframe	Fuel Quantity Probe (Left No. 17) - Removal / Installation 1159SCP460-17 1614	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 PARKER HANNIFIN CORPORATION
284138 Airframe	Fuel Quantity Probe (Left No. 18) - Removal / Installation 1159SCP460-18 1492	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 PARKER HANNIFIN CORPORATION
284139 Airframe	Fuel Quantity Probe (Left No. 19) - Removal / Installation 1159SCP460-19 1590	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 PARKER HANNIFIN CORPORATION
284141 Airframe	Fuel Quantity Probe (Right No. 1) - Removal / Installation 1159SCP460-1 1553	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 PARKER HANNIFIN CORPORATION

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
284142 Airframe	Fuel Quantity Probe (Right No. 2) - Removal / Installation 1159SCP460-2 1508	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 PARKER HANNIFIN CORPORATION
284143 Airframe	Fuel Quantity Probe (Right No. 3) - Removal / Installation 1159SCP460-3 1576	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 PARKER HANNIFIN CORPORATION
284144 Airframe	Fuel Quantity Probe (Right No. 4) - Removal / Installation 1159SCP460-4 1543	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 PARKER HANNIFIN CORPORATION
284145 Airframe	Fuel Quantity Probe (Right No. 5) - Removal / Installation 1159SCP460-5 1623	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 PARKER HANNIFIN CORPORATION
284146 Airframe	Fuel Quantity Probe (Right No. 6) - Removal / Installation 1159SCP460-6 1674	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 PARKER HANNIFIN CORPORATION
Notes: PQ093										
284147 Airframe	Fuel Quantity Probe (Right No. 7) - Removal / Installation 1159SCP460-7 1582	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 PARKER HANNIFIN CORPORATION
Notes: PQ093										

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
Logbook Position	HW	SW									
	MM Ref										
	Ops Number(s)										
284148	Fuel Quantity Probe (Right No. 8) - Removal / Installation		HRS		5530.4			0			0
	1159SCP460-8	1655	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			PARKER
			MSC				O/C				HANNIFIN
Airframe											CORPORATION
Notes: PQ093											
284149	Fuel Quantity Probe (Right No. 9) - Removal / Installation		HRS		5530.4			0			0
	1159SCP460-9	1617	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			HI-TEMP
			MSC				O/C				INSULATION INC
Airframe											
Notes: PQ093											
284150	Fuel Quantity Probe (Right No. 10) - Removal / Installation		HRS		5530.4			0			0
	1159SCP460-10	1550	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			PARKER
			MSC				O/C				HANNIFIN
Airframe											CORPORATION
Notes: PQ093											
284151	Fuel Quantity Probe (Right No. 11) - Removal / Installation		HRS		5530.4			0			0
	1159SCP460-11	1638	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			PARKER
			MSC				O/C				HANNIFIN
Airframe											CORPORATION
Notes: PQ093											
284152	Fuel Quantity Probe (Right No. 12) - Removal / Installation		HRS		5530.4			0			0
	1159SCP460-12	1687	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			PARKER
			MSC				O/C				HANNIFIN
Airframe											CORPORATION
Notes: PQ093											

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Description: Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
284153	Fuel Quantity Probe (Right No. 13) - Removal / Installation		HRS		5530.4			0			0
			AFL		2599			0			0
	1159SCP460-13	1565	MOS		174.6			28 Apr 2008			PARKER HANNIFIN CORPORATION
			MSC				O/C				
Airframe											
Notes: PQ093											
284154	Fuel Quantity Probe (Right No. 14) - Removal / Installation		HRS		5530.4			0			0
			AFL		2599			0			0
	1159SCP460-14	1559	MOS		174.6			28 Apr 2008			PARKER HANNIFIN CORPORATION
			MSC				O/C				
Airframe											
Notes: PQ093											
284155	Fuel Quantity Probe (Right No. 15) - Removal / Installation		HRS		5530.4			0			0
			AFL		2599			0			0
	1159SCP460-15	1540	MOS		174.6			28 Apr 2008			PARKER HANNIFIN CORPORATION
			MSC				O/C				
Airframe											
Notes: PQ093											
284156	Fuel Quantity Probe (Right No. 16) - Removal / Installation		HRS		5530.4			0			0
			AFL		2599			0			0
	1159SCP460-16	1595	MOS		174.6			28 Apr 2008			PARKER HANNIFIN CORPORATION
			MSC				O/C				
Airframe											
Notes: PQ093											
284157	Fuel Quantity Probe (Right No. 17) - Removal / Installation		HRS		5530.4			0			0
			AFL		2599			0			0
	1159SCP460-17	1614	MOS		174.6			28 Apr 2008			PARKER HANNIFIN CORPORATION
			MSC				O/C				
Airframe											
Notes: PQ093											

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Description: Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
284158	Fuel Quantity Probe (Right No. 18) - Removal / Installation		HRS		5530.4			0			0
			AFL		2599			0			0
	1159SCP460-18	1492	MOS		174.6			28 Apr 2008			PARKER HANNIFIN CORPORATION
			MSC				O/C				
Airframe											
Notes: PQ093											
284159	Fuel Quantity Probe (Right No. 19) - Removal / Installation		HRS		5530.4			0			0
			AFL		2599			0			0
	1159SCP460-19	1590	MOS		174.6			28 Apr 2008			PARKER HANNIFIN CORPORATION
			MSC				O/C				
Airframe											
Notes: PQ093											
284161	Probe, Lh Compensator		HRS		5530.4			0			0
	1159SCP460-21	0432	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			PARKER HANNIFIN CORPORATION
			MSC				O/C				
Airframe											
Notes: PQ093											
284162	Probe, Rh Compensator		HRS		5530.4			0			0
	1159SCP460-21	0432	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			PARKER HANNIFIN CORPORATION
			MSC				O/C				
Airframe											
Notes: PQ093											
284165	Fuel Quantity Probe (Left No. 20) - Removal / Installation		HRS		5530.4			0			0
	1159SCP460-20	1577	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			PARKER HANNIFIN CORPORATION
			MSC				O/C				
Airframe											
Notes: PQ093											

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
284166	Fuel Quantity Probe (Left No. 21) - Removal / Installation		HRS		5530.4			0			0
	1159SCP460-21	1721	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			PARKER
			MSC				O/C				HANNIFIN
Airframe											CORPORATION
Notes: PQ093											
284167	Fuel Quantity Probe (Right No. 20) - Removal / Installation		HRS		5530.4			0			0
	1159SCP460-20	1577	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			PARKER
			MSC				O/C				HANNIFIN
Airframe											CORPORATION
Notes: PQ093											
284168	Fuel Quantity Probe (Right No. 21) - Removal / Installation		HRS		5530.4			0			0
	1159SCP460-21	1734	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			PARKER
			MSC				O/C				HANNIFIN
Airframe											CORPORATION
Notes: PQ093											
284305	Main Fuel Boost Pump Pressure Switch (Left) - Removal / Installation		HRS		1642.6			3887.8			0
	8125-20	9734	AFL		643			1956			0
			MOS	TSN:32	50.3			07 Sep 2018			HYDRA-
			MSC				O/C				ELECTRIC
Airframe											COMPANY
Notes: Q300135											
284306	Alternate Fuel Boost Pump Pressure Switch (Left) - Removal / Installation		HRS		5530.4			0			0
	8125-20	8003	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			HYDRA-
			MSC				O/C				ELECTRIC
Airframe											COMPANY
Notes: Q300135											

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
284307	Main Fuel Boost Pump Pressure Switch (Right) - Removal / Installation 8125-20 8020	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 HYDRA-ELECTRIC COMPANY
Airframe										
Notes: Q300135										
284308	Alternate Fuel Boost Pump Pressure Switch (Right) - Removal / Installation 8125-20 8031	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 HYDRA-ELECTRIC COMPANY
Airframe										
Notes: Q300135										
29 - Hydraulic Power										
290009	Hydraulic Fluid (Left) - Sampling / Analysis	HRS AFL MOS MSC		4883.4 2421 151		 O/C	647 178 16 Apr 2010			0 0
Airframe										
290010	Hydraulic Fluid (Right) - Sampling / Analysis	HRS AFL MOS MSC		4882.7 2421 151		 O/C	647.7 178 16 Apr 2010			0 0
Airframe										
290021	Hydraulic Fluid Heat Exchanger (Left) - Removal / Installation 1159H20266 217	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 TEXTRON AEROSTRUCTURES
Airframe										
290022	Hydraulic Fluid Heat Exchanger (Right) - Removal / Installation 1159H20266 261	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
290023	Left System Reservoir Relief Valve - Removal / Installation 1159SCH648-1 0399	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 GAR- KENYON TECHNOLGIES
Airframe										
290024	Right System Reservoir Relief Valve - Removal / Installation 1159SCH648-1 0402	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 GAR- KENYON TECHNOLGIES
Airframe										
290100	Hydraulic Replenisher Tank - Removal / Installation 1159SCH519-7 0344	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 MEGGITT AIRDYNAMICS, INC.
Airframe										
Notes: Q306918										
291003	Hydraulic Systems - Functional Test	HRS AFL MOS MSC		130.9 49 2.6		 O/C	5399.5 2550 27 Aug 2022			0 0
Airframe										
291007	Engine-Driven Hydraulic Pump (Left) - Removal / Installation 1159SCH505-101 K1729	HRS AFL MOS MSC	TSN:3838.9 TSN:1931 TSN:123	1691.5 668 51.9		 O/C	3838.9 1931 19 Jul 2018			0 0 EATON AEROSPACE
Airframe										
291008	Engine-Driven Hydraulic Pump (Right) - Removal / Installation 1159SCH505-101 K1728	HRS AFL MOS MSC	TSN:3838.9 TSN:1931 TSN:123	1691.5 668 51.9		 O/C	3838.9 1931 19 Jul 2018			0 0 EATON AEROSPACE
Airframe										
291009	Filter, Lh Hyd System 1159H47440-1 PM0489	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
291010	Filter, Rh Hyd System 1159H47440-1 PM0478	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										
291020	Lateral Control Switch (Lat Hyd Pwr Shutoff) - Operational Check	HRS AFL MOS [HRS: +50/-50]		439.3 157 12.2	 -25	1000 	5091.1 2442 09 Nov 2021	6091.1	6141.1	0 0
Airframe										
291030	Left System Manifold - Removal / Installation AE-B451-16 0693	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 PALL AEROPOWER CORPORATION
Airframe										
Notes: Q306918										
291031	Right System Manifold - Removal / Installation AE-B466-16 0679	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 MEASUREMENTS GROUP
Airframe										
Notes: Q306918										
291033	Left System Manifold Filter / Filter Bowl (Pressure) - Removal / Installation PN SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										
291034	Right System Manifold Filter / Filter Bowl (Pressure) - Removal / Installation PN SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
291035 Airframe	Left System Manifold Filter / Filter Bowl (Main Return) - Removal / Installation AC-B451F-16 SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0
291036 Airframe	Right System Manifold Filter / Filter Bowl (Main Return) - Removal / Installation AC-B451F-16 SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0
291401 Airframe	Left System Differential Pressure Indicator (Pressure) - Detailed Inspection 052000-2A,200102	HRS AFL MOS [HRS: +50/-50]	6.5 2 .2		49.3	1000	5523.9 2597 11 Nov 2022	6573.2*	6623.2	0 0
291402 Airframe	Right System Manifold Differential Pressure Indicator (Pressure) - Detailed Inspection 052000-2A,200102	HRS AFL MOS [HRS: +50/-50]	6.5 2 .2		49.3	1000	5523.9 2597 11 Nov 2022	6573.2*	6623.2	0 0
291405 Airframe	Left System Differential Pressure Indicator (Main Return) - Detailed Inspection 052000-2A,200102	HRS AFL MOS [HRS: +50/-50]	6.5 2 .2		49.3	1000	5523.9 2597 11 Nov 2022	6573.2*	6623.2	0 0
291406 Airframe	Right System Manifold Differential Pressure Indicator (Main Return) - Detailed Inspection 052000-2A,200102	HRS AFL MOS [HRS: +50/-50]	6.5 2 .2		49.3	1000	5523.9 2597 11 Nov 2022	6573.2*	6623.2	0 0
291407 Airframe	Left System Differential Pressure Indicator (Edp) - Detailed Inspection 052000-2A,200102	HRS AFL MOS [HRS: +50/-50]	6.5 2 .2		49.3	1000	5523.9 2597 11 Nov 2022	6573.2*	6623.2	0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
291408 Airframe	Right System Manifold Differential Pressure Indicator (Edp) - Detailed Inspection 052000-2A,200102	HRS AFL MOS [HRS: +50/-50]		6.5 2 .2	49.3	1000	5523.9 2597 11 Nov 2022	6573.2*	6623.2	0 0
291415 Airframe	Valve, Comb Sys Press Relief 1159SCH648-1 0407	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0 GAR- KENYON TECHNOLGIES
291416 Airframe	Right System Manifold High-Pressure Relief Valve - Removal / Installation 1159SCH648-1 0310	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0 GAR- KENYON TECHNOLGIES
291435 Airframe	Left Pump Pressure Switch - Removal / Installation 1206P0215 SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0
291437 Airframe	Left System Manifold Check Valve - Removal / Installation PN SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0
291438 Airframe	Right System Manifold Check Valve - Removal / Installation PN SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0
291501 Airframe	Hydraulic System Shut-Off Valve (Left) - Operational Test 200202	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		190.2 71 6.1	46	24	5340.2 2528 14 May 2022	30 Jun 2024*	31 Jul 2024	0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
291502 Airframe	Hydraulic System Shut-Off Valve (Right) - Operational Test 200202	HRS AFL MOS		190.2 71 6.1	46	24	5340.2 2528 14 May 2022	30 Jun 2024*	31 Jul 2024	0 0
	[End Of Month Item] [MOS: +1m/-1m]									
291503 Airframe	Left Hydraulic System Shut-Off Valve - Removal / Installation 1159SCH239-5 AA145882	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0 ITT AEROSPACE CONTROLS
291504 Airframe	Right Hydraulic System Shut-Off Valve - Removal / Installation 1159SCH239-5 AA145883	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0 ITT AEROSPACE CONTROLS
291603 Airframe	Left System Reservoir - Removal / Installation 1159H20125-33 55-4121GT	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0
291604 Airframe	Right System Reservoir - Removal / Installation 1159H47126-15 55-4135GT	HRS AFL MOS MSC		130.9 49 2.6		O/C	5399.5 2550 27 Aug 2022			0 0
291605 Airframe	Left System Reservoir Inspection - Leak Check	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0
291606 Airframe	Right System Reservoir Inspection - Leak Check	HRS AFL MOS MSC		130.9 49 2.6		O/C	5399.5 2550 27 Aug 2022			0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
291701	Hydraulic System Accumulator (Left) - Removal / Installation 1159SCH206-5 60211-2063NA	HRS AFL MOS MSC		4593.3 2210 139.9		 O/C	937.1 389 19 Mar 2011			0 0 PNEUDRAULICS INC
Airframe										
291702	Hydraulic System Accumulator (Right) - Removal / Installation 1159SCH206-5 60211-2632	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 PNEUDRAULICS INC
Airframe										
291703	Hydraulic System Accumulator Pressure Gage (Left) - Removal / Installation GP20-24 SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 CUSTOM METAL WORKS
Airframe										
291704	Hydraulic System Accumulator Pressure Gage (Right) - Removal / Installation GP20-24 SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 CUSTOM METAL WORKS
Airframe										
291705	Valve, Lh Hydraulic Selector 1159SCH501-19 EFS0787	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 KAISER FLUID TECHNOLOGIES
Airframe										
291706	Valve, Rh Hydraulic Selector 1159SCH501-19 EFS0769	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 KAISER FLUID TECHNOLOGIES
Airframe										
292002	Auxiliary Hydraulic System - Functional Test	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
292045	Auxiliary Hydraulic System (Rudder) - Functional Test		HRS		5530.4			0			0
			AFL		2599			0			0
			MOS		174.6			28 Apr 2008			
			MSC				O/C				
Airframe											
292102	Auxiliary Hydraulic Pump - Removal / Installation		HRS		5530.4			0			0
	1159SCH603-1	K0093	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			AAR
			MSC				O/C				COMPOSITES
Airframe											
292201	Power Transfer Unit Hydraulic Pump - Removal / Installation		HRS		5530.4			0			0
	1159SCH202-1	K0444	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			PARKER
			MSC				O/C				HANNIFIN CORP-USE S03721 A2 ADDR
Airframe											
Notes: Q306918											
292202	Transducer, Aux Pressure		HRS		5530.4			0			0
	1159SCAV600-1	HAL3870	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			GULFSTREAM - LONG BEACH
			MSC				O/C				
Airframe											
Notes: Q306918											
292203	Left Hydraulic System Pressure Transducer - Removal / Installation		HRS		5530.4			0			0
	1159SCAV600-1	HAL3868	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			GULFSTREAM - LONG BEACH
			MSC				O/C				
Airframe											
Notes: Q306918											
292204	Right Hydraulic System Pressure Transducer - Removal / Installation		HRS		5530.4			0			0
	1159SCAV600-1	HAL3850	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			GULFSTREAM - LONG BEACH
			MSC				O/C				
Airframe											
Notes: Q306918											

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
292205	Power Transfer Unit - Functional Test	HRS		5530.4			0			0
		AFL		2599			0			0
		MOS		174.6			28 Apr 2008			
Airframe		MSC				O/C				
292207	Hydraulic Fluid (Auxiliary) - Sampling / Analysis	HRS		4882.7			647.7			0
		AFL		2421			178			0
		MOS		150.9			18 Apr 2010			
Airframe		MSC				O/C				
292211	Valve, Rh Flow Reg Utility 1159SCH218-1 826	HRS		5530.4			0			0
		AFL		2599			0			0
		MOS		174.6			28 Apr 2008			PNEUDRAULICS INC
Airframe		MSC				O/C				
Notes: PQ162										
292500	Auxiliary Hydraulic System Differential Pressure Indicator (Pressure) - Detailed Inspection	HRS		6.5		500	5523.9	6023.9	6073.9	0
		AFL		2			2597			0
		MOS		.2			11 Nov 2022			
		[HRS: +50/-50]								
Airframe	052000-1A,200100									
292501	Auxiliary Hydraulic System Differential Pressure Indicator (Aux Return) - Detailed Inspection	HRS		6.5		500	5523.9	6023.9	6073.9	0
		AFL		2			2597			0
		MOS		.2			11 Nov 2022			
		[HRS: +50/-50]								
Airframe	052000-1A,200100									
292502	Power Transfer Unit System Differential Pressure Indicator (Pressure Filter) - Detailed Inspection	HRS		6.5		500	5523.9	6023.9	6073.9	0
		AFL		2			2597			0
		MOS		.2			11 Nov 2022			
		[HRS: +50/-50]								
Airframe	052000-1A,200100									
292504	Auxiliary Hydraulic Pump Manifold Filter Element and Bowl - Removal / Installation	HRS		2640.5			2889.9			0
		AFL		1094			1505			0
	ACB451F8 NSN	MOS	TSN:7	90			17 May 2015			
		MSC				O/C				
Airframe										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
292508 Airframe	Power Transfer Unit Manifold - Removal / Installation 1206P0215 2767	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 ELECTRO ENTERPRISES INC
292509 Airframe	Power Transfer Unit Manifold Filter Element and Bowl - Removal / Installation PN SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
292511 Airframe Notes: Q306918	Left Hydraulic System / Power Transfer Unit Pressure Switch - Removal / Installation 1206P0215 2756	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 ELECTRO ENTERPRISES INC
292515 Airframe	Power Transfer Unit System Differential Pressure Indicator (Bypass Filter) - Detailed Inspection 052000-1A,200100	HRS AFL MOS [HRS: +50/-50]		6.5 2 .2		500	5523.9 2597 11 Nov 2022	6023.9	6073.9	0 0
292601 Airframe	Auxiliary Hydraulic System Shut-Off Control - Functional Test	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
292603 Airframe Notes: PQ246	Power Transfer Unit Shut-Off Valve - Removal / Installation 1159SCH516-1 0546	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 PALL AEROPOWER CORPORATION

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Description: Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
292604	Valve, Aux Motor Shutoff		HRS		5530.4			0			0
	1159SCH514-3	1393	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			MEGGITT SAFETY SYSTEMS
Airframe			MSC				O/C				
Notes: PQ162											
293199	Left System Pressure Switch - Removal / Installation		HRS		5530.4			0			0
	1206P0215	2746	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			ELECTRO ENTERPRISES INC
Airframe			MSC				O/C				
Notes: Q306918											
293201	Left Hydraulic System Pressure Transducer - Removal / Installation		HRS		5530.4			0			0
	1206P0215	2778	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			ELECTRO ENTERPRISES INC
Airframe			MSC				O/C				
Notes: Q306918											
293203	Hydraulic System Reservoir Temperature Transducer (Left) - Removal / Installation		HRS		190.2			5340.2			0
	1159SCH535-1	M2615	AFL		71			2528			0
			MOS	TSN:195	5.8			23 May 2022			N/A
Airframe			MSC				O/C				
293204	Hydraulic System Reservoir Temperature Transducer (Right) - Removal / Installation		HRS		5530.4			0			0
	1159SCH525-17	B0170	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			MPC PRODUCTS
Airframe			MSC				O/C				
293206	Auxiliary Hydraulic Pressure Transducer - Removal / Installation		HRS		5530.4			0			0
	1159SCAV600-1	HAL3846	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			
Airframe			MSC				O/C				

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
293310 Airframe	Left Reservoir Hydraulic Quantity Transmitter - Removal / Installation PN SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
293311 Airframe	Right Reservoir Hydraulic Quantity Transmitter - Removal / Installation PN SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
293312 Airframe	Hydraulic Reservoir Quantity Transmitter (Left) - Adjustment	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
293313 Airframe	Hydraulic Reservoir Quantity Transmitter (Right) - Adjustment	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
293317 Airframe	Auxiliary Hydraulic Pump Control - Operational Test	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
293318 Airframe	Power Transfer Unit Control - Operational Test	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
293319 Airframe	Hydraulic Temperature Sensing and Indication - Operational Test	HRS AFL MOS MSC		190.2 71 5.8		 O/C	5340.2 2528 23 May 2022			0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
293320	Hydraulic Pressure Sensing and Indication - Operational Test	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										
293321	Hydraulic Quantity Sensing and Indication - Operational Test	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										
30 - Ice and Rain Protection										
300003	Wing Anti-Ice (Left) - Operational Test - Dynamic	HRS AFL MOS MSC	2367 954 72.2			 O/C	3163.4 1645 09 Nov 2016			0 0
Airframe										
300004	Wing Anti-Ice (Right) - Operational Test - Dynamic	HRS AFL MOS MSC	2367 954 72.2			 O/C	3163.4 1645 09 Nov 2016			0 0
Airframe										
300009	Cowl Anti-Ice System (Left) - Operational Test - Dynamic	HRS AFL MOS MSC	882.2 304 23.3			 O/C	4648.2 2295 08 Dec 2020			0 0
Airframe										
300010	Cowl Anti-Ice System (Right) - Operational Test - Dynamic	HRS AFL MOS MSC	1596.4 621 47			 O/C	3934 1978 16 Dec 2018			0 0
Airframe										
301100	Wing Anti-Ice Control System - Functional Test	HRS AFL MOS MSC	2367 954 72.2			 O/C	3163.4 1645 09 Nov 2016			0 0
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
301101 Airframe	Wing Anti-Ice Control Valve (Left) - Removal / Installation 3215600-2 1156	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 GENERAL DYNAMICS AVIATIONS SERVICES
301102 Airframe	Wing Anti-Ice Control Valve (Right) - Removal / Installation 3215600-2 1679	HRS AFL MOS MSC		2367 954 72.2		 O/C	3163.4 1645 09 Nov 2016			0 0
Notes: TW: 558136DATE DUE: 08/17										
301105 Airframe	Wing Anti-Ice Overtemperature Switch (Left Inboard) - Removal / Installation PN SN-UNKNOWN	HRS AFL MOS MSC	TSN:3163.4 TSN:1645 TSN:103	2367 954 72.3		 O/C	3163.4 1645 07 Nov 2016			0 0
301106 Airframe	Wing Anti-Ice Overtemperature Switch (Right Inboard) - Removal / Installation PN SN-UNKNOWN	HRS AFL MOS MSC	TSN:3163.4 TSN:1645 TSN:103	2367 954 72.3		 O/C	3163.4 1645 07 Nov 2016			0 0
301107 Airframe	Wing Anti-Ice Mid Temperature Switch (Left) - Removal / Installation PN SN-UNKNOWN	HRS AFL MOS MSC	TSN:3163.4 TSN:1645 TSN:103	2367 954 72.3		 O/C	3163.4 1645 07 Nov 2016			0 0
301108 Airframe	Wing Anti-Ice Mid Temperature Switch (Right) - Removal / Installation PN SN-UNKNOWN	HRS AFL MOS MSC	TSN:3163.4 TSN:1645 TSN:103	2367 954 72.3		 O/C	3163.4 1645 07 Nov 2016			0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
301109	Wing Anti-Ice Overtemperature Switch (Left Outboard) - Removal / Installation PN SN-UNKNOWN	HRS AFL MOS MSC	TSN:3163.4 TSN:1645 TSN:103	2367 954 72.3		 O/C	3163.4 1645 07 Nov 2016			0 0
Airframe										
301110	Wing Anti-Ice Overtemperature Switch (Right Outboard) - Removal / Installation PN SN-UNKNOWN	HRS AFL MOS MSC	TSN:3163.4 TSN:1645 TSN:103	2367 954 72.3		 O/C	3163.4 1645 07 Nov 2016			0 0
Airframe										
301111	Wing Anti-Ice Temperature Sensor (Left No. 1) - Removal / Installation 1151834-1 1151834-05330	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 HONEYWELL ASCA INC.
Airframe										
301112	Wing Anti-Ice Temperature Sensor (Right No. 1) - Removal / Installation 1151834-1 1151834-05328	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 HONEYWELL ASCA INC.
Airframe										
301117	Wing Anti-Ice Thermal Switch (Left Inboard Overtemperature) - Functional Test	HRS AFL MOS		2367 954 72.3	 -68	 96	3163.4 1645 07 Nov 2016	 31 Aug 2024*	 30 Sep 2024	0 0
	[End Of Month Item] [MOS: +1m/-1m]									
Airframe	052000-8C									
301118	Wing Anti-Ice Thermal Switch (Right Inboard Overtemperature) - Functional Test	HRS AFL MOS		2367 954 72.3	 -68	 96	3163.4 1645 07 Nov 2016	 31 Aug 2024*	 30 Sep 2024	0 0
	[End Of Month Item] [MOS: +1m/-1m]									
Airframe	052000-8C									
301119	Wing Anti-Ice Thermal Switch (Left Middle Overtemperature) - Functional Test	HRS AFL MOS		2367 954 72.3	 -68	 96	3163.4 1645 07 Nov 2016	 31 Aug 2024*	 30 Sep 2024	0 0
	[End Of Month Item] [MOS: +1m/-1m]									
Airframe	052000-8C									

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
301120	Wing Anti-Ice Thermal Switch (Right Middle Overtemperature) - Functional Test		HRS		2367			3163.4			0
			AFL		954			1645			0
			MOS		72.3	-68	96	07 Nov 2016	31 Aug 2024*	30 Sep 2024	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-8C										
301123	Wing Anti-Ice Thermal Switch (Left Outboard Overtemperature) - Functional Test		HRS		2367			3163.4			0
			AFL		954			1645			0
			MOS		72.3	-68	96	07 Nov 2016	31 Aug 2024*	30 Sep 2024	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-8C										
301124	Wing Anti-Ice Thermal Switch (Right Outboard Overtemperature) - Functional Test		HRS		2367			3163.4			0
			AFL		954			1645			0
			MOS		72.3	-68	96	07 Nov 2016	31 Aug 2024*	30 Sep 2024	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-8C										
302101	Cowl Anti-Ice Control Valve (Left) - Functional Test		HRS		2640.5			2889.9			0
			AFL		1094			1505			0
			MOS		89.5			30 May 2015			
			MSC				O/C				
Airframe											
302102	Cowl Anti-Ice Control Valve (Right) - Functional Test		HRS		2640.5			2889.9			0
			AFL		1094			1505			0
			MOS		89.5			30 May 2015			
			MSC				O/C				
Airframe											
302103	Cowl Anti-Ice Valve (Left) - Removal / Installation		HRS	TSN:3838.9	1691.5			3838.9			0
	3215892-1	351	AFL	TSN:1931	668			1931			0
			MOS	TSN:123	51.9			20 Jul 2018			
			MSC				O/C				
Airframe											
302104	Cowl Anti-Ice Valve (Right) - Removal / Installation		HRS	TSN:3838.9	1691.5			3838.9			0
	3215892-1	353	AFL	TSN:1931	668			1931			0
			MOS	TSN:123	51.9			18 Jul 2018			
			MSC				O/C				
Airframe											

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
302105 Airframe	Transducer,L Eng Anti-Ice Pres APTE-227-1000-75G 7445-2-436	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
302106 Airframe	Transducer,R Eng Anti-Ice Pres APTE-227-1000-75G 7445-2-451	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
302107 Airframe	Thermal Anti-Ice Duct (Left Forward) - Removal / Installation GA01976-109 NSN	HRS AFL MOS MSC	TSN:2907.1 TSN:1515 TSN:93	2623.3 1084 82.4		 O/C	2907.1 1515 05 Jan 2016			0 0
302108 Airframe	Thermal Anti-Ice Duct (Right Forward) - Removal / Installation GA01976-109 NSN	HRS AFL MOS MSC	TSN:2907.1 TSN:1515 TSN:93	2623.3 1084 82.4		 O/C	2907.1 1515 05 Jan 2016			0 0
302109 Airframe	Thermal Anti-Ice Duct (Left Aft) - Removal / Installation PN SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
302110 Airframe	Thermal Anti-Ice Duct (Right Aft) - Removal / Installation PN SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
302205 Airframe	Cowl Anti-Ice Pressure Transducer (Left) - Removal / Installation APTE 2271000756 7445-2-436	HRS AFL MOS MSC		1769.5 717 54.8		 O/C	3760.9 1882 23 Apr 2018			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
302206 Logbook Position	Cowl Anti-Ice Pressure Transducer (Right) - Removal / Installation APTE-227100075G 7445-2-457	HRS AFL MOS MSC		1769.5 717 54.8		 O/C	3760.9 1882 23 Apr 2018			0 0
Airframe										
303012	Angle of Attack Probe Heat - Functional Test	HRS AFL MOS MSC		439.3 157 12.2		 O/C	5091.1 2442 11 Nov 2021			0 0
Airframe										
303013	Pitot and Total AIR Temperature Probe Heater Switch (Left) - Removal / Installation PN SN-UNKNOWN	HRS AFL MOS MSC		2652.9 1097 90.9		 O/C	2877.5 1502 20 Apr 2015			0 0
Airframe										
303015	Pitot / Static and Total AIR Temperature Probe Heater - Operational Check	HRS AFL MOS MSC		957.2 362 29.1		 O/C	4573.2 2237 12 Jun 2020			0 0
Airframe										
303101	Triple Channel Current Sensor (Left) - Removal / Installation E37076-4 SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 FINISHMASTER INC.
Airframe										
303102	Triple Channel Current Sensor (Right) - Removal / Installation E37076-4 SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 FINISHMASTER INC.
Airframe										
304021	Windshield Heat Control Unit (No. 1) - Removal / Installation 1042-1 4080	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 GULFSTREAM - LONG BEACH
Airframe										
Notes: MOD A,B,C,D,E,F,G,H										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
304022	Windshield Heat Control Unit (No. 2) - Removal / Installation		HRS		5530.4			0			0
			AFL		2599			0			0
	1042-1	4082	MOS		174.6			28 Apr 2008			GULFSTREAM - LONG BEACH
			MSC				O/C				
Airframe											
Notes: MOD A,B,C,D,E,F,G,H											
304027	Windshield Heat (Left) - Operational Test		HRS		882.2			4648.2			0
			AFL		304			2295			0
			MOS		25.1			12 Oct 2020			
			MSC				O/C				
Airframe											
304028	Windshield Heat (Right) - Operational Test		HRS		882.2			4648.2			0
			AFL		304			2295			0
			MOS		25.1			12 Oct 2020			
			MSC				O/C				
Airframe											
304105	Windshield Surface Seal (Left) - Detailed Inspection		HRS		6.5		500	5523.9	6023.9	6073.9	0
			AFL		2			2597			0
			MOS		.2		24	11 Nov 2022	30 Nov 2024	31 Dec 2024	
Airframe	052000-1A,200101		[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
304106	Windshield Surface Seal (Right) - Detailed Inspection		HRS		6.5		500	5523.9	6023.9	6073.9	0
			AFL		2			2597			0
			MOS		.2		24	11 Nov 2022	30 Nov 2024	31 Dec 2024	
Airframe	052000-1A,200101		[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
304110	Cabin Window Heat - Operational Test		HRS		882.2			4648.2			0
			AFL		304			2295			0
			MOS		23.2			09 Dec 2020			
			MSC				O/C				
Airframe											
304210	Windshield Rain Removal System - Operational Test		HRS		5530.4			0			0
			AFL		2599			0			0
			MOS		174.6			28 Apr 2008			
			MSC				O/C				
Airframe											

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
308001	Ice Detector Probe (Left) - Removal / Installation 0871HH 1078	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 GULFSTREAM DALLAS
Airframe										
Notes: VERIFIED BY Q305882										
308002	Ice Detector Probe (Right) - Removal / Installation 0871HH 02988	HRS AFL MOS MSC		1080.9 416 34.5		 O/C	4449.5 2183 31 Dec 2019			0 0
Airframe										
Notes: VERIFIED BY Q305882										
308003	Ice Detector Probe (Left) - Operational Test	HRS AFL MOS MSC		5525.5 2597 173		 O/C	4.9 2 17 Jun 2008			0 0
Airframe										
308004	Ice Detector Probe (Right) - Operational Test	HRS AFL MOS MSC		1080.9 416 34.5		 O/C	4449.5 2183 31 Dec 2019			0 0
Airframe										
31 - Indicating/Recording Systems										
312001	Cockpit Clock (Pilot) - Removal / Installation 1159SCAV409-2 4226	HRS AFL MOS MSC		2643.1 1095 90.6		 O/C	2887.3 1504 29 Apr 2015			0 0 PEERLESS ELECTRONICS INC
Airframe										
Notes: UNIT WAS PREVIOUSLY REPAIRED FEB 17, 2011 AT DAVTRON INC.P/N 1159SCAV409-2 S/N 2288 OFF										
312002	Cockpit Clock (Copilot) - Removal / Installation 1159SCAV409-2 2665	HRS AFL MOS MSC	TSN:2926.5 TSN:1487 TSN:104	1416.9 561 43		 O/C	4113.5 2038 16 Apr 2019			0 0 PEERLESS ELECTRONICS INC
Airframe										
Notes: P/N 1159SCAV409-2 OFF S/N 2217 OFF										

ATA / U=Custom / Logbook Position	Description	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
312003	Pilot Cockpit Clock Battery - Replacement LR1 NSN	HRS AFL MOS MSC		1769.5 717 55.2		O/C	3760.9 1882 10 Apr 2018			0 0
Airframe										
312004	Copilot Cockpit Clock Battery - Replacement MN9100 NSN	HRS AFL MOS MSC		957.2 362 29.1		O/C	4573.2 2237 12 Jun 2020			0 0
Airframe										
312200	Cockpit Clocks - Operational Test	HRS AFL MOS MSC		1416.9 561 43		O/C	4113.5 2038 16 Apr 2019			0 0
Airframe										
312501	Cockpit Printer - Removal / Installation 42905411 16M1021	HRS AFL MOS MSC		957.2 362 29.1		O/C	4573.2 2237 12 Jun 2020			0 0
Airframe										
313001	Dfdr - Removal / Installation 980-4710-003 ARFDR-00997	HRS AFL MOS MSC		439.3 157 12		O/C	5091.1 2442 15 Nov 2021			0 0
Airframe										
313002	Dfdr - Functional Test	HRS AFL MOS		190.2 71 5.8		24	5340.2 2528 23 May 2022	31 May 2024	30 Jun 2024	0 0
Airframe	200202	[End Of Month Item] [MOS: +1m/-1m]								
313004	Dfdr Underwater Locator Beacon - Removal / Installation DK120/90 AT117986	HRS AFL MOS MSC		882.2 304 26		O/C	4648.2 2295 16 Sep 2020			0 0
Airframe										
313006	Dfdr Underwater Locator Beacon (DK120 or DK120/90) - Battery Discard DK120/90 AT117986	HRS AFL MOS [End Of Month Item]	TSN:3	1641.7 641 49.1		84	3888.7 1958 13 Oct 2018	01 Sep 2025		0 0 SPINNEYBECK EXPIRATION
Airframe										
Notes: CODE:C, REPLACE WITH NEW DK120/90, PP COVERAGE										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
313009 Airframe	Dfdr Underwater Locator Beacon (DK120 or DK120/90) - Battery Replacement DK120/90 AT117986	HRS AFL MOS MSC	TSN:3	1641.7 641 49.1		O/C	3888.7 1958 13 Oct 2018			0 0
313010 Airframe	Dfdr Underwater Locator Beacon - Operational Test 052000-72M,200303	HRS AFL MOS [MOS: +1m/-1m]		957.2 362 29.1		84	4573.2 2237 12 Jun 2020	12 Jun 2027	12 Jul 2027	0 0
313013 Airframe	Quick Access Recorder - Download	HRS AFL MOS MSC		2698.6 1124 92.2		O/C	2831.8 1475 09 Mar 2015			0 0
Notes: FREQ REMOVED PER LETTER IN 357 FILE RE AUDIT RESPONSE. GRH 20 OCT 10										
313020 Airframe	Digital Flight Data Recorder Underwater Locator Beacon - Cleaning	HRS AFL MOS MSC		1641.7 641 49.1		O/C	3888.7 1958 13 Oct 2018			0 0
313101 Airframe	FDR Impact Switch (Fwd) - Removal / Installation 1159SCAV402-2 2679	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0 DAVTRON INC
313102 Airframe	Tri-Axial Accelerometer - Removal / Installation 3001-01-111 0308-12446	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0 AMETEK AEROSPACE GULTON STATHAM PRODUCTS
313103 Airframe	FDR Impact Switch (Aft) - Removal / Installation 1159SCAV402-2 SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0 DAVTRON INC

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
314001	Central Maintenance Computer Module - Removal / Installation		HRS		4644.2			886.2			0
			AFL		2244			355			0
	7026548-1902	06101389	MOS		142.6			27 Dec 2010			
			MSC				O/C				
Airframe											
314002	Module Cmc - Mau #1		HRS		3018.2			2512.2			0
	7034055-1901	10121499	AFL		1335			1264			0
			MOS		101.9			18 May 2014			HONEYWELL
			MSC				O/C				
Airframe											
Notes: VERFIED BY:PQ005S/N REMOVED: 08032162											
314025	Central Maintenance System - Operational Check		HRS		2640.5			2889.9			0
			AFL		1094			1505			0
			MOS		90.4			04 May 2015			
			MSC				O/C				
Airframe											
314030	Modular Avionics Unit No. 1 - Removal / Installation		HRS	TSN:4.9	5525.5			4.9			0
	7024404-1913	08031652	AFL	TSN:2	2597			2			0
			MOS	TSN:1	174.1			14 May 2008			HONEYWELL
			MSC				O/C				
Airframe											
Notes: MOD:A,B,D,E,F (VERFIED BY:PQ005)											
314034	Modular Avionics Unit No. 2 - Removal / Installation		HRS	TSN:2284.2	3246.2			2284.2			0
	7024404-1913	08031654	AFL	TSN:1167	1432			1167			0
			MOS	TSN:67	107.9			20 Nov 2013			HONEYWELL
			MSC				O/C				
Airframe											
Notes: MOD:A,B,D,E,F (VERFIED BY:PQ005)											
314035	Modular Avionics Unit No. 3 - Removal / Installation		HRS	TSN:2284.2	3246.2			2284.2			0
	7024404-1913	08041677	AFL	TSN:1167	1432			1167			0
			MOS	TSN:67	107.9			20 Nov 2013			HONEYWELL
			MSC				O/C				
Airframe											
Notes: SEE A/C4123 R&I LOG											
314101	Bus Coupler, Ascb#1		HRS		5530.4			0			0
	7027566-901	05121741	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			GULFSTREAM
			MSC				O/C				DALLAS
Airframe											
Notes: VERFIED BY:PQ005											

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Description: Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
314102	Bus Coupler, Ascb#2		HRS		5530.4			0			0
	7027566-901	07113519	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			GULFSTREAM
			MSC				O/C				DALLAS
Airframe											
Notes: VERFIED BY:PQ005											
314103	Bus Coupler, Ascb#3		HRS		5530.4			0			0
	7027566-901	08033805	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			GULFSTREAM
			MSC				O/C				DALLAS
Airframe											
Notes: VERFIED BY:PQ005											
314110	Avionics Standard Communication Bus Telnet Sweep - Check		HRS		2465.4			3065			0
			AFL		1011			1588			0
			MOS		77.5			01 Jun 2016			
			MSC				O/C				
Airframe											
314301	Power Supply Module No. 1 - Removal / Installation		HRS		5530.4			0			0
	7024440-1901	0803A249	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			HONEYWELL
			MSC				O/C				
Airframe											
314302	Power Supply Module No. 2 - Removal / Installation		HRS		5530.4			0			0
	7024440-1901	0803A251	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			HONEYWELL
			MSC				O/C				
Airframe											
Notes: VERFIED BY:PQ005											
314303	Data Base Module No. 1 - Removal / Installation		HRS		3246.2			2284.2			0
	7027208-1903	1310M004	AFL		1432			1167			0
			MOS		107.9			20 Nov 2013			HONEYWELL
			MSC				O/C				
Airframe											
314304	Data Base Module No. 2 - Removal / Installation		HRS		3246.2			2284.2			0
	7027208-1903	1310M005	AFL		1432			1167			0
			MOS		107.9			18 Nov 2013			HONEYWELL
			MSC				O/C				
Airframe											

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Description: Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
314305	Control Input / Output Module - Removal / Installation		HRS		5530.4			0			0
	7026534-1902	08023266	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			HONEYWELL
			MSC				O/C				
Airframe											
Notes: VERFIED BY:PQ005											
314306	Custom Input / Output Module No. 1 - Removal / Installation		HRS		3246.2			2284.2			0
	7026540-1903	13103715	AFL		1432			1167			0
			MOS		107.9			18 Nov 2013			HONEYWELL
			MSC				O/C				
Airframe											
314307	Single Channel Generic Input / Output Module No. 1 - Removal / Installation		HRS		882.2			4648.2			0
	7025364-1901	13067997	AFL		304			2295			0
			MOS		23			15 Dec 2020			
			MSC				O/C				
Airframe											
Notes: VERFIED BY:PQ005											
314308	Single Channel Generic Input / Output Module No. 2 - Removal / Installation		HRS		2486.2			3044.2			0
	7025364-1902	12037070	AFL		1025			1574			0
			MOS		78.3			06 May 2016			HONEYWELL
			MSC				O/C				
Airframe											
Notes: VERFIED BY:PQ005											
314311	Network Interface Controller / Processor Module No. 1 - Removal / Installation		HRS		3246.2			2284.2			0
	7038231-1902	13095444	AFL		1432			1167			0
			MOS		107.9			18 Nov 2013			HONEYWELL INTERNATIONAL
			MSC				O/C				
Airframe											
314312	Network Interface Controller / Processor Module No. 2 - Removal / Installation		HRS		3246.2			2284.2			0
	7038231-1902	12112106	AFL		1432			1167			0
			MOS		107.7			25 Nov 2013			HONEYWELL INTERNATIONAL
			MSC				O/C				
Airframe											

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
314313	Dual Channel Generic Input / Output Module No. 1 - Removal / Installation 7025365-1902 12098847	HRS AFL MOS MSC		739.1 245 19.3		 O/C	4791.3 2354 08 Apr 2021			0 0 N/A
Airframe										
314314	Advanced Graphic Module No. 1 - Removal / Installation 7036410-1901 11017178	HRS AFL MOS MSC		191.6 70 6.2		 O/C	5338.8 2529 09 May 2022			0 0
Airframe										
Notes: VERFIED BY:PQ005										
314320	Modular Avionics Unit - Operational Check	HRS AFL MOS MSC		2640.5 1094 90.4		 O/C	2889.9 1505 04 May 2015			0 0
Airframe										
314349	Module, NIC1 Personality 7519272-901 08028754	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 GULFSTREAM DALLAS
Airframe										
Notes: VERFIED BY:PQ005										
314352	Module, NIC4 Personality 7519272-901 08028547	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 GULFSTREAM DALLAS
Airframe										
Notes: VERFIED BY:PQ005										
314401	Power Supply Module No. 3 - Removal / Installation 7024440-1901 0803A246	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 HONEYWELL
Airframe										
Notes: VERFIED BY:PQ005										
314402	Power Supply Module No. 4 - Removal / Installation 7024440-1901 0803A303	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 HONEYWELL
Airframe										
Notes: VERFIED BY:PQ005										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
314403	Video Module No. 1 - Removal / Installation 7026531-1902 08031571	HRS AFL MOS MSC		3246.1 1432 107.7		 O/C	2284.3 1167 26 Nov 2013			0 0 HONEYWELL
Airframe										
Notes: VERFIED BY:PQ005										
314404	Custom Input / Output Module No. 2 - Removal / Installation 7026540-1903 13103721	HRS AFL MOS MSC		3246.2 1432 107.9		 O/C	2284.2 1167 20 Nov 2013			0 0 HONEYWELL
Airframe										
314405	Single Channel Generic Input / Output Module No. 3 - Removal / Installation 7025364-1901 08033632	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 HONEYWELL
Airframe										
Notes: VERFIED BY:PQ005										
314406	Single Channel Generic Input / Output Module No. 4 - Removal / Installation 7025364-1901 08033641	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 HONEYWELL
Airframe										
Notes: VERFIED BY:PQ005										
314409	Network Interface Controller / Processor Module No. 3 - Removal / Installation 7038231-1902 13105653	HRS AFL MOS MSC		3246.2 1432 107.8		 O/C	2284.2 1167 21 Nov 2013			0 0 HONEYWELL INTERNATIONAL
Airframe										
314410	Network Interface Controller / Processor Module No. 4 - Removal / Installation 7038231-1902 13095453	HRS AFL MOS MSC		3246.2 1432 107.7		 O/C	2284.2 1167 25 Nov 2013			0 0 HONEYWELL INTERNATIONAL
Airframe										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
314411	Dual Channel Generic Input / Output Module No. 2 - Removal / Installation 7025365-1902 09025034	HRS AFL MOS MSC		739.1 245 19.3		 O/C	4791.3 2354 08 Apr 2021			0 0 N/A
Airframe										
314412	Advanced Graphic Module No. 2 - Removal / Installation 7036410-1901 11017173	HRS AFL MOS MSC		4593.3 2210 139.9		 O/C	937.1 389 19 Mar 2011			0 0 HONEYWELL
Airframe										
Notes: VERFIED BY:PQ005										
314501	Power Supply Module No. 5 - Removal / Installation 7024440-1901 0803A230	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 HONEYWELL
Airframe										
Notes: VERFIED BY:PQ005										
314502	Power Supply Module No. 6 - Removal / Installation 7024440-1901 0803A235	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 HONEYWELL
Airframe										
Notes: VERFIED BY:PQ005										
314503	Video Module No. 2 - Removal / Installation 7026531-1902 08031572	HRS AFL MOS MSC		3246.1 1432 107.7		 O/C	2284.3 1167 26 Nov 2013			0 0 HONEYWELL
Airframe										
Notes: VERFIED BY:PQ005										
314504	Custom Input / Output Module No. 3 - Removal / Installation 7026450-1903 13103726	HRS AFL MOS MSC		3246.2 1432 107.9		 O/C	2284.2 1167 20 Nov 2013			0 0 HONEYWELL
Airframe										
314505	Single Channel Generic Input / Output Module No. 5 - Removal / Installation 7025364-1901 08033654	HRS AFL MOS MSC	TSN:4.9 TSN:2 TSN:1	5525.5 2597 174		 O/C	4.9 2 15 May 2008			0 0 HONEYWELL
Airframe										
Notes: VERFIED BY:PQ005										

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Description: Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
314506	Single Channel Generic Input / Output Module No. 6 - Removal / Installation		HRS		1642.6			3887.8			0
			AFL		643			1956			0
	7025364-1902	08094056	MOS		50.3			08 Sep 2018			HONEYWELL
			MSC				O/C				
Airframe											
Notes: VERFIED BY:PQ005											
314507	Network Interface Controller / Processor Module No. 5 - Removal / Installation		HRS		3246.2			2284.2			0
			AFL		1432			1167			0
	7038231-1902	13105573	MOS		107.9			20 Nov 2013			HONEYWELL INTERNATIONAL
			MSC				O/C				
Airframe											
314508	Network Interface Controller / Processor Module No. 6 - Removal / Installation		HRS		3246.2			2284.2			0
			AFL		1432			1167			0
	7038231-1902	13095361	MOS		107.8			21 Nov 2013			HONEYWELL INTERNATIONAL
			MSC				O/C				
Airframe											
314509	Advanced Graphic Module No. 3 - Removal / Installation		HRS		190.2			5340.2			0
	7036410-1901	08071346	AFL		71			2528			0
			MOS		6.1			12 May 2022			
			MSC				O/C				
Airframe											
Notes: VERFIED BY:PQ005											
314510	Advanced Graphic Module No. 4 - Removal / Installation		HRS		4593.3			937.1			0
	7036410-1901	11017266	AFL		2210			389			0
			MOS		139.9			19 Mar 2011			HONEYWELL
			MSC				O/C				
Airframe											
Notes: VERFIED BY:PQ005											
314521	Nic / Processor Module Battery No. 1 - Discard		HRS		5530.4			0			0
	7025879-400	B156	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			
			MSC				O/C				MANUFACTURE
Airframe											
314524	Nic / Processor Module Battery No. 2 - Discard		HRS		5530.4			0			0
	7025879-400	B179	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			
			MSC				O/C				MANUFACTURE
Airframe											

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
314527 Airframe	Nic / Processor Module Battery No. 3 - Discard 7025879-400 B115	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 MANUFACTURE
314530 Airframe	Nic / Processor Module Battery No. 4 - Discard 7025879-400 B189	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 MANUFACTURE
314533 Airframe	Nic / Processor Module Battery No. 5 - Discard 7025879-400 B130	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 MANUFACTURE
314536 Airframe	Nic / Processor Module Battery No. 6 - Discard 7025879-400 0780	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 MANUFACTURE
315001 Airframe	Central Warning System (Including Audio) - Operational Test 052000-1A,200100	HRS AFL MOS [HRS: +50/-50]		6.5 2 .2		500	5523.9 2597 11 Nov 2022	6023.9	6073.9	0 0
315005 Airframe	Switch, Alt Decompression Annu PN SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
315203 Airframe	Warn Inhibit Panel - Operational Test	HRS AFL MOS MSC		2640.5 1094 90.2		 O/C	2889.9 1505 09 May 2015			0 0
315610 Airframe	Checklist - Operational Test	HRS AFL MOS MSC		2640.5 1094 90.2		 O/C	2889.9 1505 09 May 2015			0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
316001	Display Controller No. 1 - Removal / Installation 7007540-809 06122380	HRS AFL MOS MSC		3246.1 1432 107.7		 O/C	2284.3 1167 25 Nov 2013			0 0 HONEYWELL
Airframe										
Notes: VERFIED BY:PQ005										
316002	Display Controller No. 2 - Removal / Installation 7007540-809 04122073	HRS AFL MOS MSC		2367 954 73.1		 O/C	3163.4 1645 14 Oct 2016			0 0
Airframe										
316003	Controller, Display - OPS Test	HRS AFL MOS MSC		2367 954 72.3		 O/C	3163.4 1645 07 Nov 2016			0 0
Airframe										
316004	Panel, Display Units Dimmer 7007543-903 08031276	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 HONEYWELL HPG
Airframe										
316010	Cursor Control Device (Left) - Removal / Installation 1159SCF555-9 0442	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										
Notes: REV.E										
316013	Cursor Control Device (Right) - Removal / Installation 1159SCF555-11 0446	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										
Notes: REV.E										
316021	Display Unit No. 1 - Removal / Installation 7028140-901 06021563	HRS AFL MOS MSC		4666.2 2264 143.5		 O/C	864.2 335 02 Dec 2010			0 0 HONEYWELL
Airframe										
Notes: VERFIED BY:PQ005										

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Description: Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
316022	Display Unit No. 2 - Removal / Installation		HRS		5530.4			0			0
	7028140-901	08033140	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			HONEYWELL
Airframe			MSC				O/C				
Notes: VERFIED BY:PQ005											
316023	Display Unit No. 3 - Removal / Installation		HRS		2486.2			3044.2			0
	7028140-911	13047757	AFL		1025			1574			0
			MOS		78.3			06 May 2016			HONEYWELL
Airframe			MSC				O/C				
Notes: VERFIED BY:PQ005											
316024	Display Unit No. 4 - Removal / Installation		HRS		5530.4			0			0
	7028140-901	08033144	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			HONEYWELL
Airframe			MSC				O/C				
Notes: VERFIED BY:PQ005											
316027	Electronic Display System - Return to Service Test		HRS		2640.5			2889.9			0
			AFL		1094			1505			0
			MOS		90.4			04 May 2015			
Airframe			MSC				O/C				
316201	Display Unit Manual Reversion - Operational Test		HRS		190.2		1500	5340.2	6840.2	6890.2	0
			AFL		71			2528			0
			MOS		6.1			13 May 2022			
Airframe	052000-3A,200103		[HRS: +50/-50]								
316203	Mcdu Capability to Display Standby Engine Instruments - Operational Test		HRS		2640.5			2889.9			0
			AFL		1094			1505			0
			MOS		90.4			05 May 2015			
Airframe			MSC				O/C				
316205	Dfdr Fail Message - Operational Test		HRS		190.2			5340.2			0
			AFL		71			2528			0
			MOS		6.1		24	12 May 2022	31 May 2024	30 Jun 2024	
Airframe	200202		[End Of Month Item] [MOS: +1m/-1m]								

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
316206	Configuration Message - Operational Test	HRS		957.2			4573.2			0
		AFL		362			2237			0
		MOS		29.1		36	12 Jun 2020	30 Jun 2023	31 Jul 2023	
Airframe	052000-3C,200203	[End Of Month Item] [MOS: +1m/-1m]								
316300	Cursor Control Device - Operational Test	HRS		5530.4			0			0
		AFL		2599			0			0
		MOS		174.6			28 Apr 2008			
Airframe		MSC				O/C				
319010	Planeview Operational Software - Top Level System	HRS		882.2			4648.2			0
	EB7031236-00424 UCN35682255	AFL		304			2295			0
		MOS	TSN:5	23.3			07 Dec 2020			
Airframe		MSC				O/C				
319011	Planeview System Charts - Update	HRS		6.5			5523.9			0
		AFL		2			2597			0
		DATE		5 d		14d	11 Nov 2022	25 Nov 2022		
Airframe										
Notes: UPDATED BY PILOT										
319012	CD, Planeview Operational Software	HRS		882.2			4648.2			0
	MM7033384-027 UCN35682255	AFL		304			2295			0
		MOS	TSN:5	23.3			07 Dec 2020			
Airframe		MSC				O/C				
319015	Planeview Options Data Software - Top Level System	HRS		866.2			4664.2			0
	TT60002649-40362 4123	AFL		299			2300			0
		MOS	TSN:2	22.5			31 Dec 2020			
Airframe		MSC				O/C				
319017	CD, Options Data Software	HRS		866.2			4664.2			0
	DM60002649-40362 4123	AFL		299			2300			0
		MOS	TSN:2	22.5			31 Dec 2020			
Airframe		MSC				O/C				
319020	Electronic Checklist Software - Top Level System	HRS		882.2			4648.2			0
	GVPV0104000007L.ECL 13/DEC/2019	AFL		304			2295			0
		MOS		23.3			07 Dec 2020			
Airframe		MSC				O/C				

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
319022	CD, Electronic Checklist Media GVPV0104000007L.ECL 13 DEC 2019	HRS AFL MOS MSC		882.2 304 23.3		 O/C	4648.2 2295 07 Dec 2020			0 0
Airframe										
319025	Settings / Rigging Software - Top Level System 4123VQBZM OX424402 17/DEC/2015	HRS AFL MOS MSC		882.2 304 26		 O/C	4648.2 2295 16 Sep 2020			0 0
Airframe										
319027	CD, Settings / Rigging Media 4123 VQBZM OX424402 17 DEC 2015	HRS AFL MOS MSC		882.2 304 23.3		 O/C	4648.2 2295 07 Dec 2020			0 0
Airframe										
319030	Cmc Diagnostic Software - Top Level System GIV_912_00424_01_06042 NSN 0	HRS AFL MOS MSC		882.2 304 23.3		 O/C	4648.2 2295 07 Dec 2020			0 0
Airframe										
319032	CD, Cmc Diagnostic Media GIV_912_00424_01_06042 NSN 0	HRS AFL MOS MSC		882.2 304 23.3		 O/C	4648.2 2295 07 Dec 2020			0 0
Airframe										
319040	CD, Airline Modifiable Information 69003083-501 SATCOM DIRECT	HRS AFL MOS MSC		882.2 304 23.3		 O/C	4648.2 2295 07 Dec 2020			0 0
Airframe										
Notes: REF GIVX-GER-9934 REV X 08/08/2016										
319044	Programmable CAS Software - Top Level System 370CE68D 4 APR 2007	HRS AFL MOS MSC		2640.5 1094 89.8		 O/C	2889.9 1505 22 May 2015			0 0
Airframe										
32 - Landing Gear										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
320009	Main Landing Gear (Left) Corrosion Inhibiting Compound Reapplication	HRS		190.2			5340.2			0
		AFL		71			2528			0
		MOS		6.2	33	24	10 May 2022	30 Jun 2024*	31 Jul 2024	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe	200202									
320010	Main Landing Gear (Right) Corrosion Inhibiting Compound Reapplication	HRS		190.2			5340.2			0
		AFL		71			2528			0
		MOS		6.2	33	24	10 May 2022	30 Jun 2024*	31 Jul 2024	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe	200202									
320034	Nose Landing Gear Corrosion Inhibiting Compound Reapplication	HRS		190.2			5340.2			0
		AFL		71			2528			0
		MOS		6.2	32	24	11 May 2022	30 Jun 2024*	31 Jul 2024	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe	200202									
320037	Nose Landing Gear Bungee - Lubrication	HRS		190.2			5340.2			0
		AFL		71			2528			0
		MOS		6.1		24	12 May 2022	31 May 2024	30 Jun 2024	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe	200202									
320038	Main Landing Gear Bungee (Left) - Lubrication	HRS		190.2			5340.2			0
		AFL		71			2528			0
		MOS		6.2	32	24	11 May 2022	30 Jun 2024*	31 Jul 2024	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe	200202									
320039	Main Landing Gear Bungee (Right) - Lubrication	HRS		190.2			5340.2			0
		AFL		71			2528			0
		MOS		6.2	32	24	11 May 2022	30 Jun 2024*	31 Jul 2024	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe	200202									
320101	Main Landing Gear Flow Regulator (Left) - Removal / Installation	HRS		5530.4			0			0
		AFL		2599			0			0
	159H10040-155 2764G02	MOS		174.6			28 Apr 2008			AIRLIFT HYDRAULICS INCORPORATED
		MSC				O/C				
Airframe										

Notes: Q306783

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
320102	Main Landing Gear Flow Regulator (Right) - Removal / Installation 159H10040-155 2766G02	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 AIRLIFT HYDRAULICS INCORPORATED
Airframe										
Notes: Q306783										
321001	Main Landing Gear (Left) - Removal / Installation 1159L47001-800-1 MA0521	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										
321002	Main Landing Gear (Right) - Removal / Installation 1159L40001-26 MA0522	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										
321003	Main Landing Gear and Components (Left) - Detailed Corrosion Inspection	HRS AFL MOS		882.2 304 24.4	 -21	 48	4648.2 2295 03 Nov 2020	 31 Oct 2024*	 30 Nov 2024	0 0
	[End Of Month Item] [MOS: +1m/-1m]									
Airframe	052000-4C,200204									
Notes: TW 553006CAL 12/16										
321004	Main Landing Gear and Components (Right) - Detailed Corrosion Inspection	HRS AFL MOS		882.2 304 23.4	 -52	 48	4648.2 2295 04 Dec 2020	 31 Oct 2024*	 30 Nov 2024	0 0
	[End Of Month Item] [MOS: +1m/-1m]									
Airframe	052000-4C,200204									
Notes: TW 553006CAL 12/16										
321007	Main Landing Gear Strut Assembly (Left) - Discard 1159L47001-800-1 MA0521	HRS AFL MOS		5530.4 2599 174.6		 20000 	0 0 28 Apr 2008	 20000 		0 0
Airframe										
321008	Main Landing Gear Strut Assembly (Right) - Discard 1159L40001-26 MA0522	HRS AFL MOS		5530.4 2599 174.6		 20000 	0 0 28 Apr 2008	 20000 		0 0
Airframe										

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Description: Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
321009	Main Landing Gear Structural Post (Left) - Discard 1159LM40126-7	MK0117	HRS AFL MOS		5530.4 2599 174.6		20000	0 0 28 Apr 2008	20000		0 0 AAR LANDING GEAR SERVICES
Airframe											
321010	Main Landing Gear Structural Post (Right) - Discard 1159LM40126-8	K7113	HRS AFL MOS	TSN:138.6 TSN:61	882.2 304 23.4		20000	4648.2 2295 04 Dec 2020	22234		0 0
Airframe											
321011	Main Landing Gear Structure Post (Left) - Restore 1159LM40126-7	MK0117	HRS AFL MOS		5530.4 2599 174.6		5000	0 0 28 Apr 2008	5000		0 0 AAR LANDING GEAR SERVICES
Airframe											
321012	Main Landing Gear Structure Post (Right) - Restore 1159LM40126-8	K7113	HRS AFL MOS	TSN:138.6 TSN:61	882.2 304 23.4		5000	4648.2 2295 04 Dec 2020	7234		0 0
Airframe											
321013	Pin, L MLG Fwd Trunnion 1159LM40853-3	MBM0289	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 AAR LANDING GEAR SERVICES
Airframe											
321014	Pin, R MLG Fwd Trunnion 1159LM40853-3	MBM0298	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 AAR LANDING GEAR SERVICES
Airframe											
321015	Main Landing Gear (Forward) Trunnion Pin (Left) - Restore 1159LM40853-3	ALP0366	HRS AFL MOS	 TSN:2	882.2 304 24.3		5000	4648.2 2295 06 Nov 2020	7295		0 0
Airframe											

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
321016 Airframe	Main Landing Gear (Forward) Trunnion Pin (Right) - Restore 1159LM40853-3 ALP0367	HRS AFL MOS	TSN:2	882.2 304 24.3		5000	4648.2 2295 06 Nov 2020	7295		0 0
321017 Airframe	Main Landing Gear Aft Trunnion Pin (Left) - Discard 1159LM40175-13 MBM0432	HRS AFL MOS		5530.4 2599 174.6		16500	0 0 28 Apr 2008	16500		0 0 AAR LANDING GEAR SERVICES
321018 Airframe	Main Landing Gear Aft Trunnion Pin (Right) - Discard 1159LM40175-13 MBM0430	HRS AFL MOS		5530.4 2599 174.6		16500	0 0 28 Apr 2008	16500		0 0 AAR LANDING GEAR SERVICES
321019 Airframe	Assy, L MLG Shock Strut Piston 1159LM30114-5 MK0378	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0
321020 Airframe	Assy, R MLG Shock Strut Piston 1159LM30114-5 MK0377	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0
321021 Airframe	Main Landing Gear Shock Absorber Piston Assembly (Left) - Discard 1159LM30114-5 MK0378	HRS AFL MOS		5530.4 2599 174.6		20000	0 0 28 Apr 2008	20000		0 0 PRECISION MACHINE OF SAVANNAH
321022 Airframe	Main Landing Gear Shock Absorber Piston Assembly (Right) - Discard 1159LM30114-5 MK0377	HRS AFL MOS		5530.4 2599 174.6		20000	0 0 28 Apr 2008	20000		0 0 PRECISION MACHINE OF SAVANNAH

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
321023 Airframe	Main Landing Gear Spindle Pin (Left) - Restore 1159LM40137-5 EXC0971	HRS AFL MOS	 TSN:8	2640.5 1094 89.9		5000	2889.9 1505 19 May 2015	6505		0 0 PRECISION MACHINE OF SAVANNAH
321024 Airframe	Main Landing Gear Spindle Pin (Right) - Restore 1159LM40137-5 EXC0973	HRS AFL MOS	 TSN:8	2640.5 1094 89.9		5000	2889.9 1505 19 May 2015	6505		0 0 PRECISION MACHINE OF SAVANNAH
321025 Airframe	Main Landing Gear (Left) - Rigging / Adjustment	HRS AFL MOS MSC		190.2 71 6.1		 O/C	5340.2 2528 13 May 2022			0 0
321026 Airframe	Main Landing Gear (Right) - Rigging / Adjustment	HRS AFL MOS MSC		190.2 71 6.1		 O/C	5340.2 2528 13 May 2022			0 0
321027 Airframe	Main Landing Gear Trunnion Pins (Left Forward) - Removal / Installation 1159LM40853-3 ALP0366	HRS AFL MOS MSC	 TSN:1	882.2 304 24.4		 O/C	4648.2 2295 03 Nov 2020			0 0
Notes: TW 569293CAL. 05/17										
321028 Airframe	Main Landing Gear Trunnion Pins (Right Forward) - Removal / Installation 1159LM40853-3 ALP0367	HRS AFL MOS MSC		882.2 304 23.4		 O/C	4648.2 2295 04 Dec 2020			0 0
Notes: TW 560293CAL 05/17										

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
Logbook Position	HW	SW									
	MM Ref										
	Ops Number(s)										
321029	Main Landing Gear Trunnion Pins (Left Aft) - Removal / Installation		HRS		882.2			4648.2			0
			AFL		304			2295			0
	1159LM40175-13	MBM0432	MOS		24.4			03 Nov 2020			
			MSC				O/C				
Airframe											
321030	Main Landing Gear Trunnion Pins (Right Aft) - Removal / Installation		HRS		882.2			4648.2			0
			AFL		304			2295			0
	1159LM40175-13	MBM0430	MOS		23.4			04 Dec 2020			
			MSC				O/C				
Airframe											
321031	Structural Post, L MLG		HRS	TSN:4648.2	882.2			4648.2			0
	1159LM40126-7	MK0117	AFL	TSN:2295	304			2295			0
			MOS	TSN:151	24.4			04 Nov 2020			
			MSC				O/C				
Airframe											
321032	Structural Post, R MLG		HRS	TSN:138.6	882.2			4648.2			0
	1159LM40126-8	K7113	AFL	TSN:61	304			2295			0
			MOS		23.3			08 Dec 2020			
			MSC				O/C				
Airframe											
321033	Main Landing Gear Spindle Pin (Left) - Removal / Installation		HRS	TSN:1758.3	882.2			4648.2			0
			AFL	TSN:790	304			2295			0
	1159LM40137-5	EXC0971	MOS	TSN:74	24.4			03 Nov 2020			
			MSC				O/C				
Airframe											
321034	Main Landing Gear Spindle Pin (Right) - Removal / Installation		HRS	TSN:1758.3	882.2			4648.2			0
			AFL	TSN:790	304			2295			0
	1159LM40137-5	EXC0973	MOS	TSN:75	23.4			04 Dec 2020			
			MSC				O/C				
Airframe											
321039	Main Landing Gear Sponson Bores (Left) - Structural Inspection		HRS		5530.4			0			0
			AFL		2599		5000	0	5000		0
			MOS		174.6			28 Apr 2008			
Airframe											

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
321040 Airframe	Main Landing Gear Sponson Bores (Right) - Structural Inspection	HRS AFL MOS		5530.4 2599 174.6		5000	0 0 28 Apr 2008	5000		0 0
321041 Airframe	Main Landing Gear Assembly (Left) - Restore 1159L40001-27 SN-UNKNOWN	HRS AFL MOS		5530.4 2599 174.6		5000	0 0 28 Apr 2008	5000		0 0
321042 Airframe	Main Landing Gear Assembly (Right) - Restore 1159L40001-28 SN-UNKNOWN	HRS AFL MOS		5530.4 2599 174.6		5000	0 0 28 Apr 2008	5000		0 0
321050 Airframe	Main Landing Gear Door (Left) - Removal / Installation PN SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
321051 Airframe	Main Landing Gear Door (Right) - Removal / Installation PN SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
321052 Airframe	Main Landing Gear Door Fairing (Left) - Removal / Installation PN SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
321053 Airframe	Main Landing Gear Door Fairing (Right) - Removal / Installation PN SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
321201 Airframe	Main Landing Gear Shock Absorber (Left) - Servicing 052000-3C,200204	HRS AFL MOS		882.2 304 24.4		 48	4648.2 2295 03 Nov 2020	30 Nov 2024	31 Dec 2024	0 0
	[End Of Month Item] [MOS: +1m/-1m]									

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
321202	Main Landing Gear Shock Absorber (Right) - Servicing	HRS		882.2			4648.2			0
		AFL		304			2295			0
		MOS		25		48	17 Oct 2020	31 Oct 2024	30 Nov 2024	
Airframe	052000-3C,200204	[End Of Month Item] [MOS: +1m/-1m]								
321203	Main Landing Gear Shock Absorber Cylinder Assembly (Left) - Discard 1159L40100-15 MK0361	HRS		5530.4			0			0
		AFL		2599		20000	0	20000		0
		MOS		174.6			28 Apr 2008			GULFSTREAM - LONG BEACH
Airframe										
321204	Main Landing Gear Shock Absorber Cylinder Assembly (Right) - Discard 1159L40100-15 MK0360	HRS		5530.4			0			0
		AFL		2599		20000	0	20000		0
		MOS		174.6			28 Apr 2008			
Airframe										
321205	Main Gear Shock Absorber (Left) - Restore 1159L40100-15 MK0361	HRS		5530.4			0			0
		AFL		2599		5000	0	5000		0
		MOS		174.6			28 Apr 2008			GULFSTREAM - LONG BEACH
Airframe										
321206	Main Gear Shock Absorber (Right) - Restore 1159L40100-15 MK0360	HRS		5530.4			0			0
		AFL		2599		5000	0	5000		0
		MOS		174.6			28 Apr 2008			GULFSTREAM - LONG BEACH
Airframe										
321207	Main Landing Gear Shock Absorber (Left Upper) Attach Pin - Discard 1159LM40147-13 MBM0609	HRS		5530.4			0			0
		AFL		2599		20000	0	20000		0
		MOS		174.6			28 Apr 2008			AAR LANDING GEAR SERVICES
Airframe										
321208	Main Landing Gear Shock Absorber (Right Upper) Attach Pin - Discard 1159LM40147-13 MBM0595	HRS		5530.4			0			0
		AFL		2599		20000	0	20000		0
		MOS		174.6			28 Apr 2008			AAR LANDING GEAR SERVICES
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
321209 Logbook Position	Main Landing Gear Shock Strut Attach Pin (Left Upper) - Restore 1159LM40147-13 MBM0609	HRS AFL MOS		5530.4 2599 174.6		5000	0 0 28 Apr 2008	5000		0 0 AAR LANDING GEAR SERVICES
Airframe										
321210	Main Landing Gear Shock Strut Attach Pin (Right Upper) - Restore 1159LM40147-13 MBM0595	HRS AFL MOS		5530.4 2599 174.6		5000	0 0 28 Apr 2008	5000		0 0 AAR LANDING GEAR SERVICES
Airframe										
321211	Main Landing Gear Shock Absorber (Left Lower to Universal) Attach Pin - Discard 1159LM40147-13 MBM0776	HRS AFL MOS		5530.4 2599 174.6		20000	0 0 28 Apr 2008	20000		0 0
Airframe										
321212	Main Landing Gear Shock Absorber (Right Lower to Universal) Attach Pin - Discard 1159LM40147-13 ALP1295	HRS AFL MOS	TSN:2	2367 954 73.1		20000	3163.4 1645 14 Oct 2016	21645		0 0
Airframe										
321213	Main Landing Gear Shock Strut Attach Pin (Left Lower) - Restore 1159LM40147-13 MBM0776	HRS AFL MOS		5530.4 2599 174.6		5000	0 0 28 Apr 2008	5000		0 0 AAR LANDING GEAR SERVICES
Airframe										
321214	Main Landing Gear Shock Strut Attach Pin (Right Lower) - Restore 1159LM40147-13 ALP1295	HRS AFL MOS	TSN:2	2367 954 73.1		5000	3163.4 1645 14 Oct 2016	6645		0 0
Airframe										
321215	Nut, Main Landing Gear Shock Strut Cylinder (Left) 1159LM20112-11 341	HRS AFL MOS MSC		2640.5 1094 89.8		O/C	2889.9 1505 21 May 2015			0 0
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
321216 Airframe	Nut, Main Landing Gear Shock Strut Cylinder (Right) 1159LM20112-11 330	HRS AFL MOS MSC		2640.5 1094 89.8		 O/C	2889.9 1505 21 May 2015			0 0
321217 Airframe	Main Landing Gear Shock Absorber (Left) - Removal / Installation 1159L40100-15 MK0360	HRS AFL MOS MSC	TSN:4648.2 TSN:2295 TSN:151	882.2 304 24.4		 O/C	4648.2 2295 03 Nov 2020			0 0
321218 Airframe	Main Landing Gear Shock Absorber (Right) - Removal / Installation 1159L40100-15 MK0361	HRS AFL MOS MSC	TSN:4648.2 TSN:2295 TSN:152	882.2 304 23.4		 O/C	4648.2 2295 04 Dec 2020			0 0
321219 Airframe	Cylinder, Lmg Strut 1159LM40110-15 MK0361	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 GOODRICH CORPORATION
321220 Airframe	Cylinder, Rmg Strut 1159LM40110-15 MK0360	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 GOODRICH CORPORATION
321221 Airframe	Piston, Lmg Strut 1159LM30114-5 MK0378	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 AIRLIFT HYDRAULICS INCORPORATED
321222 Airframe	Piston, Rmg Strut 1159LM30114-5 MK0377	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 AIRLIFT HYDRAULICS INCORPORATED

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
321225 Airframe	Main Landing Gear Shock Absorber (Left) - Repacking	HRS AFL MOS MSC		882.2 304 25		 O/C	4648.2 2295 17 Oct 2020			0 0
321228 Airframe	Main Landing Gear Axle Fitting Attach Pin (Left) Corrosion Inhibiting Compound Application - Servicing	HRS AFL MOS MSC		882.2 304 24.4		 O/C	4648.2 2295 03 Nov 2020			0 0
321230 Airframe	Main Landing Gear Shock Absorber (Right) - Repacking	HRS AFL MOS MSC		882.2 304 25		 O/C	4648.2 2295 17 Oct 2020			0 0
321232 Airframe	Main Landing Gear Axle Fitting Attach Pin (Right) Corrosion Inhibiting Compound Application - Servicing	HRS AFL MOS MSC		882.2 304 23.4		 O/C	4648.2 2295 04 Dec 2020			0 0
321235 Airframe	Main Landing Gear Axle Fitting (Left) Corrosion Inhibiting Compound Application - Servicing	HRS AFL MOS MSC		882.2 304 24.4		 O/C	4648.2 2295 03 Nov 2020			0 0
321236 Airframe	Main Landing Gear Axle Fitting (Right) Corrosion Inhibiting Compound Application - Servicing	HRS AFL MOS MSC		882.2 304 23.4		 O/C	4648.2 2295 04 Dec 2020			0 0
321239 Airframe	Main Landing Gear Shock Absorber (Left) Corrosion Inhibiting Compound Application - Servicing	HRS AFL MOS MSC		882.2 304 24.4		 O/C	4648.2 2295 03 Nov 2020			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
321240 Airframe	Main Landing Gear Shock Absorber (Right) Corrosion Inhibiting Compound Application - Servicing	HRS AFL MOS MSC		882.2 304 23.4		O/C	4648.2 2295 04 Dec 2020			0 0
321243 Airframe Notes: REF 13.36, 13.37 AND 13.14	Main Landing Gear Sidebrace Actuator Attach Pins and Trunnion AREA (Left) Corrosion Inhibiting Compound Application - Servicing	HRS AFL MOS MSC		882.2 304 24.4		O/C	4648.2 2295 03 Nov 2020			0 0
321244 Airframe Notes: REF 13.63, 13.37, AND 13.15	Main Landing Gear Sidebrace Actuator Attach Pins and Trunnion AREA (Right) Corrosion Inhibiting Compound Application - Servicing	HRS AFL MOS MSC		882.2 304 23.4		O/C	4648.2 2295 04 Dec 2020			0 0
321247 Airframe	Main Landing Gear Uplock Roller (Left) Corrosion Inhibiting Compound Application - Servicing	HRS AFL MOS MSC		882.2 304 24.4		O/C	4648.2 2295 03 Nov 2020			0 0
321248 Airframe	Main Landing Gear Uplock Roller (Right) Corrosion Inhibiting Compound Application - Servicing	HRS AFL MOS MSC		882.2 304 23.4		O/C	4648.2 2295 04 Dec 2020			0 0
321251 Airframe	Main Landing Gear Striker ARM (Left) Corrosion Inhibiting Compound Application - Servicing	HRS AFL MOS MSC		882.2 304 24.4		O/C	4648.2 2295 03 Nov 2020			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
321252 Airframe	Main Landing Gear Striker ARM (Right) Corrosion Inhibiting Compound Application - Servicing	HRS AFL MOS MSC		882.2 304 23.4		 O/C	4648.2 2295 04 Dec 2020			0 0
321255 Airframe	Nose Landing Gear Shock Strut and Axle Assembly Corrosion Inhibiting Compound Application - Servicing	HRS AFL MOS MSC		882.2 304 24		 O/C	4648.2 2295 16 Nov 2020			0 0
321256 Airframe	Nose Landing Gear Trunnion Assembly Corrosion Inhibiting Compound Application - Servicing	HRS AFL MOS MSC		882.2 304 24		 O/C	4648.2 2295 16 Nov 2020			0 0
321259 Airframe	Nose Landing Gear Truss Brace Assembly Corrosion Inhibiting Compound Application - Servicing	HRS AFL MOS MSC		882.2 304 24		 O/C	4648.2 2295 16 Nov 2020			0 0
321260 Airframe	Nose Landing Gear Upper Trunnion Attach Pins Corrosion Inhibiting Compound Application - Servicing	HRS AFL MOS MSC		882.2 304 24		 O/C	4648.2 2295 16 Nov 2020			0 0
321263 Airframe	Nose Landing Gear Upper Drag Brace Attach Pins Corrosion Inhibiting Compound Application - Servicing	HRS AFL MOS MSC		882.2 304 24		 O/C	4648.2 2295 16 Nov 2020			0 0
321264 Airframe	Nose Landing Gear Striker Arms Corrosion Inhibiting Compound Application - Servicing	HRS AFL MOS MSC		882.2 304 24		 O/C	4648.2 2295 16 Nov 2020			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
321265 Logbook Position	Main Landing Gear Door ROD Ends (Left) Corrosion Inhibiting Compound Application	HRS AFL MOS MSC		882.2 304 23		 O/C	4648.2 2295 15 Dec 2020			0 0
Airframe										
321266 Logbook Position	Main Landing Gear Door ROD Ends (Right) Corrosion Inhibiting Compound Application	HRS AFL MOS MSC		882.2 304 23		 O/C	4648.2 2295 15 Dec 2020			0 0
Airframe										
321272 Logbook Position	Main Landing Gear Shock Absorber (Left Universal to Axle Fitting) Attach Pin - Discard 1159LM40147-13 ALP2174	HRS AFL MOS	 TSN:24	882.2 304 24.3		 20000 	4648.2 2295 06 Nov 2020	 22295 		0 0
Airframe										
321273 Logbook Position	Main Landing Gear Shock Absorber (Right Universal to Axle Fitting) Attach Pin - Discard 1159LM40147-13 ALP2604	HRS AFL MOS	 TSN:7	882.2 304 24.3		 20000 	4648.2 2295 06 Nov 2020	 22295 		0 0
Airframe										
321276 Logbook Position	Main Landing Gear Shock Absorber Cylinder / Piston (Left) - Removal / Installation 1159LM30114-5 MK0378	HRS AFL MOS MSC		882.2 304 24.9		 O/C	4648.2 2295 20 Oct 2020			0 0
Airframe										
321277 Logbook Position	Main Landing Gear Shock Absorber Cylinder / Piston (Right) - Removal / Installation 1159LM30114-5 MK0377	HRS AFL MOS MSC		882.2 304 23.4		 O/C	4648.2 2295 04 Dec 2020			0 0
Airframe										
321301 Logbook Position	Main Landing Gear Axle Fitting (Left) - Discard 1159LM40140-7 ZKM0049	HRS AFL MOS	TSN:1793.1 TSN:656 	882.2 304 24.3		 20000 	4648.2 2295 06 Nov 2020	 21639 		0 0
Airframe										

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
Logbook Position	HW	SW									
	MM Ref										
	Ops Number(s)										
321302	Main Landing Gear Axle Fitting (Right) - Discard		HRS	TSN:1720.1	882.2			4648.2			0
	1159LM40140-7	ZKM0230	AFL	TSN:1126	304		20000	2295	21169		0
			MOS		24.8			22 Oct 2020			
Airframe											
321303	Main Landing Gear Axle (Left) - Restore		HRS	TSN:1793.1	882.2			4648.2			0
	1159LM40140-7	ZKM0049	AFL	TSN:656	304		5000	2295	7295		0
			MOS		24.3			06 Nov 2020			
Airframe											
321304	Main Landing Gear Axle (Right) - Restore		HRS	TSN:1720.1	882.2			4648.2			0
	1159LM40140-7	ZKM0230	AFL	TSN:1126	304		5000	2295	7295		0
			MOS		24.8			22 Oct 2020			
Airframe											
321305	Main Landing Gear Axle Fitting Attach Pin (Left) - Removal / Installation		HRS		882.2			4648.2			0
			AFL		304			2295			0
	1159LM40148-5	ALP0298	MOS	TSN:8	24.3			06 Nov 2020			
			MSC				O/C				
Airframe											
321306	Main Landing Gear Axle Fitting Attach Pin (Right) - Removal / Installation		HRS		3804			1726.4			0
			AFL		1763			836			0
	1159LM40148-101	00431	MOS	TSN:12	122.9			20 Aug 2012			PRECISION MACHINE OF SAVANNAH
			MSC				O/C				
Airframe											
321307	Main Landing Gear Knee Pin (Left) - Restore		HRS		5530.4			0			0
	1159LM50148-5	CFN5061	AFL		2599		5000	0	5000		0
			MOS		174.6			28 Apr 2008			
Airframe											
321308	Main Landing Gear Knee Pin (Right) - Restore		HRS		3804			1726.4			0
	1159LM50148-101	00431	AFL		1763		5000	836	5836		0
			MOS	TSN:12	122.9			20 Aug 2012			
Airframe											

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
321309 Airframe	Main Landing Gear Axle Fitting (Left) - Removal / Installation 1159LM40140-7 ZKM0049	HRS AFL MOS MSC		882.2 304 24.4		 O/C	4648.2 2295 03 Nov 2020			0 0
321310 Airframe	Main Landing Gear Axle Fitting (Right) - Removal / Installation 1159LM40140-7 ZKM0230	HRS AFL MOS MSC		882.2 304 23.4		 O/C	4648.2 2295 04 Dec 2020			0 0
321323 Airframe	Pin Assy, Uplock Roller (Left) 1159LM40159-3 ALP0806	HRS AFL MOS MSC	 TSN:8	882.2 304 24.3		 O/C	4648.2 2295 06 Nov 2020			0 0
321324 Airframe	Pin Assy, Uplock Roller (Right) 1159LM40159-3 ALP0073	HRS AFL MOS MSC	 TSN:15	2640.5 1094 89.8		 O/C	2889.9 1505 21 May 2015			0 0
321403 Airframe	Main Landing Gear Sponson Rib Assembly (Left) - Discard 1159WM20023-23 NSN4123	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
321404 Airframe	Main Landing Gear Sponson Rib Assembly (Right) - Discard 1159WM20023-24 NSN4123	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
321405 Airframe	Main Landing Gear Side Brace Pin (Left) - Restore 1159LM40164-13 TEC0028	HRS AFL MOS		5530.4 2599 174.6		 5000 	0 0 28 Apr 2008	 5000 		0 0 STORK MMA LABORATORIES INC.

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
321406 Airframe	Main Landing Gear Side Brace Pin (Right) - Restore 1159LM40164-13 ALP0275	HRS AFL MOS	TSN:4	957.2 362 29.1		5000	4573.2 2237 12 Jun 2020	7237		0 0
321407 Airframe	Main Landing Gear Side Brace Actuator (Left) - Restore 1159LH4100-147 A1545	HRS AFL MOS		882.3 304 26.5		5000	4648.1 2295 31 Aug 2020	5000		0 0
321408 Airframe	Main Landing Gear Side Brace Actuator (Right) - Restore 1159L41000-147 A733	HRS AFL MOS		882.3 304 26.5		5000	4648.1 2295 31 Aug 2020	5000		0 0
321601 Airframe	Antiskid / Brake Temperature Monitor System Harness (Left) - Removal / Installation PN SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0
321602 Airframe	Antiskid / Brake Temperature Monitor System Harness (Right) - Removal / Installation PN SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0
321805 Airframe	Nose and Main Landing Gear and Doors - Zonal Inspection 052000-1A	HRS AFL MOS [HRS: +50/-50]		6.5 2 .2		500	5523.9 2597 11 Nov 2022	6023.9	6073.9	0 0
321807 Airframe	Nose Landing Gear and Attachments - General Visual Inspection	HRS AFL MOS [HRS: +50/-50]		6.5 2 .2		500	5523.9 2597 11 Nov 2022	6023.9	6073.9	0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
322001 Airframe	Nose Landing Gear Assembly - Discard 1159L50004-21 PLT0240	HRS AFL MOS		5530.4 2599 174.6		32750	0 0 28 Apr 2008	32750		0 0 GENERAL DYNAMICS AVIATIONS SERVICES
322002 Airframe	Nose Landing Gear - Removal / Installation 1159L50004-21 PLT0240	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0 GENERAL DYNAMICS AVIATIONS SERVICES
322003 Airframe 052000-3C,200204 Notes: TW 554640 DUE 5-17TW 558136 DUE 8-17	Nose Landing Gear Components - Detailed Corrosion Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		882.2 304 24	-30	48	4648.2 2295 16 Nov 2020	31 Oct 2024*	30 Nov 2024	0 0
322004 Airframe	Nose Landing Gear Door Actuator - Discard 1159H20261-11 55-1505GTX	HRS AFL MOS	TSN:7275.5 TSN:2529	4003 1871 126.1		13000	1527.4 728 14 May 2012	11199		0 0
322200 Airframe	Nose Landing Gear Assembly - Restore 1159L50004-21 PLT0240	HRS AFL MOS		5530.4 2599 174.6		5000	0 0 28 Apr 2008	5000		0 0
322201 Airframe	Nose Landing Gear Shock Strut - Removal / Installation 1159L50500-13 PLT0240	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0 GOODRICH CORPORATION
322202 Airframe 052000-3C,200204	Nose Landing Gear Shock Strut - Servicing	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		882.2 304 24		48	4648.2 2295 16 Nov 2020	30 Nov 2024	31 Dec 2024	0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
322204 Airframe	Nose Landing Gear Shock Strut - Discard 1159L50500-13 PLT0240	HRS AFL MOS		5530.4 2599 174.6		20000	0 0 28 Apr 2008	20000		0 0
322205 Airframe	Nose Landing Gear Shock Strut - Restore 1159L50500-13 PLT0240	HRS AFL MOS		5530.4 2599 174.6		5000	0 0 28 Apr 2008	5000		0 0
322206 Airframe	Nose Landing Gear Shock Strut Cylinder Assembly - Discard 1159LM50700-15 PLT0208	HRS AFL MOS		5530.4 2599 174.6		20000	0 0 28 Apr 2008	20000		0 0
322207 Airframe	Nose Landing Gear Upper Torque ARM - Removal / Installation 1159LM50548-1 WH7075	HRS AFL MOS MSC		3021.1 1338 102.3		O/C	2509.3 1261 07 May 2014			0 0
322208 Airframe	Nose Landing Gear Lower Torque ARM - Removal / Installation 1159LM30553-3 PLT0372	HRS AFL MOS MSC	TSN:2509.3 TSN:1261 TSN:73	3021.1 1338 102.3		O/C	2509.3 1261 07 May 2014			0 0 GOODRICH CORPORATION
322301 Airframe	Nose Landing Gear Axle Fitting - Removal / Installation 1159LM50521-11 PLT0268	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0 AIRLIFT HYDRAULICS INCORPORATED
322304 Airframe	Nose Landing Gear Axle Assembly Piston - Discard 1159LM50521 SN-UNKNOWN	HRS AFL MOS		5530.4 2599 174.6		32750	0 0 28 Apr 2008	32750		0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
322305 Airframe	Nose Landing Gear Axle Fitting - Restore 1159LM50521-11 PLT0268	HRS AFL MOS		5530.4 2599 174.6		5000	0 0 28 Apr 2008	5000		0 0 AIRLIFT HYDRAULICS INCORPORATED
322401 Airframe	Nose Landing Gear Trunnion - Discard 1159LM50690-3 PLT0310	HRS AFL MOS		5530.4 2599 174.6		22750	0 0 28 Apr 2008	22750		0 0 PRO-FAB, INC.
322402 Airframe	Nose Landing Gear Trunnion - Restore 1159LM50690-3 PLT0310	HRS AFL MOS		5530.4 2599 174.6		5000	0 0 28 Apr 2008	5000		0 0 PRO-FAB, INC.
322403 Airframe	Nose Landing Gear Drag Brace - Discard 1159LM50585-1 PLT0311	HRS AFL MOS		5530.4 2599 174.6		32750	0 0 28 Apr 2008	32750		0 0 B F GOODRICH AEROSPACE
322404 Airframe	Nose Landing Gear Drag Brace - Restore 1159LM50585-1 PLT0311	HRS AFL MOS		5530.4 2599 174.6		5000	0 0 28 Apr 2008	5000		0 0 B F GOODRICH AEROSPACE
322405 Airframe	Nose Landing Gear Trunnion Pin (Left) - Discard 1159LM50611-3 PLT0092	HRS AFL MOS		5530.4 2599 174.6		32750	0 0 28 Apr 2008	32750		0 0 AAR LANDING GEAR SERVICES
322406 Airframe	Nose Landing Gear Trunnion Pins (Left) - Restore 1159LM50611-3 PLT0092	HRS AFL MOS		5530.4 2599 174.6		5000	0 0 28 Apr 2008	5000		0 0 AAR LANDING GEAR SERVICES

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
322407 Airframe	Nose Landing Gear Trunnion Pin (Right) - Discard 1159LM50613-3 PLT0131	HRS AFL MOS		5530.4 2599 174.6		32750	0 0 28 Apr 2008	32750		0 0 PRECISION MACHINE OF SAVANNAH
322408 Airframe	Nose Landing Gear Trunnion Pins (Right) - Restore 1159LM50613-3 PLT0131	HRS AFL MOS		5530.4 2599 174.6		5000	0 0 28 Apr 2008	5000		0 0 PRECISION MACHINE OF SAVANNAH
322409 Airframe	Nose Landing Gear Truss Brace Assembly - Discard 1159LM40802-5 PLT1073	HRS AFL MOS		5530.4 2599 174.6		32750	0 0 28 Apr 2008	32750		0 0 DFP MANUFACTURING CORP.
322410 Airframe	Nose Landing Gear Truss Brace Assembly - Restore 1159LM40802-5 PLT1073	HRS AFL MOS		5530.4 2599 174.6		5000	0 0 28 Apr 2008	5000		0 0 GOODRICH CORPORATION
322411 Airframe	Nose Landing Gear Upper Drag Brace Pin - Discard 1159LM40588-19 PLT1504	HRS AFL MOS		5530.4 2599 174.6		5000	0 0 28 Apr 2008	5000		0 0 GOODRICH CORPORATION
322412 Airframe	Upper NLG Drag Brace Pin - Restore 1159LM40588-19 PLT1504	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0

Notes: INTERVAL REMOVED AT REV 22.

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
322413 Airframe	Nose Landing Gear Lower Drag Brace Pin - Discard 1159LM50587-3 PLT0114	HRS AFL MOS		5530.4 2599 174.6		20000	0 0 28 Apr 2008	20000		0 0 B F GOODRICH AEROSPACE
322414 Airframe	Nose Landing Gear Lower Drag Brace Pin - Restore 1159LM50587-3 PLT0114	HRS AFL MOS		5530.4 2599 174.6		5000	0 0 28 Apr 2008	5000		0 0 B F GOODRICH AEROSPACE
322415 Airframe	Nose Landing Gear Actuator Attach Pin - Discard 1159LM40583-15 PLT0104	HRS AFL MOS		5530.4 2599 174.6		32750	0 0 28 Apr 2008	32750		0 0 PRECISION MACHINE OF SAVANNAH
322416 Airframe	Nose Landing Gear Actuator Attach Pin - Restore 1159LM40583-15 PLT0104	HRS AFL MOS		5530.4 2599 174.6		5000	0 0 28 Apr 2008	5000		0 0 PRECISION MACHINE OF SAVANNAH
322417 Airframe	Nose Landing Gear Strut / Trunnion Pins - Discard 1159LM50568-13 PLT0267	HRS AFL MOS		5530.4 2599 174.6		20000	0 0 28 Apr 2008	20000		0 0 B F GOODRICH AEROSPACE
322418 Airframe	Nose Landing Gear Strut Trunnion Pin - Restore 1159LM50568-13 PLT0267	HRS AFL MOS		5530.4 2599 174.6		5000	0 0 28 Apr 2008	5000		0 0 B F GOODRICH AEROSPACE
322419 Airframe	Nose Landing Gear Upper Torque ARM - Discard 1159LM50548-1 PLT0323	HRS AFL MOS		5530.4 2599 174.6		32750	0 0 28 Apr 2008	32750		0 0 B F GOODRICH AEROSPACE

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
322420 Airframe	Nose Landing Gear Upper Torque ARM - Restore 1159LM50548-1 PLT0323	HRS AFL MOS		5530.4 2599 174.6		5000	0 0 28 Apr 2008	5000		0 0 B F GOODRICH AEROSPACE
322421 Airframe	Nose Landing Gear Lower Torque ARM - Discard 1159LM30553-3 PLT0372	HRS AFL MOS		5530.4 2599 174.6		32750	0 0 28 Apr 2008	32750		0 0 GOODRICH CORPORATION
322422 Airframe	Nose Landing Gear Lower Torque ARM - Restore 1159LM30553-3 PLT0372	HRS AFL MOS		5530.4 2599 174.6		5000	0 0 28 Apr 2008	5000		0 0 GOODRICH CORPORATION
322424 Airframe	Nose Landing Gear Trunnion - Removal / Installation 1159LM50690-3 PLT0310	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 PRO-FAB, INC.
322425 Airframe	Nose Landing Gear Drag Brace - Removal / Installation 1159LM50585-1 PLT0311	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 B F GOODRICH AEROSPACE
322429 Airframe	Nose Landing Gear Fairing - Removal / Installation PN SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
322430 Airframe	Nose Landing Gear Bungee - Removal / Installation 159L10032-207 NSN	HRS AFL MOS MSC		190.2 71 6.1		 O/C	5340.2 2528 12 May 2022			0 0 N/A

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
322433 Logbook Position	Nose Landing Gear Truss Brace (Aft) - Removal / Installation 1159LM50806-1 PLT0199	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 GOODRICH CORPORATION
Airframe										
322436 Logbook Position	Nose Landing Gear Forward Truss Pin (Left Forward) - Removal / Installation 1159LM40565-3 PLT421091	HRS AFL MOS MSC	TSN:10	882.2 304 24		 O/C	4648.2 2295 16 Nov 2020			0 0
Airframe										
322437 Logbook Position	Nose Landing Gear Forward Truss Pin (Right Forward) - Removal / Installation 1159LM40565-3 PLT421187	HRS AFL MOS MSC	TSN:4	882.2 304 24		 O/C	4648.2 2295 16 Nov 2020			0 0
Airframe										
322438 Logbook Position	Nose Landing Gear Forward Truss Pin (Left Forward) - Discard 1159LM40565-3 PLT421091	HRS AFL MOS	TSN:10	882.2 304 24		 20000 	4648.2 2295 16 Nov 2020	 22295 		0 0
Airframe										
322439 Logbook Position	Nose Landing Gear Forward Truss Pin (Right Forward) - Discard 1159LM40565-3 PLT421187	HRS AFL MOS	TSN:4	882.2 304 24		 20000 	4648.2 2295 16 Nov 2020	 22295 		0 0
Airframe										
322440 Logbook Position	Nose Landing Gear Forward Truss Pin (Left Aft) - Removal / Installation 1159LM40565-1 SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 GOODRICH CORPORATION
Airframe										
322441 Logbook Position	Nose Landing Gear Forward Truss Pin (Right Aft) - Removal / Installation 1159LM40565-1 SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
322442 Airframe	Nose Landing Gear Forward Truss Pin (Left Aft) - Discard 1159LM40565-1 SN-UNKNOWN	HRS AFL MOS		5530.4 2599 174.6		20000	0 0 28 Apr 2008	20000		0 0
322443 Airframe	Nose Landing Gear Forward Truss Pin (Right Aft) - Discard 1159LM40565-1 SN-UNKNOWN	HRS AFL MOS		5530.4 2599 174.6		20000	0 0 28 Apr 2008	20000		0 0
322501 Airframe	Nose Gear Trunnion Attach Fittings - Detailed Inspection	HRS AFL MOS		5530.4 2599 174.6		5000	0 0 28 Apr 2008	5000		0 0
322502 Airframe	Nose Landing Gear Vertical Drag Brace Fitting Lug - Ndt Inspection	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
322503 Airframe	Nose Landing Gear Horizontal Drag Brace Fitting Skin Attachment - Detailed Inspection	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
322504 Airframe	Nose Landing Gear Horizontal Drag Brace Fitting (Forward Attach) - Ndt Inspection	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
322505 Airframe	Nose Landing Gear Trunnion Fitting Lugs - Ndt Inspection	HRS AFL MOS		5530.4 2599 174.6		8000	0 0 28 Apr 2008	8000		0 0

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
322601	Nose Gear Electrical Harness - Removal / Installation		HRS		957.2			4573.2			0
	1159SCAV531-3	NSN	AFL		362			2237			0
			MOS	TSN:10	29.1			12 Jun 2020			
			MSC				O/C				
Airframe											
Notes: TQ WRENCH C/N: 554587 DUE: 07/2017											
322805	Valve, Park/Emerg Brake Bleed		HRS		5530.4			0			0
	1159SCH245-5	2759	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			PARKER HANNIFIN CORPORATION
			MSC				O/C				
Airframe											
323001	Landing Gear Emergency Extension Nitrogen Blow-Down Bottle - Removal / Installation		HRS		6.5			5523.9			0
	1159H500091-21	ALT603-11642	AFL		2			2597			0
			MOS		.2			11 Nov 2022			
			MSC				O/C				
Airframe											
323002	Landing Gear Emergency Extension Nitrogen Blow-Down Bottle - (Hydrostatic) Restore		HRS		439.3			5091.1			0
			AFL		157			2442			0
			MOS		12.1		60	14 Nov 2021	30 Nov 2026		
			[End Of Month Item]								HYDRO CHECK
Airframe											
Notes: PN: 1159SCH233-11 SN: <NONE>.											
323003	Landing Gear Blow-Down Bottle Pressure Gage - Removal / Installation		HRS		5530.4			0			0
	GP20-24	08-0222345	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			CUSTOM METAL WORKS
			MSC				O/C				
Airframe											
323005	Landing Gear Selector Panel - Removal / Installation		HRS	TSN:4.9	5525.5			4.9			0
	A-486-19	791	AFL	TSN:2	2597			2			0
			MOS	TSN:1	174.3			08 May 2008			NORTHERN FIBER GLASS SALES INC.
			MSC				O/C				
Airframe											

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
323008	Nose Landing Gear Hydraulic Flow Regulator - Removal / Installation	HRS		5530.4			0			0
		AFL		2599			0			0
	1159SCH218-7 1249	MOS		174.6			28 Apr 2008			PNEUDRAULICS INC
		MSC				O/C				
	Airframe									
323009	Landing Gear Hydraulic Selector / Dump Valve - Removal / Installation	HRS		5530.4			0			0
		AFL		2599			0			0
	1159SCH512-19 EFS0513	MOS		174.6			28 Apr 2008			KAISER FLUID TECHNOLOGIES
		MSC				O/C				
	Airframe									
323010	Transducer, Gear Emerg Press	HRS		5530.4			0			0
	1159SCAV600-1 HAL3839	AFL		2599			0			0
		MOS		174.6			28 Apr 2008			GULFSTREAM - LONG BEACH
		MSC				O/C				
	Airframe									
323011	Landing Gear Emergency Extension Nitrogen Blow-Down Bottle - Discard	HRS		6.5			5523.9			0
		AFL		2			2597			0
	1159H500091-21 ALT603-11642	MOS		.2		180	11 Nov 2022	30 Jun 2037		
		[End Of Month Item]								MANUFACTURE
	Airframe									
323021	Main Landing Gear Side Brace (Left) - Removal / Installation	HRS		882.2			4648.2			0
		AFL		304			2295			0
	1159L41000-147 A1545	MOS		24.4			03 Nov 2020			
		MSC				O/C				
	Airframe									
	Notes: TW 553006CAL 12/16									
323022	Main Landing Gear Side Brace (Right) - Removal / Installation	HRS		882.2			4648.2			0
		AFL		304			2295			0
	1159L41000-147 A733	MOS		23.4			04 Dec 2020			
		MSC				O/C				
	Airframe									
	Notes: TW 553006CAL 12/16									

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Description: Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
323033	Main Landing Gear Actuator Down Shuttle Valve (Left) - Removal / Installation		HRS		5530.4			0			0
			AFL		2599			0			0
	1159SCH223-7	0795	MOS		174.6			28 Apr 2008			TACTAIR FLUID CONTROLS INC
			MSC				O/C				
Airframe											
Notes: Q306783											
323034	Main Landing Gear Actuator Down Shuttle Valve (Right) - Removal / Installation		HRS		5530.4			0			0
			AFL		2599			0			0
	1159SCH223-7	0739	MOS		174.6			28 Apr 2008			TACTAIR FLUID CONTROLS INC
			MSC				O/C				
Airframe											
Notes: Q306783											
323039	Main Landing Gear Bungee (Left) - Removal / Installation		HRS	TSN:1579.3	190.2			5340.2			0
	1159L20251-3	NSN	AFL	TSN:646	71			2528			0
			MOS	TSN:48	6.1			12 May 2022			N/A
			MSC				O/C				
Airframe											
323040	Main Landing Gear Bungee (Right) - Removal / Installation		HRS		190.2			5340.2			0
			AFL		71			2528			0
	1159L47903-1	SN-UNKNOWN	MOS		6.1			12 May 2022			N/A
			MSC				O/C				
Airframe											
323041	Main Landing Gear Door Actuator (Left) - Removal / Installation		HRS		5530.4			0			0
			AFL		2599			0			0
	1159H20264-23	55-4123GT	MOS		174.6			28 Apr 2008			
			MSC				O/C				
Airframe											
323042	Main Landing Gear Door Actuator (Right) - Removal / Installation		HRS		5530.4			0			0
			AFL		2599			0			0
	1159H20264-24	55-4123GT	MOS		174.6			28 Apr 2008			GULFSTREAM SAV PROD-IPT
			MSC				O/C				
Airframe											
323043	Main Gear Door Actuator End CAP Fitting (Left) - Removal / Installation		HRS		5530.4			0			0
			AFL		2599			0			0
	1159HM20178	55-4123GT	MOS		174.6			28 Apr 2008			
			MSC				O/C				
Airframe											

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
323044	Main Gear Door Actuator End CAP Fitting (Right) - Removal / Installation 1159HM20178 55-4123GT	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										
323045	Main Gear Door Actuator End CAP Fitting (Left) - Discard 1159HM20178 55-4123GT	HRS AFL MOS		5530.4 2599 174.6		 9500	0 0 28 Apr 2008	 9500		0 0
Airframe										
Notes: INTERVAL ADDED AT TR 5-2										
323046	Main Gear Door Actuator End CAP Fitting (Right) - Discard 1159HM20178 55-4123GT	HRS AFL MOS		5530.4 2599 174.6		 9500	0 0 28 Apr 2008	 9500		0 0
Airframe										
Notes: INTERVAL ADDED AT TR 5-2										
323051	Main Landing Gear Uplock Actuator (Left) - Removal / Installation 1159H20263-13 55-4122GTA	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 GULFSTREAM SAV PROD-IPT
Airframe										
323052	Main Landing Gear Uplock Actuator (Right) - Removal / Installation 1159H20263-13 55-4122GTB	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 AIRLIFT HYDRAULICS INCORPORATED
Airframe										
323060	Nose Landing Gear Actuator - Removal / Installation 1159H20262-23 55-4123GT	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 GULFSTREAM SAV PROD-IPT
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
323061 Airframe	Nose Landing Gear Door Actuator - Removal / Installation 1159H20261-11 55-1505GTX	HRS AFL MOS MSC		4003 1871 126.1		 O/C	1527.4 728 14 May 2012			0 0 GENERAL DYNAMICS AVIATIONS SERVICES
Notes: VERIFIED BY Q307641										
323064 Airframe	Nose Landing Gear Retract Actuator ROD End - Removal / Installation 1159SCL567-3 2969	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 AIRLIFT HYDRAULICS INCORPORATE
323101 Airframe	Main Landing Gear Uplock Timer Valve (Left) - Removal / Installation 1159H20265-3 FAH7205	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 FRISBY AEROSPACE LLC.
323102 Airframe	Main Landing Gear Uplock Timer Valve (Right) - Removal / Installation 1159H20265-3 FAH7194	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 FRISBY AEROSPACE LLC.
323103 Airframe	Main Landing Gear Retract Timer Valve (Left) - Removal / Installation 1159H20265-1 FAH7223	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 GULFSTREAM SAV PROD-IPT
323104 Airframe	Main Landing Gear Retract Timer Valve (Right) - Removal / Installation 1159H20265-1 FAH7208	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 GULFSTREAM SAV PROD-IPT

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Description: Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
323201	Main Landing Gear Door Control Valve (Left) - Removal / Installation		HRS		5530.4			0			0
			AFL		2599			0			0
	1159SCH231-35	3723	MOS		174.6			28 Apr 2008			GULFSTREAM - LONG BEACH
			MSC				O/C				
Airframe											
323202	Main Landing Gear Door Control Valve (Right) - Removal / Installation		HRS		5530.4			0			0
			AFL		2599			0			0
	1159SCH231-35	3740	MOS		174.6			28 Apr 2008			GULFSTREAM - LONG BEACH
			MSC				O/C				
Airframe											
323401	Regulator, L/H Flow		HRS		5530.4			0			0
	1159SCH218-5	2230	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			PNEUDRAULICS INC
			MSC				O/C				
Airframe											
Notes: Q306783											
323402	Regulator, R/H Flow		HRS		5530.4			0			0
	1159SCH218-5	2231	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			PNEUDRAULICS INC
			MSC				O/C				
Airframe											
Notes: Q306783											
323403	Main Landing Gear Hydraulic Swivels (Left Upper) - Removal / Installation		HRS		5530.4			0			0
			AFL		2599			0			0
	1159H20270-5	55-4123GT	MOS		174.6			28 Apr 2008			GULFSTREAM SAV PROD-IPT
			MSC				O/C				
Airframe											
323404	Main Landing Gear Hydraulic Swivels (Right Upper) - Removal / Installation		HRS		5530.4			0			0
			AFL		2599			0			0
	1159H20270-6	55-4123GT	MOS		174.6			28 Apr 2008			GULFSTREAM SAV PROD-IPT
			MSC				O/C				
Airframe											

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
323405	Main Landing Gear Hydraulic Swivels (Left Lower) - Removal / Installation 1159H20271-5 55-4123GT	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										
323406	Main Landing Gear Hydraulic Swivels (Right Lower) - Removal / Installation 1159H20271-6 55-4122GT	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										
323407	Main Landing Gear Hydraulic Swivels (Left) LSA15-14J6S SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										
323408	Main Landing Gear Hydraulic Swivels (Right) LSA15-14J6S SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										
323501	Nose Landing Gear Uplock Timer - Removal / Installation 1159H20265-3 FAH7198	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 FRISBY AEROSPACE LLC.
Airframe										
323502	Nose Landing Gear Retract Timer - Removal / Installation 1159H20265-1 FAH7214	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 GULFSTREAM SAV PROD-IPT
Airframe										
323601	Nose Landing Gear Door Control Valve - Removal / Installation 1159SCH231-35 3711	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 GULFSTREAM - LONG BEACH
Airframe										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
323605	Nose Landing Gear Door Hydraulic Flow Regulator - Removal / Installation 1159SCH218-7 SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										
323700	Nose Landing Gear Sequencing Linkage - Check / Adjustment	HRS AFL MOS MSC		190.2 71 6.1		 O/C	5340.2 2528 13 May 2022			0 0
Airframe										
323701	Nose Landing Gear Uplock Actuator - Removal / Installation 1159H20260-13 55-5194GT	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 GULFSTREAM SAV PROD-IPT
Airframe										
Notes: Q307641										
323800	Nose Landing Gear Retract Actuator ROD End - Discard 1159SCL567-3 2969	HRS AFL MOS		5530.4 2599 174.6		 25000 	0 0 28 Apr 2008	25000		0 0
Airframe										
323801	Nose Landing Gear Hydraulic Swivel - Removal / Installation 7438-4 0544	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 TELEDYNE CONTROLS
Airframe										
323804	Nose Landing Gear Hydraulic Swivel LSA14-15C4S SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										
323805	Nose Landing Gear Hydraulic Swivel LSA14-15C4S SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
323806	Nose Landing Gear Hydraulic Swivel LSA15-14J6S SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										
323807	Nose Landing Gear Hydraulic Swivel LSA15-14J6S SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										
323900	Landing Gear - Functional Test	HRS AFL MOS MSC		190.2 71 6.1		 O/C	5340.2 2528 13 May 2022			0 0
Airframe										
Notes: REF MULTIMETER 556311 DATE CAL"D: 09/06/16 CAL DATE DUE: 09/17.SCALE PUSH/PULL: 560619CAL DUE: 04/17										
323901	Landing Gear Emergency Extension System - Functional Check	HRS AFL MOS		882.2 304 23.4		 36	4648.2 2295 04 Dec 2020	31 Dec 2023	31 Jan 2024	0 0
Airframe	052000-3C,200203	[End Of Month Item] [MOS: +1m/-1m]								
Notes: TW 558136, CAL DUE 8/17										
323902	Landing Gear Emergency Extension Bottle Pressure Gage - Inspection	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										
323904	Landing Gear Emergency Bottle AIR Release Control Valve - Removal / Installation 1159SCH234-5 V567	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										
323905	Landing Gear Emergency Extension Handle - Rigging	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
323906	Landing Gear Cycling - Operational Test	HRS AFL MOS MSC		190.2 71 6.1		 O/C	5340.2 2528 13 May 2022			0 0
Airframe										
324001	Nose Wheel Assembly (Left) - Removal / Installation 1159L50400-37 5093LY	HRS AFL MOS MSC		190.2 71 6.1		 O/C	5340.2 2528 13 May 2022			0 0 N/A
Airframe										
Notes: TW: 551668CAL DUE: 08/17										
324002	Nose Wheel Assembly (Right) - Removal / Installation 1159L50400-37 5045GC	HRS AFL MOS MSC		190.2 71 6.1		 O/C	5340.2 2528 13 May 2022			0 0 N/A
Airframe										
Notes: TQ WRENCH: 551668CAL: 08/17										
324003	Main Wheel (Left Outboard) - Removal / Installation 1159SCL472-5 APR06-0304	HRS AFL MOS MSC		17 5 .9		 O/C	5513.4 2594 18 Oct 2022			0 0
Airframe										
Notes: TW: 557279CAL DUE: 03/17TW: 567921CAL DUE: 09/17										
324004	Main Wheel (Left Inboard) - Removal / Installation 1159SCL472-5 AUG18-2429	HRS AFL MOS MSC		613.8 204 15.9		 O/C	4916.6 2395 18 Jul 2021			0 0
Airframe										
Notes: TW: 557279CAL DUE: 03/17TW: 567921CAL DUE: 09/17										
324005	Main Wheel (Right Inboard) - Removal / Installation 1159SCL472-5 OCT11-1429	HRS AFL MOS MSC		145.7 55 4.5		 O/C	5384.7 2544 01 Jul 2022			0 0
Airframe										
Notes: TQ WRENCH: 557279 CAL: 03/17TQ WRENCH: 567921 CAL: 09/17										
324006	Main Wheel (Right Outboard) - Removal / Installation 1159SCL472-5 MAY19-2512	HRS AFL MOS MSC		613.8 204 15.9		 O/C	4916.6 2395 18 Jul 2021			0 0
Airframe										
Notes: TQ WRENCH: 557279 CAL: 03/17TQ WRENCH: 567921 CAL: 09/17										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
324007 Airframe	Nose Wheel Bearings (Left) - Inspection / Pack	HRS AFL MOS MSC		190.2 71 6.1		 O/C	5340.2 2528 13 May 2022			0 0
Notes: PN: 1159L50400-37 SN: 5093LY. REF. 8130 20161017084240 AND SC480706 ITEM #50.1 FOR WORK PERFORMED										
324008 Airframe	Nose Wheel Bearings (Right) - Inspection / Pack	HRS AFL MOS MSC		190.2 71 6.1		 O/C	5340.2 2528 13 May 2022			0 0
Notes: PN: 1159L50400-37 SN: 5045GC. REF. FAA FORM 8130-3 - 20161017135440 AND SC480706 ITEM 51.1.7										
324009 Airframe	Main Wheel Bearings (Left Outboard) - Inspection / Pack	HRS AFL MOS MSC		613.8 204 15.9		 O/C	4916.6 2395 18 Jul 2021			0 0
Notes: PN: 1159L47003-5 SN: APR07-0540.										
324010 Airframe	Main Wheel Bearings (Left Inboard) - Inspection / Pack	HRS AFL MOS MSC		613.8 204 15.9		 O/C	4916.6 2395 18 Jul 2021			0 0
324011 Airframe	Main Wheel Bearings (Right Inboard) - Inspection / Pack	HRS AFL MOS MSC		739.1 245 19.3		 O/C	4791.3 2354 08 Apr 2021			0 0
Notes: PN: 1159L47003-5 SN: FEB09-1112.										
324012 Airframe	Main Wheel Bearings (Right Outboard) - Inspection / Pack	HRS AFL MOS MSC		613.8 204 15.9		 O/C	4916.6 2395 18 Jul 2021			0 0
324014 Airframe	Nose Tire Assembly - Check	HRS AFL MOS MSC		190.2 71 6.1		 O/C	5340.2 2528 13 May 2022			0 0
Notes: PN: 1159L50400-37 SN: 5093LY.										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
324015	Main Tire Assembly (Left Outboard) - Check	HRS		613.8			4916.6			0
		AFL		204			2395			0
		MOS		15.9			18 Jul 2021			
		MSC				O/C				
Airframe										
324016	Main Tire Assembly (Right Outboard) - Check	HRS		613.8			4916.6			0
		AFL		204			2395			0
		MOS		15.9			18 Jul 2021			
		MSC				O/C				
Airframe										
324017	Wheels and Brakes - Functional Test	HRS		882.2			4648.2			0
		AFL		304			2295			0
		MOS		23.5			01 Dec 2020			
		MSC				O/C				
Airframe										
324018	Nose Wheel Ndt (Left) - Special Detailed Inspection	HRS		190.2			5340.2			0
		AFL		71			2528			0
		MOS		6.1			12 May 2022			
		MSC				O/C				
Airframe										
Notes: PN: 1159L50400-37 SN: 5093LY. REF. 8130 20161017084240 AND SC480706 ITEM #50.1 FOR WORK PERFORMED										
324019	Nose Wheel Ndt (Right) - Special Detailed Inspection	HRS		190.2			5340.2			0
		AFL		71			2528			0
		MOS		6.1			12 May 2022			
		MSC				O/C				
Airframe										
Notes: PN: 1159L50400-37 SN: 5045GC. REF. FAA FORM 8130-3 - 20161017135440 AND SC480706 ITEM 51.1										
324020	Main Wheel Ndt (Left Outboard) - Special Detailed Inspection	HRS		613.8			4916.6			0
		AFL		204			2395			0
		MOS		15.9			18 Jul 2021			
		MSC				O/C				
Airframe										
Notes: PN: 1159L47003-5 SN: APR07-0540. REF. 8130-3 20161017084413 AND SC480706 ITEM #52.1 FOR WORK PERFORMED										
324021	Main Wheel Ndt (Left Inboard) - Special Detailed Inspection	HRS		613.8			4916.6			0
		AFL		204			2395			0
		MOS		15.9			18 Jul 2021			
		MSC				O/C				
Airframe										
Notes: REF. 8130 20161017084413 AND SC480706 ITEM #53.1 FOR WORK PERFORMED										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
324022	Main Wheel Ndt (Right Inboard) - Special Detailed Inspection	HRS		739.1			4791.3			0
		AFL		245			2354			0
		MOS		19.3			08 Apr 2021			
		MSC				O/C				
Airframe										
Notes: PN: 1159L47003-5 SN: FEB09-1112. REF. FAA FORM 8130-3 - 2016017094350 AND SC480706 ITEM 53.2 FOR WORKED PERFORMED.										
324023	Main Wheel Ndt (Right Outboard) - Special Detailed Inspection	HRS		613.8			4916.6			0
		AFL		204			2395			0
		MOS		15.9			18 Jul 2021			
		MSC				O/C				
Airframe										
Notes: REF. FAA FORM 8130-3 - 2016017100914 AND SC480706 ITEM 54.2 FOR WORKED PERFORMED.										
324033	Main Tire Assembly (Left Inboard) - Check	HRS		613.8			4916.6			0
		AFL		204			2395			0
		MOS		15.9			18 Jul 2021			
		MSC				O/C				
Airframe										
324034	Main Tire Assembly (Right Inboard) - Check	HRS		739.1			4791.3			0
		AFL		245			2354			0
		MOS		19.3			08 Apr 2021			
		MSC				O/C				
Airframe										
Notes: PN: 1159L47003-5 SN: FEB09-1112.										
324040	Nose Tire (Left) - Removal / Installation 217K22-1 20500357	HRS		190.2			5340.2			0
		AFL		71			2528			0
		MOS		6.1			13 May 2022			N/A
		MSC				O/C				
Airframe										
Notes: REF. 8130 20161017084240 AND SC480706 ITEM #50.1 FOR WORK PERFORMED										
324041	Nose Tire (Right) - Removal / Installation 217K22-1 20490526	HRS		190.2			5340.2			0
		AFL		71			2528			0
		MOS		6.1			13 May 2022			N/A
		MSC				O/C				
Airframe										
Notes: REF. FAA FORM 8130-3 - 20161017135440 AND SC480706 ITEM 51.1										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
324042	Main Tire (Left Outboard) - Removal / Installation 349K82-3 21090952	HRS AFL MOS MSC		17 5 .9		 O/C	5513.4 2594 18 Oct 2022			0 0
Airframe										
Notes: REF. 8130-3 20161017084413 AND SC480706 ITEM #52.1 FOR WORK PERFORMED										
324043	Main Tire (Left Inboard) - Removal / Installation 349K82-3 82043252	HRS AFL MOS MSC		613.8 204 15.9		 O/C	4916.6 2395 18 Jul 2021			0 0
Airframe										
Notes: REF. 8130 20161017090237 AND SC480706 ITEM #53.1 FOR WORK PERFORMED										
324044	Main Tire (Right Inboard) - Removal / Installation 349K82-3 20010232	HRS AFL MOS MSC		145.7 55 4.5		 O/C	5384.7 2544 01 Jul 2022			0 0
Airframe										
Notes: REF. FAA FORM 8130-3 - 20161017094350 AND SC480706 ITEM 53.3 FOR WORK PERFORMED										
324045	Main Tire (Right Outboard) - Removal / Installation 349K82-3 21810947	HRS AFL MOS MSC		6.5 2 .2		 O/C	5523.9 2597 11 Nov 2022			0 0
Airframe										
Notes: REF. FAA FORM 8130-3 - 20161017100914 AND SC480706 ITEM 54.3 FOR WORK PERFORMED										
324101	Main Wheel Brakes (Left) - Bleeding Procedures	HRS AFL MOS MSC		882.2 304 23.5		 O/C	4648.2 2295 01 Dec 2020			0 0
Airframe										
Notes: TW: 558095 DATE DUE: 11/16TW: 558150 DATE DUE: 01/17										
324102	Main Wheel Brakes (Right) - Bleeding Procedures	HRS AFL MOS MSC		882.2 304 23.5		 O/C	4648.2 2295 01 Dec 2020			0 0
Airframe										
Notes: TW: 558095 DATE DUE: 11/16TW: 558150 DATE DUE: 01/17										
324104	Brake System Hydraulic Fuses - Operational Check	HRS AFL MOS [MOS: +1m/-1m]		882.2 304 23.5		 125	4648.2 2295 01 Dec 2020	01 May 2031	01 Jun 2031	0 0
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
324105 Airframe	Brake Assembly (Left Outboard) - Removal / Installation 1159SCL471-9 JUL06-0314	HRS AFL MOS MSC		882.2 304 24.4		 O/C	4648.2 2295 03 Nov 2020			0 0
Notes: TW: 560117CAL DUE: 11/16										
324106 Airframe	Brake Assembly (Left Inboard) - Removal / Installation 1159SCL471-9 AUG06-0322	HRS AFL MOS MSC		882.2 304 24.4		 O/C	4648.2 2295 03 Nov 2020			0 0
Notes: TW: 560117CAL DUE: 11/16										
324107 Airframe	Brake Assembly (Right Inboard) - Removal / Installation 1159SCL471-9 MAY09-0793	HRS AFL MOS MSC		882.2 304 23.4		 O/C	4648.2 2295 03 Dec 2020			0 0
Notes: TW: 560117CAL DUE: 11/16										
324108 Airframe	Brake Assembly (Right Outboard) - Removal / Installation 1159SCL471-9 S-NOV17-0128	HRS AFL MOS MSC		882.2 304 23.4		 O/C	4648.2 2295 03 Dec 2020			0 0
Notes: TW: 560117CAL DUE: 11/16										
324110 Airframe	Brake System Temperature Sensors (Left Outboard) - Removal / Installation 90001934 DEC07-0579	HRS AFL MOS MSC	TSN:2889.9 TSN:1505 TSN:85	2640.5 1094 89.8		 O/C	2889.9 1505 21 May 2015			0 0
324111 Airframe	Brake System Temperature Sensors (Left Inboard) - Removal / Installation 90001934 JAN15-1652	HRS AFL MOS MSC		2126.6 875 65.3		 O/C	3403.8 1724 07 Jun 2017			0 0
324112 Airframe	Brake System Temperature Sensors (Right Inboard) - Removal / Installation 90001934 DEC07-0578	HRS AFL MOS MSC	TSN:2889.9 TSN:1505 TSN:85	2640.5 1094 89.8		 O/C	2889.9 1505 21 May 2015			0 0 AIRCRAFT BRAKING SYSTEMS

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
324113 Airframe	Brake System Temperature Sensors (Right Outboard) - Removal / Installation 90001934 DEC07-0574	HRS AFL MOS MSC	TSN:2889.9 TSN:1505 TSN:85	2640.5 1094 89.8		O/C	2889.9 1505 21 May 2015			0 0 AIRCRAFT BRAKING SYSTEMS
324114 Airframe	Brake Pressure Indicator - Removal / Installation 162LCP636 08021321	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0 DILLON - MORGANS
324115 Airframe	Gage, Brake Accum. Pressure GP20-24 08-0222333	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0 CUSTOM METAL WORKS
324116 Airframe	Dual Brake Metering Valve (Outboard) - Removal / Installation 1159SCL502-13 1245	HRS AFL MOS MSC		4882.7 2421 149.7		O/C	647.7 178 26 May 2010			0 0 PALL AEROPOWER CORPORATION
324117 Airframe	Dual Brake Metering Valve (Inboard) - Removal / Installation 1159SCH528-13 1250	HRS AFL MOS MSC		4882.7 2421 149.7		O/C	647.7 178 26 May 2010			0 0 PALL AEROPOWER CORPORATION
324120 Airframe	Parking / Emergency Brake Accumulator - Removal / Installation 1159SCH206-5 60211-2817	HRS AFL MOS MSC		5516.4 2594 171.3		O/C	14 5 07 Aug 2008			0 0 PNEUDRAULICS INC

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
324121 Logbook Position	Landing Gear Ground Service Valve - Removal / Installation 1159SCH245-5 2732	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 PARKER HANNIFIN CORPORATION
Airframe										
324122	Parking / Emergency Brake Selector Valve - Removal / Installation 64560-3 1442	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 ARC COM FABRICS
Airframe										
324125	Brake Pressure Transmitter (Left Outboard) - Removal / Installation 1159SCH240-7 HAL5577	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 PROFESSIONAL AIRCRAFT ACCESSORIES
Airframe										
Notes: VERFIED BY PQ618										
324126	Brake Pressure Transmitter (Right Outboard) - Removal / Installation 1159SCH240-7 HAL5580	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 PROFESSIONAL AIRCRAFT ACCESSORIES
Airframe										
324127	Brake System Hydraulic Fuses (Left Outboard) - Removal / Installation 1159SCH261-5 3910	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 EATON AEROSPACE
Airframe										
Notes: VERFIED BY PQ618										
324128	Brake System Hydraulic Fuses (Left Inboard) - Removal / Installation 1159SCH261-5 3895	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 EATON AEROSPACE
Airframe										
Notes: VERFIED BY PQ618										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
324129	Brake System Hydraulic Fuses (Right Inboard) - Removal / Installation	HRS		5530.4			0			0
		AFL		2599			0			0
	1159SCH261-5 3883	MOS		174.6			28 Apr 2008			EATON AEROSPACE
		MSC				O/C				
Airframe										
Notes: VERFIED BY PQ618										
324130	Brake System Hydraulic Fuses (Right Outboard) - Removal / Installation	HRS		5530.4			0			0
		AFL		2599			0			0
	1159SCH261-5 3895	MOS		174.6			28 Apr 2008			EATON AEROSPACE
		MSC				O/C				
Airframe										
Notes: VERFIED BY PQ618										
324133	Mechanical Brake Linkage AT Rudder Pedal - General Visual Inspection	HRS		957.2			4573.2			0
		AFL		362			2237			0
		MOS		29.1		72	12 Jun 2020	30 Jun 2026	31 Jul 2026	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-6C,200206									
324137	Brake Pressure Transmitter (Left Inboard) - Removal / Installation	HRS		5530.4			0			0
		AFL		2599			0			0
	1159SCH240-7 HAL0575	MOS		174.6			28 Apr 2008			PROFESSIONAL AIRCRAFT ACCESSORIES
		MSC				O/C				
Airframe										
Notes: VERFIED BY PQ618										
324138	Brake Pressure Transmitter (Right Inboard) - Removal / Installation	HRS		5530.4			0			0
		AFL		2599			0			0
	1159SCH240-7 HAL5578	MOS		174.6			28 Apr 2008			PROFESSIONAL AIRCRAFT ACCESSORIES
		MSC				O/C				
Airframe										
Notes: VERFIED BY PQ618										
324141	Transducer, Emerg Brake Press	HRS		5530.4			0			0
		AFL		2599			0			0
	1159SCAV600-1 HAL3863	MOS		174.6			28 Apr 2008			GULFSTREAM - LONG BEACH
		MSC				O/C				
Airframe										

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Description: Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
324142	Fuse, Rh Emergency Brake 1159SCH261-5 3891		HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 EATON AEROSPACE
Airframe											
Notes: VERFIED BY PQ618											
324143	Fuse, Lh Emergency Brake 1159SCH261-5 3717		HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe											
Notes: VERFIED BY PQ618											
324145	Main Landing Gear Brake Assembly (Left Inboard) - Detailed Inspection		HRS AFL MOS MSC		4885 2422 150.3		 O/C	645.4 177 06 May 2010			0 0
Airframe											
324148	Shuttle, R Aft Aux Alt Brake 1159SCH223-5 3588		HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 GENERAL DYNAMICS AVIATIONS SERVICES
Airframe											
324149	Shuttle, R Fwd Aux Alt Brake 1159SCH223-5 3658		HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 GENERAL DYNAMICS AVIATIONS SERVICES
Airframe											
324151	Brake Metering Valve (Left) Bleeding Procedure		HRS AFL MOS MSC		4882.7 2421 149.7		 O/C	647.7 178 26 May 2010			0 0
Airframe											

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
324152 Airframe	Brake Metering Valve (Right) - Bleeding Procedure	HRS AFL MOS MSC		4882.7 2421 149.7		 O/C	647.7 178 26 May 2010			0 0
Notes: PN: X SN: <NONE>.										
324201 Airframe	Digital Antiskid Control Unit - Removal / Installation PN SN-UNKNOWN	HRS AFL MOS MSC		2652.9 1097 90.7		 O/C	2877.5 1502 24 Apr 2015			0 0 AIRCRAFT BRAKING SYSTEMS
Notes: VERFIED BY:PQ005										
324202 Airframe	Antiskid - Functional Test	HRS AFL MOS MSC		882.2 304 23.5		 O/C	4648.2 2295 01 Dec 2020			0 0
Notes: CODE SUPERSEDED REF. 13.48 FOR OPERATIONAL TEST										
324203 Airframe	Antiskid - Operational Test	HRS AFL MOS MSC		882.2 304 23.5		 O/C	4648.2 2295 01 Dec 2020			0 0
324205 Airframe	Antiskid Control Valve (Left) - Removal / Installation 6006421-1 JAN08-0960	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 AIRCRAFT BRAKING SYSTEMS
Notes: PQ618										
324206 Airframe	Antiskid Control Valve (Right) - Removal / Installation 6006421-1 JAN08-0961	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 AIRCRAFT BRAKING SYSTEMS
Notes: PQ618										

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
Logbook Position	HW	SW									
	MM Ref										
	Ops Number(s)										
324221	Wheel Speed Transducer (Left Outboard) - Removal / Installation		HRS		882.2			4648.2			0
			AFL		304			2295			0
	6006419-1	JAN08-2029	MOS		23.4			03 Dec 2020			
			MSC				O/C				
Airframe											
Notes: TW: 567921CAL DUE: 09/17											
324222	Wheel Speed Transducer (Left Inboard) - Removal / Installation		HRS	TSN:4648.2	882.2			4648.2			0
			AFL	TSN:2295	304			2295			0
	6006419-1	JAN08-2025	MOS	TSN:152	23.4			03 Dec 2020			
			MSC				O/C				
Airframe											
Notes: TW: 567921CAL DUE: 09/17											
324223	Wheel Speed Transducer (Right Inboard) - Removal / Installation		HRS		882.2			4648.2			0
			AFL		304			2295			0
	6006419-1	JAN08-2028	MOS		23.4			03 Dec 2020			
			MSC				O/C				
Airframe											
Notes: TQ WRENCH: 567921CAL: 09/17											
324224	Wheel Speed Transducer (Right Outboard) - Removal / Installation		HRS		882.2			4648.2			0
			AFL		304			2295			0
	6006419-1	JAN08-2030	MOS		23.4			03 Dec 2020			
			MSC				O/C				
Airframe											
Notes: TQ WRENCH: 567921CAL: 09/17											
324279	Switch Aux Brake Press.		HRS		5530.4			0			0
			AFL		2599			0			0
	1206P0215	SN-UNKNOWN	MOS		174.6			28 Apr 2008			ELECTRO
			MSC				O/C				ENTERPRISES
Airframe											INC

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Description: Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
324291	Valve, Lh Brake Shuttle 1159SCH223-5	3744	HRS AFL MOS MSC	5530.4 2599 174.6			O/C	0 0 28 Apr 2008			0 0 GENERAL DYNAMICS AVIATIONS SERVICES
Airframe											
Notes: VERFIED BY PQ618											
324292	Valve, Rh Brake Shuttle 1159SCH223-5	3770	HRS AFL MOS MSC	5530.4 2599 174.6			O/C	0 0 28 Apr 2008			0 0 GENERAL DYNAMICS AVIATIONS SERVICES
Airframe											
Notes: VERFIED BY PQ618											
324303	Parking / Emergency Brake - Operational Test		HRS AFL MOS	957.2 362 29.1		17	36	4573.2 2237 12 Jun 2020	30 Jun 2023*	31 Jul 2023	0 0
Airframe	052000-3C,200203		[End Of Month Item] [MOS: +1m/-1m]								
324305	Brake Wear Indicators (Left Outboard) - Detailed Inspection		HRS AFL MOS	6.5 2 .2			500	5523.9 2597 11 Nov 2022	6023.9	6073.9	0 0
Airframe	052000-1A,200100		[HRS: +50/-50]								
324306	Brake Wear Indicators (Left Inboard) - Detailed Inspection		HRS AFL MOS	6.5 2 .2			500	5523.9 2597 11 Nov 2022	6023.9	6073.9	0 0
Airframe	052000-1A,200100		[HRS: +50/-50]								
324307	Brake Wear Indicators (Right Inboard) - Detailed Inspection		HRS AFL MOS	6.5 2 .2			500	5523.9 2597 11 Nov 2022	6023.9	6073.9	0 0
Airframe	052000-1A,200100		[HRS: +50/-50]								

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
324308 Airframe	Brake Wear Indicators (Right Outboard) - Detailed Inspection 052000-1A,200100	HRS AFL MOS [HRS: +50/-50]		6.5 2 .2		500	5523.9 2597 11 Nov 2022	6023.9	6073.9	0 0
324700 Airframe	Brake Temperature Indication - Functional Test	HRS AFL MOS MSC		882.2 304 23		O/C	4648.2 2295 15 Dec 2020			0 0
325001 Airframe Notes: Q307641	Nose Wheel Steering Unit - Removal / Installation 1159SCL500-51 0568AM	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0 EATON AEROSPACE
325002 Airframe	Tiller Assembly - Removal / Installation 1159SCL500-55 0579	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0 DUNLOP AEROSPACE BRAKING SYSTEM
325003 Airframe	Steering - Functional Test	HRS AFL MOS MSC		882.2 304 23.2		O/C	4648.2 2295 10 Dec 2020			0 0
325004 Airframe	Nose Wheel Steering System - Autorig Test	HRS AFL MOS MSC		3021.1 1338 102.1		O/C	2509.3 1261 13 May 2014			0 0
325060 Airframe	Switch Nose Steering 1206P0153 SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0 ITT AEROSPACE CONTROLS

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
325201 Logbook Position	Nose Wheel Steering Unit - Lubrication	HRS AFL MOS		2157 893 66.2		2100	3373.4 1706 11 May 2017	3806		0 0
Airframe	052000-1A									
Notes: INTERVAL CHANGED AT REV 22.										
325202 Airframe	Nose Wheel Steering Collar Assembly / Slave Gear - Lubrication 052000-1A,200101	HRS AFL MOS		6.5 2 .2		500 24	5523.9 2597 11 Nov 2022	6023.9 30 Nov 2024	6073.9 31 Dec 2024	0 0
	[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]									
325204 Airframe	Nose Wheel Steering Collar Assembly - Removal / Installation 1159SCL500-23 0558	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 EATON AEROSPACE
Notes: FREQUENCY REMOVED, NOT APPLICABLE PER P/N.										
325205 Airframe	Nose Wheel Steering Collar Assembly - Discard 1159SCL500-23 0558	HRS AFL MOS		5530.4 2599 174.6		 20000 	0 0 28 Apr 2008	 20000 		0 0
326114 Airframe	Nose Landing Gear Downlock Cable Assembly - Removal / Installation 1159SCAV518-5 SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
326201 Airframe	Main Gear Weight on Wheels Switches (Left) - Removal / Installation 1159SCAV513-1 NSN	HRS AFL MOS MSC		2367 954 73.1		 O/C	3163.4 1645 13 Oct 2016			0 0
326203 Airframe	Nose Landing Gear Weight on Wheels Switch - Removal / Installation 1159SCAV514-1 SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 GULFSTREAM SAV PROD-IPT

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
326213	Weight on Wheels System - Functional Test	HRS		957.2			4573.2			0
		AFL		362			2237			0
		MOS		29.1			12 Jun 2020			
		MSC				O/C				
Airframe										
326215	Main Landing Gear Weight on Wheels Switch (Left) - Adjustment	HRS		2367			3163.4			0
		AFL		954			1645			0
		MOS		73.1			13 Oct 2016			
		MSC				O/C				
Airframe										
326216	Main Landing Gear Weight on Wheels Switch (Right) - Adjustment	HRS		3804			1726.4			0
		AFL		1763			836			0
		MOS		122.8			23 Aug 2012			
		MSC				O/C				
Airframe										
327000	Brake Metering Valve Retrofit Program	HRS		5530.4			0			0
		AFL		2599			0			0
		MOS		174.6			28 Apr 2008			
		MSC				O/C				
Airframe										
33 - Lights										
330901	Switch Panel 2501-1-006 316WY	HRS		5525.5			4.9			0
		AFL		2597			2			0
		MOS		173.4			05 Jun 2008			AIRSHOW INC.
		MSC				O/C				
Airframe										
330902	Switch Panel 2501-1-007 3175M	HRS		5525.5			4.9			0
		AFL		2597			2			0
		MOS		173.4			05 Jun 2008			AIRSHOW INC.
		MSC				O/C				
Airframe										
330903	Switch Panel 2501-1-006 316XB	HRS		5525.5			4.9			0
		AFL		2597			2			0
		MOS		173.4			05 Jun 2008			AIRSHOW INC.
		MSC				O/C				
Airframe										

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
330904	Switch Panel 2501-1-065	316NG	HRS AFL MOS MSC		5525.5 2597 173.4		O/C	4.9 2 05 Jun 2008			0 0 AIRSHOW INC.
Airframe											
330905	Switch Panel 2501-1-087	316WW	HRS AFL MOS MSC		5525.5 2597 173.4		O/C	4.9 2 03 Jun 2008			0 0 AIRSHOW INC.
Airframe											
330906	Switch Panel 2501-1-320	3172C	HRS AFL MOS MSC		5525.5 2597 173.4		O/C	4.9 2 03 Jun 2008			0 0 AIRSHOW INC.
Airframe											
330907	Switch Panel 2501-1-009	316MY	HRS AFL MOS MSC		5525.5 2597 173.4		O/C	4.9 2 03 Jun 2008			0 0 AIRSHOW INC.
Airframe											
330908	Switch Panel 2501-1-007	3175N	HRS AFL MOS MSC		5525.5 2597 173.2		O/C	4.9 2 09 Jun 2008			0 0 AIRSHOW INC.
Airframe											
330909	Switch Panel 2501-1-006	316XC	HRS AFL MOS MSC		5525.5 2597 173.2		O/C	4.9 2 09 Jun 2008			0 0 AIRSHOW INC.
Airframe											
330910	Switch Panel 2501-1-030	316RT	HRS AFL MOS MSC		5525.5 2597 173.2		O/C	4.9 2 09 Jun 2008			0 0 AIRSHOW INC.
Airframe											
330911	Switch Panel 2501-1-015	3178B	HRS AFL MOS MSC		5525.5 2597 173.2		O/C	4.9 2 09 Jun 2008			0 0 AIRSHOW INC.
Airframe											

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
330912	Switch Panel 2501-1-030	316RV	HRS AFL MOS MSC		5525.5 2597 173.2		O/C	4.9 2 09 Jun 2008			0 0 AIRSHOW INC.
Airframe											
330913	Switch Panel 2501-1-087	316WX	HRS AFL MOS MSC		5525.5 2597 173.2		O/C	4.9 2 09 Jun 2008			0 0 AIRSHOW INC.
Airframe											
330914	Switch Panel 2501-1-320	3179C	HRS AFL MOS MSC		5525.5 2597 173.4		O/C	4.9 2 03 Jun 2008			0 0 AIRSHOW INC.
Airframe											
330915	Switch Panel 2501-1-009	316NB	HRS AFL MOS MSC		5525.5 2597 173.4		O/C	4.9 2 03 Jun 2008			0 0 AIRSHOW INC.
Airframe											
331001	Annunciator Dim & Test Control Unit - Removal / Installation 1159SCAV526-7	0546	HRS AFL MOS MSC		4912.2 2432 151.7		O/C	618.2 167 24 Mar 2010			0 0 ELECTRONIC CABLE SPECIALISTS
Airframe											
331002	Landing Lights Control Unit - Removal / Installation 1151D	DR00469	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0 HONEYWELL ENGINES AND SYSTEMS
Airframe											
331100	Cockpit Annunciator Lights Dim and Test System (Press to Test) - Operational Check		HRS AFL MOS MSC		3391.5 1506 112		O/C	2138.9 1093 17 Jul 2013			0 0
Airframe											

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
331101	Cockpit Annunciator Lights Dim and Test System (Dimming) - Functional Check		HRS AFL MOS MSC		4912.2 2432 151.7		 O/C	618.2 167 24 Mar 2010			0 0
Airframe											
332022	Panel, Vestibule Light Switch 2501-1-088	3179T	HRS AFL MOS MSC		5525.5 2597 174.1		 O/C	4.9 2 13 May 2008			0 0
Airframe											
332103	Power Supply, #3 Protected AL-2000	52952	HRS AFL MOS MSC		5525.5 2597 174.6		 O/C	4.9 2 29 Apr 2008			0 0 B/E AEROSPACE LIGHTING CORPORATION
Airframe											
332104	Power Supply, #4 Protected AL-2000	52945	HRS AFL MOS MSC		5525.5 2597 174.6		 O/C	4.9 2 29 Apr 2008			0 0 B/E AEROSPACE LIGHTING CORPORATION
Airframe											
332141	Power Supply, #1 Aft Lav Prot AL-2000	52946	HRS AFL MOS MSC		5525.5 2597 174.5		 O/C	4.9 2 02 May 2008			0 0
Airframe											
332142	Power Supply, #2 Aft Lav Prot AL-2000	52938	HRS AFL MOS MSC		5525.5 2597 174.5		 O/C	4.9 2 02 May 2008			0 0
Airframe											
332190	Dimmer Module, Aft Lav Lights AL-2022	3565	HRS AFL MOS MSC		5525.5 2597 174.5		 O/C	4.9 2 02 May 2008			0 0
Airframe											

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
Logbook Position	HW	SW									
	MM Ref										
	Ops Number(s)										
332191	Dimmer, #1 Cbn Lights AL-2035-210-200	4069	HRS AFL MOS MSC		957.2 362 29.1		O/C	4573.2 2237 12 Jun 2020			0 0
Airframe											
Notes: Position: Eunder Floor											
332192	Dimmer, #2 Cbn Lights AL-2035-210-200	4066	HRS AFL MOS MSC		957.2 362 29.1		O/C	4573.2 2237 12 Jun 2020			0 0
Airframe											
Notes: Position: Eunder Floor											
332193	Dimmer, #3 Cbn Lights AL-2035-210-200	4068	HRS AFL MOS MSC		957.2 362 29.1		O/C	4573.2 2237 12 Jun 2020			0 0
Airframe											
Notes: Position: Eunder Floor											
332194	Dimmer, #4 Cbn Lights AL-2035-210-200	4121	HRS AFL MOS MSC		957.2 362 29.1		O/C	4573.2 2237 12 Jun 2020			0 0
Airframe											
Notes: Position: Eunder Floor											
332201	Light Assy, #1 Cabin 7801-090-500420	4339	HRS AFL MOS MSC		957.2 362 29.1		O/C	4573.2 2237 12 Jun 2020			0 0
Airframe											
332202	Light Assy, #2 Cabin 7801-090-500420	4341	HRS AFL MOS MSC		957.2 362 29.1		O/C	4573.2 2237 12 Jun 2020			0 0
Airframe											
332203	Light Assy, #3 Cabin 7801-285-500420	32001963	HRS AFL MOS MSC		957.2 362 29.1		O/C	4573.2 2237 12 Jun 2020			0 0
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
332204	Light Assy, #4 Cabin		HRS		957.2			4573.2			0
	7801-285-500420	32002153	AFL		362			2237			0
			MOS		29.1			12 Jun 2020			
			MSC				O/C				
Airframe											
332205	Light Assy, #5 Cabin		HRS		957.2			4573.2			0
	7801-285-500420	32001974	AFL		362			2237			0
			MOS		29.1			12 Jun 2020			
			MSC				O/C				
Airframe											
332206	Light Assy, #6 Cabin		HRS		957.2			4573.2			0
	7801-300-500420	6296	AFL		362			2237			0
			MOS		29.1			12 Jun 2020			
			MSC				O/C				
Airframe											
332207	Light Assy, #7 Cabin		HRS		957.2			4573.2			0
	7801-285-500420	32001955	AFL		362			2237			0
			MOS		29.1			12 Jun 2020			
			MSC				O/C				
Airframe											
332208	Light Assy, #8 Cabin		HRS		957.2			4573.2			0
	7801-285-500420	32001975	AFL		362			2237			0
			MOS		29.1			12 Jun 2020			
			MSC				O/C				
Airframe											
332209	Light Assy, #9 Cabin		HRS		957.2			4573.2			0
	7801-090-500420	4280	AFL		362			2237			0
			MOS		29.1			12 Jun 2020			
			MSC				O/C				
Airframe											
332210	Light Assy, #10 Cabin		HRS		957.2			4573.2			0
	7801-105-500420	3603	AFL		362			2237			0
			MOS		29.1			12 Jun 2020			
			MSC				O/C				
Airframe											
332211	Light Assy, #11 Cabin		HRS		957.2			4573.2			0
	7801-285-500420	32002181	AFL		362			2237			0
			MOS		29.1			12 Jun 2020			
			MSC				O/C				
Airframe											

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Description: Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
332212	Light Assy, #12 Cabin 7801-2852-500420	32001976	HRS AFL MOS MSC		957.2 362 29.1		 O/C	4573.2 2237 12 Jun 2020			0 0
Airframe											
Notes: ALL WORK DONE PER G450 GC415810284 REV. B.											
332213	Light Assy, #13 Cabin 7801-285-500420	32001964	HRS AFL MOS MSC		957.2 362 29.1		 O/C	4573.2 2237 12 Jun 2020			0 0
Airframe											
332214	Light Assy, #14 Cabin 7801-285-500420	32001714	HRS AFL MOS MSC		957.2 362 29.1		 O/C	4573.2 2237 12 Jun 2020			0 0
Airframe											
332215	Light Assy, #15 Cabin 7801-285-500420	32002182	HRS AFL MOS MSC		957.2 362 29.1		 O/C	4573.2 2237 12 Jun 2020			0 0
Airframe											
332216	Light Assy, #16 Cabin 7801-285-500420	32001978	HRS AFL MOS MSC		957.2 362 29.1		 O/C	4573.2 2237 12 Jun 2020			0 0
Airframe											
332217	Light Assy, #17 Cabin 7801-090-500420	4282	HRS AFL MOS MSC		957.2 362 29.1		 O/C	4573.2 2237 12 Jun 2020			0 0
Airframe											
332218	Light Assy, #18 Cabin 7801-300-500420	6383	HRS AFL MOS MSC		957.2 362 29.1		 O/C	4573.2 2237 12 Jun 2020			0 0
Airframe											
332219	Light Assy, #19 Cabin 7801-285-500420	32002155	HRS AFL MOS MSC		957.2 362 29.1		 O/C	4573.2 2237 12 Jun 2020			0 0
Airframe											

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Description: Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
332220	Light Assy, #20 Cabin 7801-120-500420	4161	HRS AFL MOS MSC		957.2 362 29.1		O/C	4573.2 2237 12 Jun 2020			0 0
Airframe											
332221	Light Assy, #21 Cabin 7801-105-500420	3602	HRS AFL MOS MSC		957.2 362 29.1		O/C	4573.2 2237 12 Jun 2020			0 0
Airframe											
332222	Light Assy, #22 Cabin 7801-105-500420	3616	HRS AFL MOS MSC		957.2 362 29.1		O/C	4573.2 2237 12 Jun 2020			0 0
Airframe											
332223	Light Assy, #23 Cabin 7801-120-500420	4167	HRS AFL MOS MSC		957.2 362 29.1		O/C	4573.2 2237 12 Jun 2020			0 0
Airframe											
332224	Light Assy, #24 Cabin 7801-120-500420	4160	HRS AFL MOS MSC		957.2 362 29.1		O/C	4573.2 2237 12 Jun 2020			0 0
Airframe											
332225	Light Assy, #25 Cabin 7801-300-500420	6286	HRS AFL MOS MSC		957.2 362 29.1		O/C	4573.2 2237 12 Jun 2020			0 0
Airframe											
332226	Light Assy, #26 Cabin 7801-120-500420	4163	HRS AFL MOS MSC		957.2 362 29.1		O/C	4573.2 2237 12 Jun 2020			0 0
Airframe											
332227	Light Assy, #27 Cabin 7801-105-500420	3605	HRS AFL MOS MSC		957.2 362 29.1		O/C	4573.2 2237 12 Jun 2020			0 0
Airframe											

Notes: ALL WORK DONE PER G450 GC415810284 REV. B.

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
332228	Light Assy, #28 Cabin 7801-105-500420	3606	HRS AFL MOS MSC		957.2 362 29.1		O/C	4573.2 2237 12 Jun 2020			0 0
Airframe											
332229	Light Assy, #29 Cabin 7801-300-500420	6318	HRS AFL MOS MSC		957.2 362 29.1		O/C	4573.2 2237 12 Jun 2020			0 0
Airframe											
332230	Light Assy, #30 Cabin 7801-090-500420	4340	HRS AFL MOS MSC		957.2 362 29.1		O/C	4573.2 2237 12 Jun 2020			0 0
Airframe											
332231	Light Assy, #31 Cabin 7801-090-500420	4343	HRS AFL MOS MSC		957.2 362 29.1		O/C	4573.2 2237 12 Jun 2020			0 0
Airframe											
332232	Light Assy, #32 Cabin 7801-105-500420	3483	HRS AFL MOS MSC		957.2 362 29.1		O/C	4573.2 2237 12 Jun 2020			0 0
Airframe											
332233	Light Assy, #33 Cabin 7801-300-500420	6373	HRS AFL MOS MSC		957.2 362 29.1		O/C	4573.2 2237 12 Jun 2020			0 0
Airframe											
332234	Light Assy, #34 Cabin 7801-105-500420	3546	HRS AFL MOS MSC		957.2 362 29.1		O/C	4573.2 2237 12 Jun 2020			0 0
Airframe											
332235	Light Assy, #35 Cabin 7801-285-500420	32002157	HRS AFL MOS MSC		957.2 362 29.1		O/C	4573.2 2237 12 Jun 2020			0 0
Airframe											

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
Logbook Position	HW	SW									
	MM Ref										
	Ops Number(s)										
332236	Light Assy, #36 Cabin 7801-300-500420	6352	HRS AFL MOS MSC		957.2 362 29.1		 O/C	4573.2 2237 12 Jun 2020			0 0
Airframe											
332237	Light Assy, #37 Cabin 7801-300-500420	6372	HRS AFL MOS MSC		957.2 362 29.1		 O/C	4573.2 2237 12 Jun 2020			0 0
Airframe											
332238	Light Assy, #38 Cabin 7801-120-500420	4156	HRS AFL MOS MSC		957.2 362 29.1		 O/C	4573.2 2237 12 Jun 2020			0 0
Airframe											
332239	Light Assy, #39 Cabin 7801-105-500420	3611	HRS AFL MOS MSC		957.2 362 29.1		 O/C	4573.2 2237 12 Jun 2020			0 0
Airframe											
332240	Light Assy, #40 Cabin 7801-300-500420	6310	HRS AFL MOS MSC		957.2 362 29.1		 O/C	4573.2 2237 12 Jun 2020			0 0
Airframe											
332241	Light Assy, #41 Cabin 7801-300-500420	6285	HRS AFL MOS MSC		957.2 362 29.1		 O/C	4573.2 2237 12 Jun 2020			0 0
Airframe											
332242	Light Assy, #42 Cabin 7801-300-500420	6282	HRS AFL MOS MSC		957.2 362 29.1		 O/C	4573.2 2237 12 Jun 2020			0 0
Airframe											
332243	Light Assy, #43 Cabin 7801-300-500420	6281	HRS AFL MOS MSC		957.2 362 29.1		 O/C	4573.2 2237 12 Jun 2020			0 0
Airframe											

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
Logbook Position	HW	SW									
	MM Ref										
	Ops Number(s)										
332244	Light Assy, #44 Cabin 7801-300-500420	6307	HRS AFL MOS MSC		957.2 362 29.1		 O/C	4573.2 2237 12 Jun 2020			0 0
Airframe											
332245	Light Assy, #45 Cabin 7801-090-500420	4279	HRS AFL MOS MSC		957.2 362 29.1		 O/C	4573.2 2237 12 Jun 2020			0 0
Airframe											
332246	Light Assy, #46 Cabin 7801-300-500420	6306	HRS AFL MOS MSC		957.2 362 29.1		 O/C	4573.2 2237 12 Jun 2020			0 0
Airframe											
332247	Light Assy, #47 Cabin 7801-300-500420	6680	HRS AFL MOS MSC		957.2 362 29.1		 O/C	4573.2 2237 12 Jun 2020			0 0
Airframe											
332248	Light Assy, #48 Cabin 7801-120-500420	4165	HRS AFL MOS MSC		957.2 362 29.1		 O/C	4573.2 2237 12 Jun 2020			0 0
Airframe											
332249	Light Assy, #49 Cabin 7801-120-500420	4159	HRS AFL MOS MSC		957.2 362 29.1		 O/C	4573.2 2237 12 Jun 2020			0 0
Airframe											
332250	Light Assy, #50 Cabin 7801-120-500420	4155	HRS AFL MOS MSC		957.2 362 29.1		 O/C	4573.2 2237 12 Jun 2020			0 0
Airframe											
332259	Light Assy, #51 Cabin 7801-090-500420	4344	HRS AFL MOS MSC		957.2 362 29.1		 O/C	4573.2 2237 12 Jun 2020			0 0
Airframe											

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
332260 Airframe	Light Assy, Fwd Lav 5800-090-451000 4636	HRS AFL MOS MSC		5525.5 2597 174.1		O/C	4.9 2 12 May 2008			0 0
332261 Airframe	Light Assy, Fwd Lav #2 5500-06QCP551 6333	HRS AFL MOS MSC		5525.5 2597 172.7		O/C	4.9 2 25 Jun 2008			0 0
332265 Airframe	Light Assy # 52 Cabin 7801-090-500420 4342	HRS AFL MOS MSC		957.2 362 29.1		O/C	4573.2 2237 12 Jun 2020			0 0
332266 Airframe	Light Assy # 53 Cabin 7801-090-500420 4338	HRS AFL MOS MSC		957.2 362 29.1		O/C	4573.2 2237 12 Jun 2020			0 0
332267 Airframe	Light Assy # 54 Cabin 7801-300-500420 6420	HRS AFL MOS MSC		957.2 362 29.1		O/C	4573.2 2237 12 Jun 2020			0 0
Notes: ALL WORK DONE PER G450 GC415810284 REV. B.										
332268 Airframe	Light Assy # 55 Cabin 7801-120-500420 4168	HRS AFL MOS MSC		957.2 362 29.1		O/C	4573.2 2237 12 Jun 2020			0 0
332269 Airframe	Light Assy # 56 Cabin 7801-105-500420 3610	HRS AFL MOS MSC		957.2 362 29.1		O/C	4573.2 2237 12 Jun 2020			0 0
332270 Airframe	Light Assy # 57 Cabin 7801-105-500420 3590	HRS AFL MOS MSC		957.2 362 29.1		O/C	4573.2 2237 12 Jun 2020			0 0

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
Logbook Position	HW	SW									
	MM Ref										
	Ops Number(s)										
332271	Light Assy # 58 Cabin		HRS		957.2			4573.2			0
	7801-300-500420	6283	AFL		362			2237			0
			MOS		29.1			12 Jun 2020			
			MSC				O/C				
Airframe											
332304	Light Assy, #1 Closet- Led		HRS		5525.5			4.9			0
	5620-10	601	AFL		2597			2			0
			MOS		174.3			07 May 2008			
			MSC				O/C				
Airframe											
332305	Light Assy, #2 Closet- Led		HRS		5525.5			4.9			0
	5620-10	428	AFL		2597			2			0
			MOS		174.1			12 May 2008			
			MSC				O/C				
Airframe											
332306	Light Assy, #3 Closet- Led		HRS		5525.5			4.9			0
	5620-10	443	AFL		2597			2			0
			MOS		174.2			09 May 2008			
			MSC				O/C				
Airframe											
332307	Light Assy, #1 Cabin Spot		HRS		5525.5			4.9			0
	5500-06	6308	AFL		2597			2			0
			MOS		173.4			05 Jun 2008			
			MSC				O/C				
Airframe											
332310	Light Assy, #2 Cabin Spot		HRS		5525.5			4.9			0
	5500-06	6309	AFL		2597			2			0
			MOS		173.4			05 Jun 2008			
			MSC				O/C				
Airframe											
332313	Light Assy, #3 Cabin Spot		HRS		5525.5			4.9			0
	5500-06	6312	AFL		2597			2			0
			MOS		173.4			05 Jun 2008			
			MSC				O/C				
Airframe											
332316	Light Assy, #4 Cabin Spot		HRS		5525.5			4.9			0
	5500-06	6313	AFL		2597			2			0
			MOS		173.4			05 Jun 2008			
			MSC				O/C				
Airframe											

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
332319	Light Assy, #5 Cabin Spot		HRS		5525.5			4.9			0
	5500-06	6314	AFL		2597			2			0
			MOS		173.4			05 Jun 2008			
			MSC				O/C				
Airframe											
332322	Light Assy, #6 Cabin Spot		HRS		5525.5			4.9			0
	5500-06	6315	AFL		2597			2			0
			MOS		173.4			05 Jun 2008			
			MSC				O/C				
Airframe											
332325	Light Assy, #7 Cabin Spot		HRS		5525.5			4.9			0
	5500-06	6318	AFL		2597			2			0
			MOS		173.4			03 Jun 2008			
			MSC				O/C				
Airframe											
332328	Light Assy, #8 Cabin Spot		HRS		5525.5			4.9			0
	5500-06	5319	AFL		2597			2			0
			MOS		173.4			03 Jun 2008			
			MSC				O/C				
Airframe											
332331	Light Assy, #9 Cabin Spot		HRS		5525.5			4.9			0
	5500-06	6322	AFL		2597			2			0
			MOS		173.2			09 Jun 2008			
			MSC				O/C				
Airframe											
332334	Light Assy, #10 Cabin Spot		HRS		5525.5			4.9			0
	5500-06	6323	AFL		2597			2			0
			MOS		173.2			09 Jun 2008			
			MSC				O/C				
Airframe											
332337	Light Assy, #11 Cabin Spot		HRS		5525.5			4.9			0
	5500-06	6327	AFL		2597			2			0
			MOS		173.2			09 Jun 2008			
			MSC				O/C				
Airframe											
332340	Light Assy, #12 Cabin Spot		HRS		5525.5			4.9			0
	5500-06	6327	AFL		2597			2			0
			MOS		173.2			09 Jun 2008			
			MSC				O/C				
Airframe											

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
Logbook Position	HW	SW									
	MM Ref										
	Ops Number(s)										
332343	Light Assy, #13 Cabin Spot 5500-06	6330	HRS AFL MOS MSC		5525.5 2597 173.2		 O/C	4.9 2 09 Jun 2008			0 0
Airframe											
332346	Light Assy, #14 Cabin Spot 5500-06	6331	HRS AFL MOS MSC		5525.5 2597 173.2		 O/C	4.9 2 09 Jun 2008			0 0
Airframe											
332349	Light Assy, #15 Cabin Spot 5500-06	6307	HRS AFL MOS MSC		5525.5 2597 173.4		 O/C	4.9 2 05 Jun 2008			0 0
Airframe											
332352	Light Assy, #16 Cabin Spot 5500-06	6310	HRS AFL MOS MSC		5525.5 2597 173.4		 O/C	4.9 2 05 Jun 2008			0 0
Airframe											
332355	Light Assy, #17 Cabin Spot 5500-06	6311	HRS AFL MOS MSC		5525.5 2597 173.4		 O/C	4.9 2 05 Jun 2008			0 0
Airframe											
332358	Light Assy, #18 Cabin Spot 5500-06	6316	HRS AFL MOS MSC		5525.5 2597 173.4		 O/C	4.9 2 05 Jun 2008			0 0
Airframe											
332361	Light Assy, #19 Cabin Spot 5500-06	6317	HRS AFL MOS MSC		5525.5 2597 173.4		 O/C	4.9 2 03 Jun 2008			0 0
Airframe											
332364	Light Assy, #20 Cabin Spot 5500-06	6320	HRS AFL MOS MSC		5525.5 2597 173.4		 O/C	4.9 2 03 Jun 2008			0 0
Airframe											

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
332367	Light Assy, #21 Cabin Spot 5500-06	6321	HRS AFL MOS MSC		5525.5 2597 173.2		 O/C	4.9 2 09 Jun 2008			0 0
Airframe											
332370	Light Assy, #22 Cabin Spot 5500-06	6324	HRS AFL MOS MSC		5525.5 2597 173.2		 O/C	4.9 2 09 Jun 2008			0 0
Airframe											
332373	Light Assy, #23 Cabin Spot 5500-06	6325	HRS AFL MOS MSC		5525.5 2597 173.2		 O/C	4.9 2 09 Jun 2008			0 0
Airframe											
332376	Light Assy, #24 Cabin Spot 5500-06	6328	HRS AFL MOS MSC		5525.5 2597 173.2		 O/C	4.9 2 09 Jun 2008			0 0
Airframe											
332379	Light Assy, #25 Cabin Spot 5500-06	6329	HRS AFL MOS MSC		5525.5 2597 173.2		 O/C	4.9 2 09 Jun 2008			0 0
Airframe											
332383	Light Assy, #1 Aft Lav Spot 5500-06	6335	HRS AFL MOS MSC		5525.5 2597 171.8		 O/C	4.9 2 21 Jul 2008			0 0
Airframe											
332395	Light Assy #28 Cabin Spot 5500-06	6332	HRS AFL MOS MSC		5525.5 2597 173.4		 O/C	4.9 2 03 Jun 2008			0 0
Airframe											
332401	Light Assy, #1 Aft Lav 5800-105-451000	2913	HRS AFL MOS MSC		5525.5 2597 171.8		 O/C	4.9 2 21 Jul 2008			0 0
Airframe											

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Description: Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
332402	Light Assy, #2 Aft Lav 5800-105-451000	3543	HRS AFL MOS MSC		5525.5 2597 171.8		 O/C	4.9 2 21 Jul 2008			0 0
Airframe											
332403	Light Assy, #3 Aft Lav 5800-105-451000	3111	HRS AFL MOS MSC		5525.5 2597 171.8		 O/C	4.9 2 21 Jul 2008			0 0
Airframe											
332404	Light Assy, #4 Aft Lav 5800-105-451000	3544	HRS AFL MOS MSC		5525.5 2597 171.8		 O/C	4.9 2 21 Jul 2008			0 0
Airframe											
332405	Light Assy, #5 Aft Lav 5800-105-451000	3109	HRS AFL MOS MSC		5525.5 2597 171.8		 O/C	4.9 2 21 Jul 2008			0 0
Airframe											
332406	Light Assy, #6 Aft Lav 5800-105-451000	3545	HRS AFL MOS MSC		5525.5 2597 171.8		 O/C	4.9 2 21 Jul 2008			0 0
Airframe											
332471	Cabin Spotlight - Operational Test (Elite)		HRS AFL MOS MSC		957.2 362 29.1		 O/C	4573.2 2237 12 Jun 2020			0 0
Airframe											
332473	Galley Lighting - Operational Test (Elite)		HRS AFL MOS MSC		882.2 304 26.2		 O/C	4648.2 2295 09 Sep 2020			0 0
Airframe											
332484	Passenger Ordinance Sign - Operational Test (Elite)		HRS AFL MOS MSC		957.2 362 29.1		 O/C	4573.2 2237 12 Jun 2020			0 0
Airframe											

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
332486 Airframe	Cabin Emergency Lighting - Operational Test (Elite)	HRS AFL MOS MSC		957.2 362 29.1		O/C	4573.2 2237 12 Jun 2020			0 0
332567 Airframe	Dome Light Assembly #1 Galley - Removal / Installation (Elite) GAC-ELRD-3000 SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0
332568 Airframe	Dome Light Assembly #2 Galley - Removal / Installation (Elite) GAC-ELRD-3000 SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0
332569 Airframe	Dome Light Assembly -Galley - Servicing (Elite)	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0
Notes: PN: GAC-ELRD-3000 SN: <NONE>.										
332570 Airframe	Compartment Light Magnetic Switch - Removal / Installation (Elite) GAC-ELRD-3000 SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0
332571 Airframe	Dome Light Assembly #1 Forward Lav - Removal / Installation (Elite) GAC-ELRD-3000 SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0
332572 Airframe	Dome Light Assembly #2 Forward Lav - Removal / Installation (Elite) GAC-ELRD-3000 SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
332573	Dome Light Assembly #1 Aft Lav - Removal / Installation (Elite) GAC-ELRD-3000 SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										
332574	Dome Light Assembly #2 Aft Lav - Removal / Installation (Elite) GAC-ELRD-3000 SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										
332575	Reading Light Assembly Fwd Lav - Removal / Installation (Elite) GAC-ELRD-3000 SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										
332576	Reading Light Assembly Aft Lav - Removal / Installation (Elite) GAC-ELRD-3000 SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										
332577	Dome Light Assembly Aft Lav - Servicing (Elite) GAC-ELRD-3000 SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										
334001	Landing Light Assembly (Left) - Removal / Installation Q4559X N/A	HRS AFL MOS MSC		3753.9 1726 121.7		 O/C	1776.5 873 25 Sep 2012			0 0
Airframe										
334002	Landing Light Assembly (Right) - Removal / Installation 50-0137-3 2225	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 HONEYWELL GRIMES AEROSPACE
Airframe										

Notes: Q306743

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
334007 Airframe	Nose Wheel Taxi Lights Lamp (Left) - Replacement 4587 NSN	HRS AFL MOS MSC		3538.7 1590 114.7		 O/C	1991.7 1009 25 Apr 2013			0 0 Bombardier
334008 Airframe	Nose Wheel Taxi Lights Lamp (Center) - Replacement 4578 NSN	HRS AFL MOS MSC		882.2 304 23.7		 O/C	4648.2 2295 24 Nov 2020			0 0
334009 Airframe	Nose Wheel Taxi Lights Lamp (Right) - Replacement 4578 NSN	HRS AFL MOS MSC		882.2 304 23.7		 O/C	4648.2 2295 24 Nov 2020			0 0
334010 Airframe	Exterior Lights - Operational Test	HRS AFL MOS MSC		2640.5 1094 89.4		 O/C	2889.9 1505 05 Jun 2015			0 0
334023 Airframe	Light, Tail Cone Strobe Assy 30-2368-1 2283	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 VOUGHT AIRCRAFT INDUSTRIES INC.
334025 Airframe	Strobe Light Power Supply Unit (Left) - Removal / Installation 60-4943-1 1664	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 TRANSTAR METALS
334026 Airframe	Strobe Light Power Supply Unit (Right) - Removal / Installation 60-4943-1 1692	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 TRANSTAR METALS

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
334027	Strobe Light Power Supply Unit (Tail) - Removal / Installation	HRS		1164.6			4365.8			0
		AFL		455			2144			0
	60-4943-1 3193	MOS	TSN:71	37.5			02 Oct 2019			TRANSTAR METALS
		MSC				O/C				
Airframe										
334035	L Ice Inspection Lights - Removal / Installation	HRS		2698.6			2831.8			0
	CMA7079B-24 NSN	AFL		1124			1475			0
		MOS		92.4			04 Mar 2015			
		MSC				O/C				
Airframe										
334039	Navigation Light Cover (Left) - Removal / Installation	HRS		5530.4			0			0
	1159WP47806-17 SN-UNKNOWN	AFL		2599			0			0
		MOS		174.6			28 Apr 2008			
		MSC				O/C				
Airframe										
334040	Navigation Light Cover (Right) - Removal / Installation	HRS		5530.4			0			0
	1159WP47806-12 SN-UNKNOWN	AFL		2599			0			0
		MOS		174.6			28 Apr 2008			
		MSC				O/C				
Airframe										
334041	Left Wing Outboard Navigation Light Assembly (Position) - Removal / Installation	HRS		4343.4			1187			0
		AFL		2048			551			0
	30-3041-9 1959	MOS	TSN:6	134.5			30 Aug 2011			
		MSC				O/C				
Airframe										
Notes: P/N 30-3041-9 OFF S/N 0278 OFFP/N 30-3041-9 ON S/N 1959										
334050	Position Light Lens - Detailed Inspection	HRS		6.5		500	5523.9	6023.9	6073.9	0
		AFL		2			2597			0
		MOS		.2		24	11 Nov 2022	30 Nov 2024	31 Dec 2024	
Airframe	052000-1A,200101	[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
334061	Left Wing Outboard Navigation Led Light Assembly (Position) - Removal / Installation	HRS		5530.4			0			0
		AFL		2599			0			0
	30-2900-1 NSN	MOS		174.6			28 Apr 2008			
		MSC				O/C				
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
334062 Logbook Position	Right Wing Inboard Navigation Led Light Assembly (Position) - Removal / Installation 30-2900-2 NSN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										
334063 Logbook Position	Left Wing Inboard Navigation Led Light Assembly (Position) - Removal / Installation 30-2900-1 NSN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										
334064 Logbook Position	Right Wing Outboard Navigation Led Light Assembly (Position) - Removal / Installation 30-2900-2 NSN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										
334065 Logbook Position	Tail Upper Navigation Led Light Assembly (Position) - Removal / Installation 30-3041-9 1959	HRS AFL MOS MSC	 TSN:6	4343.4 2048 134.5		 O/C	1187 551 30 Aug 2011			0 0
Airframe										
Notes: -7 LIGHT ASSY USES -9 LIGHT 334208P/N 30-3041-9 OFF S/N 0278 OFFP/N 30-3041-9 ON S/N 1959 ON										
334066 Logbook Position	Tail Lower Navigation Led Light Assembly (Position) - Removal / Installation 30-3041-7 SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										
Notes: -7 LIGHT ASSY USES -9 LIGHT 334209										
334091 Logbook Position	Light, Tail Anti-Collision #2 30-3041-9 0278	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
334095 Airframe	Wing-Tip Anticollision Strobe Light Assembly (Left) - Removal / Installation 30-2446-3 2297	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0 VOUGHT AIRCRAFT INDUSTRIES INC.
334096 Airframe	Wing-Tip Anticollision Strobe Light Assembly (Right) - Removal / Installation 30-2446-3 2268	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0 VOUGHT AIRCRAFT INDUSTRIES INC.
334097 Airframe Notes: CORRECTED P/N GRH	Tail Cone Anticollision Strobe Light Assembly - Removal / Installation 1159B57908-1 0273	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0 HONEYWELL GRIMES AEROSPACE
334098 Airframe	Beacon Anticollision Light Assembly - Removal / Installation 30-2140-9 1655	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0 AVIATION AVIONICS & INSTRUMENTS CORP
334099 Airframe	Anticollision Strobe Lights - Operational Test	HRS AFL MOS MSC		2367 954 72.7		O/C	3163.4 1645 25 Oct 2016			0 0
334121 Airframe	Landing Lights - Operational Test	HRS AFL MOS MSC		2367 954 72.5		O/C	3163.4 1645 02 Nov 2016			0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
334122	Taxi Lights - Operational Test	HRS AFL MOS MSC		882.2 304 23.7		 O/C	4648.2 2295 24 Nov 2020			0 0
Airframe										
Notes: PN: GE4587 SN: NSN.										
334150	Left Wing-Tip Flood / Taxi Light Assembly - Removal / Installation A775-EXP-28 SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										
334151	Right Wing-Tip Flood / Taxi Light Assembly - Removal / Installation A775-EXP-28 SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										
334152	Wing-Tip Flood / Taxi Lamp (Left) - Replacement MS25338-7079 NSN	HRS AFL MOS MSC		4343.4 2048 134.5		 O/C	1187 551 30 Aug 2011			0 0
Airframe										
334153	Wing-Tip Flood / Taxi Lamp (Right) - Replacement MS25338-7079 SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										
334203	Anticollision Beacon Light - Operational Test	HRS AFL MOS MSC		957.2 362 29.1		 O/C	4573.2 2237 12 Jun 2020			0 0
Airframe										
334208	Tail Navigation Position Lights Led (Upper) - Discard 30-3041-9 SN-UNKNOWN	HRS AFL MOS		5530.4 2599 174.6		8000 	0 0 28 Apr 2008	8000		0 0
Airframe										
334209	Tail Navigation Position Lights Led (Lower) - Discard 30-3041-9 SN-UNKNOWN	HRS AFL MOS		5530.4 2599 174.6		8000 	0 0 28 Apr 2008	8000		0 0
Airframe										

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
334210	Wing Navigation Position Lights Led (Left Outboard) - Discard		HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0
	30-2900-1	SN-UNKNOWN									
Airframe											
334211	Wing Navigation Position Lights Led (Left Inboard) - Discard		HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0
	30-2900-1	SN-UNKNOWN									
Airframe											
334212	Wing Navigation Position Lights Led (Right Outboard) - Discard		HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0
	30-2900-2	SN-UNKNOWN									
Airframe											
334213	Wing Navigation Position Lights Led (Right Inboard) - Discard		HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0
	30-2900-2	SN-UNKNOWN									
Airframe											
334214	Wing Navigation Position Lights Led (Left Outboard) - Replacement		HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0
	P/N 30-2900-1	SN-UNKNOWN									
Airframe											
334215	Wing Navigation Position Lights Led (Left Inboard) - Replacement		HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0
	P/N 30-2900-1	SN-UNKNOWN									
Airframe											
334216	Wing Navigation Position Lights Led (Right Outboard) - Replacement		HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0
	30-2900-2	SN-UNKNOWN									
Airframe											

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
334217	Wing Navigation Position Lights Led (Right Inboard) - Replacement		HRS		5530.4			0			0
			AFL		2599			0			0
	30-2900-2	SN-UNKNOWN	MOS		174.6			28 Apr 2008			
			MSC				O/C				
Airframe											
334218	Tail Navigation Position Lights Led (Upper) - Replacement		HRS		5530.4			0			0
			AFL		2599			0			0
	30-3041-7	SN-UNKNOWN	MOS		174.6			28 Apr 2008			
			MSC				O/C				
Airframe											
334401	L Logo Light - Removal / Installation		HRS		1008.2			4522.2			0
			AFL		397			2202			0
	1987	NSN	MOS		33.5			31 Jan 2020			
			MSC				O/C				
Airframe											
334403	Logo Lights - Operational Check		HRS		882.2			4648.2			0
			AFL		304			2295			0
			MOS		23.7			25 Nov 2020			
			MSC				O/C				
Airframe											
335001	Batt, #1 Emergency Lights (Bruce)		HRS		5530.4			0			0
			AFL		2599			0			0
	100865	X	MOS		174.6			28 Apr 2008			
			MSC				O/C				
Airframe											
335002	Batt, #2 Emergency Lights (Bruce)		HRS		5525.5			4.9			0
			AFL		2597			2			0
	100865	C04296	MOS		172.7			25 Jun 2008			
			MSC				O/C				
Airframe											
335003	Batt, #3 Emergency Lights (Bruce)		HRS		5530.4			0			0
			AFL		2599			0			0
	100865	X	MOS		174.6			28 Apr 2008			
			MSC				O/C				
Airframe											
335005	Emergency Floorpath Lighting Battery Packs - Operational Check		HRS		6.5		500	5523.9	6023.9		0
			AFL		2			2597			0
			MOS		.2			11 Nov 2022			
Airframe											

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
335006 Airframe	Emergency Floorpath Lighting Battery Pack (Deep Cycle) (No. 1) - Restore	HRS AFL MOS		190.2 71 5.9	-25	18	5340.2 2528 18 May 2022	31 Oct 2023*	30 Nov 2023	0 0
		[End Of Month Item] [MOS: +1m/-1m]								
335007 Airframe	Emergency Floorpath Lighting Battery Pack (Deep Cycle) (No. 2) - Restore	HRS AFL MOS		190.2 71 5.9	-25	18	5340.2 2528 18 May 2022	31 Oct 2023*	30 Nov 2023	0 0
		[End Of Month Item] [MOS: +1m/-1m]								
335008 Airframe	Emergency Floorpath Lighting Battery Pack (Deep Cycle) (No. 3) - Restore	HRS AFL MOS		190.2 71 5.9	-25	18	5340.2 2528 18 May 2022	31 Oct 2023*	30 Nov 2023	0 0
		[End Of Month Item] [MOS: +1m/-1m]								
335016 Airframe	Pack, #1 Emergency Batt(Bruce) 2013-BR B11913	HRS AFL MOS MSC		190.2 71 5.9		 O/C	5340.2 2528 18 May 2022			0 0 N/A
335017 Airframe	Pack, #2 Emergency Batt(Bruce) 2013-BR B12987	HRS AFL MOS MSC		190.2 71 5.9		 O/C	5340.2 2528 18 May 2022			0 0 N/A
335018 Airframe	Pack, #3 Emergency Batt(Bruce) 2013-BR B12539	HRS AFL MOS MSC		190.2 71 5.9		 O/C	5340.2 2528 18 May 2022			0 0 N/A
335020 Airframe	Exterior / Interior Emergency Lighting - Operational Test 052000-1C,200201	HRS AFL MOS		190.2 71 6	26	12	5340.2 2528 17 May 2022	30 Jun 2023*	31 Jul 2023	0 0
		[End Of Month Item] [MOS: +1m/-1m]								

Notes: REFERENCE ICA DOCUMENT GC41486A000 REV - FOR STC ST02987AT-D

34 - Navigation

ATA U=Custom / Logbook Position	Description / Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
341001	Radio Altimeter Antenna (No. 1) (Transmit) - Removal / Installation	HRS	TSN:4573.2	957.2			4573.2			0
		AFL	TSN:2237	362			2237			0
	DM PN19-2-1 4642	MOS	TSN:145	29.1			12 Jun 2020			
		MSC				O/C				
Airframe										
341002	Radio Altimeter Antenna (No. 1) (Receive) - Removal / Installation	HRS	TSN:4573.2	957.2			4573.2			0
		AFL	TSN:2237	362			2237			0
	DM PN19-2-1 4644	MOS	TSN:145	29.1			12 Jun 2020			
		MSC				O/C				
Airframe										
341003	Radio Altimeter Antenna (No. 2) (Transmit) - Removal / Installation	HRS		957.2			4573.2			0
		AFL		362			2237			0
	DM PN19-2-1 4688	MOS		29.1			12 Jun 2020			
		MSC				O/C				
Airframe										
341004	Radio Altimeter Antenna (No. 2) (Receive) - Removal / Installation	HRS		957.2			4573.2			0
		AFL		362			2237			0
	DM PN19-2-1 4690	MOS		29.1			12 Jun 2020			
		MSC				O/C				
Airframe										
341005	Radio Altimeter System - Operational Check	HRS		190.2			5340.2			0
		AFL		71			2528			0
		MOS		6.2	5	12	09 May 2022	31 May 2023*	30 Jun 2023	
Airframe		[End Of Month Item] [MOS: +1m/-1m]								
341006	Radio Altimeter R/T - Zero Altitude Adjustment	HRS		190.2			5340.2			0
		AFL		71			2528			0
		MOS		5.9	-5	12	19 May 2022	31 May 2023*	30 Jun 2023	
Airframe		[End Of Month Item] [MOS: +1m/-1m]								
Notes: OPERATOR C/W ASC 20 AND IS OPERATING CAT II. GRH 18 FEB 11										
341010	Radio Altimeter R/T No. 1 - Removal / Installation	HRS		5530.4			0			0
	7001840-932 0803E549	AFL		2599			0			0
		MOS		174.6			28 Apr 2008			HONEYWELL
		MSC				O/C				
Airframe										
Notes: J-AD										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
341011 Airframe	Radio Altimeter R/T No. 2 - Removal / Installation 7001840-932 0803E554	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 HONEYWELL
341020 Airframe	AIR Data Module No. 1 - Removal / Installation HG1153CA04 08022874	HRS AFL MOS MSC	TSN:1121.5 TSN:506 TSN:39	4408.9 2093 135.8		 O/C	1121.5 506 22 Jul 2011			0 0 HONEYWELL INTERNATIONAL
341021 Airframe	AIR Data Module No. 2 - Removal / Installation HG1153CA04 08032920	HRS AFL MOS MSC		4480 2140 137		 O/C	1050.4 459 17 Jun 2011			0 0 HONEYWELL INTERNATIONAL
341022 Airframe	AIR Data Module No. 3 - Removal / Installation HG1153CA04 08032907	HRS AFL MOS MSC		4408.9 2093 135.8		 O/C	1121.5 506 22 Jul 2011			0 0 HONEYWELL INTERNATIONAL
341023 Airframe	AIR Data Module No. 1 - Certification 052000-12M_CAT2	HRS AFL MOS [End Of Month Item]		190.2 71 6.2	 -9	 12	5340.2 2528 09 May 2022	30 Apr 2023*		0 0 CALIBRATION
Notes: OPERATOR C/W ASC 20 AND IS OPERATING CAT II. CMP 341304										
341024 Airframe	AIR Data Module No. 2 - Certification 052000-12M_CAT2	HRS AFL MOS [End Of Month Item]		190.2 71 6.2	 -9	 12	5340.2 2528 09 May 2022	30 Apr 2023*		0 0 CALIBRATION
Notes: OPERATOR C/W ASC 20 AND IS OPERATING CAT II. CMP 341305										
341025 Airframe	AIR Data Module No. 3 - Certification 052000-12M_CAT2	HRS AFL MOS [End Of Month Item]		190.2 71 6.2	 -9	 12	5340.2 2528 09 May 2022	30 Apr 2023*		0 0 CALIBRATION
Notes: OPERATOR C/W ASC 20 AND IS OPERATING CAT II. CMP 341306										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
341029 Airframe	Digital AIR Data Computing System - Functional Check 200301	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		697.6 234 18.5	31	24	4832.8 2365 30 Apr 2021	31 May 2023*	30 Jun 2023	0 0
341030 Airframe	Pitot / Static System - Reconnect Check	HRS AFL MOS MSC		957.2 362 29.1		 O/C	4573.2 2237 12 Jun 2020			0 0
341095 Airframe	Total AIR Temperature Probe - Operational Check	HRS AFL MOS MSC		2640.5 1094 90.2		 O/C	2889.9 1505 09 May 2015			0 0
341098 Airframe	Tat Probe No. 1 - Removal / Installation 102LK2AG A77398	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 CITY PLATING
341099 Airframe	Tat Probe No. 2 - Removal / Installation 102LK2AG A77892	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 CITY PLATING
341100 Airframe Notes: VERF PQ049	Left Pitot Probe - Removal / Installation 0851GE 385751	HRS AFL MOS MSC	 TSN:18	957.2 362 29.1		 O/C	4573.2 2237 12 Jun 2020			0 0
341101 Airframe Notes: VERF PQ049	Right Pitot Probe - Removal / Installation 0851GE 386169	HRS AFL MOS MSC	 TSN:18	957.2 362 29.1		 O/C	4573.2 2237 12 Jun 2020			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
341102 Airframe	Stby Pitot Probe - Removal / Installation 0851GE 362209	HRS AFL MOS MSC	TSN:7	1795.4 728 55.5		O/C	3735 1871 01 Apr 2018			0 0 GOODRICH SENSOR SYSTEMS
341200 Airframe	AIR Data System - Operational Check	HRS AFL MOS MSC		4480 2140 137		O/C	1050.4 459 17 Jun 2011			0 0
341300 Airframe	Pitot / Static Systems Probes / Lines - Contamination Check	HRS AFL MOS MSC		1769.5 717 54.5		O/C	3760.9 1882 30 Apr 2018			0 0
341301 Airframe	Pitot/Stat Sys-Func Ck(91.411)	HRS AFL MOS MSC		5525.5 2597 171.6		O/C	4.9 2 29 Jul 2008			0 0
341302 Airframe	Stby Alt A/SP Ind-Fc(91.411)	HRS AFL MOS MSC		5525.5 2597 171.6		O/C	4.9 2 29 Jul 2008			0 0
341304 Airframe	AIR Data System No. 1 - Functional / Leak Test 052000-12M_CAT2 Notes: OPERATOR C/W ASC 20 AND IS OPERATING CAT II. GRH 18 FEB 11	HRS AFL MOS [End Of Month Item]		190.2 71 6.2		12	5340.2 2528 10 May 2022	30 Apr 2023		0 0 CALIBRATION
341305 Airframe	AIR Data System No. 2 - Functional / Leak Test 052000-12M_CAT2 Notes: OPERATOR C/W ASC 20 AND IS OPERATING CAT II. GRH 18 FEB 11	HRS AFL MOS [End Of Month Item]		190.2 71 6.2	-9	12	5340.2 2528 09 May 2022	30 Apr 2023*		0 0 CALIBRATION

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
341306	AIR Data System No. 3 - Functional / Leak Test		HRS		190.2			5340.2			0
			AFL		71			2528			0
			MOS		6.2	-9	12	09 May 2022	30 Apr 2023*		
Airframe	052000-12M_CAT2		[End Of Month Item]								CALIBRATION
Notes: OPERATOR C/W ASC 20 AND IS OPERATING CAT II. GRH 18 FEB 11											
341307	Standby Pitot / Static System - Functional / Leak Check		HRS		190.2			5340.2			0
			AFL		71			2528			0
			MOS		6.2	-9	12	09 May 2022	30 Apr 2023*		
Airframe	052000-12M_CAT2		[End Of Month Item]								CALIBRATION
Notes: OPERATOR C/W ASC 20 AND IS OPERATING CAT II. GRH 18 FEB 11											
342001	Standby Bearing Distance Indicator - Removal / Installation		HRS		1769.5			3760.9			0
			AFL		717			1882			0
	501-1871-0101	1244	MOS		54.7			25 Apr 2018			HUGHES
		1.0	MSC				O/C				INDUSTRIAL
Airframe											
Notes: MOD 2,6,7,9											
342005	Integrated Standby Flight Display - Removal / Installation		HRS		5474.5			55.9			0
	501-1860-0102	0165	AFL		2582			17			0
		2.2	MOS		170.1			13 Sep 2008			L-3
Airframe			MSC				O/C				COMMUNICATIONS AVIONICS SYSTEMS INC.
Notes: MOD 1,2,4,5,6,7,8,9,12,13,15											
342015	Dcm-3100		HRS		5530.4			0			0
	501-1870-32	1884	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			L-3
Airframe			MSC				O/C				COMMUNICATIONS AVIONICS SYSTEMS INC.
342603	Ohu - Removal / Installation		HRS		6.5			5523.9			0
	7023171-901	04-090219	AFL		2			2597			0
			MOS		.2			11 Nov 2022			
Airframe			MSC				O/C				

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
342604 Airframe	Combiner Assembly - Removal / Installation 7023172-907 05120680	HRS AFL MOS MSC		2367 954 73.1		 O/C	3163.4 1645 14 Oct 2016			0 0
Notes: TW CN 558097 CAL DUE 11/16/15										
342608 Airframe	Visual Guidance System - Operational Check	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
342621 Airframe	Forward Looking Infrared Camera Assembly - Preventive Maintenance 48534-101 584	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 OVERHAUL
Notes: CAMERA ON CONDITION - SEE ATTACHED LETTER. 11 MAR 2011.RGC										
342622 Airframe	Forward Looking Infrared Camera - Removal / Installation 48534-101 584	HRS AFL MOS MSC		181 68 5.7		 O/C	5349.4 2531 25 May 2022			0 0 N/A
342623 Airframe	Enhanced Vision System Processor - Removal / Installation 48535-101 559	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 4 FLIGHT
Notes: VERFIED BY:PQ005										
342624 Airframe	Enhanced Vision System Sapphire Window - Functional Test	HRS AFL MOS [HRS: +50/-50]		5525.5 2597 173.1	-4.9	10000 	4.9 2 12 Jun 2008	10000*	10050	0 0 KOLLSMAN, INC.
Notes: PN: 48856-101 SN: 728.										
342625 Airframe	Enhanced Vision System Window Heat Controller - Removal / Installation 49322-101 563	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 TAPIS CORP

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
342633 Airframe	Enhanced Vision System - Functional Check	HRS AFL MOS MSC		181 68 5.7		 O/C	5349.4 2531 26 May 2022			0 0
342701 Airframe	Integrated Standby Flight Display / Magnetometer - Compensation Adjustments	HRS AFL MOS MSC		5525.5 2597 172.7		 O/C	4.9 2 24 Jun 2008			0 0
342702 Airframe	Magnetometer - Removal / Installation 501-1826-01 2670	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 L-3 COMMUNICATIONS AVIONICS SYSTEMS INC.
Notes: VERFIED BY:PQ005										
342710 Airframe	Integrated Standby Flight Display - Functional Check	HRS AFL MOS MSC		2640.5 1094 89.7		 O/C	2889.9 1505 26 May 2015			0 0
342715 Airframe	Integrated Standby Flight Display / Magnetometer - Calibration Check	HRS AFL MOS MSC		5525.5 2597 172.8		 O/C	4.9 2 23 Jun 2008			0 0
342801 Airframe	Stby Ebdi - Operational Check	HRS AFL MOS MSC		1769.5 717 54.7		 O/C	3760.9 1882 25 Apr 2018			0 0
342900 Airframe	Enhanced Vision System Window Manual Heat - Operational Check	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Notes: PN: N/A SN: <NONE>.										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
343001 Airframe	Marker Beacon Antenna - Removal / Installation S35-2000-10 106-0437	HRS AFL MOS MSC	TSN:4573.2 TSN:2237 TSN:145	957.2 362 29.1		O/C	4573.2 2237 12 Jun 2020			0 0
343003 Airframe	Diplexer, Marker Beacon DMH21-1 35998	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0 SENSOR SYSTEMS INC
343004 Airframe	Diplexer, Glide Scope Power SSPD-332-3 1400	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0 A E PETSCHE CO INC
343005 Airframe	Power Divider, Marker Beacon SSPD-113-39 1153	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0
343006 Airframe	Diplexer, Marker Beacon (#2) DMH21-1 36288	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0
343101 Airframe	Glide Slope Antenna - Removal / Installation S41422-2 111-6175	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0 CASTLE METALS/A.M. CASTLE & CO
344001 Airframe	Inertial Reference Unit No. 1 - Removal / Installation HG2100AB07 56010882	HRS AFL MOS MSC		4593.3 2210 139.9		O/C	937.1 389 19 Mar 2011			0 0 AEROCONTROLEX GROUP

Notes: VERFIED BY:PQ005

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
344002 Airframe	Inertial Reference Unit No. 2 - Removal / Installation HG2100AB07 56012436	HRS AFL MOS MSC		4593.3 2210 139.9		 O/C	937.1 389 19 Mar 2011			0 0 AEROCONTROLEX GROUP
Notes: VERFIED BY:PQ005										
344003 Airframe	Inertial Reference Unit No. 3 - Removal / Installation HG2100AB07 56015879	HRS AFL MOS MSC		4593.3 2210 139.9		 O/C	937.1 389 19 Mar 2011			0 0 AEROCONTROLEX GROUP
Notes: VERFIED BY:PQ005										
344025 Airframe	Irs MODE Select Panel - Operational Check	HRS AFL MOS MSC		2640.5 1094 90.4		 O/C	2889.9 1505 04 May 2015			0 0
344033 Airframe	Module, #1 Irs Personality 7519272-901 08028805	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 GULFSTREAM DALLAS
Notes: VERFIED BY:PQ005										
344036 Airframe	Module, #2 Irs Personality 7519272-901 08028803	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 GULFSTREAM DALLAS
Notes: VERFIED BY:PQ005										
344039 Airframe	Module, #3 Irs Personality 7519272-901 08038856	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 GULFSTREAM DALLAS
Notes: VERFIED BY:PQ005										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
344101	Weather Radar Receiver / Transmitter Assembly - Removal / Installation 7021450-801 08068622	HRS AFL MOS MSC		5525.5 2597 171.4		 O/C	4.9 2 05 Aug 2008			0 0 HONEYWELL
Airframe										
344105	Weather Radar Controller No. 1 - Removal / Installation 7006921-825 03042921	HRS AFL MOS MSC		2367 954 73		 O/C	3163.4 1645 17 Oct 2016			0 0
Airframe										
344106	Weather Radar Controller No. 2 - Removal / Installation 7006921-825 08043604	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 REBLING PLASTICS
Airframe										
344111	Weather Radar System - Operational Check	HRS AFL MOS MSC		2367 954 72.3		 O/C	3163.4 1645 07 Nov 2016			0 0
Airframe										
344155	Lightning Sensor System - Operational Check	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										
Notes: PN: 7012738-905 SN: <NONE>.										
344201	Enhanced Ground Proximity Warning System Module No. 1 - Removal / Installation 7028419-1904 08022093	HRS AFL MOS MSC	TSN:886.2 TSN:355 TSN:32	4644.2 2244 142.6		 O/C	886.2 355 27 Dec 2010			0 0 HONEYWELL
Airframe										
344202	Enhanced Ground Proximity Warning System Module No. 2 - Removal / Installation 7028419-1904 08032047	HRS AFL MOS MSC	TSN:886.2 TSN:355 TSN:32	4644.2 2244 142.6		 O/C	886.2 355 27 Dec 2010			0 0 HONEYWELL
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
344203 Airframe	Egpws - Return to Service Test	HRS AFL MOS MSC		4644.2 2244 142.6		 O/C	886.2 355 27 Dec 2010			0 0
344204 Airframe	Egpws - Database Update	HRS AFL MOS MSC		866.2 299 22.4		 O/C	4664.2 2300 04 Jan 2021			0 0
Notes: GREEN DISC 996-0146-568										
344207 Airframe	Egpws - Operational Test	HRS AFL MOS MSC		2640.5 1094 90.4		 O/C	2889.9 1505 04 May 2015			0 0
344208 Airframe	Inertial Reference System - Operational Check	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
344301 Airframe	TCAS Computer - Removal / Installation 7517900-55020 20007592	HRS AFL MOS MSC		3246.2 1432 107.9		 O/C	2284.2 1167 18 Nov 2013			0 0 AVGROUP ATLANTA
344302 Airframe	TCAS - Operational Check	HRS AFL MOS MSC		882.2 304 23		 O/C	4648.2 2295 15 Dec 2020			0 0
Notes: PN: 7517900-55004 SN: <NONE>. OPS CHECK PERFORMED AND FOUND SATIS.										
344303 Airframe	TCAS Antenna (Upper) - Removal / Installation 7514060-902 ANE28465	HRS AFL MOS MSC	TSN:4573.2 TSN:2237 TSN:145	957.2 362 29.1		 O/C	4573.2 2237 12 Jun 2020			0 0
Notes: PQ162										

ATA / U=Custom / Logbook Position	Description	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
	Part Number / Serial Number									
	HW / SW									
	MM Ref									
	Ops Number(s)									
344304	TCAS Antenna (Lower) - Removal / Installation	HRS	TSN:4573.2	957.2			4573.2			0
	DM NI50-9-2 10521	AFL	TSN:2237	362			2237			0
		MOS	TSN:145	29.1			12 Jun 2020			
		MSC				O/C				
Airframe										
345005	VOR / ILS / Data Link Module No. 1 - Removal / Installation	HRS		804.8			4725.6			0
	7026202-801 15059016	AFL		275			2324			0
		MOS		20.7			26 Feb 2021			
		MSC				O/C				
Airframe										
345006	VOR / ILS / Data Link Module No. 2 - Removal / Installation	HRS		5530.4			0			0
	7026202-801 08033326	AFL		2599			0			0
		MOS		174.6			28 Apr 2008			HONEYWELL
		MSC				O/C				
Airframe										
Notes: VERFIED BY:PQ005										
345011	Very High Frequency Omnidirectional Range / Instrument Landing System / Data Link - Functional Check	HRS		957.2			4573.2			0
		AFL		362			2237			0
		MOS		29.1			12 Jun 2020			
		MSC				O/C				
Airframe										
345025	Mini Cabinet, Comm/Nav	HRS	TSN:2284.2	3246.2			2284.2			0
	7026240-902 08031654	AFL	TSN:1167	1432			1167			0
		MOS	TSN:67	107.8			22 Nov 2013			HONEYWELL
		MSC				O/C				
Airframe										
Notes: VERFIED BY:PQ005										
345055	Antenna, Left VOR/LOC	HRS		5530.4			0			0
	DM N4-17-1/P 25901	AFL		2599			0			0
		MOS		174.6			28 Apr 2008			AIL SYSTEMS INC.
		MSC				O/C				
Airframe										
345056	Antenna, Right VOR/LOC	HRS		5530.4			0			0
	DM N4-17-1/P 25903	AFL		2599			0			0
		MOS		174.6			28 Apr 2008			AIL SYSTEMS INC.
		MSC				O/C				
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
345060 Airframe	Mcdu Software Load (Warranty Managed Program)	HRS AFL MOS MSC		2157 893 66.2		 O/C	3373.4 1706 11 May 2017			0 0
345101 Airframe	DME Module No. 1 - Removal / Installation 7510184-855 0803D614	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 HONEYWELL
Notes: VERFIED BY:PQ005										
345102 Airframe	DME Module No. 2 - Removal / Installation 7510184-855 0803D595	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 HONEYWELL
Notes: VERFIED BY:PQ005										
345105 Airframe	DME Antenna No. 1 - Removal / Installation DM NI50-9-2 10496	HRS AFL MOS MSC	TSN:4573.2 TSN:2237 TSN:145	957.2 362 29.1		 O/C	4573.2 2237 12 Jun 2020			0 0
345106 Airframe	DME Antenna No. 2 - Removal / Installation DM NI50-9-2 10724	HRS AFL MOS MSC	TSN:4573.2 TSN:2237 TSN:145	957.2 362 29.1		 O/C	4573.2 2237 12 Jun 2020			0 0
345115 Airframe	DME System - Functional Check	HRS AFL MOS MSC		957.2 362 29.1		 O/C	4573.2 2237 12 Jun 2020			0 0
345201 Airframe	ADF Receiver Module No. 1 - Removal / Installation 7510114-855 0803C681	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 HONEYWELL
Notes: VERFIED BY:PQ005										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
345202	ADF Receiver Module No. 2 - Removal / Installation 7510114-855 0711C442	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 HONEYWELL
Airframe										
Notes: SEE R&I LOG A/C 4123. PQ211										
345203	ADF System No. 1 - Operational Check	HRS AFL MOS MSC		882.2 304 23		 O/C	4648.2 2295 15 Dec 2020			0 0
Airframe										
345204	ADF System No. 2 - Operational Check	HRS AFL MOS MSC		882.2 304 23		 O/C	4648.2 2295 15 Dec 2020			0 0
Airframe										
345205	ADF Antenna No. 1 - Removal / Installation 7510300-901 0708C950	HRS AFL MOS MSC	TSN:4573.2 TSN:2237 TSN:145	957.2 362 29.1		 O/C	4573.2 2237 12 Jun 2020			0 0
Airframe										
Notes: PQ162										
345206	ADF Antenna No. 2 - Removal / Installation 7510300-901 0710E095	HRS AFL MOS MSC	TSN:4573.2 TSN:2237 TSN:144	957.2 362 29.1		 O/C	4573.2 2237 12 Jun 2020			0 0
Airframe										
345301	MODE S Diversity Transponder Module No. 1 - Removal / Installation 7517402-970 0803D783	HRS AFL MOS MSC		3246.2 1432 107.6		 O/C	2284.2 1167 28 Nov 2013			0 0 HONEYWELL
Airframe										
Notes: VERFIED BY:PQ005										
345302	MODE S Diversity Transponder Module No. 2 - Removal / Installation 7517402-970 0803D789	HRS AFL MOS MSC		3246.2 1432 107.8		 O/C	2284.2 1167 22 Nov 2013			0 0 HONEYWELL
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
345305	ATC No. 1 - Functional Test / Inspection (FAR 91.413)	HRS		697.6			4832.8			0
		AFL		234			2365			0
		MOS		18.5		24	30 Apr 2021	30 Apr 2023		
Airframe	052000-24M	[End Of Month Item]								CALIBRATION
345306	ATC No. 2 - Functional Test / Inspection (FAR 91.413)	HRS		697.6			4832.8			0
		AFL		234			2365			0
		MOS		18.5		24	30 Apr 2021	30 Apr 2023		
Airframe	052000-24M	[End Of Month Item]								CALIBRATION
345315	ATC MODE S Antenna No. 1 (Upper) - Removal / Installation DM NI50-9-2 10501	HRS	TSN:4573.2	957.2			4573.2			0
		AFL	TSN:2237	362			2237			0
		MOS	TSN:145	29.1			12 Jun 2020			
		MSC				O/C				
Airframe										
Notes: PQ162										
345316	ATC MODE S Antenna No. 2 (Upper) - Removal / Installation DM NI50-9-2 10510	HRS	TSN:4573.2	957.2			4573.2			0
		AFL	TSN:2237	362			2237			0
		MOS	TSN:145	29.1			12 Jun 2020			
		MSC				O/C				
Airframe										
Notes: PQ162										
345317	ATC MODE S Antenna No. 1 (Lower) - Removal / Installation DM NI50-9-2 10516	HRS	TSN:4573.2	957.2			4573.2			0
		AFL	TSN:2237	362			2237			0
		MOS	TSN:145	29.1			12 Jun 2020			
		MSC				O/C				
Airframe										
345318	ATC MODE S Antenna No. 2 (Lower) - Removal / Installation DM NI50-9-2 10509	HRS	TSN:4573.2	957.2			4573.2			0
		AFL	TSN:2237	362			2237			0
		MOS	TSN:145	29.1			12 Jun 2020			
		MSC				O/C				
Airframe										
345801	GPS Antenna (No. 1) - Removal / Installation S67-1575-237 825-1452	HRS	TSN:366.7	957.2			4573.2			0
		AFL	TSN:160	362			2237			0
		MOS	TSN:75	29.1			12 Jun 2020			
		MSC				O/C				
Airframe										
Notes: PQ162										

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
345802	GPS Antenna (No. 2) - Removal / Installation		HRS	TSN:3636.1	957.2			4573.2			0
	S67-1575-237	825-0548	AFL	TSN:1848	362			2237			0
			MOS	TSN:113	29.1			12 Jun 2020			
			MSC				O/C				
Airframe											
Notes: PQ162											
345810	GPS - Operational Check		HRS		791			4739.4			0
			AFL		271			2328			0
			MOS		20.3			08 Mar 2021			
			MSC				O/C				
Airframe											
345813	GPS Module No. 1 - Removal / Installation		HRS		1140.1			4390.3			0
	245-604067-100	19028883	AFL		447			2152			0
			MOS	TSN:8	37			16 Oct 2019			B/E AEROSPACE, INC.
			MSC				O/C				
Airframe											
Notes: VERFIED BY:PQ005											
345814	GPS Module No. 2 - Removal / Installation		HRS		791			4739.4			0
	245-604067-100	08043000	AFL		271			2328			0
			MOS		20.3			08 Mar 2021			
			MSC				O/C				
Airframe											
Notes: VERFIED BY:PQ005											
346000	Multifunction Control Display Unit - Operational Test		HRS		844.4			4686			0
			AFL		290			2309			0
			MOS		22.1			13 Jan 2021			
			MSC				O/C				
Airframe											
346001	Multifunction Control Display Unit No. 1 - Removal / Installation		HRS		408.1			5122.3			0
	7025725-951	08043388	AFL		143			2456			0
			MOS		11.2			09 Dec 2021			
			MSC				O/C				
Airframe											
Notes: FOUN S/N 06071945 INSTALLED											
346002	Multifunction Control Display Unit No. 2 - Removal / Installation		HRS		408.1			5122.3			0
	7025725-951	0591382	AFL		143			2456			0
			MOS		11.2			09 Dec 2021			
			MSC				O/C				
Airframe											
Notes: MOD:A,B,C,D,E (VERFIED BY:PQ005)S/N REMOVED: 05061236											

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
346003	Multifunction Control Display Unit No. 3 - Removal / Installation 7025725-951 05041149	HRS AFL MOS MSC		957.2 362 29.1		 O/C	4573.2 2237 12 Jun 2020			0 0
Airframe										
Notes: MOD:A,B,C,D,E (VERFIED BY:PQ005)										
346005	FMS - Software Verification	HRS AFL MOS MSC		2640.5 1094 90.2		 O/C	2889.9 1505 09 May 2015			0 0
Airframe										
346025	FMS Nav Database - Update	HRS AFL DATE [DAYS: -8]		6.5 2 5 d	 -10	 28d	5523.9 2597 11 Nov 2022	29 Nov 2022*		0 0
Airframe										
Notes: UPDATED BY PILOT										
346040	Data Management Unit - Removal / Installation 7031051-901 08031569	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 HONEYWELL
Airframe										
Notes: VERFIED BY:PQ005										
346500	Visual Guidance System - Return to Service Test	HRS AFL MOS MSC		2367 954 72.3		 O/C	3163.4 1645 07 Nov 2016			0 0
Airframe										
35 - Oxygen										
350001	Oxygen System - Operational Test	HRS AFL MOS MSC		279.7 99 7.5		 O/C	5250.7 2500 30 Mar 2022			0 0
Airframe										
351001	Crew Oxygen System (Pilot) - Operational Check	HRS AFL MOS MSC		1416.9 561 42.8		 O/C	4113.5 2038 23 Apr 2019			0 0
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
351002 Airframe	Crew Oxygen System (Copilot) - Operational Check	HRS AFL MOS MSC		2197.2 909 68		 O/C	3333.2 1690 16 Mar 2017			0 0
351003 Airframe	Crew Oxygen System (Observer) - Operational Check	HRS AFL MOS MSC		1416.9 561 42.8		 O/C	4113.5 2038 23 Apr 2019			0 0
351011 Airframe	Crew Oxygen Mask (Pilot) - Restore MC10-15-158 SE13880	HRS AFL MOS [End Of Month Item]		1416.9 561 42.8		 72	4113.5 2038 23 Apr 2019	30 Apr 2025		0 0 IN EROS CORPORATION OVERHAUL
Notes: VERIFIED BY Q124019										
351012 Airframe	Crew Oxygen Mask (Copilot) - Restore MC10-15-158 70282	HRS AFL MOS [End Of Month Item]		2197.2 909 68		 72	3333.2 1690 16 Mar 2017	31 Mar 2023		0 0 IN EROS CORPORATION OVERHAUL
351013 Airframe	Crew Oxygen Mask (Observer) - Restore MC10-15-158* 140669	HRS AFL MOS [End Of Month Item]		1416.9 561 42.8		 72	4113.5 2038 23 Apr 2019	30 Apr 2025		0 0 IN EROS CORPORATION OVERHAUL
Notes: VERIFIED BY Q124019										
351021 Airframe	Crew Oxygen Mask and Regulator (Pilot) - Removal / Installation MC10-15-158 SE13880	HRS AFL MOS MSC		1416.9 561 42.8		 O/C	4113.5 2038 23 Apr 2019			0 0 IN EROS CORPORATION
351022 Airframe	Crew Oxygen Mask and Regulator (Copilot) - Removal / Installation MC10-15-158 70282	HRS AFL MOS MSC		2197.2 909 68		 O/C	3333.2 1690 16 Mar 2017			0 0 IN EROS CORPORATION

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
351023 Logbook Position: Airframe	Crew Oxygen Mask and Regulator (Observer) - Removal / Installation MC10-15-158* 140669	HRS AFL MOS MSC		1416.9 561 42.8		 O/C	4113.5 2038 23 Apr 2019			0 0
351026 Airframe	Crew Oxygen Mask Box (Copilot) - Removal / Installation MXP326-2 SE38085	HRS AFL MOS MSC		2197.2 909 68		 O/C	3333.2 1690 16 Mar 2017			0 0
351101 Airframe Notes: Q303331	Crew Oxygen Servicing Pressure Gage - Removal / Installation P24094-1 0670	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 GULFSTREAM DALLAS
351102 Airframe	Crew Oxygen Quantity Gage (Cockpit) - Removal / Installation 163LCP81 07100899	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 GULFSTREAM BRN SPARES IPT
351110 Airframe	Crew Oxygen Mask / Regulator / Box Assembly (Pilot) - Detailed Inspection 052000-3C,200203	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		957.2 362 29.1		 36	4573.2 2237 12 Jun 2020	30 Jun 2023	31 Jul 2023	0 0
351111 Airframe	Crew Oxygen Mask / Regulator / Box Assembly (Copilot) - Detailed Inspection 052000-3C,200203	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		957.2 362 29.1		 36	4573.2 2237 12 Jun 2020	30 Jun 2023	31 Jul 2023	0 0
351112 Airframe	Crew Oxygen Mask / Regulator / Box Assembly (Observer) - Detailed Inspection 052000-3C,200203	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		957.2 362 29.1		 36	4573.2 2237 12 Jun 2020	30 Jun 2023	31 Jul 2023	0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
351201 Airframe	Crew Oxygen Cylinder (No. 1) - Discard 805983-15 C12080070	HRS AFL MOS [End Of Month Item]		2157 893 66.2		180	3373.4 1706 09 May 2017	31 May 2027		0 0 AV OX INC MANUFACTURE
Notes: VERIFIED BY Q124019										
351202 Airframe	Passenger Oxygen Cylinder (No. 2) - Discard 805983-15 ALT282-46307	HRS AFL MOS [End Of Month Item]		6.5 2 .2		180	5523.9 2597 11 Nov 2022	31 Jan 2037		0 0 MANUFACTURE
Notes: VERIFIED BY Q124019										
351206 Airframe	Crew Oxygen Low-Pressure Switch - Operational Test	HRS AFL MOS MSC		2157 893 66.2		O/C	3373.4 1706 10 May 2017			0 0
351207 Airframe	Passenger Oxygen Low-Pressure Switch (No. 2 Bottle) - Operational Test	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0
351208 Airframe	Passenger Oxygen Low Pressure Switch - Operational Test	HRS AFL MOS MSC		2157 893 66.2		O/C	3373.4 1706 10 May 2017			0 0
351211 Airframe	Crew Oxygen Bottle (No. 1) - (Hydrostatic) Functional Test	HRS AFL MOS [End Of Month Item]		560.5 185 14.1		60	4969.9 2414 14 Sep 2021	31 Jul 2026		0 0 HYDRO CHECK
Notes: PN: 805983-15 SN: C12080070.										
351212 Airframe	Passenger Oxygen Bottle (No. 2) - (Hydrostatic) Functional Test	HRS AFL MOS [End Of Month Item]		279.7 99 7.5		60	5250.7 2500 30 Mar 2022	31 Mar 2027		0 0 HYDRO CHECK
Notes: PN: 805983-15 SN: C08030765. VERIFIED BY Q124019										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
351221 Logbook Position	Crew Oxygen Cylinder (No. 1) - Removal / Installation 805983-15 C20080116	HRS AFL MOS MSC		560.5 185 14.1		 O/C	4969.9 2414 14 Sep 2021			0 0
Airframe										
Notes: REF: OPEN/CLOSE CARDS FOR PANEL CLOSURE INDEX 5 PAGE 14REF: 12.23, 12.24,12.25,12.26 FOR FOLLOW ON CMP"S REGULATOR PN:805982-01REGULATOR SN: C12010762CURRENT HYDRO: 09/2016NEXT HYDRO DUE : 09/2021CYL DOM: 12/2011CYL EXP: 12/2026TW# 55										
351222 Logbook Position	Passenger Oxygen Cylinder (No. 2) Removal / Installation 805983-15 ALT282-46307	HRS AFL MOS MSC		6.5 2 .2		 O/C	5523.9 2597 11 Nov 2022			0 0
Airframe										
351301 Logbook Position	Valve, Crew Oxygen Shutoff 01C74T01-1 15595	HRS AFL MOS MSC	5530.4 2599 174.6			 O/C	0 0 28 Apr 2008			0 0
Airframe										
352001 Logbook Position	Passenger Oxygen System (Automatic MODE) - Functional Test	HRS AFL MOS		882.2 304 23.2		 36	4648.2 2295 09 Dec 2020	31 Dec 2023	31 Jan 2024	0 0
Airframe	[End Of Month Item] [MOS: +1m/-1m] 052000-3C,200203									
352003 Logbook Position	Passenger Oxygen System (Manual MODE) - Operational Test	HRS AFL MOS		957.2 362 29.1		 36	4573.2 2237 12 Jun 2020	30 Jun 2023	31 Jul 2023	0 0
Airframe	[End Of Month Item] [MOS: +1m/-1m] 052000-3C,200203									
352004 Logbook Position	Passenger Oxygen Drop-Down Mask Assemblies - Detailed Inspection	HRS AFL MOS		957.2 362 29.1		 36	4573.2 2237 12 Jun 2020	30 Jun 2023	31 Jul 2023	0 0
Airframe	[End Of Month Item] [MOS: +1m/-1m] 052000-3C,200203									
352005 Logbook Position	Passenger Oxygen Servicing Pressure Gage - Removal / Installation P24094-1 0678	HRS AFL MOS MSC	5530.4 2599 174.6			 O/C	0 0 28 Apr 2008			0 0 GULFSTREAM DALLAS
Airframe										
Notes: Q303331										

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Description: Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
352010	Passenger Oxygen Quantity Gage (Cockpit) - Removal / Installation		HRS		5530.4			0			0
			AFL		2599			0			0
	163LCP81	07100902	MOS		174.6			28 Apr 2008			GULFSTREAM BRN SPARES IPT
			MSC				O/C				
Airframe											
352013	Passenger Oxygen Low-Pressure Switch - Removal / Installation		HRS		5530.4			0			0
			AFL		2599			0			0
	P24029-9	2567	MOS		174.6			28 Apr 2008			PACIFIC PRECISION PRODUCTS
			MSC				O/C				
Airframe											
Notes: Q303331											
352014	Passenger Oxygen Controller - Removal / Installation		HRS		3639.9			1890.5			0
	412040-11	0912	AFL		1663			936			0
			MOS		118.9			19 Dec 2012			GULFSTREAM - LONG BEACH
			MSC				O/C				
Airframe											
352017	Crew Oxygen Low-Pressure Switch - Removal / Installation		HRS		5530.4			0			0
			AFL		2599			0			0
	P24029-9	2554	MOS		174.6			28 Apr 2008			PACIFIC PRECISION PRODUCTS
			MSC				O/C				
Airframe											
Notes: Q303331											
352101	Presentation Unit #1 Oxygen		HRS		5525.5			4.9			0
	833-610-15	M08031291	AFL		2597			2			0
			MOS	TSN:3	173.2			09 Jun 2008			AVOX SYSTEM, INC.
			MSC				O/C				
Airframe											
352102	Presentation Unit #2 Oxygen		HRS		5525.5			4.9			0
	833-610-14	M08040035	AFL		2597			2			0
			MOS	TSN:2	173.2			09 Jun 2008			AVOX SYSTEM, INC.
			MSC				O/C				
Airframe											

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
Logbook Position	HW	SW									
	MM Ref										
	Ops Number(s)										
352103	Presentation Unit #3 Oxygen 833-610-14	M08040037	HRS AFL MOS MSC	TSN:2	5525.5 2597 173.2		O/C	4.9 2 09 Jun 2008			0 0 AVOX SYSTEM, INC.
Airframe											
352104	Presentation Unit #4 Oxygen 833-610-14	M08040042	HRS AFL MOS MSC	TSN:2	5525.5 2597 173.2		O/C	4.9 2 09 Jun 2008			0 0 AVOX SYSTEM, INC.
Airframe											
352105	Presentation Unit #5 Oxygen 833-610-14	M08040044	HRS AFL MOS MSC	TSN:2	5525.5 2597 173.2		O/C	4.9 2 09 Jun 2008			0 0 AVOX SYSTEM, INC.
Airframe											
352106	Presentation Unit #6 Oxygen 833-610-15	M08031301	HRS AFL MOS MSC	TSN:3	5525.5 2597 173.2		O/C	4.9 2 09 Jun 2008			0 0 AVOX SYSTEM, INC.
Airframe											
352107	Presentation Unit #7 Oxygen 833-610-15	M08031302	HRS AFL MOS MSC	TSN:3	5525.5 2597 173.2		O/C	4.9 2 09 Jun 2008			0 0 AVOX SYSTEM, INC.
Airframe											
352108	Presentation Unit #8 Oxygen 833-610-14	M08040045	HRS AFL MOS MSC	TSN:2	5525.5 2597 173.2		O/C	4.9 2 09 Jun 2008			0 0 AVOX SYSTEM, INC.
Airframe											
352109	Presentation Unit #9 Oxygen 833-610-14	M08040049	HRS AFL MOS MSC		5525.5 2597 173.2		O/C	4.9 2 09 Jun 2008			0 0 AVOX SYSTEM, INC.
Airframe											

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
Logbook Position	HW	SW									
	MM Ref										
	Ops Number(s)										
352110	Presentation Unit #10 Oxygen 833-610-15	M08031303	HRS AFL MOS MSC	TSN:3	5525.5 2597 173.2		O/C	4.9 2 09 Jun 2008			0 0 AVOX SYSTEM, INC.
Airframe											
352111	Presentation Unit #11 Oxygen 833-610-15	M08031304	HRS AFL MOS MSC	TSN:3	5525.5 2597 173.2		O/C	4.9 2 09 Jun 2008			0 0 AVOX SYSTEM, INC.
Airframe											
352112	Presentation Unit #12 Oxygen 833-610-14	M08040055	HRS AFL MOS MSC	TSN:2	5525.5 2597 173.2		O/C	4.9 2 09 Jun 2008			0 0 AVOX SYSTEM, INC.
Airframe											
352113	Presentation Unit #13 Oxygen 833-610-14	M08040051	HRS AFL MOS MSC	TSN:2	5525.5 2597 173.2		O/C	4.9 2 09 Jun 2008			0 0 AVOX SYSTEM, INC.
Airframe											
352114	Presentation Unit #14 Oxygen 833-610-14	M08040056	HRS AFL MOS MSC	TSN:2	5525.5 2597 173.2		O/C	4.9 2 09 Jun 2008			0 0 AVOX SYSTEM, INC.
Airframe											
352115	Presentation Unit #15 Oxygen 833-610-14	M08040065	HRS AFL MOS MSC	TSN:2	5525.5 2597 173.2		O/C	4.9 2 09 Jun 2008			0 0
Airframe											
352116	Presentation Unit #16 Oxygen 833-610-14	M08040067	HRS AFL MOS MSC	TSN:2	5525.5 2597 173.2		O/C	4.9 2 09 Jun 2008			0 0
Airframe											

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
Logbook Position	HW	SW									
	MM Ref										
	Ops Number(s)										
352117	Presentation Unit #17 Oxygen 833-610-14	M08040068	HRS AFL MOS MSC	 TSN:2 	5525.5 2597 173.2 		 O/C	4.9 2 09 Jun 2008 			0 0
Airframe											
352118	Presentation Unit #18 Oxygen 833-610-14	M08040070	HRS AFL MOS MSC	 TSN:2 	5525.5 2597 173.2 		 O/C	4.9 2 09 Jun 2008 			0 0
Airframe											
352119	Presentation Unit #19 Oxygen 833-610-14	M08040074	HRS AFL MOS MSC	 TSN:2 	5525.5 2597 173.2 		 O/C	4.9 2 09 Jun 2008 			0 0
Airframe											
352120	Presentation Unit, Jumpseat 833-801-03	D07120108	HRS AFL MOS MSC	 	5525.5 2597 174.1 		 O/C	4.9 2 14 May 2008 			0 0 HUGHES INDUSTRIAL
Airframe											
352121	Presentation Unit Galley 833-610-15	M08031322	HRS AFL MOS MSC	 TSN:4 	5525.5 2597 171.9 		 O/C	4.9 2 18 Jul 2008 			0 0 AVOX SYSTEM, INC.
Airframe											
352122	Presentation Unit Aft Lav 833-610-15	M08031323	HRS AFL MOS MSC	 	5525.5 2597 171.9 		 O/C	4.9 2 18 Jul 2008 			0 0 AVOX SYSTEM, INC.
Airframe											
352123	Presentation Unit Fwd Lav 833-610-15	M08031316	HRS AFL MOS MSC	 TSN:4 	5525.5 2597 171.9 		 O/C	4.9 2 18 Jul 2008 			0 0 AVOX SYSTEM, INC.
Airframe											

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
352125 Airframe	Presentation Unit #20 Oxygen 833-610-15 M08031305	HRS AFL MOS MSC	TSN:3	5525.5 2597 173.2		O/C	4.9 2 09 Jun 2008			0 0
352126 Airframe	Presentation Unit #21 Oxygen 833-610-15 M08031314	HRS AFL MOS MSC	TSN:3	5525.5 2597 173.2		O/C	4.9 2 09 Jun 2008			0 0
352127 Airframe	Presentation Unit #22 Oxygen 833-610-14 M08040078	HRS AFL MOS MSC	TSN:2	5525.5 2597 173.2		O/C	4.9 2 09 Jun 2008			0 0
352506 Airframe	Therapeutic Oxygen System (Outlet No. 1) - Functional Test 052000-3C,200203	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		957.2 362 29.1		36	4573.2 2237 12 Jun 2020	30 Jun 2023	31 Jul 2023	0 0
352516 Airframe	Therapeutic Oxygen Mask (No. 1) - Detailed Inspection 052000-3C,200203	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		957.2 362 29.1	12	36	4573.2 2237 12 Jun 2020	30 Jun 2023*	31 Jul 2023	0 0
353001 Airframe	Portable Oxygen Bottle (No. 1) - Removal / Installation 5600-9M6A-F30AN P20060418	HRS AFL MOS MSC	TSN:507.4 TSN:163 TSN:12	190.2 71 6.2		O/C	5340.2 2528 10 May 2022			0 0
353002 Airframe	Portable Oxygen Bottle and Mask Assembly (No. 1) - Detailed Inspection 052000-1C,200201	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		190.2 71 6.2	33	12	5340.2 2528 10 May 2022	30 Jun 2023*	31 Jul 2023	0 0

Notes: REFERENCE ICA DOCUMENT GC42801A344 REV - FOR STC ST03579AT-D

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
353003	Portable Oxygen Bottle (No. 1) - (Hydrostatic) Functional Test	HRS		697.6			4832.8			0
		AFL		234			2365			0
		MOS		18.5		60	30 Apr 2021	30 Jun 2025		
		[End Of Month Item]								HYDRO CHECK
Airframe										
Notes: PN: 5600-9M6A-F30AN SN: <NONE>. NEXT O/H DUE: 6/2016.										
353004	Portable Oxygen Bottle and Mask Assembly - Operational Test	HRS		957.2			4573.2			0
		AFL		362			2237			0
		MOS		29.1		36	12 Jun 2020	30 Jun 2023	31 Jul 2023	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-3C,200203									
Notes: REFERENCE ICA DOCUMENT GC42801A344 REV - FOR STC ST03579AT-D										
353005	Portable Oxygen Bottle Mask (No. 1) - Inspection	HRS		5530.4			0			0
		AFL		2599			0			0
		MOS		174.6			28 Apr 2008			
		MSC				O/C				
Airframe										
353016	Portable Oxygen Mask (No. 1) - Restore 10800A2F A2Q05	HRS		4644.3			886.1			0
		AFL		2244			355			0
		MOS		142.6			27 Dec 2010			AVOX SYSTEM, INC.
		MSC				O/C				
Airframe										
36 - Pneumatic										
360011	Valve, Ttp/Bag Door Seal Solen 320154-4-1 1808	HRS		5530.4			0			0
		AFL		2599			0			0
		MOS		174.6			28 Apr 2008			GENERAL DYNAMICS AVIATIONS SERVICES
		MSC				O/C				
Airframe										
Notes: Q302557										
361001	Bleed AIR Controller (Left) - Removal / Installation 1152564-3 115264-00276	HRS		1416.9			4113.5			0
		AFL		561			2038			0
		MOS		42.7			24 Apr 2019			HONEYWELL ENGINES SYSTEMS & SERVICE
		MSC				O/C				
Airframe										

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
Logbook Position	HW	SW									
	MM Ref										
	Ops Number(s)										
361002	Bleed AIR Controller (Right) - Removal / Installation		HRS		1416.9			4113.5			0
	1152564-3	115264-00634	AFL		561			2038			0
			MOS		42.7			24 Apr 2019			HONEYWELL
			MSC				O/C				ENGINES SYSTEMS & SERVICE
Airframe											
361105	Pressure Regulating and Shut-Off Valve (Left) - Removal / Installation		HRS		5530.4			0			0
	3215868-2	368	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			HONEYWELL
			MSC				O/C				ENGINES SYSTEMS & SERVICE
Airframe											
361106	Pressure Regulating and Shut-Off Valve (Right) - Removal / Installation		HRS		1596.4			3934			0
	3215868-2	282	AFL		621			1978			0
			MOS		47.1			14 Dec 2018			HONEYWELL
			MSC				O/C				ENGINES SYSTEMS & SERVICE
Airframe											
361107	Valve, L Eng Bleed AIR Check		HRS		5530.4			0			0
	3202362-1	1509	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			GULFSTREAM
			MSC				O/C				SAV PROD-IPT
Airframe											
361108	Valve, R Eng Bleed AIR Check		HRS		5530.4			0			0
	3202362-1	1510	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			
			MSC				O/C				
Airframe											
361109	High-Stage 12 Regulating Valve (Left) - Removal / Installation		HRS		5530.4			0			0
	3291684-1	384	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			
			MSC				O/C				
Airframe											

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
361110	High-Stage 12 Regulating Valve (Right) - Removal / Installation 3291684-1 388	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										
361201	Auxiliary Power Unit Check Valve - Removal / Installation 123312-9-1 19246	HRS AFL MOS MSC		560.5 185 14.1		 O/C	4969.9 2414 14 Sep 2021			0 0
Airframe										
361202	Auxiliary Power Unit Check Valve - Detailed Inspection	HRS AFL MOS		560.5 185 14.1	30.1	5000	4969.9 2414 14 Sep 2021	10000*	10050	0 0
Airframe	052000-10A,200110	[HRS: +50/-50]								
361203	Bleed AIR Isolation Shut-Off Valve - Removal / Installation 3291826-1 291	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 HONEYWELL-ENGINEERING SYSTEMS & SERV.
Airframe										
Notes: VER BY Q307597										
361204	High-Stage 12 Servo Regulator Valve and Torque Motor (Left) - Removal / Installation 3215636-3 1195	HRS AFL MOS MSC	TSN:3760.9 TSN:1882 TSN:120	1769.5 717 54.8		 O/C	3760.9 1882 23 Apr 2018			0 0 HONEYWELL ENGINES SYSTEMS & SERVICE
Airframe										
361205	High-Stage 12 Servo Regulator Valve and Torque Motor (Right) - Removal / Installation 3215636-3 1194	HRS AFL MOS MSC	TSN:3760.9 TSN:1882 TSN:120	1769.5 717 54.8		 O/C	3760.9 1882 23 Apr 2018			0 0 HONEYWELL ENGINES SYSTEMS & SERVICE
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
361211 Airframe	Valve, L Bleed AIR 3214068-3-1 4053	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0 HONEYWELL-ENGINEERING SYSTEMS & SERV.
361212 Airframe	Valve, R Bleed AIR 3214068-3-1 4046	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0 HONEYWELL-ENGINEERING SYSTEMS & SERV.
361215 Airframe	Bleed AIR Flow Control and Pressure Regulation - Operational Test	HRS AFL MOS MSC		882.2 304 23.3		O/C	4648.2 2295 08 Dec 2020			0 0
361401 Airframe Notes: Q306859	Bleed AIR Precooler (Left) - Removal / Installation 2340118-1-1 1541	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0 GULFSTREAM SAV PROD-IPT
361402 Airframe Notes: Q306859	Bleed AIR Precooler (Right) - Removal / Installation 2340118-1-1 1548	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0 GULFSTREAM SAV PROD-IPT
361403 Airframe Notes: Q306859	Precooler Inlet Temperature Sensor (Left) - Removal / Installation 1150124-2 1150124-07433	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0 HONEYWELL ASCA INC.

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
361404	Precooler Inlet Temperature Sensor (Right) - Removal / Installation		HRS		5530.4			0			0
			AFL		2599			0			0
	1150124-2	1150124-07339	MOS		174.6			28 Apr 2008			HONEYWELL ASCA INC.
			MSC				O/C				
Airframe											
Notes: Q306859											
361405	Bleed AIR Temperature Servo Pressure Regulator and Torque Motor (Left) - Removal / Installation		HRS		5530.4			0			0
			AFL		2599			0			0
	540-1394-2	D0806	MOS		174.6			28 Apr 2008			
			MSC				O/C				
Airframe											
361406	Bleed AIR Temperature Servo Pressure Regulator and Torque Motor (Right) - Removal / Installation		HRS		5530.4			0			0
			AFL		2599			0			0
	540-1394-2	D0867	MOS		174.6			28 Apr 2008			
			MSC				O/C				
Airframe											
361407	Fan AIR Valve (Left) - Removal / Installation		HRS		5530.4			0			0
	397150-3-1	2633	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			
			MSC				O/C				
Airframe											
Notes: Q306859											
361408	Fan AIR Valve (Right) - Removal / Installation		HRS		5530.4			0			0
	397150-3-1	2635	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			
			MSC				O/C				
Airframe											
Notes: Q306859											
361409	Fan AIR Valve (Left) - Functional Check		HRS		5530.4			0			0
			AFL		2599			0			0
			MOS		174.6			28 Apr 2008			
			MSC				O/C				
Airframe											
361410	Fan AIR Valve (Right) - Functional Check		HRS		5530.4			0			0
			AFL		2599			0			0
			MOS		174.6			28 Apr 2008			
			MSC				O/C				
Airframe											

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
361413	Bleed AIR Precooler (Left) - Cleaning	HRS		5530.4			0			0
		AFL		2599			0			0
		MOS		174.6			28 Apr 2008			
Airframe		MSC				O/C				
361414	Bleed AIR Precooler (Right) - Cleaning	HRS		5530.4			0			0
		AFL		2599			0			0
		MOS		174.6			28 Apr 2008			
Airframe		MSC				O/C				
361600	Ground Connect Check Valve - Removal / Installation 123312-9-1 19513	HRS		5530.4			0			0
		AFL		2599			0			0
		MOS		174.6			28 Apr 2008			ELECTRO ENTERPRISES INC
Airframe		MSC				O/C				
361601	Ground Connect Check Valve - Detailed Inspection	HRS		5530.4			0			0
		AFL		2599			0			0
		MOS		174.6			28 Apr 2008			
Airframe		MSC				O/C				
362101	Manifold Pressure Sensor (Left) - Removal / Installation 1151584-1 1151584-05599	HRS		5530.4			0			0
		AFL		2599			0			0
		MOS		174.6			28 Apr 2008			HONEYWELL ASCA INC.
Airframe		MSC				O/C				
Notes: VER BY Q307597										
362102	Manifold Pressure Sensor (Right) - Removal / Installation 1151584-1 1151584-05598	HRS		5530.4			0			0
		AFL		2599			0			0
		MOS		174.6			28 Apr 2008			HONEYWELL ASCA INC.
Airframe		MSC				O/C				
Notes: VER BY Q307597										
362105	Pressure Sense/Ind,L-Func Test	HRS		5530.4			0			0
		AFL		2599			0			0
		MOS		174.6			28 Apr 2008			
Airframe		MSC				O/C				

ATA / U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
362106	Pressure Sense/Ind,R-Func Test	HRS		5530.4			0			0
		AFL		2599			0			0
		MOS		174.6			28 Apr 2008			
		MSC				O/C				
Airframe										
38 - Water/Waste										
380001	Vacuum Toilet (Aft) - Removal / Installation	HRS		5530.4			0			0
	7900268 63-1442	AFL		2599			0			0
		MOS		174.6			28 Apr 2008			ENVIROVAC, INC.
		MSC				O/C				
Airframe										
Notes: VERIFIED BY PQ202										
380002	Vacuum Toilet (Forward) - Removal / Installation	HRS	TSN:4.9	5525.5			4.9			0
	7900268 63-1456	AFL	TSN:2	2597			2			0
		MOS	TSN:2	172.9			19 Jun 2008			
		MSC				O/C				
Airframe										
380003	Vacuum Blower - Removal / Installation	HRS		429.8			5100.6			0
	7900138-004 1204	AFL		153			2446			0
		MOS		11.9			18 Nov 2021			
		MSC				O/C				
Airframe										
Notes: VERFIED BY Q302557										
380004	Logic Control Module - Removal / Installation	HRS		5530.4			0			0
	7700-201-002 1886	AFL		2599			0			0
		MOS		174.6			28 Apr 2008			
		MSC				O/C				
Airframe										
380005	Status Panel - Removal / Installation	HRS		5530.4			0			0
	7700202-004 457	AFL		2599			0			0
		MOS		174.6			28 Apr 2008			
		MSC				O/C				
Airframe										
380006	Waste Tank - Removal / Installation	HRS	TSN:4573.2	957.2			4573.2			0
	7900295 43-877	AFL	TSN:2237	362			2237			0
		MOS	TSN:146	29.1			12 Jun 2020			
		MSC				O/C				
Airframe										
Notes: Q302557										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
380008 Logbook Position	Valve, Vacuum Toilet Dump 2651-375-1 298512	HRS AFL MOS MSC	TSN:2	1596.4 621 47		O/C	3934 1978 17 Dec 2018			0 0 SCALAMANDRE
Airframe										
Notes: Q302557										
380015	Waste Tank Delta P Level Sensor - Removal / Installation 7700248 1586	HRS AFL MOS MSC	TSN:1	1596.4 621 47		O/C	3934 1978 16 Dec 2018			0 0
Airframe										
380018	Waste Tank Ultrasonic Level Sensor (Left) - Removal / Installation 7700953 0774	HRS AFL MOS MSC		957.2 362 29.1		O/C	4573.2 2237 12 Jun 2020			0 0
Airframe										
380019	Waste Tank Ultrasonic Level Sensor (Right) - Removal / Installation 7700953 0754	HRS AFL MOS MSC	TSN:4573.2 TSN:2237 TSN:146	957.2 362 29.1		O/C	4573.2 2237 12 Jun 2020			0 0
Airframe										
380022	Waste Tank Ultrasonic Level Sensor (Left) - Cleaning	HRS AFL MOS MSC		2367 954 72.4		O/C	3163.4 1645 05 Nov 2016			0 0
Airframe										
380023	Waste Tank Ultrasonic Level Sensor (Right) - Cleaning	HRS AFL MOS MSC		2367 954 72.4		O/C	3163.4 1645 05 Nov 2016			0 0
Airframe										
381001	Conformal Water Tank - Removal / Installation 4E4293-3 N0806601	HRS AFL MOS MSC	TSN:4648.2 TSN:2295 TSN:152	882.2 304 23.4		O/C	4648.2 2295 03 Dec 2020			0 0
Airframe										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
381008	Conformal Water Tank Manual Shut-Off Valve - Removal / Installation	HRS		2986.2			2544.2			0
		AFL		1308			1291			0
	4E4473-1 N0626904	MOS	TSN:92	100.6			28 Jun 2014			
		MSC				O/C				
Airframe										
381011	Heater, Galley Water	HRS		1769.5			3760.9			0
	MRX-2000-102 2002-402	AFL		717			1882			0
		MOS		54.7			24 Apr 2018			
		MSC				O/C				
Airframe										
Notes: GC427180153 REV.A										
381012	Heater, Fwd Lav Water	HRS		5525.5			4.9			0
	MRX-1000-102 1002-1415	AFL		2597			2			0
		MOS		174.1			13 May 2008			DYNAMO AVIATION INC.
		MSC				O/C				
Airframe										
381013	Heater, Aft Lav Water	HRS		5525.5			4.9			0
	MRX-1000-102 1002-1417	AFL		2597			2			0
		MOS		174.6			29 Apr 2008			DYNAMO AVIATION INC.
		MSC				O/C				
Airframe										
381023	Water Level Controller - Removal / Installation	HRS		5530.4			0			0
	4E4186-1 U0390	AFL		2599			0			0
		MOS		174.6			28 Apr 2008			GOODRICH
		MSC				O/C				
Airframe										
381026	Sterilizer, Potable Water	HRS		2367			3163.4			0
	09-130021-102 1-0637	AFL		954			1645			0
		MOS	TSN:102	72.4			05 Nov 2016			
		MSC				O/C				
Airframe										
381027	Water Sterilizer Quartz Glass Sheath - Restore	HRS		2640.5		3000	2889.9	5889.9		0
	NPS-A6 NSN	AFL		1094			1505			0
		MOS		89.9			18 May 2015			
Airframe	200106									
Notes: REFERENCE ICA DOCUMENT GC42801A344 REV - FOR STC ST03579AT-D										

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
Logbook Position	HW	SW									
	MM Ref										
	Ops Number(s)										
381028	Germicidal Lamp - Discard		HRS		2640.5		3000	2889.9	5889.9		0
	NPS-A6	NSN	AFL		1094			1505			0
			MOS		89.9			18 May 2015			INTERNATIONAL WATER GUARD INDUSTRIES
Airframe	200106										
Notes: REFERENCE ICA DOCUMENT GC42801A344 REV - FOR STC ST03579AT-D											
381029	Water System - Operational Test		HRS		190.2			5340.2			0
			AFL		71			2528			0
			MOS		6.1			12 May 2022			
			MSC				O/C				
Airframe											
381035	Potable Water System - Cleaning / Sanitizing		HRS		4882.7			647.7			0
			AFL		2421			178			0
			MOS		149.7			26 May 2010			
			MSC				O/C				
Airframe											
381039	Water Sterilizer - Removal / Installation		HRS		190.2			5340.2			0
	09-130021-102	1-0637	AFL		71			2528			0
			MOS		6.1			12 May 2022			N/A
			MSC				O/C				
Airframe											
Notes: REFER TO ITEM 7.30 FOR LEAK CHECK.											
381040	Valve, Water Sterilization		HRS		5525.5			4.9			0
	4E4483-1	N0808107	AFL		2597			2			0
			MOS		173.8			22 May 2008			GOODRICH
			MSC				O/C				
Airframe											
381052	Water Sterilizer Filter - Removal / Installation		HRS		6.5			5523.9			0
	06-133802-001	SN-UNKNOWN	AFL		2			2597			0
			MOS		.2			11 Nov 2022			
			MSC				O/C				
Airframe											
381055	Contoller, Power Switching		HRS		5530.4			0			0
	4E4265-1	U338	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			GOODRICH
			MSC				O/C				
Airframe											

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
381060	Switch, Aft H2O Heater Blanket		HRS		5530.4			0			0
	2457-1-2	2PNVD	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			TAPIS CORP
			MSC				O/C				
Airframe											
381065	Contactor, Aft Baggage		HRS		5530.4			0			0
	SA-106E	CP-93257	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			SPINNEYBECK
			MSC				O/C				
Airframe											
381200	Water Sterilizer Filter - Discard		HRS		6.5			5523.9			0
	06-133802-001	SN-UNKNOWN	AFL		2			2597			0
(381200)			MOS		.2		12	11 Nov 2022	30 Nov 2023	31 Dec 2023	
Airframe			[End Of Month Item] [MOS: +1m]								
381205	Water System Level Indicators - Operational Test		HRS		5530.4			0			0
			AFL		2599			0			0
			MOS		174.6			28 Apr 2008			
			MSC				O/C				
Airframe											
381303	Supply Line Motor Drain Valve - Operational Test		HRS		190.2			5340.2			0
			AFL		71			2528			0
			MOS		6.1	35	24	12 May 2022	30 Jun 2024*	31 Jul 2024	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
	200202										
381304	Drain Line Motor Drain Valve - Operational Test		HRS		190.2			5340.2			0
			AFL		71			2528			0
			MOS		6.1	43	24	12 May 2022	30 Jun 2024*	31 Jul 2024	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
	200202										
381305	Supply Line Motor Drain Valve - Removal / Installation		HRS		1089.5			4440.9			0
	4E4491-1	N0712801	AFL		421			2178			0
			MOS		34.2			11 Jan 2020			
			MSC				O/C				
Airframe											
381307	Drain Line Motor Drain Valve - Removal / Installation		HRS		2640.5			2889.9			0
	4E4493-1	N0612505	AFL		1094			1505			0
			MOS		90			15 May 2015			GOODRICH
			MSC				O/C				
Airframe											

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
Logbook Position	HW	SW									
	MM Ref										
	Ops Number(s)										
381309	Supply / Fill / Purge Valve - Removal / Installation 4E4492-1	N0709401	HRS AFL MOS MSC		4059.2 1886 127.8		 O/C	1471.2 713 22 Mar 2012			0 0
Airframe											
381310	Valve, Galley Annex H2O Manual 4E4474-1	N0804603	HRS AFL MOS MSC		5525.5 2597 174.2		 O/C	4.9 2 10 May 2008			0 0
Airframe											
381311	Valve, Manual (Galley) 4E4474-1	N0804608	HRS AFL MOS MSC		5525.5 2597 174.4		 O/C	4.9 2 05 May 2008			0 0
Airframe											
381312	Valve, Manual (Galley) 4E4474-1	N0804604	HRS AFL MOS MSC		5525.5 2597 174.4		 O/C	4.9 2 05 May 2008			0 0
Airframe											
381313	Valve, Manual (Fwd Lavatory) 4E4474-1	N0805110	HRS AFL MOS MSC		5525.5 2597 174.1		 O/C	4.9 2 13 May 2008			0 0
Airframe											
381314	Valve, Manual (Aft Lavatory) 4E4474-1	N0804613	HRS AFL MOS MSC		5525.6 2597 174.6		 O/C	4.8 2 29 Apr 2008			0 0
Airframe											
381321	Valve, Back Flow (Annex) 4E4350-1	N0807415	HRS AFL MOS MSC		5525.5 2597 174.1		 O/C	4.9 2 12 May 2008			0 0
Airframe											
381322	Valve, Back Flow (Galley) 4E4350-1	N0807408	HRS AFL MOS MSC		5525.5 2597 174.4		 O/C	4.9 2 05 May 2008			0 0
Airframe											

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
381323	Valve, Crew Refresh Check 4E4350-1 SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										
381411	Potable Water Storage Tank - External Fill	HRS AFL MOS MSC		190.2 71 6.1		 O/C	5340.2 2528 13 May 2022			0 0
Airframe										
381420	Fill / Overflow Valve - Removal / Installation PN SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										
381422	Water System Servicing Cable - Rigging	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										
381501	Water Supply Line Lnnerline Heater Controller (Left) - Removal / Installation 3434-01 1134	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 COX & COMPANY INC
Airframe										
381502	Water Supply Line Lnnerline Heater Controller (Right) - Removal / Installation 3434-01 1091	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 TAPIS CORP
Airframe										
381503	Controller, Water Heater #3 3434-01 1080	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 COX & COMPANY INC
Airframe										
381510	Interline Controller 3435-01 423	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
381511 Airframe	Innerline Heater - SELF-Test	HRS AFL MOS MSC		957.2 362 29.1		 O/C	4573.2 2237 12 Jun 2020			0 0
381512 Airframe	Water System Heaters - Operational Test	HRS AFL MOS MSC		957.2 362 29.1		 O/C	4573.2 2237 12 Jun 2020			0 0
381513 Airframe	Power Switching Controller - Removal / Installation PN SN-UNKNOWN	HRS AFL MOS MSC		2652.9 1097 90.7		 O/C	2877.5 1502 24 Apr 2015			0 0
381514 Airframe	Potable Water Heating System Adjustment/Test	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
381516 Airframe	Water Drain Line Innerline Heater (Left) - Removal / Installation 3432-108 405	HRS AFL MOS MSC	TSN:26	957.2 362 29.1		 O/C	4573.2 2237 12 Jun 2020			0 0
381517 Airframe	Water Drain Line Innerline Heater (Right) - Removal / Installation 3432-110 346	HRS AFL MOS MSC	TSN:11	2640.5 1094 90		 O/C	2889.9 1505 15 May 2015			0 0
381525 Airframe	Water Supply Line Lnnerline Heater (Left) - Removal / Installation 3432-106 357	HRS AFL MOS MSC		2640.5 1094 90.1		 O/C	2889.9 1505 12 May 2015			0 0

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
381526	Water Supply Line Lnnerline Heater (Right) - Removal / Installation		HRS		2640.5			2889.9			0
			AFL		1094			1505			0
	3432-109	349	MOS		90.1			12 May 2015			
			MSC				O/C				
Airframe											
382104	Valve, Aft Lav H2O Shutoff		HRS		1008.2			4522.2			0
	4E4485-1	N1130603	AFL		397			2202			0
			MOS		33.5			02 Feb 2020			
			MSC				O/C				
Airframe											
383001	Aft Drain Mast - Removal / Installation		HRS	TSN:132.3	957.2			4573.2			0
	70WS001-216	HN7818	AFL	TSN:59	362			2237			0
			MOS	TSN:9	29.1			12 Jun 2020			
			MSC				O/C				
Airframe											
383011	Vacuum Toilet Rinse Valve (Aft) - Removal / Installation		HRS		882.2			4648.2			0
	7800001-008	20061804	AFL		304			2295			0
			MOS	TSN:2	24.3			06 Nov 2020			
			MSC				O/C				
Airframe											
383022	Valve, Aft Toilet Drain		HRS		5525.5			4.9			0
	4E4350-1	N0807413	AFL		2597			2			0
			MOS		174.3			08 May 2008			
			MSC				O/C				
Airframe											
383305	Waste Tank - Draining		HRS		882.2			4648.2			0
			AFL		304			2295			0
			MOS		26.2			09 Sep 2020			
			MSC				O/C				
Airframe											
383310	Logic Control Module System - Operational Test		HRS		957.2			4573.2			0
			AFL		362			2237			0
			MOS		29.1			12 Jun 2020			
			MSC				O/C				
Airframe											
383500	Waste Drain Valve - Removal / Installation		HRS		3144.8			2385.6			0
	2651-375-1	4HWHF	AFL		1378			1221			0
			MOS		104.7			26 Feb 2014			
			MSC				O/C				
Airframe											

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
383501	Dump Valve Cable Assembly - Removal / Installation 570-713-252 NSN	HRS AFL MOS MSC	 TSN:10 	1596.4 621 47 		 O/C	3934 1978 17 Dec 2018 			0 0
Airframe										
384001	AIR Compressor - Removal / Installation PN SN-UNKNOWN	HRS AFL MOS MSC	 	2652.9 1097 90.7 		 O/C	2877.5 1502 24 Apr 2015 			0 0
Airframe										
49 - Airborne Auxiliary Power										
490001	APU - APU - Removal / Installation 3800794-1 P-238	HRS APUS MOS MSC	TSN:3035.1 TSN:2621 TSN:86 	2268.5 2312 89.4 		 O/C	2962 3140 04 Jun 2015 			0 0
APU										
490003	APU - Auxiliary Power Unit Performance Run - Functional Test	HRS APUS MOS MSC	 	2268.5 2312 89.4 		 O/C	2962 3140 04 Jun 2015 			0 0
APU										
Notes: REACTIVATED PER 2010 AUDIT RESPONSE. GRH										
491010	APU - APU Aft Mount Adapter - Detailed Inspection	HRS APUS MOS MSC	 	2268.5 2312 90.3 		 O/C	2962 3140 08 May 2015 			0 0
APU										
491104	APU - Pallet Assembly (Including Forward and Aft Bracket and Mounts) - General Visual Inspection	HRS APUS MOS MSC	 	2268.5 2312 90.3 		 O/C	2962 3140 08 May 2015 			0 0
APU										
491105	APU - Auxiliary Power Unit Vibration Isolators - General Visual Inspection	HRS APUS MOS MSC	 	2268.5 2312 90.3 		 O/C	2962 3140 08 May 2015 			0 0
APU										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
491206	APU - Auxiliary Power Unit Inlet Door Actuator - Removal / Installation	HRS		3079.5			2151			0
		APUS		3189			2263			0
	2741624-2 709	MOS		112			16 Jul 2013			
		MSC				O/C				
APU										
Notes: Q302557										
491208	APU - Inlet Door Actuator - Rigging	HRS		260			4970.5			0
		APUS		348			5104			0
		MOS		15			17 Aug 2021			
		MSC				O/C				
APU										
491216	APU - AIR Intake Duct - Removal / Installation	HRS		2741.5			2489			0
	1159SCP781-1 148	APUS		2861			2591			0
		MOS		104.7			24 Feb 2014			
		MSC				O/C				
APU										
491221	APU - Oil Cooler Inlet Duct - Removal / Installation	HRS	TSN:2489	2741.5			2489			0
	PN SN-UNKNOWN	APUS	TSN:2591	2861			2591			0
		MOS	TSN:71	104.6			27 Feb 2014			
		MSC				O/C				
APU										
491230	APU - Auxiliary Power Unit Rotary Variable Transducer - Removal / Installation	HRS		260			4970.5			0
		APUS		348			5104			0
	2714252-1 1453	MOS		15			17 Aug 2021			
		MSC				O/C				
APU										
491301	APU - APU Compartment Drains - Operational Test	HRS		3532			1698.5			0
		APUS		3621			1831			0
		MOS		122.8			23 Aug 2012			
		MSC				O/C				
APU										
491302	APU - Auxiliary Power Unit Drains - Operational Test	HRS		91.5			5139			0
		APUS		128			5324			0
		MOS		5.8	20	24	23 May 2022	30 Jun 2024*	31 Jul 2024	
APU	200202	[End Of Month Item] [MOS: +1m/-1m]								
491304	APU Compartment Drains - Operational Check	HRS		697.6			4832.8			0
		AFL		234			2365			0
		MOS		18.5	31	24	30 Apr 2021	31 May 2023*	30 Jun 2023	
Airframe		[End Of Month Item] [MOS: +1m/-1m]								

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
491305 Logbook Position: Airframe	APU Compartment Drain Collectors - General Visual Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		697.6 234 18.5	31	24	4832.8 2365 30 Apr 2021	31 May 2023*	30 Jun 2023	0 0
492002 Logbook Position: APU	APU - APU Compressor Rotor - Discard 3822632-1 070316004165	HRS APUS MOS		5230.5 5452 175.7		20000 20000	0 0 25 Mar 2008	20000 20000		0 0
492003 Logbook Position: APU	APU - APU Turbine Rotor - Discard 3842368-1 08-01345-00580	HRS APUS MOS		5230.5 5452 175.7		10000 10000	0 0 25 Mar 2008	10000 10000		0 0
492301 Logbook Position: APU	APU - Power Section - Inspection	HRS APUS MOS MSC		2268.5 2312 90.3		 O/C	2962 3140 07 May 2015			0 0
493009 Logbook Position: APU	APU - Fuel Solenoid Valve - Removal / Installation 692545-18 03467	HRS APUS MOS MSC		5230.5 5452 175.7		 O/C	0 0 25 Mar 2008			0 0 HONEYWELL ENGINES SYSTEMS & SERVICE
493101 Logbook Position: APU	APU - Fuel Control Unit - Removal Installation 3882730-11 35511	HRS APUS MOS MSC		906.5 1092 42.6		 O/C	4324 4360 29 Apr 2019			0 0
493116 Logbook Position: APU	APU - Primary Fuel Manifold - Removal / Installation 3830155-2 SN-UNKNOWN	HRS APUS MOS MSC		5230.5 5452 175.7		 O/C	0 0 25 Mar 2008			0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
493117	APU - Secondary Fuel Manifold - Removal / Installation 3830156-2 SN-UNKNOWN	HRS APUS MOS MSC		5230.5 5452 175.7		 O/C	0 0 25 Mar 2008			0 0
APU										
493402	APU - Fuel Filter Mechanical Delta-P Indicator - Detailed Inspection	HRS APUS MOS		91.5 128 6.1		500	5139 5324 12 May 2022	5639	5689	0 0
APU	052000-500APU	[HRS: +50/-50]								
494001	APU - Starter Motor - Removal / Installation 70210-2704458-1 821	HRS APUS MOS MSC		1078.5 1244 47.1		 O/C	4152 4208 12 Dec 2018			0 0
APU										
Notes: TW SN# 558140, CAL DUE 8/2017. [CMP UPDATE FOR CORRECTED HOURS AND CYCLES]										
494003	APU - APU Starter Motor Brushes - Detailed Inspection	HRS APUS MOS MSC		2932.5 2972 107.9		 O/C	2298 2480 19 Nov 2013			0 0
APU										
494004	APU - Starter Motor Brushes - Removal / Installation UNKNOWN NSN	HRS APUS MOS MSC		2932.5 2972 107.9		 O/C	2298 2480 19 Nov 2013			0 0
APU										
494005	APU - APU Starter Motor Brushes (Brush Wear Measurement / Brush Cleaning) - Restore	HRS APUS MOS		492.5 4765 29.1	14	600	4738 687 12 Jun 2020	5352*	5402	0 0
APU		[HRS: +50/-50]								
Notes: [CMP UPDATE FOR CORRECTED HOURS AND CYCLES]										
494200	APU - Starter Motor Brushes - Cleaning	HRS APUS MOS MSC		1308 1459 55.1		 -	3922.5 3993 13 Apr 2018			0 0
APU										

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
494201	APU - Ignition Exciter - Removal / Installation 3876280-1	080218085524	HRS APUS MOS MSC		5230.5 5452 175.7		 O/C	0 0 25 Mar 2008			0 0 HONEYWELL AVIATION AFTERMARKET SERVICES
APU											
494206	APU - Igniter Plug (No. 1) - Removal / Installation 0AF21	99193-SOEV-30463	HRS APUS MOS MSC		4701.5 5082 151		 O/C	529 370 17 Apr 2010			0 0
APU											
495001	APU - Surge Control Valve - Removal / Installation 3884538-6	1665	HRS APUS MOS MSC		5230.5 5452 175.7		 O/C	0 0 25 Mar 2008			0 0 HONEYWELL ENGINES SYSTEMS & SERVICE
APU											
495002	APU - APU Load Control Valve - Removal / Installation 109804-7	1597	HRS APUS MOS MSC		1078.5 1244 46.9		 O/C	4152 4208 19 Dec 2018			0 0 HONEYWELL AVIATION AFTERMARKET SERVICES
APU											
495107	APU - Fan Assembly - Removal / Installation 3884629-5	56-8253	HRS APUS MOS MSC		2741.5 2861 104.6		 O/C	2489 2591 27 Feb 2014			0 0
APU											
496101	APU - Electronic Control Unit - Removal / Installation 2119584-3002*	87-P0117	HRS APUS MOS MSC		484.5 659 28.3		 O/C	4746 4793 08 Jul 2020			0 0
APU											

ATA / U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
497001	APU Egt / RPM Indicator - Removal / Installation 38760003-3 0657	HRS AFL MOS MSC		5530.4 2599 175.7		O/C	0 0 25 Mar 2008			0 0 INTERTECHNIQUE
Airframe										
Notes: VERIFIED BY PQ246										
497500	APU - Starter Counter - Removal / Installation 3876317-1 SN-UNKNOWN	HRS APUS MOS MSC		5230.5 5452 175.7		O/C	0 0 25 Mar 2008			0 0
APU										
498002	APU - Exhaust Duct - Removal / Installation 1159SCP774-1 0343	HRS APUS MOS MSC	TSN:2256 TSN:2102	494 671 29.1		O/C	4736.5 4781 12 Jun 2020			0 0
APU										
498100	APU - APU Exhaust Duct - General Visual Inspection 200202	HRS APUS MOS [End Of Month Item] [MOS: +1m/-1m]		91.5 128 6.2	33	24	5139 5324 10 May 2022	30 Jun 2024*	31 Jul 2024	0 0
APU										
499003	APU - AIR / Oil Cooler - Removal / Installation 160366-2 1826	HRS APUS MOS MSC		5230.5 5452 175.7		O/C	0 0 25 Mar 2008			0 0
APU										
499006	APU - Low Oil Pressure Switch - Removal / Installation 3876001-6 SN-UNKNOWN	HRS APUS MOS MSC		5230.5 5452 175.7		O/C	0 0 25 Mar 2008			0 0 HONEYWELL ENGINES SYSTEMS & SERVICE
APU										
499007	APU - Switch, APU Lube/Gen Delta-P 3882617-1 SN-UNKNOWN	HRS APUS MOS MSC		5230.5 5452 175.7		O/C	0 0 25 Mar 2008			0 0
APU										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
499008 APU	APU - APU Oil Temperature Control Valve - Removal / Installation 160148-2 1850	HRS APUS MOS MSC		5230.5 5452 175.7		O/C	0 0 25 Mar 2008			0 0
499009 APU	APU - Oil Temperature Sensor - Removal / Installation MS28034-3 146324	HRS APUS MOS MSC		5230.5 5452 175.7		O/C	0 0 25 Mar 2008			0 0 ELECTRO ENTERPRISES INC
499015 APU	APU - Oil Filter Element - Removal / Installation 3609088-1 NSN	HRS APUS MOS MSC	TSN:43	91.5 128 6.1		O/C	5139 5324 14 May 2022			0 0 N/A
499017 APU	APU - Auxiliary Power Unit Oil Filter Mechanical Delta-P Indicator - General Visual Inspection 052000-500APU	HRS APUS MOS [HRS: +50/-50]		91.5 128 5.8		500	5139 5324 23 May 2022	5639	5689	0 0
499020 APU	APU - APU Oil System Magnetic Chip Detector - Detailed Inspection 052000-500APU Notes: REF ITEM 20.4 IN CORRIDOR FOR LEAK CHECK.	HRS APUS MOS [HRS: +50/-50]		490 666 29.1		750	4740.5 4786 12 Jun 2020	5490.5	5540.5	0 0
499115 APU	APU - Lube Pump Assembly - Removal / Installation 3881903-1 SN-UNKNOWN	HRS APUS MOS MSC		5230.5 5452 175.7		O/C	0 0 25 Mar 2008			0 0
499121 APU	APU - AIR / Oil Cooler Supply Tube - Removal / Installation 3881849-1 SN-UNKNOWN	HRS APUS MOS MSC		5230.5 5452 175.7		O/C	0 0 25 Mar 2008			0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
499123	APU - Auxiliary Power Unit AIR / Oil Cooler - Detailed Inspection	HRS		1308		1500	3922.5	5422.5	5472.5	0
		APUS		1459			3993			0
		MOS		54.7			26 Apr 2018			
		[HRS: +50/-50]								
APU										
Notes: BRIDGE ALIGNED WITH APU 1A PER AMM REV 23 (MB)										
49APU1	APU 3800794-1 P-238	HRS		5530.4			0			0
		AFL		2599			0			0
		MOS		174.8			21 Apr 2008			
		MSC				E/C				
Airframe										
51 - STD Practices and Struct-Genrl										
510013	External Metallic Surfaces - Polishing	HRS		190.2			5340.2			0
		AFL		71			2528			0
		MOS		5.9	-6	12	20 May 2022	31 May 2023*	30 Jun 2023	
Airframe		[End Of Month Item] [MOS: +1m/-1m]								
510045	Bl 0 Wing Splice - Inspection	HRS		5530.4			0			0
		AFL		2599			0			0
		MOS		174.6			28 Apr 2008			
		MSC				O/C				
Airframe										
52 - Doors										
520005	Cabin Doors and Exits View from Ground - Zonal Inspection	HRS		697.6			4832.8			0
		AFL		234			2365			0
		MOS		18.5		24	30 Apr 2021	30 Apr 2023	31 May 2023	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-24M,200301									
520010	Cabin Doors and Exits - Zonal Inspection	HRS		2367			3163.4			0
		AFL		954			1645			0
		MOS		72.3	-68	96	07 Nov 2016	31 Aug 2024*	30 Sep 2024	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-96M,200304									
Notes: REF 20.10										
521001	Main Entrance Door - Removal / Installation 1159B57011-802-27 4123	HRS	TSN:4648.2	882.2			4648.2			0
		AFL	TSN:2295	304			2295			0
		MOS	TSN:152	23.4			03 Dec 2020			
		MSC				O/C				
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
521003 Airframe	Main Entrance Door Actuator - Removal / Installation 159H10030-51 55-5176 GT	HRS AFL MOS MSC		866.2 299 22.5		 O/C	4664.2 2300 30 Dec 2020			0 0 N/A
Notes: VERF Q124721										
521004 Airframe	Valve, Main Ent Door Reducer 1159SCH219-25 521	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 PNEUDRAULICS INC
Notes: VERF Q124721										
521005 Airframe	Main Entrance Door Selector Valve - Removal / Installation 1159SCH247-3 1648G	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 PNEUDRAULICS INC
Notes: VERF Q124721										
521007 Airframe	Main Entrance Door Bayonet Position Indicator DOTS - General Visual Inspection 052000-5C,200205,200206	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		957.2 362 29.1		 72	4573.2 2237 12 Jun 2020	30 Jun 2026	31 Jul 2026	0 0
521008 Airframe	Main Entrance Door Hinge Pins - Removal / Installation 1159BM50108-11 NSN	HRS AFL MOS MSC	TSN:1030.5 TSN:649 TSN:38	882.2 304 23.4		 O/C	4648.2 2295 03 Dec 2020			0 0
521009 Airframe	Main Entrance Door Hinge Pins - Detailed Inspection 052000-3C,200203	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		957.2 362 29.1		 36	4573.2 2237 12 Jun 2020	30 Jun 2023	31 Jul 2023	0 0
521010 Airframe	Main Entrance Door - Lubrication 052000-1C,200201	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		190.2 71 6.1	 29	 12	5340.2 2528 14 May 2022	30 Jun 2023*	31 Jul 2023	0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
521011	Main Entrance Door - Zonal Inspection	HRS		2367			3163.4			0
		AFL		954			1645			0
		MOS		72.7	-55	96	25 Oct 2016	31 Aug 2024*	30 Sep 2024	
Airframe	052000-96M,200304	[End Of Month Item] [MOS: +1m/-1m]								
521012	Main Entrance Door Internal - Detailed Inspection	HRS		957.2			4573.2			0
		AFL		362			2237			0
		MOS		29.1	-3	72	12 Jun 2020	30 Jun 2026*	31 Jul 2026	
Airframe	052000-72M,200303	[End Of Month Item] [MOS: +1m/-1m]								
521015	Main Entrance Door - Operating Procedures	HRS		190.2			5340.2			0
		AFL		71			2528			0
		MOS		6.1			14 May 2022			
Airframe		MSC				O/C				
521016	Main Entrance Door Cables - Tension Check	HRS		957.2			4573.2			0
		AFL		362			2237			0
		MOS		29.1		72	12 Jun 2020	30 Jun 2026	31 Jul 2026	
Airframe	052000-6C,200206	[End Of Month Item] [MOS: +1m/-1m]								
521023	Main Entrance Door Pin Bearing Plates-Insp	HRS		5530.4			0			0
		AFL		2599			0			0
		MOS		174.6			28 Apr 2008			
Airframe		MSC				O/C				
521031	Main Entrance Door Structure-Insp	HRS		5530.4			0			0
		AFL		2599			0			0
		MOS		174.6			28 Apr 2008			
Airframe		MSC				O/C				
521049	Regulator, Door Seal Pressure 3215634-5 SN-UNKNOWN	HRS		5530.4			0			0
		AFL		2599			0			0
		MOS		174.6			28 Apr 2008			HONEYWELL ENGINES SYSTEMS & SERVICE
Airframe		MSC				O/C				

ATA / U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
521302	Main Entrance Door Secondary Lock Handle Assembly - Removal / Installation	HRS		4665.9			864.5			0
		AFL		2267			332			0
	1159AMM50077-15 NSN	MOS		143.7			24 Nov 2010			Gulfstream Aerospace Corp
		MSC				O/C				
Airframe										
522001	Emergency Exit Cabin Windows (Left No. 1) - Removal / Installation	HRS		882.2			4648.2			0
		AFL		304			2295			0
	1159CE50001-79 0702425-07222H0821	MOS		23.9			20 Nov 2020			
		MSC				O/C				
Airframe										
Notes: Q306743										
522002	Emergency Exit Cabin Windows (Left No. 2) - Removal / Installation	HRS	TSN:4648.1	882.2			4648.2			0
		AFL	TSN:2295	304			2295			0
	1159CE50001-79 0802552-07364H0112	MOS	TSN:151	23.9			20 Nov 2020			
		MSC				O/C				
Airframe										
Notes: Q306743										
522003	Emergency Exit Cabin Windows (Right No. 1) - Removal / Installation	HRS	TSN:4690.7	882.2			4648.2			0
		AFL	TSN:2325	304			2295			0
	1159CE50001-79 0802588-08037H2804	MOS		23.9			20 Nov 2020			
		MSC				O/C				
Airframe										
522004	Emergency Exit Cabin Windows (Right No. 2) - Removal / Installation	HRS		882.2			4648.2			0
		AFL		304			2295			0
	1159CE50001-79 0802611-0203343052	MOS		23.9			20 Nov 2020			
		MSC				O/C				
Airframe										
Notes: Q306743										
522005	Emergency Exit Window Release Mechanism - Functional Test	HRS		882.2			4648.2			0
		AFL		304			2295			0
		MOS		25.9		48	18 Sep 2020	30 Sep 2024	31 Oct 2024	
	[End Of Month Item] [MOS: +1m/-1m]									
Airframe	052000-4C,200204									
Notes: PUSH-PULL SCALE #560619 CAL DUE 04/17.										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
522010	Overwing Emergency Exits - Zonal Inspection	HRS		2367			3163.4			0
		AFL		954			1645			0
		MOS		72.3	-68	96	07 Nov 2016	31 Aug 2024*	30 Sep 2024	
Airframe	052000-96M,200304	[End Of Month Item] [MOS: +1m/-1m]								
523001	Baggage Door - Removal / Installation	HRS	TSN:4648.2	882.2			4648.2			0
	1159B41046-35 4123	AFL	TSN:2295	304			2295			0
		MOS	TSN:152	23.4			03 Dec 2020			
		MSC				O/C				
Airframe										
523003	Baggage Compartment Door Seal - Detailed Inspection	HRS		190.2			5340.2			0
		AFL		71			2528			0
		MOS		6.1	48	24	13 May 2022	30 Jun 2024*	31 Jul 2024	
Airframe	200202	[End Of Month Item] [MOS: +1m/-1m]								
523005	Baggage Compartment Door - Lubrication	HRS		190.2			5340.2			0
		AFL		71			2528			0
		MOS		6.1	30	12	13 May 2022	30 Jun 2023*	31 Jul 2023	
Airframe	052000-1C,200201	[End Of Month Item] [MOS: +1m/-1m]								
523006	Baggage Compartment Door - Zonal Inspection	HRS		2367			3163.4			0
		AFL		954			1645			0
		MOS		72.9	-48	96	18 Oct 2016	31 Aug 2024*	30 Sep 2024	
Airframe	052000-96M,200304	[End Of Month Item] [MOS: +1m/-1m]								
523008	Baggage Compartment Door Seal Check Valve - Operational Test	HRS		190.2			5340.2			0
		AFL		71			2528			0
		MOS		6.1	48	24	13 May 2022	30 Jun 2024*	31 Jul 2024	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe	200202									
523009	Baggage Compartment Door Seal Pressure Regulator - Removal / Installation	HRS		5530.4			0			0
		AFL		2599			0			0
	3215634-5 2580	MOS		174.6			28 Apr 2008			HONEYWELL ENGINES SYSTEMS & SERVICE
		MSC				O/C				
Airframe										

Notes: Q302557

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
523012 Airframe	Baggage Compartment Door Inflatable Seal System - Operational Test 200202	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		190.2 71 6.1		24	5340.2 2528 13 May 2022	31 May 2024	30 Jun 2024	0 0
523016 Airframe	Baggage Compartment Door Seal Pressure Regulator - Functional Test 200202	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		190.2 71 6.1	30	24	5340.2 2528 13 May 2022	30 Jun 2024*	31 Jul 2024	0 0
523018 Airframe	Baggage Compartment Door Stop Fittings and Internal Structure - Detailed Inspection	HRS AFL MOS		5530.4 174.6		15000** 	0 28 Apr 2008	15000		0 0
523201 Airframe	Baggage Compartment Door Internal - Detailed Inspection 052000-192/144M,200307	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		5530.4 2599 171.1		192**	0 0 12 Aug 2008	31 Aug 2024	30 Sep 2024	0 0
524001 Airframe	Tail Compartment Door - Zonal Inspection 052000-144M	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		882.2 304 26.5	-21	144	4648.2 2295 02 Sep 2020	31 Aug 2032*	30 Sep 2032	0 0
524004 Airframe	Door, Tail Compartment 1159B51527-27 4123	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
527001 Airframe	Main Entrance Door Secondary Handle Lock Switch and Circuitry - Operational Test 200202	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		190.2 71 6.1	41	24	5340.2 2528 14 May 2022	30 Jun 2024*	31 Jul 2024	0 0

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Description: Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
527003	Main Entrance Door Locked Relay Circuit - Functional Test		HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe											
528101	Door, Nose Gear Left 1159B50510-49	4123	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe											
528102	Door, Nose Gear Right 1159B50510-50	4123	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe											
Notes: 307641											
528103	Door, Nose Gear Fairing 1159B50511-800-25	4123	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 LEONARD'S METAL INC.
Airframe											
Notes: Q307641											
528105	Door, L Main Gear 1159B42000-405	GC3325	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 STORK FOKKER AESP B.V.
Airframe											
528106	Door, R Main Gear 1159B42000-406	GC3323	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 STORK FOKKER AESP B.V.
Airframe											
528107	Door, L Main Gear Fairing 1159W40871-407	GC3326	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 STORK FOKKER AESP B.V.
Airframe											

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Description: Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
528108	Door, R Main Gear Fairing 1159W40871-408	GC3326	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 STORK FOKKER AESP B.V.
Airframe											
53 - Fuselage											
530005	Radome - Removal / Installation 1159B57290-9	3-287	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe											
Notes: PQ093											
530007	Cockpit Section 1159B30800-S801	SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe											
530008	Forward Combo Section 1159B47004-801-1	4123	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe											
530009	Center Mid Section 1159B20005-805	4123	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe											
530010	Aft Mid Section 1159B40009-812-5	4123	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe											
530011	Torque Box 1159B21700-816-5	4123	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe											

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
530012 Airframe	Aft Fuselage Section 1159B47006-804-1 4123	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
530013 Airframe	Tail Cone Section 1159B52901-45 4123	HRS AFL MOS MSC	TSN:3163.4 TSN:1645 TSN:102	2367 954 72.8		 O/C	3163.4 1645 22 Oct 2016			0 0
530016 Airframe	Fuselage Skins and Stringers - General Visual Inspection	HRS AFL MOS		 174.6		15000** 15000**	 28 Apr 2008	15000 15000		0 0
530018 Airframe	Fuselage Penetration - Inspection	HRS AFL MOS		5530.4 174.6		 10000**	0 28 Apr 2008	 10000		0 0
530026 Airframe	Longeron 9 and Longeron 13 - Detailed Inspection	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
530027 Airframe	Longeron 13 - Detailed Inspection	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
530201 Airframe	Radome to Structure Perimeter Steps - Check	HRS AFL MOS MSC		5525.5 2597 172.9		 O/C	4.9 2 18 Jun 2008			0 0
530202 Airframe	Static Ports (Reduced Vertical Separation Minimums) - Inspection 052000-24M,200301	HRS AFL MOS		697.6 234 18.5	 31	 24	4832.8 2365 30 Apr 2021	 31 May 2023*	 30 Jun 2023	0 0
		[End Of Month Item] [MOS: +1m/-1m]								

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
530205 Logbook Position	Birdstrike Plate (Left) - Removal / Installation 1159B50207-33 NSN	HRS AFL MOS MSC	TSN:459.7 TSN:199 TSN:13	957.2 362 29.1		 O/C	4573.2 2237 12 Jun 2020			0 0
Airframe										
Notes: T.W. #560291. CAL DUE: 04/17										
530206 Airframe	Birdstrike Plate (Right) - Removal / Installation 1159B50207-34 NSN	HRS AFL MOS MSC	TSN:1226.7 TSN:490 TSN:35	190.2 71 6.2		 O/C	5340.2 2528 11 May 2022			0 0 N/A
Notes: T.W. #560291. CAL DUE: 04/17										
531005 Airframe	External Lower Fuselage FS -4 Thru FS 596 - Zonal Inspection 052000-24M,200301	HRS AFL MOS		697.6 234 18.5		 24	4832.8 2365 30 Apr 2021	30 Apr 2023	31 May 2023	0 0
	[End Of Month Item] [MOS: +1m/-1m]									
531010 Airframe	Radome FS 4 Thru FS 44 - Zonal Inspection 052000-96M,200304	HRS AFL MOS		2367 954 73		 96	3163.4 1645 16 Oct 2016	31 Oct 2024	30 Nov 2024	0 0
	[End Of Month Item] [MOS: +1m/-1m]									
531012 Airframe	External Radome Fairing Installation - Detailed Inspection 052000-1A,200100	HRS AFL MOS		6.5 2 .2		500	5523.9 2597 11 Nov 2022	6023.9	6073.9	0 0
	[HRS: +50/-50]									
531013 Airframe	Enhanced Vision System Fairing and Rain Diverter Internal and External Non-Metal Surfaces - Detailed Inspection 052000-96M,200304	HRS AFL MOS		2367 954 72.9	-48	 96	3163.4 1645 18 Oct 2016	31 Aug 2024*	30 Sep 2024	0 0
	[End Of Month Item] [MOS: +1m/-1m]									
531014 Airframe	Enhanced Vision System Sapphire Window Installation - Detailed Inspection 052000-1A,200100	HRS AFL MOS		6.5 2 .2		500	5523.9 2597 11 Nov 2022	6023.9	6073.9	0 0
	[HRS: +50/-50]									

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
531015	Nose Landing Gear Wheel Well FS 44 - FS 119 - Zonal Inspection	HRS		190.2	4.7	500	5340.2	5844.9*	5894.9	0
		AFL		71			2528			0
		MOS		6.2	4	12	10 May 2022	31 May 2023*	30 Jun 2023	
	[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]									
Airframe	052000-1A									
531019	Cockpit Internal Skin and Substructure FS 63 - FS 145 - Detailed Inspection	HRS		5530.4			0			0
		AFL		2599			0			0
		MOS		171.1		192**	12 Aug 2008	31 Aug 2024	30 Sep 2024	
	[End Of Month Item] [MOS: +1m/-1m]									
Airframe	052000-192/144M,200307									
531020	Cockpit Below Floor FS 63 - FS 145 - Zonal Inspection	HRS		2367			3163.4			0
		AFL		954			1645			0
		MOS		72.9		96	18 Oct 2016	31 Oct 2024	30 Nov 2024	
	[End Of Month Item] [MOS: +1m/-1m]									
Airframe	052000-96M,200304									
531021	Cockpit Below Floor FS 63 - FS 145 (Wiring Harness) - (Enhanced) Zonal Inspection	HRS		2367			3163.4			0
		AFL		954			1645			0
		MOS		72.9	-48	96	18 Oct 2016	31 Aug 2024*	30 Sep 2024	
	[End Of Month Item] [MOS: +1m/-1m]									
Airframe	052000-96M,200304									
531035	Cabin Below Floor FS 193 - FS 321.50 - Zonal Inspection	HRS		2367			3163.4			0
		AFL		954			1645			0
		MOS		73		96	15 Oct 2016	31 Oct 2024	30 Nov 2024	
	[End Of Month Item] [MOS: +1m/-1m]									
Airframe	052000-96M,200304									
531040	Upper Surface of Center Wing FS 321.50 - FS 452 - Zonal Inspection	HRS		2367			3163.4			0
		AFL		954			1645			0
		MOS		73		96	15 Oct 2016	31 Oct 2024	30 Nov 2024	
	[End Of Month Item] [MOS: +1m/-1m]									
Airframe	052000-96M,200304									
531041	Overwing AREA FS 257.50 - FS 512 Between Drag Beam and Wing to Body Fairing - Zonal Inspection	HRS		2367			3163.4			0
		AFL		954			1645			0
		MOS		73		96	15 Oct 2016	31 Oct 2024	30 Nov 2024	
	[End Of Month Item] [MOS: +1m/-1m]									
Airframe	052000-96M,200304									

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
531045	Main Landing Gear Wheel Wells FS 452 - FS 496 - Zonal Inspection	HRS		190.2	4.7	500	5340.2	5844.9*	5894.9	0
		AFL		71			2528			0
		MOS		6.2	4	12	10 May 2022	31 May 2023*	30 Jun 2023	
		[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
Airframe	052000-1A									
531046	Main Landing Gear Wheel Wells FS 452 - FS 496 (Lower Cove Panel Drain Hole) - (Enhanced) Zonal Inspection	HRS		190.2	4.7	500	5340.2	5844.9*	5894.9	0
		AFL		71			2528			0
		MOS		6.2	4	12	10 May 2022	31 May 2023*	30 Jun 2023	
		[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
Airframe	052000-1A									
531047	Main Landing Gear Wheel Wells FS 452 - FS 496 (Wiring Harness) - (Enhanced) Zonal Inspection	HRS		190.2	4.7	500	5340.2	5844.9*	5894.9	0
		AFL		71			2528			0
		MOS		6.2	45	12	10 May 2022	30 Jun 2023*	31 Jul 2023	
		[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
Airframe	052000-1A									
531055	Aft Cabin Below Floor FS 498 - FS 539 - Zonal Inspection	HRS		882.2			4648.2			0
		AFL		304			2295			0
		MOS		25.7	21	48	24 Sep 2020	31 Oct 2024*	30 Nov 2024	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-48M,200302									
531060	Baggage Compartment Below Floor FS 539 - FS 596 - Zonal Inspection	HRS		882.2			4648.2			0
		AFL		304			2295			0
		MOS		25.8	22	48	23 Sep 2020	31 Oct 2024*	30 Nov 2024	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-48M,200302									
531065	External Upper Fuselage FS 44 - FS 596 View from Ground - Zonal Inspection	HRS		697.6			4832.8			0
		AFL		234			2365			0
		MOS		18.5		24	30 Apr 2021	30 Apr 2023	31 May 2023	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-24M,200301									
531066	External Upper Fuselage FS 44 - FS 596 - Zonal Inspection	HRS		2367			3163.4			0
		AFL		954			1645			0
		MOS		72.6	-58	96	28 Oct 2016	31 Aug 2024*	30 Sep 2024	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-96M,200304									

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
531068 Airframe	External Aft Fuselage and Empennage FS 596 - FS 864 - Zonal Inspection 052000-96M,200304	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		2367 954 72.9		96	3163.4 1645 19 Oct 2016	31 Oct 2024	30 Nov 2024	0 0
531070 Airframe	Cockpit Above Floor FS 63 - FS 145 - Zonal Inspection 052000-192M,200308	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		2640.5 1094 90		192	2889.9 1505 15 May 2015	31 May 2031	30 Jun 2031	0 0
531075 Airframe	Cabin Above Floor FS 145 - FS 596 Fuselage Penetrations and Lavatory Behind Panels - Zonal Inspection 052000-144M,200306	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		882.2 304 25.5	-51	144	4648.2 2295 02 Oct 2020	31 Aug 2032*	30 Sep 2032	0 0
531080 Airframe	Left Electronic Equipment Rack FS 141 - FS 165 - Zonal Inspection 052000-48M,200302	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		882.2 304 26	30	48	4648.2 2295 16 Sep 2020	31 Oct 2024*	30 Nov 2024	0 0
531081 Airframe	Right Electronic Equipment Rack FS 145 - FS 181 - Zonal Inspection 052000-48M,200302	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		882.2 304 26	30	48	4648.2 2295 16 Sep 2020	31 Oct 2024*	30 Nov 2024	0 0
531082 Airframe	Baggage Compartment Electronic Equipment Rack FS 584 - FS 594 - Zonal Inspection 052000-48M,200302	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		882.2 304 26	-16	48	4648.2 2295 16 Sep 2020	31 Aug 2024*	30 Sep 2024	0 0
531083 Airframe	Cabin Above Floor FS 145 - FS 596 Lavatory Behind Panels - (Enhanced) Zonal Inspection 052000-144M,200306	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		882.2 304 25.5	-51	144	4648.2 2295 02 Oct 2020	31 Aug 2032*	30 Sep 2032	0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
531084	Right Electronic Equipment Rack FS 145 - FS 181 (Below Lower Shelf) - (Enhanced) Zonal Inspection	HRS		882.2			4648.2			0
		AFL		304			2295			0
		MOS		26	-16	48	16 Sep 2020	31 Aug 2024*	30 Sep 2024	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-48M,200302									
531085	Aft Fuselage and Empennage FS 596 - FS 864 Viewed from Ground - Zonal Inspection	HRS		697.6			4832.8			0
		AFL		234			2365			0
		MOS		18.5	31	24	30 Apr 2021	31 May 2023*	30 Jun 2023	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-24M,200301									
531093	Lavatory Service Panel Pressure Box Structure - Detailed Inspection	HRS		5530.4			0			0
		AFL		2599			0			0
		MOS		174.6			28 Apr 2008			
		MSC				O/C				
Airframe										
531095	Aft Fuselage Above Floor FS 596 - FS 812.50 - Zonal Inspection	HRS		697.6			4832.8			0
		AFL		234			2365			0
		MOS		18.5	31	24	30 Apr 2021	31 May 2023*	30 Jun 2023	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-24M,200301									
531097	APU Enclosure FS 605 - FS 635 - Zonal Inspection	HRS		697.6			4832.8			0
		AFL		234			2365			0
		MOS		18.5	31	24	30 Apr 2021	31 May 2023*	30 Jun 2023	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-24M,200301									
531100	Aft Fuselage Below Floor FS 596 - FS 635 - Zonal Inspection	HRS		882.2			4648.2			0
		AFL		304			2295			0
		MOS		25.9	26	48	18 Sep 2020	31 Oct 2024*	30 Nov 2024	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-48M,200302									
531101	Nose Landing Gear Skin Cutout - Ndt Inspection	HRS		5530.4			0			0
		AFL		2599		8000	0	8000		0
		MOS		174.6			28 Apr 2008			
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
531105 Airframe	Aft Fuselage Below Floor FS 635 - FS 812.50 - Zonal Inspection 052000-96M,200304	HRS AFL MOS		2367 954 73.1		96	3163.4 1645 13 Oct 2016	31 Oct 2024	30 Nov 2024	0 0
		[End Of Month Item] [MOS: +1m/-1m]								
531110 Airframe	Tail Cone FS 812.50 - FS 864 - Zonal Inspection 052000-192M,200308	HRS AFL MOS		5530.4 2599 171.1		192	0 0 12 Aug 2008	31 Aug 2024	30 Sep 2024	0 0
		[End Of Month Item] [MOS: +1m/-1m]								
531115 Airframe	Cockpit Window Skins (Left) - Ndt Inspection	HRS AFL MOS		5530.4 174.6		8000**	0 28 Apr 2008	8000		0 0
531116 Airframe	Cockpit Window Skins (Right) - Ndt Inspection	HRS AFL MOS		5530.4 174.6		8000**	0 28 Apr 2008	8000		0 0
531201 Airframe	Bulkhead Installation FS 133 - Detailed Inspection	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
531205 Airframe	Bulkhead Installation FS 63 - Detailed Inspection	HRS AFL MOS		5530.4 2599 174.6		8000	0 0 28 Apr 2008	8000		0 0
531216 Airframe	FS 119 Frame - Detailed Inspection	HRS AFL MOS		5530.4 174.6		8000**	0 28 Apr 2008	8000		0 0
531225 Airframe	FS 145 Frame - Detailed Inspection	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
531300 Airframe	Butt Line 12 Longeron (Left) - Detailed Inspection 052000-144M,200306	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		882.2 304 24.6	-76	144	4648.2 2295 27 Oct 2020	31 Aug 2032*	30 Sep 2032	0 0
531305 Airframe	Butt Line 12 Longeron (Right) - Detailed Inspection 052000-144M,200306	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		882.2 304 24.6	-76	144	4648.2 2295 27 Oct 2020	31 Aug 2032*	30 Sep 2032	0 0
531702 Airframe	Cockpit Crossbeam - Ndt Inspection	HRS AFL MOS		5530.4 174.6		8000**	0 28 Apr 2008	8000		0 0
531703 Airframe	Cockpit Lower RAIL Bl 0 Splice - Ndt Inspection	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0
531705 Airframe	Windshield Rails and Posts Internal (Left) - Detailed Inspection 052000-144M,200306	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		882.2 304 24.6	-78	144	4648.2 2295 29 Oct 2020	31 Aug 2032*	30 Sep 2032	0 0
531706 Airframe	Windshield Rails and Posts Internal (Right) - Detailed Inspection 052000-144M,200306	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		882.2 304 24.6	-78	144	4648.2 2295 29 Oct 2020	31 Aug 2032*	30 Sep 2032	0 0
531707 Airframe	Upper Cockpit RAIL (Left) - Ndt Inspection	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0
531708 Airframe	Upper Cockpit RAIL (Right) - Ndt Inspection	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
531715 Airframe	Side Post Upper Attachment (Left) - Ndt Inspection	HRS AFL MOS		5530.4 174.6		 8000** 	0 28 Apr 2008	 8000 		0 0
531716 Airframe	Side Post Upper Attachment (Right) - Ndt Inspection	HRS AFL MOS		5530.4 174.6		 8000** 	0 28 Apr 2008	 8000 		0 0
531717 Airframe	Cockpit Side Post and RAIL Lower Attachment (Left) - Ndt Inspection	HRS AFL MOS		5530.4 174.6		 6100** 	0 28 Apr 2008	 6100 		0 0
531718 Airframe	Cockpit Side Post and RAIL Lower Attachment (Right) - Ndt Inspection	HRS AFL MOS		5530.4 174.6		 6100** 	0 28 Apr 2008	 6100 		0 0
531721 Airframe	Center Post Lower Attachment - Ndt Inspection	HRS AFL MOS		5530.4 174.6		 6300** 	0 28 Apr 2008	 6300 		0 0
531722 Airframe	Upper Center Post - Ndt Inspection	HRS AFL MOS MSC		5530.4 2599 174.6 		 O/C	0 0 28 Apr 2008 	 		0 0
531723 Airframe	Cockpit Center Post - Removal / Installation 1159BM50024 SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6 		 O/C	0 0 28 Apr 2008 	 		0 0
531724 Airframe	Cockpit Center Post - Discard 1159BM50024 SN-UNKNOWN	HRS AFL MOS		5530.4 2599 174.6		 16000 	0 0 28 Apr 2008	 16000 		0 0

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Description: Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
531725	Cockpit Side Post (Left) - Removal / Installation		HRS		5530.4			0			0
	1159BM50025	SN-UNKNOWN	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			
			MSC				O/C				
Airframe											
531726	Cockpit Side Post (Right) - Removal / Installation		HRS		5530.4			0			0
	1159BM50025	SN-UNKNOWN	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			
			MSC				O/C				
Airframe											
531727	Cockpit Side Post (Left) - Discard		HRS		5530.4			0			0
	1159BM50025	SN-UNKNOWN	AFL		2599		16000	0	16000		0
			MOS		174.6			28 Apr 2008			
Airframe											
531728	Cockpit Side Post (Right) - Discard		HRS		5530.4			0			0
	1159BM50025	SN-UNKNOWN	AFL		2599		16000	0	16000		0
			MOS		174.6			28 Apr 2008			
Airframe											
531729	Cockpit Lower RAIL Fastener (Left) - Replacement		HRS		5530.4			0			0
	1159BM50033	SN-UNKNOWN	AFL		2599		15000	0	15000		0
			MOS		174.6			28 Apr 2008			
Airframe											
531730	Cockpit Lower RAIL Fastener (Right) - Replacement		HRS		5530.4			0			0
	1159BM50033	SN-UNKNOWN	AFL		2599		15000	0	15000		0
			MOS		174.6			28 Apr 2008			
Airframe											
532006	Shear Clips, Floor Beam (FS321.5) - Discard		HRS		5530.4			0			0
	1159B20478	NSN	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			
			MSC				O/C				
Airframe											
532100	Pedestal Assembly		HRS		5530.4			0			0
	1159SCF551-9	101668	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			AIRCRAFT SEATING PRODUCTS
			MSC				O/C				
Airframe											

Notes: VERIFIED BY PQ211

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
532105 Airframe	Internal Skin and Substructure FS 145 - FS 345.875 - Detailed Inspection 052000-144M,200306	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		882.2 304 25.5	-51	144	4648.2 2295 02 Oct 2020	31 Aug 2032*	30 Sep 2032	0 0
532110 Airframe	Emergency Exit Windows Internal Skin and Substructure FS 345.875 - FS 452 - Detailed Inspection 052000-144M,200306	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		882.2 304 25.5	-51	144	4648.2 2295 02 Oct 2020	31 Aug 2032*	30 Sep 2032	0 0
532112 Airframe	Cabin Above Floor FS 452.50 - FS 596 - Detailed Inspection 052000-144M,200306	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		882.2 304 25.5	-51	144	4648.2 2295 02 Oct 2020	31 Aug 2032*	30 Sep 2032	0 0
532115 Airframe	Baggage Door Surround Structure - Detailed Inspection 052000-144/96M,200305	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		882.2 304 26.1	-33	96	4648.2 2295 14 Sep 2020	31 Aug 2028*	30 Sep 2028	0 0
532120 Airframe	Internal Skin Panels Below Stringer 19 (Left) - Detailed Inspection 052000-96M,200304	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		2367 954 73	-45	96	3163.4 1645 15 Oct 2016	31 Aug 2024*	30 Sep 2024	0 0
532121 Airframe	Internal Skin Panels Below Stringer 19 (Right) - Detailed Inspection 052000-96M,200304	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		2367 954 73	-45	96	3163.4 1645 15 Oct 2016	31 Aug 2024*	30 Sep 2024	0 0
532201 Airframe	FS 169 Bulkhead - Ndt Inspection	HRS AFL MOS		5530.4 2599 174.6		8000	0 0 28 Apr 2008	8000		0 0

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
532202	Below Floor FS 321 Bulkhead - Ndt Inspection		HRS		5530.4			0			0
			AFL				8000**		8000		0
			MOS		174.6			28 Apr 2008			
Airframe											
532301	Main Entrance Door Pin Support - Detailed Inspection		HRS		5530.4			0			0
			AFL		2599			0			0
			MOS		174.6			28 Apr 2008			
Airframe			MSC				O/C				
532302	Dorsal Longeron Splice AT FS 287 - Ndt Inspection		HRS				15000**		15000		0
			AFL				15000**		15000		0
			MOS		174.6			28 Apr 2008			
Airframe											
532500	Floor Structure Under Galleys, Lavatories FS 139 - FS 596 (Wet Areas) - Detailed Inspection		HRS		2367			3163.4			0
			AFL		954			1645			0
			MOS		73		96	16 Oct 2016	31 Oct 2024	30 Nov 2024	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-96M,200304										
532501	Cabin Below Floor FS 145 - FS 193 - Zonal Inspection		HRS		882.2			4648.2			0
			AFL		304			2295			0
			MOS		24.6	-57	48	27 Oct 2020	31 Aug 2024*	30 Sep 2024	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-48M,200302										
532505	Floor Structure Not Under Galleys, Lavatories FS 139 - FS 596 (Dry Areas) - Detailed Inspection		HRS		5530.4			0			0
			AFL		2599			0			0
			MOS		171.1		192**	12 Aug 2008	31 Aug 2024	30 Sep 2024	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-192/144M,200307										
532510	Pressure Floorboards FS 321.50 - FS 498 - Detailed Inspection		HRS		882.2			4648.2			0
			AFL		304			2295			0
			MOS		25.5		144	02 Oct 2020	31 Oct 2032	30 Nov 2032	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-144M,200306										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
532520 Airframe	Floor Beam to Wing Links Fittings and Installations - Detailed Inspection 052000-96M,200304	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		2367 954 73	-45	96	3163.4 1645 15 Oct 2016	31 Aug 2024*	30 Sep 2024	0 0
532600 Airframe	Electronic Equipment Racks Upper Fuselage Attachments (Left) - Detailed Inspection 052000-192/144M,200307	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		5530.4 2599 171.1		192**	0 0 12 Aug 2008	31 Aug 2024	30 Sep 2024	0 0
532601 Airframe	Electronic Equipment Racks Upper Fuselage Attachments (Right) - Detailed Inspection 052000-192/144M,200307	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		5530.4 2599 171.1		192**	0 0 12 Aug 2008	31 Aug 2024	30 Sep 2024	0 0
532602 Airframe	Electronic Equipment Racks Upper Fuselage Attachments (Baggage) - Detailed Inspection 052000-192/144M,200307	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		5530.4 2599 171.1		192**	0 0 12 Aug 2008	31 Aug 2024	30 Sep 2024	0 0
532901 Airframe	Main Entrance Door Cutout Surround Structure - Ndt Inspection	HRS AFL MOS		5530.4 174.6		12000**	0 28 Apr 2008	12000		0 0
532905 Airframe	Main Entrance Door Surround Longeron - Ndt Inspection	HRS AFL MOS		5530.4 2599 174.6		8000	0 28 Apr 2008	8000		0 0
533001 Airframe	Drag Beam - Detailed Inspection	HRS AFL MOS		 174.6		15000** 15000**	 28 Apr 2008	15000 15000		0 0

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW MM Ref Ops Number(s)	SW									Manufacturer Date Type
533015 Airframe	Baggage Door Coaming Assembly - Detailed Inspection		HRS AFL MOS [HRS: +50/-50]		1129.5 441 36.6	41.4	2250	4400.9 2158 29 Oct 2019	6692.3*	6742.3	0 0
533201 Airframe	Wing Pressure Box Cutout FS 321 and FS 498 Bulkhead - X-Ray Inspection		HRS AFL MOS		5530.4 174.6		15000**	0 28 Apr 2008	15000		0 0
533202 Airframe	Wing Pressure Box Cutout FS 498 Bulkhead - X-Ray Inspection		HRS AFL MOS		5530.4 174.6		15000**	0 28 Apr 2008	15000		0 0
533300 Airframe	Longeron 24 Left and Right FS 632 - 758 - Detailed Inspection		HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
533400 Airframe	Wing Attach Fittings - Detailed Inspection 052000-96M,200304		HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		2367 954 73	-45	96	3163.4 1645 15 Oct 2016	31 Aug 2024*	30 Sep 2024	0 0
533410 Airframe	Torque Box and Main Landing Gear Door Support - Detailed Inspection 052000-96M,200304		HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		2367 954 73	-46	96	3163.4 1645 16 Oct 2016	31 Aug 2024*	30 Sep 2024	0 0
533501 Airframe	Pressure Floor Structure - Ndt Inspection		HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
533600	Bulkhead and Web Below Floor FS 539 - Detailed Inspection	HRS		2367			3163.4			0
		AFL		954			1645			0
		MOS		73		96	15 Oct 2016	31 Oct 2024	30 Nov 2024	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-96M,200304									
533605	Bulkhead and Web Above Floor FS 539 - Detailed Inspection	HRS		5530.4			0			0
		AFL		2599			0			0
		MOS		171.1		192**	12 Aug 2008	31 Aug 2024	30 Sep 2024	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-192/144M,200307									
533610	Upper and Lower Engine Mount Fitting Straps FS 596 Bulkhead - Detailed Inspection	HRS		5530.4			0			0
		AFL		2599			0			0
		MOS		171.1		192**	12 Aug 2008	31 Aug 2024	30 Sep 2024	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-192/144M,200307									
533615	Pressure Bulkhead Forward Face Below Floor FS 596 - Detailed Inspection	HRS		2367			3163.4			0
		AFL		954			1645			0
		MOS		73	-45	96	15 Oct 2016	31 Aug 2024*	30 Sep 2024	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-96M,200304									
533620	Pressure Bulkhead Forward Face Above Floor FS 596 - Detailed Inspection	HRS		2640.5			2889.9			0
		AFL		1094			1505			0
		MOS		90.4		192**	05 May 2015	31 May 2031	30 Jun 2031	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-192/144M,200307									
533625	Pressure Bulkhead Aft Face Above Floor FS 596 - Detailed Inspection	HRS		882.2			4648.2			0
		AFL		304			2295			0
		MOS		25.9	-37	144	18 Sep 2020	31 Aug 2032*	30 Sep 2032	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-144M,200306									
533629	Forward Engine Mounts FS 539 (Left) - Detailed Inspection	HRS		1769.5			3760.9			0
		AFL		717			1882			0
		MOS		54.9			19 Apr 2018			
		MSC				O/C				
Airframe										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
533630	Forward Engine Mounts FS 539 (Right) - Detailed Inspection	HRS AFL MOS MSC		1769.5 717 54.9		 O/C	3760.9 1882 19 Apr 2018			0 0
Airframe										
533635	Aft Engine Mounts FS 596 (Left) - Detailed Inspection	HRS AFL MOS MSC		560.5 185 14.1		 O/C	4969.9 2414 14 Sep 2021			0 0
Airframe										
533636	Aft Engine Mounts FS 596 (Right) - Detailed Inspection	HRS AFL MOS MSC		560.5 185 14.1		 O/C	4969.9 2414 14 Sep 2021			0 0
Airframe										
533640	Thrust Strut Attach Fitting (Left) - Detailed Inspection	HRS AFL MOS MSC		1769.5 717 54.9		 O/C	3760.9 1882 19 Apr 2018			0 0
Airframe										
533645	Thrust Strut Attach Fitting (Right) - Detailed Inspection	HRS AFL MOS MSC		1769.5 717 54.9		 O/C	3760.9 1882 19 Apr 2018			0 0
Airframe										
533646	Aft Fuselage Thrust Strut Attachment - Detailed Inspection	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										
533701	Cabin Windows Surround Structure Tee Forging - Inspection	HRS AFL MOS		5530.4 174.6		 15000** 	0 28 Apr 2008	 15000 		0 0
Airframe										
534001	Mid Fuselage Miscellaneous Cutouts - Inspection	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
534002	Internal Skin and Substructure FS 498 - FS 596 Below Stringer 19 - Detailed Inspection		HRS		2367			3163.4			0
			AFL		954			1645			0
			MOS		73		96	15 Oct 2016	31 Oct 2024	30 Nov 2024	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-96M,200304										
534024	NLG Well Skin Cutout-Insp		HRS		5530.4			0			0
			AFL		2599			0			0
			MOS		174.6			28 Apr 2008			
			MSC				O/C				
Airframe											
534101	Baggage Door Surround Structure - X-Ray Inspection		HRS		5530.4			0			0
			AFL		2599			0			0
			MOS		174.6			28 Apr 2008			
			MSC				O/C				
Airframe											
534201	Below Floor FS 498 Bulkhead - Ndt Inspection		HRS				15000**		15000		0
			AFL				15000**		15000		0
			MOS		174.6			28 Apr 2008			
Airframe											
534202	Flat Pressure Bulkhead, Forward and Aft, Face (Accessible Portions) Above Floor, FS 596 - Special Detailed Inspection		HRS		1416.9			4113.5			0
			AFL		561			2038			0
			MOS		42.8		72	23 Apr 2019	30 Apr 2025	31 May 2025	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
534301	Dorsal Longeron AT FS 539 - Ndt Inspection		HRS		5530.4		15000	0	15000		0
			AFL		2599		15000	0	15000		0
			MOS		174.6			28 Apr 2008			
Airframe											
534302	Longeron 17 Between FS 498 and FS 596 - Detailed Inspection		HRS		5530.4			0			0
			AFL		2599			0			0
			MOS		174.6			28 Apr 2008			
			MSC				O/C				
Airframe											

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
534601 Airframe	Vertical Fin to Fuselage Attach Frame (FS 713) - Ndt Inspection	HRS AFL MOS		 174.6		15000** 15000**	 28 Apr 2008	15000 15000		0 0
534602 Airframe	Vertical Fin to Fuselage Attach Frame (FS 757) - Ndt Inspection	HRS AFL MOS		 174.6		15000** 15000**	 28 Apr 2008	15000 15000		0 0
534603 Airframe	Vertical Fin to Fuselage Attach Frame (FS 793) - Ndt Inspection	HRS AFL MOS		 174.6		15000** 15000**	 28 Apr 2008	15000 15000		0 0
534701 Airframe	Engine Mount to Fuselage Attach Fittings AT FS 539 - Ndt Inspection	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
534702 Airframe	Engine Mount to Fuselage Attach Fittings AT FS 596 - Ndt Inspection	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
534703 Airframe	Thrust Strut Fuselage Fitting - Ndt Inspection	HRS AFL MOS		5530.4 174.6		 15000** 	0 28 Apr 2008	 15000 		0 0
534704 Airframe	Forward Engine Mounts FS 539 - Ndt Inspection	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0

ATA U=Custom Logbook Position	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
534801	Aft Fuselage Miscellaneous Cutouts - Ndt Inspection	HRS		5530.4			0			0
		AFL				15000**		15000		0
		MOS		174.6			28 Apr 2008			
Airframe										
535005	Tail Compartment Above Floor Electrical Junction Boxes - Detailed Inspection	HRS		2367			3163.4			0
		AFL		954			1645			0
		MOS		72.9	-48	96	18 Oct 2016	31 Aug 2024*	30 Sep 2024	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-96M,200304									
535009	Internal Nose Compartment FS 44 - FS 63 - Zonal Inspection	HRS		2367			3163.4			0
		AFL		954			1645			0
		MOS		72.9		96	18 Oct 2016	31 Oct 2024	30 Nov 2024	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-96M,200304									
535018	Bl 6 Breather Beam Aft of FS 452 - Inspection	HRS		5530.4			0			0
		AFL		2599			0			0
		MOS		174.6			28 Apr 2008			
		MSC				O/C				
Airframe										
535020	Bl 6 Breather Beam FS 370 - FS 427 - Inspection	HRS		5530.4			0			0
		AFL		2599		4000	0	4000		0
		MOS		174.6			28 Apr 2008			
Airframe										
535400	APU Enclosure, Including Floor Installation and Pallet - Damage Inspection	HRS		2640.5			2889.9			0
		AFL		1094			1505			0
		MOS		90.3			08 May 2015			
		MSC				O/C				
Airframe										
535701	Aft Engine Mounts FS 596 - Ndt Inspection	HRS		5530.4			0			0
		AFL		2599			0			0
		MOS		174.6			28 Apr 2008			
		MSC				O/C				
Airframe										
537003	Wing Attach Frames - Inspection	HRS				15000**		15000		0
		AFL				9000**		9000		0
		MOS		174.6			28 Apr 2008			
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
539051 Airframe	Pressure Bulkhead Composite Panels and Beams FS 596 - Detailed Inspection 200110	HRS AFL MOS		560.5 185 14.1		5000	4969.9 2414 14 Sep 2021	9969.9		0 0
539465 Airframe	Tension Tie Straps FS 370 and FS 427 - Ndt Inspection	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
539466 Airframe	Frame to Floor Clips Between FS 345 and FS 452 - Inspection	HRS AFL MOS		5530.4 2599 174.6		 9000 	0 0 28 Apr 2008	 9000 		0 0
539502 Airframe	Cockpit Side Windshield Post - Inspection	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
539503 Airframe	Cockpit Aft Windshield Post - Eddy Current	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
539504 Airframe	Cabin Window Frames FS 193B - FS 287 - Ndt Inspection	HRS AFL MOS		5530.4 174.6		 9000** 	0 28 Apr 2008	 9000 		0 0
539509 Airframe	Cabin Window Frames FS 306 - FS 442 - Ndt Inspection	HRS AFL MOS		5530.4 174.6		 5000** 	0 28 Apr 2008	 5000 		0 0
539517 Airframe	Lower Antenna and Penetration Interface - Detailed Inspection 200303	HRS AFL MOS		957.2 362 29.1	 -17	 72	4573.2 2237 12 Jun 2020	 31 May 2026*	 30 Jun 2026	0 0
		[End Of Month Item] [MOS: +1m/-1m]								

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
539518	Exterior Upper Antenna and Penetration Interface - Detailed Inspection	HRS		957.2			4573.2			0
		AFL		362			2237			0
		MOS		29.1		72	12 Jun 2020	30 Jun 2026	31 Jul 2026	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe	200303									
54 - Nacelles/Pylons										
541005	Powerplant and Pylon View from Ground (Left) - Zonal Inspection	HRS		697.6			4832.8			0
		AFL		234			2365			0
		MOS		18.5		24	30 Apr 2021	30 Apr 2023	31 May 2023	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-24M,200301									
541006	Powerplant and Pylon View from Ground (Right) - Zonal Inspection	HRS		697.6			4832.8			0
		AFL		234			2365			0
		MOS		18.5		24	30 Apr 2021	30 Apr 2023	31 May 2023	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-24M,200301									
541010	Pylons Internal (Left) - Zonal Inspection	HRS		882.2			4648.2			0
		AFL		304			2295			0
		MOS		25.8		48	23 Sep 2020	30 Sep 2024	31 Oct 2024	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-48M,200302									
541011	Pylons Internal (Right) - Zonal Inspection	HRS		882.2			4648.2			0
		AFL		304			2295			0
		MOS		25.8		48	23 Sep 2020	30 Sep 2024	31 Oct 2024	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-48M,200302									
545001	Pylon Assembly - L/H 1159P47800-800-1 SN-UNKNOWN	HRS		5530.4			0			0
		AFL		2599			0			0
		MOS		174.6			28 Apr 2008			
		MSC				O/C				
Airframe										
545002	Pylon Assembly - R/H 1159P47800-800-3 SN-UNKNOWN	HRS		5530.4			0			0
		AFL		2599			0			0
		MOS		174.6			28 Apr 2008			
		MSC				O/C				
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
545003 Airframe	Pylon Leading Edge - Polishing	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		190.2 71 5.9	-6	12	5340.2 2528 20 May 2022	31 May 2023*	30 Jun 2023	0 0
545005 Airframe	Pylon Boards (Left) - Detailed Inspection 052000-48M,200306	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		882.2 304 26		144	4648.2 2295 17 Sep 2020	30 Sep 2032	31 Oct 2032	0 0
545010 Airframe	Pylon Boards (Right) - Detailed Inspection 052000-48M,200306	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		882.2 304 26		144	4648.2 2295 17 Sep 2020	30 Sep 2032	31 Oct 2032	0 0
55 - Stabilizers										
551001 Airframe Notes: PQ093	Horizontal Stabilizer - Removal / Installation 1159CS20001-S9 4123	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0
551002 Airframe	Horizontal Stabilizer General Skins - General Visual Inspection	HRS AFL MOS		2640.5 1094 90.3	-2889.9 -1505	15000** 15000**	2889.9 1505 08 May 2015	15000* 15000*		0 0
551003 Airframe	Horizontal Stabilizer Front Beam (Internal) - Zonal Inspection 052000-192M,200308	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		5530.4 2599 171.1		192	0 0 12 Aug 2008	31 Aug 2024	30 Sep 2024	0 0
551005 Airframe	Horizontal Stabilizer Front Beam (Leading Edge Removed) {Left} - Detailed Inspection 052000-192/144M,200307	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		5530.4 2599 171.1		192**	0 0 12 Aug 2008	31 Aug 2024	30 Sep 2024	0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
551006 Logbook Position	Horizontal Stabilizer Front Beam (Leading Edge Removed) {Right} - Detailed Inspection	HRS AFL MOS		5530.4 2599 171.1		192**	0 0 12 Aug 2008	31 Aug 2024	30 Sep 2024	0 0
	[End Of Month Item] [MOS: +1m/-1m]									
Airframe	052000-192/144M,200307									
551010	Horizontal Stabilizer Assembly (Interior) - Detailed Inspection	HRS AFL MOS		2367 954 73.1	-43	96	3163.4 1645 13 Oct 2016	31 Aug 2024*	30 Sep 2024	0 0
	[End Of Month Item] [MOS: +1m/-1m]									
Airframe	052000-96M,200304									
551012	Horizontal Stabilizer Box (Internal) - Zonal Inspection	HRS AFL MOS		2640.5 1094 90.3		192	2889.9 1505 08 May 2015	31 May 2031	30 Jun 2031	0 0
	[End Of Month Item] [MOS: +1m/-1m]									
Airframe	052000-192M,200308									
551013	Elevator Hinge (Left) - Detailed Inspection	HRS AFL MOS		5530.4 2599 171.1		192**	0 0 12 Aug 2008	31 Aug 2024	30 Sep 2024	0 0
	[End Of Month Item] [MOS: +1m/-1m]									
Airframe	052000-192/144M,200307									
551014	Elevator Hinge (Right) - Detailed Inspection	HRS AFL MOS		5530.4 2599 171.1		192**	0 0 12 Aug 2008	31 Aug 2024	30 Sep 2024	0 0
	[End Of Month Item] [MOS: +1m/-1m]									
Airframe	052000-192/144M,200307									
551020	Horizontal Stabilizer Attach Pivot Fittings (Stabilizer Installed) - Detailed Inspection	HRS AFL MOS		5530.4 2599 171.1		192**	0 0 12 Aug 2008	31 Aug 2024	30 Sep 2024	0 0
	[End Of Month Item] [MOS: +1m/-1m]									
Airframe	052000-192/144M,200307									
551110	Horizontal Stabilizer Trailing Edge, Rear Beam and Elevator Assembly - Zonal Inspection	HRS AFL MOS		2367 954 73.1	-43	96	3163.4 1645 13 Oct 2016	31 Aug 2024*	30 Sep 2024	0 0
	[End Of Month Item] [MOS: +1m/-1m]									
Airframe	052000-96M,200304									

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
551111	Horizontal Stabilizer Rub Blocks - Functional Test		HRS		2640.5		3000	2889.9	5889.9	5939.9	0
			AFL		1094			1505			0
			MOS		89.6			29 May 2015			
Airframe	052000-6A,200106		[HRS: +50/-50]								
551112	Horizontal Stabilizer Rub Blocks - General Visual Inspection		HRS		2640.5		3000	2889.9	5889.9	5939.9	0
			AFL		1094			1505			0
			MOS		89.6			29 May 2015			
Airframe	052000-6A,200106		[HRS: +50/-50]								
551113	Horizontal Stabilizer Leading Edge - Polishing		HRS		190.2			5340.2			0
			AFL		71			2528			0
			MOS		5.9	-6	12	20 May 2022	31 May 2023*	30 Jun 2023	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
551201	Horizontal Stabilizer Stringers, Spars and Ribs - Inspection		HRS		5530.4			0			0
			AFL		2599			0			0
			MOS		174.6			28 Apr 2008			
			MSC				O/C				
Airframe											
551202	Horizontal Stabilizer Access Cutouts - Detailed Inspection		HRS		5530.4			0			0
			AFL				19500**		19500		0
			MOS		174.6			28 Apr 2008			
Airframe											
551501	Horizontal Stabilizer Pivot Fitting - Ndt Inspection		HRS		5530.4			0			0
			AFL		2599			0			0
			MOS		174.6			28 Apr 2008			
			MSC				O/C				
Airframe											
551701	Horizontal Stabilizer Actuator Fitting - Special Detailed Inspection		HRS				15000**		15000		0
			AFL				15000**		15000		0
			MOS		174.6			28 Apr 2008			
Airframe											
552001	Elevator Skins - General Visual Inspection		HRS		5530.4			0			0
			AFL		2599			0			0
			MOS		174.6			28 Apr 2008			
			MSC				O/C				
Airframe											

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
552002 Airframe	Elevator Spars and Ribs - Detailed Inspection	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
552005 Airframe	Elevator to Horizontal Stabilizer Hinges (Elevator Installed) {Left} - Detailed Inspection 052000-192/144M,200307	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		5530.4 2599 171.1		 192**	0 0 12 Aug 2008	31 Aug 2024	30 Sep 2024	0 0
552006 Airframe	Elevator to Horizontal Stabilizer Hinges (Elevator Installed) {Right} - Detailed Inspection 052000-192/144M,200307	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		5530.4 2599 171.1		 192**	0 0 12 Aug 2008	31 Aug 2024	30 Sep 2024	0 0
552010 Airframe	Elevator Assemblies Internal (Left) - Detailed Inspection 052000-192/144M,200307	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		5530.4 2599 171.1		 192**	0 0 12 Aug 2008	31 Aug 2024	30 Sep 2024	0 0
552015 Airframe	Elevator Assemblies Internal (Right) - Detailed Inspection 052000-192/144M,200307	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		5530.4 2599 171.1		 192**	0 0 12 Aug 2008	31 Aug 2024	30 Sep 2024	0 0
552020 Airframe	Elevator Ballast Weights (Left) - Detailed Inspection 052000-144/96M,200305	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		882.2 304 24.4	-85	 96	4648.2 2295 05 Nov 2020	31 Aug 2028*	30 Sep 2028	0 0
552025 Airframe	Elevator Ballast Weights (Right) - Detailed Inspection 052000-144/96M,200305	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		882.2 304 24.4	-85	 96	4648.2 2295 05 Nov 2020	31 Aug 2028*	30 Sep 2028	0 0
552301 Airframe	Elevator Torque Tube Fitting - Ndt Inspection	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
552302 Airframe	Elevator Hinge Fittings - Ndt Inspection	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0
553001 Airframe Notes: PQ211	Vertical Stabilizer - Removal / Installation 1159CS20003-33 4123	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0
553002 Airframe	Vertical Stabilizer General Skins - General Visual Inspection	HRS AFL MOS		2640.5 1094 90.1	-2889.9 -1505	15000** 15000**	2889.9 1505 13 May 2015	15000* 15000*		0 0
553005 Airframe	Vertical Stabilizer Assembly (Interior) - Detailed Inspection 052000-192/144M,200307	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		5530.4 2599 171.1		192**	0 0 12 Aug 2008	31 Aug 2024	30 Sep 2024	0 0
553010 Airframe	Vertical Stabilizer Front Beam Internal - Detailed Inspection 052000-192/144M,200307	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		5530.4 2599 171.1		192**	0 0 12 Aug 2008	31 Aug 2024	30 Sep 2024	0 0
553013 Airframe	Vertical Stabilizer Leading Edge - Polishing	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		190.2 71 5.9	-6	12	5340.2 2528 20 May 2022	31 May 2023*	30 Jun 2023	0 0
553015 Airframe	Vertical Stabilizer Leading Edge Lower Section (Internal) - Zonal Inspection 052000-192M,200308	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		5530.4 2599 171.1		192	0 0 12 Aug 2008	31 Aug 2024	30 Sep 2024	0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
553016 Airframe	Vertical Stabilizer Box Section Internal Structure - Zonal Inspection 052000-192M,200308	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		2640.5 1094 90.1		192	2889.9 1505 13 May 2015	31 May 2031	30 Jun 2031	0 0
553018 Airframe	Vertical CAP, SATCOM Antenna and Bullet Fairing - Zonal Inspection 052000-96M,200304	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		2367 954 73.1	-43	96	3163.4 1645 13 Oct 2016	31 Aug 2024*	30 Sep 2024	0 0
553020 Airframe	Vertical Stabilizer Rear Beam (Aft) Face - Zonal Inspection 052000-96M,200304	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		2367 954 73.1	-44	96	3163.4 1645 14 Oct 2016	31 Aug 2024*	30 Sep 2024	0 0
553030 Airframe	Stabilizer Pivot Fitting - Detailed Inspection 052000-192/144M,200307	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		5530.4 2599 171.1		192**	0 0 12 Aug 2008	31 Aug 2024	30 Sep 2024	0 0
553035 Airframe	Vertical Stabilizer Assembly Upper Part of Boomerang Fitting - General Visual Inspection 052000-192/144M,200307	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		5530.4 2599 171.1		192**	0 0 12 Aug 2008	31 Aug 2024	30 Sep 2024	0 0
553201 Airframe	Vertical Stabilizer Stringers, Spars and Ribs - General Visual Inspection	HRS AFL MOS		5530.4 174.6		19500**	0 28 Apr 2008	19500		0 0
553202 Airframe	Vertical Stabilizer Access Cutouts - Detailed Inspection	HRS AFL MOS		5530.4 174.6		19500**	0 28 Apr 2008	19500		0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
553401 Airframe	Vertical Stabilizer Rear Beam AT Pivot Fitting - Detailed Inspection	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0
553501 Airframe	Vertical Stabilizer Pivot Fitting - Ndt Inspection	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0
554007 Airframe 200110	Rudder Exterior- Inspection	HRS AFL MOS		560.5 185 14.1		5000	4969.9 2414 14 Sep 2021	9969.9		0 0
554010 Airframe 052000-144M,200306	Rudder Assembly Internal - Detailed Inspection [End Of Month Item] [MOS: +1m/-1m]	HRS AFL MOS		882.2 304 25.9	-37	144	4648.2 2295 18 Sep 2020	31 Aug 2032*	30 Sep 2032	0 0
554015 Airframe 052000-96M,200304	Rudder Ballast Weight - Detailed Inspection [End Of Month Item] [MOS: +1m/-1m]	HRS AFL MOS		2367 954 73.1	-43	96	3163.4 1645 13 Oct 2016	31 Aug 2024*	30 Sep 2024	0 0
554020 Airframe 052000-192/144M,200307	Rudder to Vertical Stabilizer Attachment (Hinge Assemblies) - Detailed Inspection [End Of Month Item] [MOS: +1m/-1m]	HRS AFL MOS		5530.4 2599 171.1		192**	0 0 12 Aug 2008	31 Aug 2024	30 Sep 2024	0 0
554301 Airframe	Composite Rudder Hinge Fittings - Detailed Inspection	HRS AFL MOS		2599 174.6		15000**	0 28 Apr 2008	15000		0 0
554401 Airframe	Rudder Torque Tube Support Structure - Detailed Inspection	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
554402	Rudder Torque Tube - Detailed Inspection	HRS		5530.4			0			0
		AFL		2599			0			0
		MOS		174.6			28 Apr 2008			
Airframe		MSC				O/C				
56 - Windows										
561005	Windshield (Left) - Removal / Installation 1159SCB5102-13 17325H2302	HRS	TSN:887.3	882.2			4648.2			0
		AFL	TSN:413	304			2295			0
		MOS	TSN:34	24.4			04 Nov 2020			
Airframe		MSC				O/C				
561006	Windshield (Right) - Removal / Installation 1159SCB5102-15 17227H3925	HRS	TSN:887.3	882.2			4648.2			0
		AFL	TSN:413	304			2295			0
		MOS	TSN:38	24.4			04 Nov 2020			
Airframe		MSC				O/C				
561011	Side Windows (Left) - Removal / Installation 1159SCB5100-9 18011H6007	HRS	TSN:887.3	882.2			4648.2			0
		AFL	TSN:413	304			2295			0
		MOS	TSN:33	24.4			04 Nov 2020			
Airframe		MSC				O/C				
561012	Side Windows (Right) - Removal / Installation 1159SCB5100-11 19143H3709	HRS		882.2			4648.2			0
		AFL		304			2295			0
		MOS	TSN:16	24.4			04 Nov 2020			
Airframe		MSC				O/C				
561021	Cockpit Side Window Attachment Bolts (Left) - Discard NAS1580A3T24 NSN	HRS		5530.4			0			0
		AFL		2599			0			0
		MOS		174.6			28 Apr 2008			HONEYWELL
Airframe		MSC				O/C				HPG
561022	Cockpit Side Window Attachment Bolts (Right) - Discard NAS1580A3T24 NSN	HRS		5530.4			0			0
		AFL		2599			0			0
		MOS		174.6			28 Apr 2008			HONEYWELL
Airframe		MSC				O/C				HPG

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
562001 Airframe	Fixed Cabin Windows (Left No. 1) - Removal / Installation 1159CE50001-75 0802584	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 PPG INDUSTRIES INC
Notes: Q306743										
562002 Airframe	Fixed Cabin Windows (Left No. 2) - Removal / Installation 1159CE50001-75 0802614	HRS AFL MOS MSC	TSN:647.7 TSN:178 TSN:25	4882.7 2421 149.6		 O/C	647.7 178 27 May 2010			0 0 PPG INDUSTRIES INC
Notes: Q306743										
562003 Airframe	Fixed Cabin Windows (Left No. 3) - Removal / Installation 1159CE50001-75 0802574	HRS AFL MOS MSC	TSN:647.7 TSN:178 TSN:25	4882.7 2421 149.6		 O/C	647.7 178 27 May 2010			0 0 PPG INDUSTRIES INC
Notes: Q306743										
562004 Airframe	Fixed Cabin Windows (Left No. 4) - Removal / Installation 1159CE50001-75 0702444	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 PPG INDUSTRIES INC
Notes: Q306743										
562006 Airframe	Fixed Cabin Windows (Right No. 1) - Removal / Installation 1159CE50001-75 0702333	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 GULFSTREAM SAV PROD-IPT
Notes: Q306743										
562007 Airframe	Fixed Cabin Windows (Right No. 2) - Removal / Installation 1159CE50001-75 0802557	HRS AFL MOS MSC	TSN:647.7 TSN:178 TSN:25	4882.7 2421 149.6		 O/C	647.7 178 27 May 2010			0 0 PPG INDUSTRIES INC
Notes: Q306743										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
562008	Fixed Cabin Windows (Right No. 3) - Removal / Installation 1159CE50001-75 0702422	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 PPG INDUSTRIES INC
Airframe										
Notes: Q306743										
562009	Fixed Cabin Windows (Right No. 4) - Removal / Installation 1159CE50001-75 0702439	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 PPG INDUSTRIES INC
Airframe										
Notes: Q306743										
562021	Fixed Cabin Window Inner Pane (Left No. 1) - Removal / Installation 1159SCCE500-53 08039H3063	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 PPG INDUSTRIES INC
Airframe										
Notes: Q306743										
562022	Fixed Cabin Window Inner Pane (Left No. 2) - Removal / Installation 1159SCCE500-53 07364H0106	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 PPG INDUSTRIES INC
Airframe										
Notes: Q306743										
562023	Fixed Cabin Window Inner Pane (Left No. 3) - Removal / Installation 1159SCCE500-53 08039H3062	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 PPG INDUSTRIES INC
Airframe										
Notes: Q306743										
562024	Fixed Cabin Window Inner Pane (Left No. 4) - Removal / Installation 1159SCCE500-53 08037H2790	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 PPG INDUSTRIES INC
Airframe										
Notes: Q306743										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
562026	Fixed Cabin Window Inner Pane (Right No. 1) - Removal / Installation 1159SCCE500-53 07312H0160	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 PPG INDUSTRIES INC
Airframe										
Notes: Q306743										
562027	Fixed Cabin Window Inner Pane (Right No. 2) - Removal / Installation 1159SCCE500-53 07174H0990	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 PPG INDUSTRIES INC
Airframe										
Notes: Q306743										
562028	Fixed Cabin Window Inner Pane (Right No. 3) - Removal / Installation 1159SCCE500-19 10335H9449	HRS AFL MOS MSC		4644.2 2244 142.6		 O/C	886.2 355 27 Dec 2010			0 0 PPG INDUSTRIES INC
Airframe										
Notes: Q306743										
562029	Fixed Cabin Window Inner Pane (Right No. 4) - Removal / Installation 1159SCCE500-53 07364H0116	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 PPG INDUSTRIES INC
Airframe										
Notes: Q306743										
562031	Emergency Exit Cabin Window Inner Pane (Left No. 1) - Removal / Installation 1159SCCE500-53 07222H0821	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 PPG INDUSTRIES INC
Airframe										
Notes: Q306743										
562032	Emergency Exit Cabin Window Inner Pane (Left No. 2) - Removal / Installation 1159SCCE500-53 07364H0112	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 PPG INDUSTRIES INC
Airframe										
Notes: Q306743										

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Description: Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
562033	Emergency Exit Cabin Window Inner Pane (Right No. 1) - Removal / Installation		HRS		5530.4			0			0
			AFL		2599			0			0
	1159SCCE500-53	08034H2804	MOS		174.6			28 Apr 2008			PPG INDUSTRIES INC
			MSC				O/C				
Airframe											
Notes: Q306743											
562034	Emergency Exit Cabin Window Inner Pane (Right No. 2) - Removal / Installation		HRS		5530.4			0			0
			AFL		2599			0			0
	1159SCCE500-53	08039H3058	MOS		174.6			28 Apr 2008			PPG INDUSTRIES INC
			MSC				O/C				
Airframe											
Notes: Q306743											
562115	Cabin Windows - Leak Check		HRS		882.2			4648.2			0
			AFL		304			2295			0
			MOS		25.5			02 Oct 2020			
			MSC				O/C				
Airframe											
57 - Wings											
570001	Wing Assy, Left		HRS		5530.4			0			0
	1159W40003-1	4123	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			
			MSC				O/C				
Airframe											
570002	Wing Assy, Right		HRS		5530.4			0			0
	1159W40003-2	4124	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			
			MSC				O/C				
Airframe											
570003	Box, Lh Inboard T.E.		HRS		5530.4			0			0
	1159W20164-804-7	4122	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			GULFSTREAM SAV PROD-IPT
			MSC				O/C				
Airframe											
570004	Box, Rh Inboard T.E.		HRS		5530.4			0			0
	1159W20164-804-8	4122	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			GULFSTREAM SAV PROD-IPT
			MSC				O/C				
Airframe											

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
570005 Airframe	Box, Lh Outboard T.E. 1159WH40804-802-13 4123	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 GULFSTREAM SAV PROD-IPT
570006 Airframe	Box, Rh Outboard T.E. 1159WH40804-802-14 4123	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 GULFSTREAM SAV PROD-IPT
570007 Airframe	Upper Wing Wedges (Left) - Removal / Installation PN SN-UNKNOWN	HRS AFL MOS MSC		882.2 304 23.5		 O/C	4648.2 2295 02 Dec 2020			0 0
570008 Airframe	Upper Wing Wedges (Right) - Removal / Installation PN SN-UNKNOWN	HRS AFL MOS MSC		882.2 304 23.5		 O/C	4648.2 2295 02 Dec 2020			0 0
570009 Airframe	Wing Lower Surface Viewed from Ground (Left) - Zonal Inspection 052000-24M,200301	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		697.6 234 18.5		 24	4832.8 2365 30 Apr 2021	30 Apr 2023	31 May 2023	0 0
570010 Airframe	Wing Lower Surface Viewed from Ground (Right) - Zonal Inspection 052000-24M,200301	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		697.6 234 18.5		 24	4832.8 2365 30 Apr 2021	30 Apr 2023	31 May 2023	0 0
570014 Airframe	Main Landing Gear Side Brace Attachment Fitting - Ndt Inspection	HRS AFL MOS		5530.4 174.6		 15000**	0 28 Apr 2008	 15000		0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
570017	Wing Wedge Internal and External Surface - Detailed Inspection	HRS		2367			3163.4			0
		AFL		954			1645			0
		MOS		73.1	-44	96	14 Oct 2016	31 Aug 2024*	30 Sep 2024	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-96M,200304									
570018	Wing Surface Located Under Wing Wedge - Detailed Inspection	HRS		2367			3163.4			0
		AFL		954			1645			0
		MOS		73.1	-44	96	14 Oct 2016	31 Aug 2024*	30 Sep 2024	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-96M									
Notes: COMPLIED WITH GULFSTREAM G450 CMP 570018										
570201	Wing Box Structure Forward Spar Through Gap Bands (Left) - Detailed Inspection	HRS		2367			3163.4			0
		AFL		954			1645			0
		MOS		73.2	-41	96	11 Oct 2016	31 Aug 2024*	30 Sep 2024	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-96M,200304									
570202	Wing Box Structure Forward Spar Through Gap Bands (Right) - Detailed Inspection	HRS		2367			3163.4			0
		AFL		954			1645			0
		MOS		73.2	-41	96	11 Oct 2016	31 Aug 2024*	30 Sep 2024	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-96M,200304									
570205	Wing Tank Internal (Left) - Detailed Inspection	HRS		2367			3163.4			0
		AFL		954			1645			0
		MOS		73.4		96	04 Oct 2016	31 Oct 2024	30 Nov 2024	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-96M,200304									
570206	Wing Tank Internal (Right) - Detailed Inspection	HRS		2367			3163.4			0
		AFL		954			1645			0
		MOS		73.4		96	05 Oct 2016	31 Oct 2024	30 Nov 2024	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-96M,200304									
570207	Wing Tank Internal Inboard 3 Panels Each Wing - Detail Inspection	HRS		68.4			5462			0
		AFL		24			2575			0
		MOS		2.2	-9	24	09 Sep 2022	31 Aug 2024*	30 Sep 2024	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-48M,200302									
Notes: LEFT WING COMPLIED WITH DURING COMPLETION OF CMP 570205 ITEM 17.18RIGHT WING COMPLIED WITH DURING COMPLETION OF CMP 570206 ITEM 17.19										

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
570208	Wing Fasteners Cadmium Plating Degradation (Left) - Check		HRS AFL MOS MSC		68.4 24 2.2		 O/C	5462 2575 09 Sep 2022			0 0
Airframe											
570209	Wing Fasteners Cadmium Plating Degradation (Right) - Check		HRS AFL MOS MSC		68.4 24 2.2		 O/C	5462 2575 09 Sep 2022			0 0
Airframe											
570210	Wing Fasteners Cadmium Plating Degradation Inboard 3 Panels Each Wing - Check		HRS AFL MOS MSC		68.4 24 2.2		 O/C	5462 2575 09 Sep 2022			0 0
Airframe											
571015	Wing Front Beam (Left) - Ndt Inspection		HRS AFL MOS		 2599 174.6		17000** 	 0 28 Apr 2008	17000		0 0
Airframe											
571016	Wing Front Beam (Right) - Ndt Inspection		HRS AFL MOS		 2599 174.6		17000** 	 0 28 Apr 2008	17000		0 0
Airframe											
571017	Wing Rear Beam (Left) - Ndt Inspection		HRS AFL MOS		 2599 174.6		17000** 	 0 28 Apr 2008	17000		0 0
Airframe											
571018	Wing Rear Beam (Right) - Ndt Inspection		HRS AFL MOS		 2599 174.6		17000** 	 0 28 Apr 2008	17000		0 0
Airframe											
571053	FS 452 Inboard Attach Fittings - Detailed Inspection		HRS AFL MOS		5530.4 174.6		 15000** 	0 28 Apr 2008	15000		0 0
Airframe											

ATA U=Custom Logbook Position	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
571055	FS 345 Inboard and Outboard Attach Fittings - Detailed Inspection	HRS AFL MOS		5530.4 174.6		 10000** 	0 28 Apr 2008	 10000 		0 0
Airframe										
571057	FS 452 Bl 6 Attach Fitting - Detailed Inspection	HRS AFL MOS		5530.4 174.6		 15000** 	0 28 Apr 2008	 15000 		0 0
Airframe										
571058	FS 345 Bl 6 Attach Fitting - Detailed Inspection	HRS AFL MOS MSC		5530.4 2599 174.6 		 O/C	0 0 28 Apr 2008 			0 0
Airframe										
571072	Wing Front Beam AT Bl 35.8 and Rbs 103.3 (Left) - Ndt Inspection	HRS AFL MOS MSC		5530.4 2599 174.6 		 O/C	0 0 28 Apr 2008 			0 0
Airframe										
571073	Wing Front Beam AT Bl 35.8 and Rbs 103.3 (Right) - Ndt Inspection	HRS AFL MOS MSC		5530.4 2599 174.6 		 O/C	0 0 28 Apr 2008 			0 0
Airframe										
571074	Left Wing Front Beam-Rbs 103.3-Eddy Current	HRS AFL MOS MSC		5530.4 2599 174.6 		 O/C	0 0 28 Apr 2008 			0 0
Airframe										
571075	Right Wing Front Beam-Rbs 103.3-Eddy Current	HRS AFL MOS MSC		5530.4 2599 174.6 		 O/C	0 0 28 Apr 2008 			0 0
Airframe										
571076	Wing Rear Beam CAP AT Bl 35.8 (Left) - Ndt Inspection	HRS AFL MOS		 2599 174.6		17000** 	 0 28 Apr 2008	17000 		0 0
Airframe										

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
571077	Wing Rear Beam CAP AT Bl 35.8 (Right) - Ndt Inspection		HRS AFL MOS	 	 2599 174.6		17000** 	 0 28 Apr 2008	17000 		0 0
Airframe											
571078	Wing Rear Beam CAP AT Rbs 103.3 (Left) - Ndt Inspection		HRS AFL MOS	 	 2599 174.6		17000** 	 0 28 Apr 2008	17000 		0 0
Airframe											
571079	Wing Rear Beam CAP AT Rbs 103.3 (Right) - Ndt Inspection		HRS AFL MOS	 	 2599 174.6		17000** 	 0 28 Apr 2008	17000 		0 0
Airframe											
571080	Wing Front Beam AT Rbs 154.7 (Left) - Ndt Inspection		HRS AFL MOS	 	 174.6		15000** 15000** 	 28 Apr 2008	15000 15000 		0 0
Airframe											
571081	Wing Front Beam AT Rbs 154.7 (Right) - Ndt Inspection		HRS AFL MOS	 	 174.6		15000** 15000** 	 28 Apr 2008	15000 15000 		0 0
Airframe											
571082	Wing Front and Rear Beam AT Rbs 204.6 (Left Front) - Ndt Inspection		HRS AFL MOS	 	 174.6		15000** 15000** 	 28 Apr 2008	15000 15000 		0 0
Airframe											
571083	Wing Front and Rear Beam AT Rbs 204.6 (Right Front) - Ndt Inspection		HRS AFL MOS	 	 174.6		15000** 15000** 	 28 Apr 2008	15000 15000 		0 0
Airframe											

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
571084	Wing Front Beam Rbs 280.6 (Left) - Ndt Inspection		HRS				15000**		15000		0
			AFL				15000**		15000		0
			MOS		174.6			28 Apr 2008			
Airframe											
571085	Wing Front Beam Rbs 280.6 (Right) - Ndt Inspection		HRS				15000**		15000		0
			AFL				15000**		15000		0
			MOS		174.6			28 Apr 2008			
Airframe											
571086	Wing Rear Beam AT Rbs 230.1 (Left) - Ndt Inspection		HRS				17000**		17000		0
			AFL		2599			0			0
			MOS		174.6			28 Apr 2008			
Airframe											
571087	Wing Rear Beam AT Rbs 230.1 (Right) - Ndt Inspection		HRS				17000**		17000		0
			AFL		2599			0			0
			MOS		174.6			28 Apr 2008			
Airframe											
571090	Wing Rib CAP AT Rear Beam Rbs 204.6 (Left) - Ndt Inspection		HRS				15000**		15000		0
			AFL				15000**		15000		0
			MOS		174.6			28 Apr 2008			
Airframe											
571091	Wing Rib CAP AT Rear Beam Rbs 204.6 (Right) - Ndt Inspection		HRS				15000**		15000		0
			AFL				15000**		15000		0
			MOS		174.6			28 Apr 2008			
Airframe											
571095	Wing Fasteners Cadmium Plating Degradation (Left) - Cleaning / Rework		HRS		68.4			5462			0
			AFL		24			2575			0
			MOS		2.2			09 Sep 2022			
			MSC				O/C				
Airframe											

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
571096 Airframe	Wing Fasteners Cadmium Plating Degradation (Right) - Cleaning / Rework	HRS AFL MOS MSC		68.4 24 2.2		 O/C	5462 2575 09 Sep 2022			0 0
571101 Airframe	Front Beam Bl 0 Splice - Ndt Inspection	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
571201 Airframe	Wing Rear Beam Splice Bl 0 - Ndt Inspection	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
571203 Airframe Notes: ADDED BY AMM REV. 26 DATED 05 MARCH 2018 (MB)	Wing Rear Spar Web AT Bl 85 Sponson Attach (Left) - Ndt Inspection	HRS AFL MOS		5530.4 174.6		 11700** 	0 28 Apr 2008	 11700 		0 0
571204 Airframe Notes: ADDED BY AMM REV. 26 DATED 05 MARCH 2018 (MB)	Wing Rear Spar Web AT Bl 85 Sponson Attach (Right) - Ndt Inspection	HRS AFL MOS		5530.4 174.6		 11700** 	0 28 Apr 2008	 11700 		0 0
571300 1159WM20023-23 NSN4123 Airframe	Main Landing Gear Sponson Rib Assembly (Left) - Discard	HRS AFL MOS		5530.4 2599 174.6		 20000 	0 0 28 Apr 2008	 20000 		0 0
571301 1159SB20623-8 NSN Airframe	Main Landing Gear Sponson Rib Assembly (Right) - Discard	HRS AFL MOS	 TSN:4	882.2 304 23.8		 20000 	4648.2 2295 23 Nov 2020	 22295 		0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
571401	Upper Cover Stringers - General Visual Inspection	HRS				15000**		15000		0
		AFL				15000**		15000		0
		MOS		174.6			28 Apr 2008			
Airframe										
571402	Lower Cover Stringers - General Visual Inspection	HRS				10000**		10000		0
		AFL		2599			0			0
		MOS		174.6			28 Apr 2008			
Airframe										
571403	Lower Wing Cover Stringer Runout - General Visual Inspection	HRS				27000**		27000		0
		AFL		2599			0			0
		MOS		171.1			12 Aug 2008			
Airframe										
571404	Lower Cover Spanwise Splice - General Visual Inspection	HRS				16000**		16000		0
		AFL		2599			0			0
		MOS		174.6			28 Apr 2008			
Airframe										
571405	Wing Lower Cover Access Cutout - Detailed Inspection	HRS		5530.4			0			0
		AFL		2599			0			0
		MOS		174.6			28 Apr 2008			
		MSC				O/C				
Airframe										
571600	Forward Inboard and Outboard Attach Fittings FS 345 - Ndt Inspection (Inboard)	HRS		5530.4			0			0
		AFL				10000**		10000		0
		MOS		174.6			28 Apr 2008			
Airframe										
571601	Wing-to-Fuselage Attach Fitting Corrosion Resistant Steel / Titanium Fitting (Left) - Detailed Inspection	HRS		2367			3163.4			0
		AFL		954			1645			0
		MOS		73.4	-35	96	05 Oct 2016	31 Aug 2024*	30 Sep 2024	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-96M,200304									

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
571602	Wing-to-Fuselage Attach Fitting Corrosion Resistant Steel / Titanium Fitting (Right) - Detailed Inspection	HRS		2367			3163.4			0
		AFL		954			1645			0
		MOS		73.4	-34	96	04 Oct 2016	31 Aug 2024*	30 Sep 2024	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-96M,200304									
Notes: REFERENCE LOWER FUSELAGE OPEN/CLOSE CARD INDEX#5 FOR PANEL CLOSURES.										
571603	Forward Inboard and Outboard Attach Fittings FS 345 - Ndt Inspection (Outboard)	HRS		5530.4			0			0
		AFL				10000**		10000		0
		MOS		174.6			28 Apr 2008			
Airframe										
571703	Butt Line 0 Wing Splice - Ndt Inspection	HRS				15000**		15000		0
		AFL				15000**		15000		0
		MOS		174.6			28 Apr 2008			
Airframe										
573001	Winglet (Left) - Removal / Installation 1159W40701-7 1665L	HRS		5530.4			0			0
		AFL		2599			0			0
		MOS		174.6			28 Apr 2008			TERMA INDUSTRIES GRENNAA AS
Airframe		MSC				O/C				
Notes: Q303708										
573002	Winglet (Right) - Removal / Installation 1159W40701-8 1665R	HRS		5530.4			0			0
		AFL		2599			0			0
		MOS		174.6			28 Apr 2008			GULFSTREAM SAV PROD-IPT
Airframe		MSC				O/C				
Notes: Q303708										
573010	Winglet Blade View from Ground (Left) - Zonal Inspection	HRS		697.6			4832.8			0
		AFL		234			2365			0
		MOS		18.5		24	30 Apr 2021	30 Apr 2023	31 May 2023	
Airframe	052000-24M,200301	[End Of Month Item] [MOS: +1m/-1m]								

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
573011	Winglet Blade View from Ground (Right) - Zonal Inspection	HRS		697.6			4832.8			0
		AFL		234			2365			0
		MOS		18.5		24	30 Apr 2021	30 Apr 2023	31 May 2023	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-24M,200301									
573013	Winglet Attach Hardware (Left) - Inspection	HRS		957.2			4573.2			0
		AFL		362			2237			0
(573013)		MOS		29.1		72	12 Jun 2020	30 Jun 2026	31 Jul 2026	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe	200206									
573014	Winglet Attach Hardware (Right) - Inspection	HRS		957.2			4573.2			0
		AFL		362			2237			0
(573014)		MOS		29.1		72	12 Jun 2020	30 Jun 2026	31 Jul 2026	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe	200206									
573019	Winglet Blade View from Wing (Left) - Zonal Inspection	HRS		2367			3163.4			0
		AFL		954			1645			0
		MOS		73.1		96	12 Oct 2016	31 Oct 2024	30 Nov 2024	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-96M,200304									
573020	Winglet Blade View from Wing (Right) - Zonal Inspection	HRS		2367			3163.4			0
		AFL		954			1645			0
		MOS		73.1		96	12 Oct 2016	31 Oct 2024	30 Nov 2024	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-96M,200304									
573201	Winglet Attach Hardware - Ndt Inspection	HRS		5530.4			0			0
		AFL		2599			0			0
		MOS		174.6			28 Apr 2008			
		MSC				O/C				
Airframe										
573202	Winglet Leading Edge - Polishing	HRS		190.2			5340.2			0
		AFL		71			2528			0
		MOS		5.9	-6	12	20 May 2022	31 May 2023*	30 Jun 2023	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe										
574001	Wing Inboard Leading Edge Assembly (Left) - Removal / Installation	HRS		2367			3163.4			0
		AFL		954			1645			0
	1159W40010-9 10237375	MOS		72.3			07 Nov 2016			
		MSC				O/C				
Airframe										

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Description: Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
574002	Wing Center Leading Edge Assembly (Left) - Removal / Installation		HRS		2367			3163.4			0
			AFL		954			1645			0
	1159W40011-7	10261419	MOS		72.3			07 Nov 2016			
			MSC				O/C				
Airframe											
Notes: METER 320440, CAL DUE 9/17											
574003	Wing Outboard Leading Edge Assembly (Left) - Removal / Installation		HRS		2367			3163.4			0
			AFL		954			1645			0
	1159W40012-7	10195603	MOS		72.3			07 Nov 2016			
			MSC				O/C				
Airframe											
Notes: METER 320440, CAL DUE 9/17											
574004	Fillet, L Wing Inbd Short		HRS		2367			3163.4			0
	1159W40400-27	10280609	AFL		954			1645			0
			MOS		72.5			02 Nov 2016			
			MSC				O/C				
Airframe											
Notes: REF. 1159W40400 REV. F											
574007	Wing Inboard Leading Edge Assembly (Right) - Removal / Installation		HRS		2367			3163.4			0
			AFL		954			1645			0
	1159W40010-10	10244569	MOS		72.3			07 Nov 2016			
			MSC				O/C				
Airframe											
574008	Wing Center Leading Edge Assembly (Right) - Removal / Installation		HRS		2367			3163.4			0
			AFL		954			1645			0
	1159W40011-8	10244565	MOS		72.3			07 Nov 2016			
			MSC				O/C				
Airframe											
574009	Wing Outboard Leading Edge Assembly (Right) - Removal / Installation		HRS		2367			3163.4			0
			AFL		954			1645			0
	1159W40012-8	10261432	MOS		72.3			07 Nov 2016			
			MSC				O/C				
Airframe											
Notes: METER 320440, CAL DUE 9/17											

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
574010	Fillet, R Wing Inbd Short		HRS		2367			3163.4			0
	1159W40400-28	10228279	AFL		954			1645			0
			MOS		72.6			28 Oct 2016			
			MSC				O/C				
Airframe											
Notes: REF. 1159W40400 REV. F											
574013	Wing Leading Edge - Polishing		HRS		190.2			5340.2			0
			AFL		71			2528			0
			MOS		5.9	-6	12	20 May 2022	31 May 2023*	30 Jun 2023	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
574015	Wing Leading Edge Bl 35.80 - Bl 433 Inboard of Navigation Light (Left) - Zonal Inspection		HRS		697.6			4832.8			0
			AFL		234			2365			0
			MOS		18.5		24	30 Apr 2021	30 Apr 2023	31 May 2023	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-24M,200301										
574016	Wing Leading Edge Bl 35.80 - Bl 433 Inboard of Navigation Light (Right) - Zonal Inspection		HRS		697.6			4832.8			0
			AFL		234			2365			0
			MOS		18.5		24	30 Apr 2021	30 Apr 2023	31 May 2023	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-24M,200301										
574017	Wing Leading Edge With Gap Bands Removed (Left) - Zonal Inspection		HRS		2367			3163.4			0
			AFL		954			1645			0
			MOS		72.3	-68	96	07 Nov 2016	31 Aug 2024*	30 Sep 2024	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-96M,200304										
574018	Wing Leading Edge With Gap Bands Removed (Right) - Zonal Inspection		HRS		2367			3163.4			0
			AFL		954			1645			0
			MOS		72.3	-68	96	07 Nov 2016	31 Aug 2024*	30 Sep 2024	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-96M,200304										
574019	Wing Leading Edges Removed (Left) - Zonal Inspection		HRS		5530.4			0			0
			AFL		2599			0			0
			MOS		171.1		192	12 Aug 2008	31 Aug 2024	30 Sep 2024	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-192M,200308										

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
574020	Wing Leading Edges Removed (Right) - Zonal Inspection		HRS		5530.4			0			0
			AFL		2599			0			0
			MOS		171.1		192	12 Aug 2008	31 Aug 2024	30 Sep 2024	
Airframe	052000-192M,200308		[End Of Month Item] [MOS: +1m/-1m]								
575001	Wing Trailing Edge Lower (Left) - Zonal Inspection		HRS		697.6			4832.8			0
			AFL		234			2365			0
			MOS		18.5	31	24	30 Apr 2021	31 May 2023*	30 Jun 2023	
Airframe	052000-24M,200301		[End Of Month Item] [MOS: +1m/-1m]								
575002	Wing Trailing Edge Lower (Right) - Zonal Inspection		HRS		697.6			4832.8			0
			AFL		234			2365			0
			MOS		18.5	31	24	30 Apr 2021	31 May 2023*	30 Jun 2023	
Airframe	052000-24M,200301		[End Of Month Item] [MOS: +1m/-1m]								
575003	Wing Trailing Edge Upper (Left) - Zonal Inspection		HRS		1416.9			4113.5			0
			AFL		561			2038			0
			MOS		43		96	17 Apr 2019	30 Apr 2027	31 May 2027	
Airframe	052000-96M,200304		[End Of Month Item] [MOS: +1m/-1m]								
575004	Wing Trailing Edge Upper (Right) - Zonal Inspection		HRS		1416.9			4113.5			0
			AFL		561			2038			0
			MOS		43		96	17 Apr 2019	30 Apr 2027	31 May 2027	
Airframe	052000-96M,200304		[End Of Month Item] [MOS: +1m/-1m]								
575005	Wing Box Section (Left) - Zonal Inspection		HRS		2367			3163.4			0
			AFL		954			1645			0
			MOS		73.4	-34	96	04 Oct 2016	31 Aug 2024*	30 Sep 2024	
Airframe	052000-96M,200304		[End Of Month Item] [MOS: +1m/-1m]								
575006	Wing Box Section (Right) - Zonal Inspection		HRS		2367			3163.4			0
			AFL		954			1645			0
			MOS		73.4	-35	96	05 Oct 2016	31 Aug 2024*	30 Sep 2024	
Airframe	052000-96M,200304		[End Of Month Item] [MOS: +1m/-1m]								
575007	Wing Rear Beam (Left) - Zonal Inspection		HRS		697.6			4832.8			0
			AFL		234			2365			0
			MOS		18.5	31	24	30 Apr 2021	31 May 2023*	30 Jun 2023	
Airframe	052000-24M,200301		[End Of Month Item] [MOS: +1m/-1m]								

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
575008	Wing Rear Beam (Right) - Zonal Inspection		HRS		697.6			4832.8			0
			AFL		234			2365			0
			MOS		18.5	31	24	30 Apr 2021	31 May 2023*	30 Jun 2023	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-24M,200301										
575009	Wing Rear Beam AT Aileron (Left) - Zonal Inspection		HRS		2367			3163.4			0
			AFL		954			1645			0
			MOS		73.4	-34	96	04 Oct 2016	31 Aug 2024*	30 Sep 2024	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-96M,200304										
575010	Wing Rear Beam AT Aileron (Right) - Zonal Inspection		HRS		2367			3163.4			0
			AFL		954			1645			0
			MOS		73.4	-34	96	04 Oct 2016	31 Aug 2024*	30 Sep 2024	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-96M,200304										
Notes: REFERENCE 18.3 BONDING WIRE											
575011	Wing Upper Surface View from Wing (Left) - Zonal Inspection		HRS		2367			3163.4			0
			AFL		954			1645			0
			MOS		73.1		96	13 Oct 2016	31 Oct 2024	30 Nov 2024	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-96M,200304										
575012	Wing Upper Surface View from Wing (Right) - Zonal Inspection		HRS		2367			3163.4			0
			AFL		954			1645			0
			MOS		73.1		96	13 Oct 2016	31 Oct 2024	30 Nov 2024	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-96M,200304										
575015	Wing Rear Beam (Left Flap AREA Cove Panel Drain Hole) - (Enhanced) Zonal Inspection		HRS		697.6			4832.8			0
			AFL		234			2365			0
			MOS		18.5	31	24	30 Apr 2021	31 May 2023*	30 Jun 2023	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-24M,200301										
575016	Wing Rear Beam (Right Flap AREA Cove Panel Drain Hole) - (Enhanced) Zonal Inspection		HRS		697.6			4832.8			0
			AFL		234			2365			0
			MOS		18.5	31	24	30 Apr 2021	31 May 2023*	30 Jun 2023	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-24M,200301										

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
575017	Wing Rear Beam AT Aileron (Left Cove Panel Drain Hole) - (Enhanced) Zonal Inspection		HRS		2367			3163.4			0
			AFL		954			1645			0
			MOS		73.4	-34	96	04 Oct 2016	31 Aug 2024*	30 Sep 2024	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-96M,200304										
575018	Wing Rear Beam AT Aileron (Right Cove Panel Drain Hole) - (Enhanced) Zonal Inspection		HRS		2367			3163.4			0
			AFL		954			1645			0
			MOS		73.4	-34	96	04 Oct 2016	31 Aug 2024*	30 Sep 2024	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-96M,200304										
575111	Flap Rollers and Track Support - Detailed Inspection		HRS		5530.4			0			0
			AFL		2599			0			0
			MOS		174.6			28 Apr 2008			
			MSC				O/C				
Airframe											
575301	Flaps, Spoilers and Ailerons Support and Attach Fittings (Left) - General Visual Inspection		HRS		882.2			4648.2			0
			AFL		304			2295			0
			MOS		25.5	-51	96	02 Oct 2020	31 Aug 2028*	30 Sep 2028	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-144/96M,200305										
575302	Flaps, Spoilers and Ailerons Support and Attach Fittings (Right) - General Visual Inspection		HRS		882.2			4648.2			0
			AFL		304			2295			0
			MOS		25.1	-61	96	12 Oct 2020	31 Aug 2028*	30 Sep 2028	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-144/96M,200305										
575303	Flap Spar - X-Ray Inspection		HRS		5530.4			0			0
			AFL		2599			0			0
			MOS		174.6			28 Apr 2008			
			MSC				O/C				
Airframe											
575304	Flap Track A Roller Fittings - Ndt Inspection		HRS		5530.4			0			0
			AFL				13000**		13000		0
			MOS		174.6			28 Apr 2008			
Airframe											

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
575305 Airframe	Flap Track D Roller Fitting - Ndt Inspection	HRS AFL MOS		5530.4 174.6		 13000** 	0 28 Apr 2008	 13000 		0 0
575306 Airframe	Flap Track A Beam - Ndt Inspection	HRS AFL MOS		5530.4 174.6		 9500** 	0 28 Apr 2008	 9500 		0 0
575307 Airframe	Flap Track B Beam - Ndt Inspection	HRS AFL MOS		5530.4 174.6		 9500** 	0 28 Apr 2008	 9500 		0 0
575308 Airframe	Flap Track C Beam - Ndt Inspection	HRS AFL MOS		5530.4 174.6		 9500** 	0 28 Apr 2008	 9500 		0 0
575309 Airframe	Flap Track D Beam - Ndt Inspection	HRS AFL MOS		5530.4 174.6		 9500** 	0 28 Apr 2008	 9500 		0 0
575310 Airframe	Flap Track Support Fittings - Ndt Inspection	HRS AFL MOS		5530.4 174.6		 6200** 	0 28 Apr 2008	 6200 		0 0
575311 Airframe	Flap Track B Roller Fittings - Ndt Inspection	HRS AFL MOS		5530.4 174.6		 9500** 	0 28 Apr 2008	 9500 		0 0
575312 Airframe	Flap Track C Roller Fittings - Ndt Inspection	HRS AFL MOS		5530.4 174.6		 9500** 	0 28 Apr 2008	 9500 		0 0

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
575601	Trailing Edge Flight Control Attach Hinge and Support Fittings (Left) - Detailed Inspection		HRS		882.2			4648.2			0
			AFL		304			2295			0
			MOS		25.5	-51	96	02 Oct 2020	31 Aug 2028*	30 Sep 2028	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-144/96M,200305										
575602	Trailing Edge Flight Control Attach Hinge and Support Fittings (Right) - Detailed Inspection		HRS		882.2			4648.2			0
			AFL		304			2295			0
			MOS		25.1	-61	96	12 Oct 2020	31 Aug 2028*	30 Sep 2028	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-144/96M,200305										
576001	Aileron Attach Fittings - Ndt Inspection		HRS				25300**		25300		0
			AFL		2599			0			0
			MOS		174.6			28 Apr 2008			
Airframe											
576002	Aileron Trim Tab Hinge Fitting - Detailed Inspection		HRS				25300**		25300		0
			AFL		2599			0			0
			MOS		174.6			28 Apr 2008			
Airframe											
576005	Aileron Ballast Weights (Left) - Detailed Inspection		HRS		2367			3163.4			0
			AFL		954			1645			0
			MOS		73.5	-30	96	30 Sep 2016	31 Aug 2024*	30 Sep 2024	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-96M,200304										
576006	Aileron Ballast Weights (Right) - Detailed Inspection		HRS		2367			3163.4			0
			AFL		954			1645			0
			MOS		73.5	-30	96	30 Sep 2016	31 Aug 2024*	30 Sep 2024	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-96M,200304										
576010	Aileron Tab / Spoilers External for Delamination - Special Detailed Inspection		HRS		2367			3163.4			0
			AFL		954			1645			0
			MOS		73.1	-43	96	13 Oct 2016	31 Aug 2024*	30 Sep 2024	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe	052000-96M,200304										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
577001	Spoiler Structural Body and Drive Hinge Fitting Lugs - Ndt Inspection	HRS				15000**		15000		0
		AFL				15000**		15000		0
		MOS		174.6			28 Apr 2008			
Airframe										
577002	Spoiler Drive Hinge Fitting Lugs - Ndt Inspection	HRS		5530.4			0			0
		AFL		2599			0			0
		MOS		174.6			28 Apr 2008			
		MSC				O/C				
Airframe										
71 - Power Plant										
710001	Engine (Left) - Removal / Installation	HRS	TSN:3760.9	1691.5			3838.9			0
	TAY611-8C 85245	AFL	TSN:1882	668			1931			0
		MOS		51.7			25 Jul 2018			ROLLS ROYCE CANADA LTD
		MSC				O/C				
Airframe										
710002	Engine (Right) - Removal / Installation	HRS	TSN:3760.9	1691.5			3838.9			0
	TAY611-8C 85244	AFL	TSN:1882	668			1931			0
		MOS		51.7			24 Jul 2018			ROLLS ROYCE CANADA LTD
		MSC				O/C				
Airframe										
710003	No. 1 Engine - Engine Midlife Insp	HRS		1691.5		6000	3760.9	9760.9		0
		ENC		668			1882			0
		MOS		52.3			07 Jul 2018			
Engine										
Notes: PN: TAY611-8C SN: 85245. ENGINE DECLARED TASK ORIENTED										
710003 (710004)	No. 2 Engine - Engine Midlife Insp	HRS		1691.5		6000	3760.9	9760.9		0
		ENC		668			1882			0
		MOS		52.3			07 Jul 2018			
Engine										
Notes: PN: TAY611-8C SN: 85244. ENGINE DECLARED TASK ORIENTED										

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Description: Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
710005	No. 1 Engine - Engine Overhaul TAY611-8C	85245	HRS ENC MOS		5452.4 2550 175.7		12000 240	0 0 24 Mar 2008	12000 24 Mar 2028		0 0 ROLLS-ROYCE CUSTOMER BUSINESS OVERHAUL
Engine											
Notes: ENGINE DECLARED TASK ORIENTED											
710005 (710006)	No. 2 Engine - Engine Overhaul TAY611-8C	85244	HRS ENC MOS		5452.4 2550 176.2		12000 240	0 0 11 Mar 2008	12000 11 Mar 2028		0 0 ROLLS-ROYCE CUSTOMER BUSINESS OVERHAUL
Engine											
Notes: ENGINE DECLARED TASK ORIENTED											
710007	No. 1 Engine - Engine Performance Run		HRS ENC MOS MSC		5452.4 2550 175.7		 O/C	0 0 24 Mar 2008			0 0
Engine											
710007 (710008)	No. 2 Engine - Engine Performance Run		HRS ENC MOS MSC		5452.4 2550 176.2		 O/C	0 0 11 Mar 2008			0 0
Engine											
710009	No. 1 Engine - Powerplant - Adjustment / Test - General		HRS ENC MOS MSC		5139.2 2446 159.2		 O/C	313.2 104 09 Aug 2009			0 0
Engine											
710009 (710010)	No. 2 Engine - Powerplant - Adjustment / Test - General		HRS ENC MOS MSC		5452.4 2550 176.2		 O/C	0 0 11 Mar 2008			0 0
Engine											
710011	No. 1 Engine - Engine Run - Pre-Operational Checks		HRS ENC MOS MSC		882.2 304 23		 O/C	4570.2 2246 15 Dec 2020			0 0
Engine											

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
710011 (710012)	No. 2 Engine - Engine Run - Pre-Operational Checks	HRS		882.2			4570.2			0
		ENC		304			2246			0
		MOS		23			15 Dec 2020			
		MSC				O/C				
Engine										
710013	No. 1 Engine - Engine Run - Checklist	HRS		882.2			4570.2			0
		ENC		304			2246			0
		MOS		23.3			07 Dec 2020			
		MSC				O/C				
Engine										
Notes: RUNUP ACCOMPLISHED AND FOUND SATIS.										
710013 (710014)	No. 2 Engine - Engine Run - Checklist	HRS		882.2			4570.2			0
		ENC		304			2246			0
		MOS		23.3			08 Dec 2020			
		MSC				O/C				
Engine										
Notes: RUNUP ACCOMPLISHED AND FOUND SATIS.										
710015	No. 1 Engine - Engine Test 1 - Wet Motor Operation Leak Check	HRS		1691.5			3760.9			0
		ENC		668			1882			0
		MOS		51.8			23 Jul 2018			
		MSC				O/C				
Engine										
710015 (710016)	No. 2 Engine - Engine Test 1 - Wet Motor Operation Leak Check	HRS		1691.5			3760.9			0
		ENC		668			1882			0
		MOS		51.7			24 Jul 2018			
		MSC				O/C				
Engine										
710017	No. 1 Engine - Engine Run Leak Check Test 2A - Lp Fuel System, Hp Fuel System (Bypass Duct Mounted), AIR and Oil Systems	HRS		756.7			4695.7			0
		ENC		249			2301			0
		MOS		19.4			04 Apr 2021			
		MSC				O/C				
Engine										
710017 (710018)	No. 2 Engine - Engine Run Leak Check Test 2A - Lp Fuel System, Hp Fuel System (Bypass Duct Mounted), AIR and Oil Systems	HRS		882.2			4570.2			0
		ENC		304			2246			0
		MOS		23.3			08 Dec 2020			
		MSC				O/C				
Engine										

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
710019	No. 1 Engine - Engine Run Leak Check Test 2B - Hp Fuel System (Core Mounted)		HRS ENC MOS MSC		5452.4 2550 175.7		 O/C	0 0 24 Mar 2008			0 0
Engine											
710019 (710020)	No. 2 Engine - Engine Run Leak Check Test 2B - Hp Fuel System (Core Mounted)		HRS ENC MOS MSC		5452.4 2550 176.2		 O/C	0 0 11 Mar 2008			0 0
Engine											
710021	No. 1 Engine - Engine Test 3 - Thrust Reverser Check		HRS ENC MOS MSC		5452.4 2550 175.7		 O/C	0 0 24 Mar 2008			0 0
Engine											
710021 (710022)	No. 2 Engine - Engine Test 3 - Thrust Reverser Check		HRS ENC MOS MSC		5452.4 2550 176.2		 O/C	0 0 11 Mar 2008			0 0
Engine											
710023	No. 1 Engine - Engine - T/R Lru Leak Check		HRS ENC MOS MSC		5452.4 2550 175.7		 O/C	0 0 24 Mar 2008			0 0
Engine											
710023 (710024)	No. 2 Engine - Engine - T/R Lru Leak Check		HRS ENC MOS MSC		5452.4 2550 176.2		 O/C	0 0 11 Mar 2008			0 0
Engine											
710025	No. 1 Engine - Engine Test 4 - Engine Power Assurance Check		HRS ENC MOS MSC		957.2 362 29.1		 O/C	4495.2 2188 12 Jun 2020			0 0
Engine											

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
710025 (710026)	No. 2 Engine - Engine Test 4 - Engine Power Assurance Check	HRS ENC MOS MSC		957.2 362 29.1		 O/C	4495.2 2188 12 Jun 2020			0 0
Engine										
710027	No. 1 Engine - Engine Low-Pressure Rotor Assembly - Run Down Time Test	HRS ENC MOS MSC		5452.4 2550 175.7		 O/C	0 0 24 Mar 2008			0 0
Engine										
710027 (710028)	No. 2 Engine - Engine Low-Pressure Rotor Assembly - Run Down Time Test	HRS ENC MOS MSC		5452.4 2550 176.2		 O/C	0 0 11 Mar 2008			0 0
Engine										
710029	No. 1 Engine - Engine Test 6 - Vibration Survey	HRS ENC MOS MSC		5452.4 2550 175.7		 O/C	0 0 24 Mar 2008			0 0
Engine										
710029 (710030)	No. 2 Engine - Engine Test 6 - Vibration Survey	HRS ENC MOS MSC		2545.3 1035 82.4		 O/C	2907.1 1515 05 Jan 2016			0 0
Engine										
710031	No. 1 Engine - Engine Low-Pressure Compressor - Trim Balance Three Weight Method	HRS ENC MOS MSC		5452.4 2550 175.7		 O/C	0 0 24 Mar 2008			0 0
Engine										
710031 (710032)	No. 2 Engine - Engine Low-Pressure Compressor - Trim Balance Three Weight Method	HRS ENC MOS MSC		2943.1 1289 103		 O/C	2509.3 1261 15 Apr 2014			0 0
Engine										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
710033 Logbook Position	No. 1 Engine - Engine Test 7 - Low-Pressure Compressor Fan Trim Balance Alternate	HRS ENC MOS MSC		5452.4 2550 175.7		 O/C	0 0 24 Mar 2008			0 0
Engine										
710033 (710034) Logbook Position	No. 2 Engine - Engine Test 7 - Low-Pressure Compressor Fan Trim Balance Alternate	HRS ENC MOS MSC		2943.1 1289 103		 O/C	2509.3 1261 15 Apr 2014			0 0
Engine										
710035 Logbook Position	No. 1 Engine - Low-Pressure Compressor Fan Blade SET - RE-Index	HRS ENC MOS MSC		5452.4 2550 175.7		 O/C	0 0 24 Mar 2008			0 0
Engine										
710035 (710036) Logbook Position	No. 2 Engine - Low-Pressure Compressor Fan Blade SET - RE-Index	HRS ENC MOS MSC		2943.1 1289 103		 O/C	2509.3 1261 15 Apr 2014			0 0
Engine										
710037 Logbook Position	No. 1 Engine - Engine Test 9 - Full Authority Digital Engine Control Operational Test	HRS ENC MOS MSC		1416.9 561 43		 O/C	4035.5 1989 16 Apr 2019			0 0
Engine										
Notes: EEC OPS TEST I.A.W CMP 710037 MM REF: 71-00-00 & CMP 710037 MM REF: 71-00-00 SATIS.										
710037 (710038) Logbook Position	No. 2 Engine - Engine Test 9 - Full Authority Digital Engine Control Operational Test	HRS ENC MOS MSC		1416.9 561 43		 O/C	4035.5 1989 16 Apr 2019			0 0
Engine										
Notes: PN: TEEC2000-05-AE SN: <NONE>. FADEC OPS TEST I.A.W AMM CH 71-00-00 FOUND SATIS. MEL CH. 73-4, CAT "A" DATED 02-JULY-2009 CLEARED.										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
710039 Logbook Position	No. 1 Engine - Cockpit Engine Vibration Monitor EVM Card - Vibration Run	HRS ENC MOS MSC		1691.5 668 51.7		 O/C	3760.9 1882 24 Jul 2018			0 0
Engine										
710039 (710040) Logbook Position	No. 2 Engine - Cockpit Engine Vibration Monitor EVM Card - Vibration Run	HRS ENC MOS MSC		1691.5 668 51.7		 O/C	3760.9 1882 24 Jul 2018			0 0
Engine										
710051 Logbook Position	No. 1 Engine - Engine Calendar Life	HRS ENC MOS		1691.5 668 52.3		 120	3760.9 1882 07 Jul 2018	 07 Jul 2028		0 0
Engine										
Notes: PN: TAY611-8C SN: 85245.										
710051 (710052) Logbook Position	No. 2 Engine - Engine Calendar Life	HRS ENC MOS		1691.5 668 51.9		 120	3760.9 1882 19 Jul 2018	 19 Jul 2028		0 0
Engine										
Notes: PN: TAY611-8C SN: 85244.										
710055 Logbook Position	No. 1 Engine - Engine Health Monitoring	HRS ENC MOS MSC		5452.4 2550 175.7		 O/C	0 0 24 Mar 2008			0 0
Engine										
710055 (710060) Logbook Position	No. 2 Engine - Engine Health Monitoring	HRS ENC MOS MSC		5452.4 2550 176.2		 O/C	0 0 11 Mar 2008			0 0
Engine										
710061 Logbook Position	No. 1 Engine - Engine Maintenance Program Declaration	HRS ENC MOS		5447.5 2548 171.1		 	4.9 2 12 Aug 2008			0 0
Engine										
Notes: ENGINE DECLARED TASK ORIENTED										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
710061 (710062)	No. 2 Engine - Engine Maintenance Program Declaration	HRS ENC MOS		5447.5 2548 171.1			4.9 2 12 Aug 2008			0 0
Engine										
Notes: ENGINE DECLARED TASK ORIENTED										
710065	No. 1 Engine - Powerplant - Preparation for Ground Operations	HRS ENC MOS MSC		882.2 304 23		 O/C	4570.2 2246 15 Dec 2020			0 0
Engine										
710065 (710066)	No. 2 Engine - Powerplant - Preparation for Ground Operations	HRS ENC MOS MSC		882.2 304 23		 O/C	4570.2 2246 15 Dec 2020			0 0
Engine										
710067	No. 1 Engine - Powerplant - Start Procedure	HRS ENC MOS MSC		5452.4 2550 175.7		 O/C	0 0 24 Mar 2008			0 0
Engine										
710067 (710068)	No. 2 Engine - Powerplant - Start Procedure	HRS ENC MOS MSC		5452.4 2550 176.2		 O/C	0 0 11 Mar 2008			0 0
Engine										
710069	No. 1 Engine - Powerplant - Stop Procedure	HRS ENC MOS MSC		5452.4 2550 175.7		 O/C	0 0 24 Mar 2008			0 0
Engine										
710069 (710070)	No. 2 Engine - Powerplant - Stop Procedure	HRS ENC MOS MSC		5452.4 2550 176.2		 O/C	0 0 11 Mar 2008			0 0
Engine										
710073	No. 1 Engine - Powerplant - Dry Motor Operation	HRS ENC MOS MSC		1691.5 668 51.8		 O/C	3760.9 1882 23 Jul 2018			0 0
Engine										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
710073 (710074)	No. 2 Engine - Powerplant - Dry Motor Operation	HRS		1691.5			3760.9			0
		ENC		668			1882			0
		MOS		51.7			24 Jul 2018			
		MSC				O/C				
Engine										
711001	Engine Nose Cowl (Left) - Removal / Installation 1159P41150-9 4097	HRS	TSN:5307.2	882.2			4648.2			0
		AFL	TSN:2360	304			2295			0
		MOS		24			17 Nov 2020			
		MSC				O/C				
Airframe										
711002	Engine Nose Cowl (Right) - Removal / Installation 1159P41150-021 4067	HRS		1691.5			3838.9			0
		AFL		668			1931			0
		MOS		51.9			18 Jul 2018			
		MSC				O/C				
Airframe										
711003	Inlet Cowl Aerodynamic Surfaces (Left) - Detailed Inspection	HRS		4882.7			647.7			0
		AFL		2421			178			0
		MOS		149.9			19 May 2010			
		MSC				O/C				
Airframe										
711004	Inlet Cowl Aerodynamic Surfaces (Right) - Detailed Inspection	HRS		4882.7			647.7			0
		AFL		2421			178			0
		MOS		149.9			19 May 2010			
		MSC				O/C				
Airframe										
711010	Engine Cowling (Right) - Adjustment / Test	HRS		5530.4			0			0
		AFL		2599			0			0
		MOS		174.6			28 Apr 2008			
		MSC				O/C				
Airframe										
711011	Engine Lower Cowl Door (Left) - Open and Close Procedure	HRS		439.3			5091.1			0
		AFL		157			2442			0
		MOS		12.1			12 Nov 2021			
		MSC				O/C				
Airframe										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
711012	Engine Lower Cowl Door (Right) - Open and Close Procedure	HRS AFL MOS MSC		439.3 157 12.1		 O/C	5091.1 2442 12 Nov 2021			0 0
Airframe										
711013	Engine Upper Cowl Door (Left) - Open and Close Procedure	HRS AFL MOS MSC		882.2 304 23.1		 O/C	4648.2 2295 14 Dec 2020			0 0
Airframe										
711014	Engine Upper Cowl Door (Right) - Open and Close Procedure	HRS AFL MOS MSC		882.2 304 23.3		 O/C	4648.2 2295 08 Dec 2020			0 0
Airframe										
711015	Fixed Cowl (Left) - Detailed Inspection	HRS AFL MOS MSC		1691.5 668 52		 O/C	3838.9 1931 17 Jul 2018			0 0
Airframe										
711016	Fixed Cowl (Right) - Detailed Inspection	HRS AFL MOS MSC		1691.5 668 52		 O/C	3838.9 1931 17 Jul 2018			0 0
Airframe										
711017	Fixed Cowl (Left) - Removal / Installation 1159P41250-103 3637056/001	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 VOUGHT AIRCRAFT INDUSTRIES
Airframe										
711018	Fixed Cowl (Right) - Removal / Installation 1159P41250-104 4358224/001	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
711019 Airframe	Engine Lower Cowl Door (Left) - Removal / Installation 1159P41230-51 4268897/001	HRS AFL MOS MSC	TSN:3838.9 TSN:1931 TSN:123	1691.5 668 51.8		 O/C	3838.9 1931 22 Jul 2018			0 0 VOUGHT AIRCRAFT INDUSTRIES
711020 Airframe	Engine Lower Cowl Door (Right) - Removal / Installation 1159P41230-52 4014875/001	HRS AFL MOS MSC	TSN:3838.9 TSN:1931 TSN:123	1691.5 668 51.8		 O/C	3838.9 1931 22 Jul 2018			0 0 VOUGHT AIRCRAFT INDUSTRIES INC.
711021 Airframe	Upper Cowl Door (Left) - Removal / Installation 1159P41210-45 4250635/001	HRS AFL MOS MSC	TSN:3838.9 TSN:1931 TSN:123	1691.5 668 51.8		 O/C	3838.9 1931 22 Jul 2018			0 0
711022 Airframe	Upper Cowl Door (Right) - Removal / Installation 1159P41210-46 4196441/001	HRS AFL MOS MSC		1691.5 668 51.8		 O/C	3838.9 1931 22 Jul 2018			0 0
711100 Airframe	Powerplant Nose Cowl Internal (View from Ground) (Left) - Zonal Inspection 052000-24M,200301	HRS AFL MOS		697.6 234 18.5		 24	4832.8 2365 30 Apr 2021	 30 Apr 2023	 31 May 2023	0 0
	[End Of Month Item] [MOS: +1m/-1m]									
711101 Airframe	Powerplant Nose Cowl Internal (View from Ground) (Right) - Zonal Inspection 052000-24M,200301	HRS AFL MOS		697.6 234 18.5		 24	4832.8 2365 30 Apr 2021	 30 Apr 2023	 31 May 2023	0 0
	[End Of Month Item] [MOS: +1m/-1m]									
711305 Airframe	Powerplant / Nacelle External (Left) - Zonal Inspection 052000-96M,200304	HRS AFL MOS		1769.5 717 54.7		 96	3760.9 1882 26 Apr 2018	 30 Apr 2026	 31 May 2026	0 0
	[End Of Month Item] [MOS: +1m/-1m]									

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
711306 Airframe	Powerplant / Nacelle External (Right) - Zonal Inspection 052000-96M,200304	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		1769.5 717 54.8		96	3760.9 1882 23 Apr 2018	30 Apr 2026	31 May 2026	0 0
711310 Airframe	Powerplant Nose Cowls Internal (Left) - Zonal Inspection 052000-144M,200306	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		882.2 304 25.9	-37	144	4648.2 2295 18 Sep 2020	31 Aug 2032*	30 Sep 2032	0 0
711311 Airframe	Powerplant Nose Cowls Internal (Right) - Zonal Inspection 052000-144M,200306	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		882.2 304 25.9	-37	144	4648.2 2295 18 Sep 2020	31 Aug 2032*	30 Sep 2032	0 0
711315 Airframe	Powerplant and Nacelle Doors Internal (Left) - Zonal Inspection 052000-2A,200102	HRS AFL MOS [HRS: +50/-50]	6.5	6.5 2 .2	49.3	1000	5523.9 2597 11 Nov 2022	6573.2*	6623.2	0 0
711316 Airframe	Powerplant and Nacelle Doors Internal (Right) - Zonal Inspection 052000-2A,200102	HRS AFL MOS [HRS: +50/-50]	6.5	6.5 2 .2	49.3	1000	5523.9 2597 11 Nov 2022	6573.2*	6623.2	0 0
712005 Airframe	Housing, L Eng Trunnion 1159PM40000-1 BAL1162	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0 THAYER AEROSPACE
712006 Airframe	Housing, R Eng Trunnion 1159PM40000-3 BAL1282	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0 SUMMA TECHNOLOGY INC

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
712007	Engine Trunnion Housing (Left) - Ndt Inspection	HRS		5530.4			0			0
		AFL				13500**		13500		0
		MOS		174.6			28 Apr 2008			
Airframe										
712008	Engine Trunnion Housing (Right) - Ndt Inspection	HRS		5530.4			0			0
		AFL				13500**		13500		0
		MOS		174.6			28 Apr 2008			
Airframe										
712009	Engine Trunnion Canister (Isolator) Assembly (Left) - Removal / Installation	HRS		5530.4			0			0
		AFL		2599			0			0
	94756-192 1929	MOS		174.6			28 Apr 2008			BARRY CONTROL AEROSPACE
		MSC				O/C				
Airframe										
712010	Engine Trunnion Canister (Isolator) Assembly (Right) - Removal / Installation	HRS		5530.4			0			0
		AFL		2599			0			0
	94756-192 1928	MOS		174.6			28 Apr 2008			BARRY CONTROL AEROSPACE
		MSC				O/C				
Airframe										
712011	Isolator Core (Left) - Ndt Inspection	HRS		5530.4			0			0
		AFL		2599			0			0
		MOS		174.6			28 Apr 2008			
		MSC				O/C				
Airframe										
712012	Isolator Core (Right) - Ndt Inspection	HRS		5530.4			0			0
		AFL		2599			0			0
		MOS		174.6			28 Apr 2008			
		MSC				O/C				
Airframe										
712013	Engine Mount Beam (Left, Forward) - Removal / Installation	HRS		5530.4			0			0
		AFL		2599			0			0
	1159PM41310-9 0246	MOS		174.6			28 Apr 2008			SUMMA TECHNOLOGY INC
		MSC				O/C				
Airframe										

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
712014	Engine Mount Beam (Right, Forward) - Removal / Installation		HRS		5530.4			0			0
			AFL		2599			0			0
	1159PM41310-9	0223	MOS		174.6			28 Apr 2008			SUMMA TECHNOLOGY INC
			MSC				O/C				
Airframe											
712015	Engine Mount Beam (Left, Aft) - Removal / Installation		HRS		5530.4			0			0
	1159PM41320-3	0195	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			THAYER AEROSPACE
			MSC				O/C				
Airframe											
712016	Engine Mount Beam (Right, Aft) - Removal / Installation		HRS		5530.4			0			0
	1159PM41320-3	0180	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			THAYER AEROSPACE
			MSC				O/C				
Airframe											
712017	Engine Isolator Mount Bolt Assembly (Left Forward) - Ndt Inspection / Discard		HRS		5530.4		8500	0	8500		0
			AFL		2599			0			0
			MOS		174.6			28 Apr 2008			
Airframe											
Notes: PN: 94756-07 SN: 5161.											
712018	Engine Isolator Mount Bolt Assembly (Left Aft) - Ndt Inspection / Discard		HRS		5530.4		8500	0	8500		0
			AFL		2599			0			0
			MOS		174.6			28 Apr 2008			
Airframe											
Notes: PN: 94756-06 SN: 5157.											
712019	Engine Isolator Mount Bolt Assembly (Right Forward) - Ndt Inspection / Discard		HRS		5530.4		8500	0	8500		0
			AFL		2599			0			0
			MOS		174.6			28 Apr 2008			
Airframe											
Notes: PN: 94756-07 SN: 5162.											

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
712020	Engine Isolator Mount Bolt Assembly (Right Aft) - Ndt Inspection / Discard		HRS AFL MOS		5530.4 2599 174.6		8500	0 0 28 Apr 2008	8500		0 0
Airframe											
Notes: PN: 94756-06 SN: 5158.											
712021	Engine Isolator Mount Bolt Assembly (Left, Forward) - Ndt Inspection		HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0
Airframe											
712022	Engine Isolator Mount Bolt Assembly (Right, Forward) - Ndt Inspection		HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0
Airframe											
712023	Engine Isolator Mount Bolt Assembly (Left, Aft) - Ndt Inspection		HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0
Airframe											
712024	Engine Isolator Mount Bolt Assembly (Right, Aft) - Ndt Inspection		HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0
Airframe											
712029	Bolt, L Eng Trunnion Tie 07-9062-03	BAL4795	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0 PROSYS INFORMATION SYSTEMS
Airframe											

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
Logbook Position	HW	SW									
	MM Ref										
	Ops Number(s)										
712030	Bolt, R Eng Trunnion Tie 07-9062-03	BAL4798	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 PROSYS INFORMATION SYSTEMS
Airframe											
712031	Engine Trunnion Tie Bolt (Left) - Ndt Inspection		HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe											
712032	Engine Trunnion Tie Bolt (Right) - Ndt Inspection		HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe											
712039	Engine Mount Beam (Left, Forward) - Ndt Inspection		HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe											
712040	Engine Mount Beam (Right, Forward) - Ndt Inspection		HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe											
712041	Engine Mount Beam (Left, Aft) - Ndt Inspection		HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe											
712042	Engine Mount Beam (Right, Aft) - Ndt Inspection		HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe											
712043	Engine Inboard Mount Link (Left, Forward) - Ndt Inspection		HRS AFL MOS		 2599 174.6		9400** 	 0 28 Apr 2008	9400		0 0
Airframe											

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
712044 Logbook Position	Engine Inboard Mount Link (Right, Forward) - Ndt Inspection	HRS AFL MOS		2599 174.6		9400**	0 28 Apr 2008	9400		0 0
Airframe										
712045	Engine Inboard Mount Link (Left, Aft) - Ndt Inspection	HRS AFL MOS		2599 174.6		9500**	0 28 Apr 2008	9500		0 0
Airframe										
712046	Engine Inboard Mount Link (Right, Aft) - Ndt Inspection	HRS AFL MOS		2599 174.6		9500**	0 28 Apr 2008	9500		0 0
Airframe										
712047	Engine Inboard Mount Link (Left Forward) - Removal / Installation PN SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0
Airframe										
712048	Engine Inboard Mount Link (Right Forward) - Removal / Installation PN SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0
Airframe										
712049	Engine Inboard Mount Link (Left Aft) - Removal / Installation PN SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0
Airframe										
712050	Engine Inboard Mount Link (Right Aft) - Removal / Installation PN SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		O/C	0 0 28 Apr 2008			0 0
Airframe										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
712051	Engine Forward Outboard Suspension Link (Left) - Removal / Installation 94756-08 BALH3000	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 BARRY CONTROL AEROSPACE
Airframe										
712052	Engine Forward Outboard Suspension Link (Right) - Removal / Installation 94756-08 BALH3019	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 BARRY CONTROL AEROSPACE
Airframe										
712053	Engine Forward Outboard Suspension Link (Left) - Ndt Inspection	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										
712054	Engine Forward Outboard Suspension Link (Right) - Ndt Inspection	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										
712057	Thrust Strut (Left) - Magnaflux	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										
712058	Thrust Strut (Right) - Magnaflux	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										
712069	Engine Mount Vibration Isolator (Left Forward Mount, Forward) - Discard 94756-04 SN-UNKNOWN	HRS AFL MOS		5530.4 2599 174.6		8500 	0 0 28 Apr 2008	8500		0 0
Airframe										

Notes: ENGINE DECLARED TASK ORIENTED

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
712070	Engine Mount Vibration Isolator (Right Forward Mount, Forward) - Discard 94756-04 SN-UNKNOWN	HRS AFL MOS		5530.4 2599 174.6		8500	0 0 28 Apr 2008	8500		0 0
Airframe										
Notes: ENGINE DECLARED TASK ORIENTED										
712071	Engine Vibration Isolator (Left Forward Mount, Aft) - Discard 94756-04 5255	HRS AFL MOS		5530.4 2599 174.6		8500	0 0 28 Apr 2008	8500		0 0
Airframe										
Notes: ENGINE DECLARED TASK ORIENTED										
712072	Engine Vibration Isolator (Right Forward Mount, Aft) - Discard 94756-04 5296	HRS AFL MOS		5530.4 2599 174.6		8500	0 0 28 Apr 2008	8500		0 0
Airframe										
Notes: ENGINE DECLARED TASK ORIENTED										
712073	Engine Trunnion Canister (Left) - Restore 94756-192 1929	HRS AFL MOS		5530.4 2599 174.6		8500	0 0 28 Apr 2008	8500		0 0
Airframe										
Notes: ENGINE DECLARED TASK ORIENTED										
712074	Engine Trunnion Canister (Right) - Restore 94756-192 1928	HRS AFL MOS		5530.4 2599 174.6		8500	0 0 28 Apr 2008	8500		0 0
Airframe										
Notes: ENGINE DECLARED TASK ORIENTED										
712093	Engine Mount Vibration Isolator (Left Aft Mount, Forward) - Discard 94756-13 SN-UNKNOWN	HRS AFL MOS		5530.4 2599 174.6		8500	0 0 28 Apr 2008	8500		0 0
Airframe										
Notes: ENGINE DECLARED TASK ORIENTED										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
712094	Engine Mount Vibration Isolator (Right Aft Mount, Forward) - Discard 94756-13 SN-UNKNOWN	HRS AFL MOS		5530.4 2599 174.6		8500	0 0 28 Apr 2008	8500		0 0
Airframe										
Notes: ENGINE DECLARED TASK ORIENTED										
712095	Engine Vibration Isolator (Left Aft Mount, Aft) - Discard 94756-13 3010	HRS AFL MOS	 TSN:234	1769.5 717 54.9		8500	3760.9 1882 20 Apr 2018	12260.9		0 0
Airframe										
Notes: ENGINE DECLARED TASK ORIENTED										
712096	Engine Vibration Isolator (Right Aft Mount, Aft) - Discard 94756-13 4988	HRS AFL MOS	 	5530.4 2599 174.6		8500	0 0 28 Apr 2008	8500		0 0
Airframe										
Notes: ENGINE DECLARED TASK ORIENTED										
712101	Engine Mount Vibration Isolator (Left Forward Mount, Forward) - Removal / Installation 94756-04 5255	HRS AFL MOS MSC	 	5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 BARRY CONTROL AEROSPACE
Airframe										
712102	Engine Mount Vibration Isolator (Right Forward Mount, Forward) - Removal / Installation 94756-04 5296	HRS AFL MOS MSC	TSN:2284.3 TSN:1167 TSN:67 	3246.1 1432 107.7		 O/C	2284.3 1167 26 Nov 2013			0 0 BARRY CONTROL AEROSPACE
Airframe										
712103	Engine Mount Vibration Isolator (Left Forward Mount, Aft) - Removal / Installation 94756-04 5188	HRS AFL MOS MSC	 	5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 BARRY CONTROL AEROSPACE
Airframe										
712104	Engine Mount Vibration Isolator (Right Forward Mount, Aft) - Removal / Installation 94756-04 5254	HRS AFL MOS MSC	TSN:2284.3 TSN:1167 TSN:67 	3246.1 1432 107.7		 O/C	2284.3 1167 26 Nov 2013			0 0 BARRY CONTROL AEROSPACE
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
712105 Airframe	Engine Mount Vibration Isolator (Left Aft Mount, Forward) - Removal / Installation 94756-13 5013	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 API
712106 Airframe	Engine Mount Vibration Isolator (Right Aft Mount, Forward) - Removal / Installation 94756-13 4988	HRS AFL MOS MSC	TSN:2284.3 TSN:1167 TSN:67	3246.1 1432 107.7		 O/C	2284.3 1167 26 Nov 2013			0 0 API
712107 Airframe	Engine Mount Vibration Isolator (Left Aft Mount, Aft) - Removal / Installation 94756-13 3010	HRS AFL MOS MSC	 TSN:234	1769.5 717 54.9		 O/C	3760.9 1882 20 Apr 2018			0 0 API
712108 Airframe	Engine Mount Vibration Isolator (Right Aft Mount, Aft) - Removal / Installation 94756-13 5028	HRS AFL MOS MSC	TSN:2284.3 TSN:1167 TSN:67	3246.1 1432 107.7		 O/C	2284.3 1167 26 Nov 2013			0 0 API
712115 Airframe	Engine Mount Vibration Isolators (Left) - Detailed Inspection	HRS AFL MOS MSC		1769.5 717 54.9		 O/C	3760.9 1882 20 Apr 2018			0 0
712120 Airframe	Engine Mount Vibration Isolators (Right) - Detailed Inspection	HRS AFL MOS MSC		1769.5 717 54.9		 O/C	3760.9 1882 19 Apr 2018			0 0
712217 Airframe	Side Trunnion Mount Lugs, Spherical Bearing Housing and Front Link Mount Lugs (Left) - Detailed Inspection	HRS AFL MOS MSC		1691.5 668 51.7		 O/C	3838.9 1931 25 Jul 2018			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
712218 Airframe	Side Trunnion Mount Lugs, Spherical Bearing Housing and Front Link Mount Lugs (Right) - Detailed Inspection	HRS AFL MOS MSC		1691.5 668 51.7		 O/C	3838.9 1931 25 Jul 2018			0 0
712219 Airframe	Engine Mount and Support Links (Left) - Detailed Inspection	HRS AFL MOS MSC		1769.5 717 54.9		 O/C	3760.9 1882 19 Apr 2018			0 0
712220 Airframe	Engine Mount and Support Links (Right) - Detailed Inspection	HRS AFL MOS MSC		1769.5 717 54.9		 O/C	3760.9 1882 19 Apr 2018			0 0
712301 Airframe	Thrust Strut (Left) - Removal / Installation 1159P41310-1 T-621	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 TEB INC
712302 Airframe	Thrust Strut (Right) - Removal / Installation 1159P41310-2 T-595	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 R-V METAL FABRICATING INC
712319 Airframe	Thrust Strut (Left) - Magnaflux Inspection	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
712320 Airframe	Thrust Strut (Right) - Magnaflux Inspection	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
717001 (717002)	No. 2 Engine - Drains Tank Ejector Pump - Removal / Installation EJP101 SOE05-046	HRS ENC MOS MSC	TSN:1478 TSN:846	4522.9 2168 141		 O/C	929.5 382 15 Feb 2011			0 0 Goodrich
Engine										
717101	No. 1 Engine - Drains Tank Ejector Pump - Inspection	HRS ENC MOS MSC		5452.4 2550 175.7		 O/C	0 0 24 Mar 2008			0 0
Engine										
717101 (717102)	No. 2 Engine - Drains Tank Ejector Pump - Inspection	HRS ENC MOS MSC		4522.9 2168 141		 O/C	929.5 382 15 Feb 2011			0 0
Engine										
Notes: FOUND EJP BLOCKED. REPLAED EJP										
719001U	Engine Trend Monitoring Data Download, Engine 1 and Engine 2	HRS AFL MOS		2639.4 1092 86.7			2891 1507 26 Aug 2015			0 0
Airframe										
Notes: REMOVED AT OPERRATOR REQUEST 6-30-10 GRH										
719997	No. 1 Engine - Available Code	HRS ENC MOS MSC		5452.4 2550 175.7		 O/C	0 0 24 Mar 2008			0 0
Engine										
719997	No. 2 Engine - Available Code	HRS ENC MOS MSC		5452.4 2550 176.2		 O/C	0 0 11 Mar 2008			0 0
Engine										
71EN1	No. 1 Engine TAY611-8 85245	HRS AFL MOS MSC	TSN:3760.9 TSN:1882	1691.5 668 52		 E/C	3838.9 1931 15 Jul 2018			0 0
Airframe										

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Description: Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
71EN2	No. 2 Engine TAY611-8	85244	HRS AFL MOS MSC	TSN:3760.9 TSN:1882	1691.5 668 52		E/C	3838.9 1931 15 Jul 2018			0 0
Airframe											
72 - Engine											
720011	No. 1 Engine - Hp Compressor Stage 1 Blades - Special Detailed Inspection		HRS ENC MOS MSC		882.2 304 24.4		O/C	4570.2 2246 04 Nov 2020			0 0
Engine											
720011 (720012)	No. 2 Engine - Hp Compressor Stage 1 Blades - Special Detailed Inspection		HRS ENC MOS MSC		882.2 304 23.9		O/C	4570.2 2246 18 Nov 2020			0 0
Engine											
720013	No. 1 Engine - Hp Compressor Stage 7 and Stage 8 Blades - Special Detailed Inspection		HRS ENC MOS MSC		882.2 304 24.4		O/C	4570.2 2246 04 Nov 2020			0 0
Engine											
720013 (720014)	No. 2 Engine - Hp Compressor Stage 7 and Stage 8 Blades - Special Detailed Inspection		HRS ENC MOS MSC		882.2 304 24.4		O/C	4570.2 2246 04 Nov 2020			0 0
Engine											
720015	No. 1 Engine - Hp Compressor Stage 12 Blades - Special Detailed Inspection		HRS ENC MOS MSC		882.2 304 24.4		O/C	4570.2 2246 04 Nov 2020			0 0
Engine											
720015 (720016)	No. 2 Engine - Hp Compressor Stage 12 Blades - Special Detailed Inspection		HRS ENC MOS MSC		882.2 304 24.4		O/C	4570.2 2246 04 Nov 2020			0 0
Engine											

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
720017 Engine	No. 1 Engine - IP Compressor Stage 1 Blades - Special Detailed Inspection	HRS ENC MOS MSC		882.2 304 24.4		 O/C	4570.2 2246 04 Nov 2020			0 0
720017 (720018) Engine	No. 2 Engine - IP Compressor Stage 1 Blades - Special Detailed Inspection	HRS ENC MOS MSC		882.2 304 24.4		 O/C	4570.2 2246 04 Nov 2020			0 0
720019 Engine	No. 1 Engine - IP Compressor Stage 3 Blades - Special Detailed Inspection	HRS ENC MOS MSC		882.2 304 24.4		 O/C	4570.2 2246 04 Nov 2020			0 0
720019 (720020) Engine	No. 2 Engine - IP Compressor Stage 3 Blades - Special Detailed Inspection	HRS ENC MOS MSC		882.2 304 24.4		 O/C	4570.2 2246 04 Nov 2020			0 0
720021 Engine	No. 1 Engine - Lp Turbine Stage 2 and Stage 3 Blades - Inspection	HRS ENC MOS MSC		882.2 304 24.4		 O/C	4570.2 2246 04 Nov 2020			0 0
720021 (720022) Engine	No. 2 Engine - Lp Turbine Stage 2 and Stage 3 Blades - Inspection	HRS ENC MOS MSC		882.2 304 24.1		 O/C	4570.2 2246 13 Nov 2020			0 0
720023 Engine	No. 1 Engine - Hp Turbine Stage 2 Blades and Lp Turbine Stage 1 Blades - Inspection	HRS ENC MOS MSC		882.2 304 24.4		 O/C	4570.2 2246 04 Nov 2020			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
720023 (720024) Engine	No. 2 Engine - Hp Turbine Stage 2 Blades and Lp Turbine Stage 1 Blades - Inspection	HRS ENC MOS MSC		882.2 304 24.1		 O/C	4570.2 2246 13 Nov 2020			0 0
722001 Engine	No. 1 Engine - Cone Engine Nose Spinner JR56026 SN-UNKNOWN	HRS ENC MOS MSC		5452.4 2550 175.7		 O/C	0 0 24 Mar 2008			0 0
722001 (722002) Engine	No. 2 Engine - Cone Engine Nose Spinner JR56026 SN-UNKNOWN	HRS ENC MOS MSC		5452.4 2550 176.2		 O/C	0 0 11 Mar 2008			0 0
722005 Engine	No. 1 Engine - Spinner, Fairing and Nose Tip CAP - Detailed Inspection 052000-4A	HRS ENC MOS [HRS: +50/-50]		1691.5 668 55.1		2000	3760.9 1882 12 Apr 2018	5760.9	5810.9	0 0
722005 (722010) Engine	No. 2 Engine - Spinner, Fairing and Nose Tip CAP - Detailed Inspection 052000-4A	HRS ENC MOS [HRS: +50/-50]		1691.5 668 55.1		2000	3760.9 1882 12 Apr 2018	5760.9	5810.9	0 0
723001 Engine	No. 1 Engine - Low-Pressure Compressor Fan Module - Removal / Installation JR34563A STDK50514	HRS ENC MOS		5452.4 2550 175.7		 12000 	0 0 24 Mar 2008	 12000 		0 0
723001 (723002) Engine	No. 2 Engine - Low-Pressure Compressor Fan Module - Removal / Installation JR34563A STDK50519	HRS ENC MOS		5452.4 2550 176.2		 12000 	0 0 11 Mar 2008	 12000 		0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
723101	No. 1 Engine - Low-Pressure Compressor Blades - Detailed Inspection	HRS ENC MOS		6.5 2 .2		1000	5445.9 2548 11 Nov 2022	6445.9	6495.9	0 0
		[HRS: +50/-50]								
Engine	052000-2A,200098									
723101 (723102)	No. 2 Engine - Low-Pressure Compressor Blades - Detailed Inspection	HRS ENC MOS		6.5 2 .2		1000	5445.9 2548 11 Nov 2022	6445.9	6495.9	0 0
		[HRS: +50/-50]								
Engine	052000-2A,200099									
Notes: PN: JR29577A SN: <NONE>.										
723113	No. 1 Engine - No. 1 Low-Pressure Compressor (Fan) Blade - Removal / Installation JR58319 RGD32876	HRS ENC MOS		5452.4 2550 175.7		12000	0 0 24 Mar 2008	12000		0 0
Engine										
723113 (723137)	No. 2 Engine - No. 1 Low-Pressure Compressor (Fan) Blade - Removal / Installation JR58319 RGD32866	HRS ENC MOS		5452.4 2550 176.2		12000	0 0 11 Mar 2008	12000		0 0
Engine										
723114	No. 1 Engine - No. 2 Low-Pressure Compressor (Fan) Blade - Removal / Installation JR58319 RGD32986	HRS ENC MOS		5452.4 2550 175.7		12000	0 0 24 Mar 2008	12000		0 0
Engine										
723114 (723138)	No. 2 Engine - No. 2 Low-Pressure Compressor (Fan) Blade - Removal / Installation JR58319 RGD32893	HRS ENC MOS	TSN:2509.3 TSN:1261	2943.1 1289 102.2		12000	2509.3 1261 10 May 2014	12000		0 0
Engine										
723115	No. 1 Engine - No. 3 Low-Pressure Compressor (Fan) Blade - Removal / Installation JR58319 RGD33005	HRS ENC MOS		5452.4 2550 175.7		12000	0 0 24 Mar 2008	12000		0 0
Engine										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
723115 (723139)	No. 2 Engine - No. 3 Low-Pressure Compressor (Fan) Blade - Removal / Installation JR58319 RGD32887	HRS ENC MOS	TSN:2509.3 TSN:1261 TSN:74	2943.1 1289 102.2		12000	2509.3 1261 10 May 2014	12000		0 0
Engine										
723116	No. 1 Engine - No. 4 Low-Pressure Compressor (Fan) Blade - Removal / Installation JR58319 RGD32905	HRS ENC MOS		5452.4 2550 175.7		12000	0 0 24 Mar 2008	12000		0 0
Engine										
723116 (723140)	No. 2 Engine - No. 4 Low-Pressure Compressor (Fan) Blade - Removal / Installation JR58319 RGD32891	HRS ENC MOS		5452.4 2550 176.2		12000	0 0 11 Mar 2008	12000		0 0
Engine										
723117	No. 1 Engine - No. 5 Low-Pressure Compressor (Fan) Blade - Removal / Installation JR58319 RGD32990	HRS ENC MOS		5452.4 2550 175.7		12000	0 0 24 Mar 2008	12000		0 0
Engine										
723117 (723141)	No. 2 Engine - No. 5 Low-Pressure Compressor (Fan) Blade - Removal / Installation JR58319 RGD32900	HRS ENC MOS		5452.4 2550 176.2		12000	0 0 11 Mar 2008	12000		0 0
Engine										
723118	No. 1 Engine - No. 6 Low-Pressure Compressor (Fan) Blade - Removal / Installation JR58319 RGD32872	HRS ENC MOS		5452.4 2550 175.7		12000	0 0 24 Mar 2008	12000		0 0
Engine										
723118 (723142)	No. 2 Engine - No. 6 Low-Pressure Compressor (Fan) Blade - Removal / Installation JR58319 RGD32895	HRS ENC MOS		5452.4 2550 176.2		12000	0 0 11 Mar 2008	12000		0 0
Engine										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
723119 Logbook Position	No. 1 Engine - No. 7 Low-Pressure Compressor (Fan) Blade - Removal / Installation JR58319 RGD32987	HRS ENC MOS		5452.4 2550 175.7		12000	0 0 24 Mar 2008	12000		0 0
Engine										
723119 (723143)	No. 2 Engine - No. 7 Low-Pressure Compressor (Fan) Blade - Removal / Installation JR58319 RGD32889	HRS ENC MOS		5452.4 2550 176.2		12000	0 0 11 Mar 2008	12000		0 0
Engine										
723120	No. 1 Engine - No. 8 Low-Pressure Compressor (Fan) Blade - Removal / Installation JR58319 RGD32868	HRS ENC MOS		5452.4 2550 175.7		12000	0 0 24 Mar 2008	12000		0 0
Engine										
723120 (723144)	No. 2 Engine - No. 8 Low-Pressure Compressor (Fan) Blade - Removal / Installation JR58319 RGD32884	HRS ENC MOS		5452.4 2550 176.2		12000	0 0 11 Mar 2008	12000		0 0
Engine										
723121	No. 1 Engine - No. 9 Low-Pressure Compressor (Fan) Blade - Removal / Installation JR58319 RGD32981	HRS ENC MOS		5452.4 2550 175.7		12000	0 0 24 Mar 2008	12000		0 0
Engine										
723121 (723145)	No. 2 Engine - No. 9 Low-Pressure Compressor (Fan) Blade - Removal / Installation JR58319 RGD32874	HRS ENC MOS		5452.4 2550 176.2		12000	0 0 11 Mar 2008	12000		0 0
Engine										
723122	No. 1 Engine - No. 10 Low-Pressure Compressor (Fan) Blade - Removal / Installation JR58319 RGD32931	HRS ENC MOS		5452.4 2550 175.7		12000	0 0 24 Mar 2008	12000		0 0
Engine										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
723122 (723146)	No. 2 Engine - No. 10 Low-Pressure Compressor (Fan) Blade - Removal / Installation JR58319 RGD32896	HRS ENC MOS		5452.4 2550 176.2		12000	0 0 11 Mar 2008	12000		0 0
Engine										
723123	No. 1 Engine - No. 11 Low-Pressure Compressor (Fan) Blade - Removal / Installation JR58319 RGD33006	HRS ENC MOS		5452.4 2550 175.7		12000	0 0 24 Mar 2008	12000		0 0
Engine										
723123 (723147)	No. 2 Engine - No. 11 Low-Pressure Compressor (Fan) Blade - Removal / Installation JR58319 RGD32898	HRS ENC MOS		5452.4 2550 176.2		12000	0 0 11 Mar 2008	12000		0 0
Engine										
723124	No. 1 Engine - No. 12 Low-Pressure Compressor (Fan) Blade - Removal / Installation JR58319 RGD32875	HRS ENC MOS		5452.4 2550 175.7		12000	0 0 24 Mar 2008	12000		0 0
Engine										
723124 (723148)	No. 2 Engine - No. 12 Low-Pressure Compressor (Fan) Blade - Removal / Installation JR58319 RGD32892	HRS ENC MOS		5452.4 2550 176.2		12000	0 0 11 Mar 2008	12000		0 0
Engine										
723125	No. 1 Engine - No. 13 Low-Pressure Compressor (Fan) Blade - Removal / Installation JR58319 RGD32878	HRS ENC MOS		5452.4 2550 175.7		12000	0 0 24 Mar 2008	12000		0 0
Engine										
723125 (723149)	No. 2 Engine - No. 13 Low-Pressure Compressor (Fan) Blade - Removal / Installation JR58319 RGD32882	HRS ENC MOS		5452.4 2550 176.2		12000	0 0 11 Mar 2008	12000		0 0
Engine										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
723126	No. 1 Engine - No. 14 Low-Pressure Compressor (Fan) Blade - Removal / Installation JR58319 RGD32993	HRS ENC MOS		5452.4 2550 175.7		12000	0 0 24 Mar 2008	12000		0 0
Engine										
723126 (723150)	No. 2 Engine - No. 14 Low-Pressure Compressor (Fan) Blade - Removal / Installation JR58319 RGD32886	HRS ENC MOS		5452.4 2550 176.2		12000	0 0 11 Mar 2008	12000		0 0
Engine										
723127	No. 1 Engine - No. 15 Low-Pressure Compressor (Fan) Blade - Removal / Installation JR58319 RGD32871	HRS ENC MOS		5452.4 2550 175.7		12000	0 0 24 Mar 2008	12000		0 0
Engine										
723127 (723151)	No. 2 Engine - No. 15 Low-Pressure Compressor (Fan) Blade - Removal / Installation JR58319 RGD32865	HRS ENC MOS		5452.4 2550 176.2		12000	0 0 11 Mar 2008	12000		0 0
Engine										
723128	No. 1 Engine - No. 16 Low-Pressure Compressor (Fan) Blade - Removal / Installation JR58319 RGD32883	HRS ENC MOS		5452.4 2550 175.7		12000	0 0 24 Mar 2008	12000		0 0
Engine										
723128 (723152)	No. 2 Engine - No. 16 Low-Pressure Compressor (Fan) Blade - Removal / Installation JR58319 RGD32888	HRS ENC MOS		5452.4 2550 176.2		12000	0 0 11 Mar 2008	12000		0 0
Engine										
723129	No. 1 Engine - No. 17 Low-Pressure Compressor (Fan) Blade - Removal / Installation JR58319 RGD32997	HRS ENC MOS		5452.4 2550 175.7		12000	0 0 24 Mar 2008	12000		0 0
Engine										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
723129 (723153)	No. 2 Engine - No. 17 Low-Pressure Compressor (Fan) Blade - Removal / Installation JR58319 RGD32901	HRS ENC MOS		5452.4 2550 176.2		12000	0 0 11 Mar 2008	12000		0 0
Engine										
723130	No. 1 Engine - No. 18 Low-Pressure Compressor (Fan) Blade - Removal / Installation JR58319 RGD32877	HRS ENC MOS		5452.4 2550 175.7		12000	0 0 24 Mar 2008	12000		0 0
Engine										
723130 (723154)	No. 2 Engine - No. 18 Low-Pressure Compressor (Fan) Blade - Removal / Installation JR58319 RGD32879	HRS ENC MOS		5452.4 2550 176.2		12000	0 0 11 Mar 2008	12000		0 0
Engine										
723131	No. 1 Engine - No. 19 Low-Pressure Compressor (Fan) Blade - Removal / Installation JR58319 RGD33004	HRS ENC MOS		5452.4 2550 175.7		12000	0 0 24 Mar 2008	12000		0 0
Engine										
723131 (723155)	No. 2 Engine - No. 19 Low-Pressure Compressor (Fan) Blade - Removal / Installation JR58319 RGD32894	HRS ENC MOS		5452.4 2550 176.2		12000	0 0 11 Mar 2008	12000		0 0
Engine										
723132	No. 1 Engine - No. 20 Low-Pressure Compressor (Fan) Blade - Removal / Installation JR58319 RGD32906	HRS ENC MOS		5452.4 2550 175.7		12000	0 0 24 Mar 2008	12000		0 0
Engine										
723132 (723156)	No. 2 Engine - No. 20 Low-Pressure Compressor (Fan) Blade - Removal / Installation JR58319 RGD32899	HRS ENC MOS		5452.4 2550 176.2		12000	0 0 11 Mar 2008	12000		0 0
Engine										

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Description: Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
723133	No. 1 Engine - No. 21 Low-Pressure Compressor (Fan) Blade - Removal / Installation JR58319	RGD32867	HRS ENC MOS		5452.4 2550 175.7		 12000	0 0 24 Mar 2008	 12000		0 0
Engine											
723133 (723157)	No. 2 Engine - No. 21 Low-Pressure Compressor (Fan) Blade - Removal / Installation JR58319	RGD32890	HRS ENC MOS		5452.4 2550 176.2		 12000	0 0 11 Mar 2008	 12000		0 0
Engine											
723134	No. 1 Engine - No. 22 Low-Pressure Compressor (Fan) Blade - Removal / Installation JR58319	RGD32962	HRS ENC MOS		5452.4 2550 175.7		 12000	0 0 24 Mar 2008	 12000		0 0
Engine											
723134 (723158)	No. 2 Engine - No. 22 Low-Pressure Compressor (Fan) Blade - Removal / Installation JR58319	RGD32903	HRS ENC MOS		5452.4 2550 176.2		 12000	0 0 11 Mar 2008	 12000		0 0
Engine											
723201	No. 1 Engine - Lp Compressor Outlet Guide Vane - Inspection / Check		HRS ENC MOS MSC		1691.5 668 54.7		 O/C	3760.9 1882 26 Apr 2018			0 0
Engine											
723201 (723202)	No. 2 Engine - Lp Compressor Outlet Guide Vane - Inspection / Check		HRS ENC MOS MSC		1691.5 668 55.1		 O/C	3760.9 1882 12 Apr 2018			0 0
Engine											
723301	No. 1 Engine - Disk Rotor, Stage 1 IP Compressor - Discard JR28921	STDK50212	HRS ENC MOS		5452.4 2550 175.7		 12000	0 0 24 Mar 2008	 12000		0 0
Engine											

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
723301 (723302)	No. 2 Engine - Disk Rotor, Stage 1 IP Compressor - Discard JR28921 STDK50219	HRS ENC MOS		5452.4 2550 176.2		12000	0 0 11 Mar 2008	12000		0 0
Engine										
723303	No. 1 Engine - Disk Rotor, Stage 2 IP Compressor - Discard JR28922 STDK50368	HRS ENC MOS		5452.4 2550 175.7		12000	0 0 24 Mar 2008	12000		0 0
Engine										
723303 (723304)	No. 2 Engine - Disk Rotor, Stage 2 IP Compressor - Discard JR28922 STDK50361	HRS ENC MOS		5452.4 2550 176.2		12000	0 0 11 Mar 2008	12000		0 0
Engine										
723305	No. 1 Engine - Disk Rotor, Stage 3 IP Compressor - Discard JR29568 STDK50239	HRS ENC MOS		5452.4 2550 175.7		12000	0 0 24 Mar 2008	12000		0 0
Engine										
723305 (723306)	No. 2 Engine - Disk Rotor, Stage 3 IP Compressor - Discard JR29568 VSTDK0002	HRS ENC MOS		5452.4 2550 176.2		12000	0 0 11 Mar 2008	12000		0 0
Engine										
723307	No. 1 Engine - Shaft, Drive Lp & IP Compressor - Discard JR35036 PAVN9130	HRS ENC MOS		5452.4 2550 175.7		12000	0 0 24 Mar 2008	12000		0 0
Engine										
723307 (723308)	No. 2 Engine - Shaft, Drive Lp & IP Compressor - Discard JR35036 PAVN9129	HRS ENC MOS		5452.4 2550 176.2		12000	0 0 11 Mar 2008	12000		0 0
Engine										

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Description: Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
723401	No. 1 Engine - Shaft, Rear Hp Compressor Rotor - Discard		HRS		1691.5			3760.9			0
			ENC		717		12000	1833	13833		0
	JR35207A	RRDSFTPABX27043	MOS		52.2			09 Jul 2018			
Engine											
723401 (723402)	No. 2 Engine - Shaft, Rear Hp Compressor Rotor - Discard		HRS		1691.5			3760.9			0
			ENC		717		12000	1833	13833		0
	JR35207A	RRDSFTPABX27022	MOS		52.7			26 Jun 2018			
Engine											
723403	No. 1 Engine - Shaft, Drive Lp Compressor Rotor - Discard		HRS		5452.4			0			0
			ENC		2550		12000	0	12000		0
	JR35037	PABX24861	MOS		175.7			24 Mar 2008			
Engine											
723403 (723404)	No. 2 Engine - Shaft, Drive Lp Compressor Rotor - Discard		HRS		5452.4			0			0
			ENC		2550		12000	0	12000		0
	JR35037	PABX24848	MOS		176.2			11 Mar 2008			
Engine											
723409	No. 1 Engine - Disk Rotor, Stage 1 Hp Compressor - Discard		HRS		5452.4			0			0
			ENC		2550		12000	0	12000		0
	JR18049	EEBE1051	MOS		175.7			24 Mar 2008			
Engine											
723409 (723410)	No. 2 Engine - Disk Rotor, Stage 1 Hp Compressor - Discard		HRS		5452.4			0			0
			ENC		2550		12000	0	12000		0
	JR18049	EEBE3949	MOS		176.2			11 Mar 2008			
Engine											
723411	No. 1 Engine - Disk Rotor, Stage 2 Hp Compressor - Discard		HRS		5452.4			0			0
			ENC		2550		12000	0	12000		0
	JR18742	SETP14833	MOS		175.7			24 Mar 2008			
Engine											

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
723411 (723412)	No. 2 Engine - Disk Rotor, Stage 2 Hp Compressor - Discard JR18742 SETP14789	HRS ENC MOS		5452.4 2550 176.2		12000	0 0 11 Mar 2008	12000		0 0
Engine										
723413	No. 1 Engine - Disk Rotor, Stage 3 Hp Compressor - Discard JR18743 EEBE3265	HRS ENC MOS		5452.4 2550 175.7		12000	0 0 24 Mar 2008	12000		0 0
Engine										
723413 (723414)	No. 2 Engine - Disk Rotor, Stage 3 Hp Compressor - Discard JR18743 EEBE3114	HRS ENC MOS		5452.4 2550 176.2		12000	0 0 11 Mar 2008	12000		0 0
Engine										
723415	No. 1 Engine - Disk Rotor, Stage 4 Hp Compressor - Discard JR18744 EEBE3125	HRS ENC MOS		5452.4 2550 175.7		12000	0 0 24 Mar 2008	12000		0 0
Engine										
723415 (723416)	No. 2 Engine - Disk Rotor, Stage 4 Hp Compressor - Discard JR18744 EEBE8566	HRS ENC MOS		1691.5 668 52.7		12000	3760.9 1882 26 Jun 2018	13882		0 0
Engine										
723417	No. 1 Engine - Disk Rotor, Stage 5 Hp Compressor - Discard JR18746 EEBE3217	HRS ENC MOS		5452.4 2550 175.7		12000	0 0 24 Mar 2008	12000		0 0
Engine										
723417 (723418)	No. 2 Engine - Disk Rotor, Stage 5 Hp Compressor - Discard JR18746 EEBE3208	HRS ENC MOS		5452.4 2550 176.2		12000	0 0 11 Mar 2008	12000		0 0
Engine										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
723419	No. 1 Engine - Disk Rotor, Stage 6 Hp Compressor - Discard JR18748 EEBE3182	HRS ENC MOS		5452.4 2550 175.7		12000	0 0 24 Mar 2008	12000		0 0
Engine										
723419 (723420)	No. 2 Engine - Disk Rotor, Stage 6 Hp Compressor - Discard JR18748 EEBE3049	HRS ENC MOS		5452.4 2550 176.2		12000	0 0 11 Mar 2008	12000		0 0
Engine										
723421	No. 1 Engine - Disk Rotor, Stage 7 Hp Compressor - Discard JR13814 EEBE3523	HRS ENC MOS		5452.4 2550 175.7		12000	0 0 24 Mar 2008	12000		0 0
Engine										
723421 (723422)	No. 2 Engine - Disk Rotor, Stage 7 Hp Compressor - Discard JR13814 EEBE3445	HRS ENC MOS		5452.4 2550 176.2		12000	0 0 11 Mar 2008	12000		0 0
Engine										
723423	No. 1 Engine - Disk Rotor, Stage 8 Hp Compressor - Discard JR13815 EEBH7606	HRS ENC MOS		5452.4 2550 175.7		12000	0 0 24 Mar 2008	12000		0 0
Engine										
723423 (723424)	No. 2 Engine - Disk Rotor, Stage 8 Hp Compressor - Discard JR13815 EEBH7580	HRS ENC MOS		5452.4 2550 176.2		12000	0 0 11 Mar 2008	12000		0 0
Engine										
723425	No. 1 Engine - Disk Rotor, Stage 9 Hp Compressor - Discard JR13816 EEBH7626	HRS ENC MOS		5452.4 2550 175.7		12000	0 0 24 Mar 2008	12000		0 0
Engine										

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723425 (723426)	No. 2 Engine - Disk Rotor, Stage 9 Hp Compressor - Discard		HRS ENC MOS		5452.4 2550 176.2		12000	0 0 11 Mar 2008	12000		0 0
	JR13816	EEBH7542									
Engine											
723427	No. 1 Engine - Disk Rotor, Stage 10 Hp Compressor - Discard		HRS ENC MOS		5452.4 2550 175.7		12000	0 0 24 Mar 2008	12000		0 0
	JR18750	EEBH7554									
Engine											
723427 (723428)	No. 2 Engine - Disk Rotor, Stage 10 Hp Compressor - Discard		HRS ENC MOS		5452.4 2550 176.2		12000	0 0 11 Mar 2008	12000		0 0
	JR18750	EEBH7525									
Engine											
723429	No. 1 Engine - Disk Rotor, Stage 11 Hp Compressor - Discard		HRS ENC MOS		5452.4 2550 175.7		12000	0 0 24 Mar 2008	12000		0 0
	JR18751	EEBH7591									
Engine											
723429 (723430)	No. 2 Engine - Disk Rotor, Stage 11 Hp Compressor - Discard		HRS ENC MOS		5452.4 2550 176.2		12000	0 0 11 Mar 2008	12000		0 0
	JR18751	EEBH7217									
Engine											
723431	No. 1 Engine - Disk Rotor, Stage 12 Hp Compressor - Discard		HRS ENC MOS		5452.4 2550 175.7		12000	0 0 24 Mar 2008	12000		0 0
	JR18449	EEBH7969									
Engine											
723431 (723432)	No. 2 Engine - Disk Rotor, Stage 12 Hp Compressor - Discard		HRS ENC MOS		5452.4 2550 176.2		12000	0 0 11 Mar 2008	12000		0 0
	JR18449	EEBH7968									
Engine											

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
723501 Logbook Position	No. 1 Engine - Intermediate-Pressure Compressor Case - Inspection	HRS ENC MOS MSC		5452.4 2550 175.7		 O/C	0 0 24 Mar 2008			0 0
Engine										
723501 (723502) Logbook Position	No. 2 Engine - Intermediate-Pressure Compressor Case - Inspection	HRS ENC MOS MSC		5452.4 2550 176.2		 O/C	0 0 11 Mar 2008			0 0
Engine										
723853 (723854) Logbook Position	No. 2 Engine - Low-Pressure Compressor Rotating Fairing - Removal / Installation JR58345 F747-279	HRS ENC MOS MSC		2545.3 1035 82.5		 O/C	2907.1 1515 31 Dec 2015			0 0
Engine										
724005 Logbook Position	No. 1 Engine - Engine Combustion and High Pressure Turbine Section - Special Detailed Inspection	HRS ENC MOS [HRS: +50/-50]		2565.1 1046 90.6		3000** 	2887.3 1504 28 Apr 2015	5887.3	5937.3	0 0
Engine										
Notes: ENGINE DECLARED TASK ORIENTED										
724005 (724006) Logbook Position	No. 2 Engine - Engine Combustion and High Pressure Turbine Section - Special Detailed Inspection	HRS ENC MOS [HRS: +50/-50]		2565.1 1046 90.6		3000** 	2887.3 1504 28 Apr 2015	5887.3	5937.3	0 0
Engine										
Notes: ENGINE DECLARED TASK ORIENTED										
724007 Logbook Position	No. 1 Engine - Engine Borescope - Inspection	HRS ENC MOS MSC		882.2 304 24		 O/C	4570.2 2246 16 Nov 2020			0 0
Engine										
724007 (724008) Logbook Position	No. 2 Engine - Engine Borescope - Inspection	HRS ENC MOS MSC		882.2 304 24.4		 O/C	4570.2 2246 04 Nov 2020			0 0
Engine										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
724101	No. 1 Engine - Case Assy, Combustion JR29577A RC80T8	HRS ENC MOS MSC		5452.4 2550 175.7		 O/C	0 0 24 Mar 2008			0 0
Engine										
724101 (724102)	No. 2 Engine - Case Assy, Combustion JR29577A SN-UNKNOWN	HRS ENC MOS MSC		5452.4 2550 176.2		 O/C	0 0 11 Mar 2008			0 0
Engine										
724103	No. 1 Engine - Combustion Liners - Special Detailed Inspection	HRS ENC MOS MSC		882.2 304 24.4		 O/C	4570.2 2246 04 Nov 2020			0 0
Engine										
724103 (724104)	No. 2 Engine - Combustion Liners - Special Detailed Inspection	HRS ENC MOS MSC		882.2 304 24.4		 O/C	4570.2 2246 04 Nov 2020			0 0
Engine										
724109	No. 1 Engine - High-Pressure Turbine Nozzle Guide Vanes - Special Detailed Inspection	HRS ENC MOS MSC		2565.1 1046 90.6		 O/C	2887.3 1504 28 Apr 2015			0 0
Engine										
724109 (724110)	No. 2 Engine - High-Pressure Turbine Nozzle Guide Vanes - Special Detailed Inspection	HRS ENC MOS MSC		2565.1 1046 90.6		 O/C	2887.3 1504 28 Apr 2015			0 0
Engine										
724111	No. 1 Engine - High-Pressure Turbine Stage 1 Blades - Special Detailed Inspection	HRS ENC MOS MSC		4804.7 2372 151		 O/C	647.7 178 16 Apr 2010			0 0
Engine										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
724111 (724112) Logbook Position: Engine	No. 2 Engine - High-Pressure Turbine Stage 1 Blades - Special Detailed Inspection	HRS ENC MOS MSC		4804.7 2372 151		O/C	647.7 178 17 Apr 2010			0 0
724201 Engine	No. 1 Engine - Shaft, Hp Turbine - Discard JR35030A RRDSFTEABX5707	HRS ENC MOS		1691.5 668 52.2		12000	3760.9 1882 09 Jul 2018	13882		0 0
724201 (724202) Engine	No. 2 Engine - Shaft, Hp Turbine - Discard JR35030A RRDSFTEABX5713	HRS ENC MOS		1691.5 668 52.7		12000	3760.9 1882 26 Jun 2018	13882		0 0
724203 Engine	No. 1 Engine - Disk Rotor, Stage 1 Hp Turbine - Discard JR57975 SETM24254	HRS ENC MOS		5452.4 2550 175.7		12000	0 0 24 Mar 2008	12000		0 0
724203 (724204) Engine	No. 2 Engine - Disk Rotor, Stage 1 Hp Turbine - Discard JR57975 SETM24223	HRS ENC MOS		5452.4 2550 176.2		12000	0 0 11 Mar 2008	12000		0 0
724205 Engine	No. 1 Engine - Disk Rotor, Stage 2 Hp Turbine - Discard JR57978 EEBH8058	HRS ENC MOS		5452.4 2550 175.7		12000	0 0 24 Mar 2008	12000		0 0
724205 (724206) Engine	No. 2 Engine - Disk Rotor, Stage 2 Hp Turbine - Discard JR57978 EEBH7846	HRS ENC MOS		5452.4 2550 176.2		12000	0 0 11 Mar 2008	12000		0 0
724207 Engine	No. 1 Engine - Sleeve, Stage 2 Hp Turbine - Discard NPH7674 GETM24771	HRS ENC MOS		5452.4 2550 175.7		12000	0 0 24 Mar 2008	12000		0 0

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
724207 (724208)	No. 2 Engine - Sleeve, Stage 2 Hp Turbine - Discard NPH7674	GETM24702	HRS ENC MOS		5452.4 2550 176.2		12000	0 0 11 Mar 2008	12000		0 0
Engine											
725001	No. 1 Engine - Shaft, Lp Turbine - Discard JR35039	EAVN1489	HRS ENC MOS		5452.4 2550 175.7		12000	0 0 24 Mar 2008	12000		0 0
Engine											
725001 (725002)	No. 2 Engine - Shaft, Lp Turbine - Discard JR35039	EAVN1498	HRS ENC MOS		5452.4 2550 176.2		12000	0 0 11 Mar 2008	12000		0 0
Engine											
725003	No. 1 Engine - Disk Rotor, Stage 1 Lp Turbine - Discard JR57972	EETM6799	HRS ENC MOS	TSN:4539 TSN:2048	1691.5 668 52.2		12000	3760.9 1882 09 Jul 2018	11834		0 0
Engine											
725003 (725004)	No. 2 Engine - Disk Rotor, Stage 1 Lp Turbine - Discard JR57972	EETM8093	HRS ENC MOS		5452.4 2550 176.2		12000	0 0 11 Mar 2008	12000		0 0
Engine											
725005	No. 1 Engine - Disk Rotor, Stage 2 Lp Turbine - Discard JR57973	EETM8047	HRS ENC MOS		5452.4 2550 175.7		12000	0 0 24 Mar 2008	12000		0 0
Engine											
725005 (725006)	No. 2 Engine - Disk Rotor, Stage 2 Lp Turbine - Discard JR57973	EETM7886	HRS ENC MOS		5452.4 2550 176.2		12000	0 0 11 Mar 2008	12000		0 0
Engine											
725007	No. 1 Engine - Disk Rotor, Stage 3 Lp Turbine - Discard JR57974	EETM8103	HRS ENC MOS		5452.4 2550 175.7		12000	0 0 24 Mar 2008	12000		0 0
Engine											

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
725007 (725008)	No. 2 Engine - Disk Rotor, Stage 3 Lp Turbine - Discard JR57974 EETM8106	HRS ENC MOS		5452.4 2550 176.2		12000	0 0 11 Mar 2008	12000		0 0
Engine										
725201	No. 1 Engine - Low-Pressure Turbine Bearing and Support Spoke Fairings - Inspection	HRS ENC MOS MSC		5452.4 2550 175.7		O/C	0 0 24 Mar 2008			0 0
Engine										
725201 (725202)	No. 2 Engine - Low-Pressure Turbine Bearing and Support Spoke Fairings - Inspection	HRS ENC MOS MSC		5452.4 2550 176.2		O/C	0 0 11 Mar 2008			0 0
Engine										
726105	No. 1 Engine - Engine Starter Splines - Lubrication / Inspection	HRS ENC MOS	1691.5 668 51.9		3000 144		3760.9 1882 19 Jul 2018	6760.9 31 Jul 2030	6810.9 31 Aug 2030	0 0
	[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]									
Engine	052000-6A									
Notes: CARD E.I.E. - CORRECT S/N IS 85245 (MB)										
726105 (726110)	No. 2 Engine - Engine Starter Splines - Lubrication / Inspection	HRS ENC MOS	1691.5 668 51.9		3000 144		3760.9 1882 18 Jul 2018	6760.9 31 Jul 2030	6810.9 31 Aug 2030	0 0
	[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]									
Engine	052000-6A									
726115	No. 1 Engine - Gearbox Mounts and Link - Detailed Inspection	HRS ENC MOS	2562.5 1045 90.4		3000		2889.9 1505 04 May 2015	5889.9	5939.9	0 0
	[HRS: +50/-50]									
Engine	052000-6A									
726115 (726120)	No. 2 Engine - Gearbox Mounts and Link - Detailed Inspection	HRS ENC MOS	2562.5 1045 90.4		3000		2889.9 1505 04 May 2015	5889.9	5939.9	0 0
	[HRS: +50/-50]									
Engine	052000-6A									

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
726125 Engine	No. 1 Engine - Gearbox Accessory Mounting Features - Detailed Inspection 052000-6A	HRS ENC MOS [HRS: +50/-50]		2562.5 1045 90.4		3000	2889.9 1505 04 May 2015	5889.9	5939.9	0 0
726125 (726130) Engine	No. 2 Engine - Gearbox Accessory Mounting Features - Detailed Inspection 052000-6A	HRS ENC MOS [HRS: +50/-50]		2562.5 1045 90.4		3000	2889.9 1505 04 May 2015	5889.9	5939.9	0 0
727105 Engine	No. 1 Engine - Engine System and Dressing Bypass Support / Attachments - Detailed Inspection 052000-2A,200098	HRS ENC MOS [HRS: +50/-50]		6.5 2 .2		1000	5445.9 2548 11 Nov 2022	6445.9	6495.9	0 0
727105 (727106) Engine	No. 2 Engine - Engine System and Dressing Bypass Support / Attachments - Detailed Inspection 052000-2A,200099	HRS ENC MOS [HRS: +50/-50]		6.5 2 .2		1000	5445.9 2548 11 Nov 2022	6445.9	6495.9	0 0
727107 Engine	No. 1 Engine - Engine Bypass Duct Outer Surface - Detailed Inspection 052000-6A	HRS ENC MOS [HRS: +50/-50]		2562.5 1045 90.4		3000	2889.9 1505 04 May 2015	5889.9	5939.9	0 0
727107 (727108) Engine	No. 2 Engine - Engine Bypass Duct Outer Surface - Detailed Inspection 052000-6A	HRS ENC MOS [HRS: +50/-50]		2562.5 1045 90.4		3000	2889.9 1505 04 May 2015	5889.9	5939.9	0 0
727127 Engine	No. 1 Engine - Fan Outlet Guide Vanes - General Visual Inspection 200098	HRS ENC MOS [HRS: +50/-50]		6.5 2 .2		1000	5445.9 2548 11 Nov 2022	6445.9	6495.9	0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
727127 (727128)	No. 2 Engine - Fan Outlet Guide Vanes - General Visual Inspection	HRS ENC MOS		6.5 2 .2		1000	5445.9 2548 11 Nov 2022	6445.9	6495.9	0 0
Engine	200099	[HRS: +50/-50]								
73 - Engine Fuel and Control										
731001	No. 1 Engine - Low-Pressure Fuel Pump - Removal / Installation BP230/6 6305	HRS ENC MOS MSC		5452.4 2550 175.7		 O/C	0 0 24 Mar 2008			0 0
Engine										
731001 (731002)	No. 2 Engine - Low-Pressure Fuel Pump - Removal / Installation BP230/6 6308	HRS ENC MOS MSC		5452.4 2550 176.2		 O/C	0 0 11 Mar 2008			0 0
Engine										
731003	No. 1 Engine - High-Pressure Fuel Pump - Removal / Installation GD502 SPF08-011	HRS ENC MOS MSC		5452.4 2550 175.7		 O/C	0 0 24 Mar 2008			0 0 DALLAS AIRMOTIVE, INC.
Engine										
731003 (731004)	No. 2 Engine - High-Pressure Fuel Pump - Removal / Installation GD502 SPF07-073	HRS ENC MOS MSC		5452.4 2550 176.2		 O/C	0 0 11 Mar 2008			0 0 DALLAS AIRMOTIVE, INC.
Engine										
731005	No. 1 Engine - Flow Meter, Eng Fuel 9-217-73 111123-292	HRS ENC MOS MSC		5452.4 2550 175.7		 O/C	0 0 24 Mar 2008			0 0 ROLLS-ROYCE CUSTOMER BUSINESS GROUP
Engine										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
731005 (731006) Engine	No. 2 Engine - Flow Meter, Eng Fuel 9-217-73 111123-290	HRS ENC MOS MSC		5452.4 2550 176.2		 O/C	0 0 11 Mar 2008			0 0 ROLLS-ROYCE CUSTOMER BUSINESS GROUP
731007 Engine	No. 1 Engine - Pump, Engine EPA Ejector EJP101 SOE07-070	HRS ENC MOS MSC		1221.1 471 38.5		 O/C	4231.3 2079 31 Aug 2019			0 0 DALLAS AIRMOTIVE, INC.
731007 (731008) Engine	No. 2 Engine - Pump, Engine EPA Ejector EJP101 SOE05-046	HRS ENC MOS MSC		4522.9 2168 141		 O/C	929.5 382 15 Feb 2011			0 0 DALLAS AIRMOTIVE, INC.
731011 Engine	No. 1 Engine - EPA Filter R/I 77139107 SN-UNKNOWN	HRS ENC MOS MSC		5452.4 2550 175.7		 O/C	0 0 24 Mar 2008			0 0
731011 (731012) Engine	No. 2 Engine - EPA Filter R/I 77139107 SN-UNKNOWN	HRS ENC MOS MSC		5452.4 2550 176.2		 O/C	0 0 11 Mar 2008			0 0
731021 Engine	No. 1 Engine - Low-Pressure Fuel Filter Element - Removal / Installation MFFA370-2 120345	HRS ENC MOS MSC		882.2 304 23.3		 O/C	4570.2 2246 08 Dec 2020			0 0
Notes: P/N REMOVED: MFFA370-2S/N REMOVED: 103109										

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
731021 (731022)	No. 2 Engine - Low-Pressure Fuel Filter Element - Removal / Installation		HRS		6.5			5445.9			0
	MFFA370/2	122672	ENC		2			2548			0
			MOS		.2			11 Nov 2022			
			MSC				O/C				
Engine											
Notes: P/N REMOVED: MFFA370-2S/N REMOVED: 103112											
731023	No. 1 Engine - Low-Pressure Fuel Filter Element - Discard		HRS		6.5		1000	5445.9	6445.9	6495.9	0
	MFFA370-2	122655	ENC		2			2548			0
			MOS	TSN:14	.6			28 Oct 2022			
Engine			[HRS: +50/-50]								
Notes: P/N REMOVED: MFFA370-2S/N REMOVED: 103109											
731023 (731024)	No. 2 Engine - Low-Pressure Fuel Filter Element - Discard		HRS		6.5		1000	5445.9	6445.9	6495.9	0
	MFFA370-2	122672	ENC		2			2548			0
			MOS	TSN:15	.2			11 Nov 2022			
Engine			[HRS: +50/-50]								
731100	No. 1 Engine - Fuel Spray Nozzle (No. 1) - Removal / Installation		HRS		5452.4			0			0
	6830096E19	8382H	ENC		2550			0			0
			MOS		175.7			24 Mar 2008			
			MSC				O/C				
Engine											
731100 (731120)	No. 2 Engine - Fuel Spray Nozzle (No. 1) - Removal / Installation		HRS		5452.4			0			0
	6830096E19	8450H	ENC		2550			0			0
			MOS		176.2			11 Mar 2008			
			MSC				O/C				
Engine											
731101	No. 1 Engine - Fuel Spray Nozzle (No. 2) - Removal / Installation		HRS		5452.4			0			0
	6830096E19	8382H	ENC		2550			0			0
			MOS		175.7			24 Mar 2008			
			MSC				O/C				
Engine											
731101 (731121)	No. 2 Engine - Fuel Spray Nozzle (No. 2) - Removal / Installation		HRS		5452.4			0			0
	6830096E19	8406H	ENC		2550			0			0
			MOS		176.2			11 Mar 2008			
			MSC				O/C				
Engine											

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Description: Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
731102	No. 1 Engine - Fuel Spray Nozzle (No. 3) - Removal / Installation		HRS		5452.4			0			0
			ENC		2550			0			0
	6830096E19	8383H	MOS		175.7			24 Mar 2008			
			MSC				O/C				
Engine											
731102 (731122)	No. 2 Engine - Fuel Spray Nozzle (No. 3) - Removal / Installation		HRS		5452.4			0			0
			ENC		2550			0			0
	6830096E19	8407H	MOS		176.2			11 Mar 2008			
			MSC				O/C				
Engine											
731103	No. 1 Engine - Fuel Spray Nozzle (No. 4) - Removal / Installation		HRS		5452.4			0			0
			ENC		2550			0			0
	6830096E19	8384H	MOS		175.7			24 Mar 2008			
			MSC				O/C				
Engine											
731103 (731123)	No. 2 Engine - Fuel Spray Nozzle (No. 4) - Removal / Installation		HRS		5452.4			0			0
			ENC		2550			0			0
	6830096E19	8408H	MOS		176.2			11 Mar 2008			
			MSC				O/C				
Engine											
731104	No. 1 Engine - Fuel Spray Nozzle (No. 5) - Removal / Installation		HRS		5452.4			0			0
			ENC		2550			0			0
	6830096E19	8385H	MOS		175.7			24 Mar 2008			
			MSC				O/C				
Engine											
731104 (731124)	No. 2 Engine - Fuel Spray Nozzle (No. 5) - Removal / Installation		HRS		5452.4			0			0
			ENC		2550			0			0
	6830096E19	8409H	MOS		176.2			11 Mar 2008			
			MSC				O/C				
Engine											
731105	No. 1 Engine - Fuel Spray Nozzle (No. 6) - Removal / Installation		HRS		5452.4			0			0
			ENC		2550			0			0
	6830096E19	8386H	MOS		175.7			24 Mar 2008			
			MSC				O/C				
Engine											

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
731105 (731125)	No. 2 Engine - Fuel Spray Nozzle (No. 6) - Removal / Installation 6830096E19 SN-UNKNOWN	HRS ENC MOS MSC		5452.4 2550 176.2		O/C	0 0 11 Mar 2008			0 0
Engine										
731106	No. 1 Engine - Fuel Spray Nozzle (No. 7) - Removal / Installation 6830096E21 0057L	HRS ENC MOS MSC		5452.4 2550 175.7		O/C	0 0 24 Mar 2008			0 0
Engine										
731106 (731126)	No. 2 Engine - Fuel Spray Nozzle (No. 7) - Removal / Installation 6830096E21 0062L	HRS ENC MOS MSC		5452.4 2550 176.2		O/C	0 0 11 Mar 2008			0 0
Engine										
731107	No. 1 Engine - Fuel Spray Nozzle (No. 8) - Removal / Installation 6830096E20 1691J	HRS ENC MOS MSC		5452.4 2550 175.7		O/C	0 0 24 Mar 2008			0 0
Engine										
731107 (731127)	No. 2 Engine - Fuel Spray Nozzle (No. 8) - Removal / Installation 6830096E20 1703J	HRS ENC MOS MSC		5452.4 2550 176.2		O/C	0 0 11 Mar 2008			0 0
Engine										
731108	No. 1 Engine - Fuel Spray Nozzle (No. 9) - Removal / Installation 6830096E20 1692J	HRS ENC MOS MSC		5452.4 2550 175.7		O/C	0 0 24 Mar 2008			0 0
Engine										
731108 (731128)	No. 2 Engine - Fuel Spray Nozzle (No. 9) - Removal / Installation 6830096E20 1704J	HRS ENC MOS MSC		5452.4 2550 176.2		O/C	0 0 11 Mar 2008			0 0
Engine										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
731109	No. 1 Engine - Fuel Spray Nozzle (No. 10) - Removal / Installation 6830096E20 1693J	HRS ENC MOS MSC		5452.4 2550 175.7		 O/C	0 0 24 Mar 2008			0 0
Engine										
731109 (731129)	No. 2 Engine - Fuel Spray Nozzle (No. 10) - Removal / Installation 6830096E20 1705J	HRS ENC MOS MSC		5452.4 2550 176.2		 O/C	0 0 11 Mar 2008			0 0
Engine										
732001	No. 1 Engine - Electronic Engine Controller - Removal / Installation TEEC2000-05AH BX780321	HRS ENC MOS MSC		1008.2 397 33.5		 O/C	4444.2 2153 02 Feb 2020			0 0
Engine										
732001 (732002)	No. 2 Engine - Electronic Engine Controller - Removal / Installation TEEC2000-05-AH BX780162	HRS ENC MOS MSC		1008.2 397 33.5		 O/C	4444.2 2153 02 Feb 2020			0 0
Engine										
732115	No. 1 Engine - Fuel Metering Unit - Removal / Installation FMU1101 SFF11-013	HRS ENC MOS MSC		756.7 249 19.4		 O/C	4695.7 2301 04 Apr 2021			0 0
Engine										
Notes: CMP UPDATE - S/N SFF07-074 REMOVED AND ENGINE TIMES CORRECTED (MB)										
732115 (732116)	No. 2 Engine - Fuel Metering Unit - Removal / Installation FMU1101 SFF06-050	HRS ENC MOS MSC		5452.4 2550 176.2		 O/C	0 0 11 Mar 2008			0 0
Engine										
732117	No. 1 Engine - Fuel Metering Unit Mounting Block - Removal / Installation TMB101 SOF08-006	HRS ENC MOS MSC		5452.4 2550 175.7		 O/C	0 0 24 Mar 2008			0 0
Engine										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
732117 (732118)	No. 2 Engine - Fuel Metering Unit Mounting Block - Removal / Installation TMB101 SOF08-002	HRS ENC MOS MSC		5452.4 2550 176.2		 O/C	0 0 11 Mar 2008			0 0
Engine										
733101	No. 1 Engine - Fuel Flow Transmitter - Removal / Installation 9-217-73 111123-292	HRS ENC MOS MSC		5452.4 2550 175.7		 O/C	0 0 24 Mar 2008			0 0 ROLLS-ROYCE CUSTOMER BUSINESS GROUP
Engine										
733101 (733102)	No. 2 Engine - Fuel Flow Transmitter - Removal / Installation 9-217-73 111123-290	HRS ENC MOS MSC		5452.4 2550 176.2		 O/C	0 0 11 Mar 2008			0 0 ROLLS-ROYCE CUSTOMER BUSINESS GROUP
Engine										
733309	No. 1 Engine - Fuel Low-Pressure Transducer - Removal / Installation APT11B1500 K0268	HRS ENC MOS MSC		5452.4 2550 175.7		 O/C	0 0 24 Mar 2008			0 0
Engine										
733309 (733310)	No. 2 Engine - Fuel Low-Pressure Transducer - Removal / Installation APT11B1500 K0552	HRS ENC MOS MSC		3168.1 1383 107.6		 O/C	2284.3 1167 28 Nov 2013			0 0
Engine										
74 - Ignition										
741001	No. 1 Engine - Ignition Unit (No. 1) - Removal / Installation 9060440-2 318380059	HRS ENC MOS MSC		957.2 362 29.1		 O/C	4495.2 2188 12 Jun 2020			0 0
Engine										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
741001 (741002) Engine	No. 2 Engine - Ignition Unit (No. 1) - Removal / Installation 9060440-2 08079117	HRS ENC MOS MSC		957.2 362 29.1		 O/C	4495.2 2188 12 Jun 2020			0 0
741003 Engine	No. 1 Engine - Ignition Unit (No. 2) - Removal / Installation 9060440-2 08068236	HRS ENC MOS MSC		957.2 362 29.1		 O/C	4495.2 2188 12 Jun 2020			0 0
741003 (741004) Engine	No. 2 Engine - Ignition Unit (No. 2) - Removal / Installation 9060440-2 08068235	HRS ENC MOS MSC		957.2 362 29.1		 O/C	4495.2 2188 12 Jun 2020			0 0
742001 Engine	No. 1 Engine - No. 1 Igniter Plug - Removal / Installation Y183-5 19095049	HRS ENC MOS MSC	TSN:198.6 TSN:112 TSN:9	882.2 304 26		 O/C	4570.2 2246 17 Sep 2020			0 0
742001 (742002) Engine	No. 2 Engine - No. 1 Igniter Plug - Removal / Installation Y183-5 21020697	HRS ENC MOS MSC		6.5 2 .2		 O/C	5445.9 2548 11 Nov 2022			0 0
742003 Engine	No. 1 Engine - No. 2 Igniter Plug - Removal / Installation Y183-5 19095099	HRS ENC MOS MSC	TSN:198.6 TSN:112 TSN:11	882.2 304 24.4		 O/C	4570.2 2246 04 Nov 2020			0 0
742003 (742004) Engine	No. 2 Engine - No. 2 Igniter Plug - Removal / Installation Y183-5 21020683	HRS ENC MOS MSC		6.5 2 .2		 O/C	5445.9 2548 11 Nov 2022			0 0
742009 Engine	No. 1 Engine - Ignition System Relight Circuit - Operational Check 052000-2A,200098	HRS ENC MOS [HRS: +50/-50]		6.5 2 .2		1000 	5445.9 2548 11 Nov 2022	6445.9	6495.9	0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
742009 (742010)	No. 2 Engine - Ignition System Relight Circuit - Operational Check	HRS ENC MOS		6.5 2 .2		1000	5445.9 2548 11 Nov 2022	6445.9	6495.9	0 0
Engine	052000-2A,200099	[HRS: +50/-50]								
742011	No. 1 Engine - No. 1 External Ignition Lead - Removal / Installation 650093 SN-UNKNOWN	HRS ENC MOS MSC		5452.4 2550 175.7		 O/C	0 0 24 Mar 2008			0 0
Engine										
742011 (742012)	No. 2 Engine - No. 1 External Ignition Lead - Removal / Installation 650093 SN-UNKNOWN	HRS ENC MOS MSC		5452.4 2550 176.2		 O/C	0 0 11 Mar 2008			0 0
Engine										
742013	No. 1 Engine - No. 2 External Ignition Lead - Removal / Installation 650092 SN-UNKNOWN	HRS ENC MOS MSC		5452.4 2550 175.7		 O/C	0 0 24 Mar 2008			0 0
Engine										
742013 (742014)	No. 2 Engine - No. 2 External Ignition Lead - Removal / Installation 650092 SN-UNKNOWN	HRS ENC MOS MSC		5452.4 2550 176.2		 O/C	0 0 11 Mar 2008			0 0
Engine										
742015	No. 1 Engine - No. 1 Igniter Plug - Detailed Inspection	HRS ENC MOS		6.5 2 .2		1000	5445.9 2548 11 Nov 2022	6445.9	6495.9	0 0
Engine	200098	[HRS: +50/-50]								
742015 (742016)	No. 2 Engine - No. 1 Igniter Plug - Detailed Inspection	HRS ENC MOS		6.5 2 .2		1000	5445.9 2548 11 Nov 2022	6445.9	6495.9	0 0
Engine	200099	[HRS: +50/-50]								

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
742017	No. 1 Engine - No. 2 Igniter Plug - Detailed Inspection	HRS		6.5		1000	5445.9	6445.9	6495.9	0
		ENC		2			2548			0
		MOS		.2			11 Nov 2022			
Engine	200098	[HRS: +50/-50]								
742017 (742018)	No. 2 Engine - No. 2 Igniter Plug - Detailed Inspection	HRS		6.5		1000	5445.9	6445.9	6495.9	0
		ENC		2			2548			0
		MOS		.2			11 Nov 2022			
Engine	200099	[HRS: +50/-50]								
75 - AIR										
750001	No. 1 Engine - Handling Bleed Valve Actuator - Removal / Installation	HRS		5452.4			0			0
		ENC		2550			0			0
	HBVA101 SAF08-019	MOS		175.7			24 Mar 2008			
		MSC				O/C				
Engine										
750001 (750002)	No. 2 Engine - Handling Bleed Valve Actuator - Removal / Installation	HRS		5452.4			0			0
		ENC		2550			0			0
	HBVA101 SAF07-154	MOS		176.2			11 Mar 2008			
		MSC				O/C				
Engine										
750003	No. 1 Engine - Bleed Valve - Adjustment / Test	HRS		5452.4			0			0
		ENC		2550			0			0
		MOS		175.7			24 Mar 2008			
		MSC				O/C				
Engine										
750003 (750004)	No. 2 Engine - Bleed Valve - Adjustment / Test	HRS		5452.4			0			0
		ENC		2550			0			0
		MOS		176.2			11 Mar 2008			
		MSC				O/C				
Engine										
750007	No. 1 Engine - Variable Inlet Guide Vane Actuator - Removal / Installation	HRS		5452.4			0			0
		ENC		2550			0			0
	VIGVA101 SAF08-016	MOS		175.7			24 Mar 2008			
		MSC				O/C				
Engine										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
750007 (750008)	No. 2 Engine - Variable Inlet Guide Vane Actuator - Removal / Installation VIGVA101 SAF07-146	HRS ENC MOS MSC		5452.4 2550 176.2		O/C	0 0 11 Mar 2008			0 0
Engine										
750009	No. 1 Engine - Variable Inlet Guide Vanes Linkage - Adjustment / Test	HRS ENC MOS MSC		5452.4 2550 175.7		O/C	0 0 24 Mar 2008			0 0
Engine										
750009 (750010)	No. 2 Engine - Variable Inlet Guide Vanes Linkage - Adjustment / Test	HRS ENC MOS MSC		5452.4 2550 176.2		O/C	0 0 11 Mar 2008			0 0
Engine										
750019	No. 1 Engine - Low-Pressure Cooling AIR Outlet Tube - Removal / Installation X SN-UNKNOWN	HRS ENC MOS MSC		5452.4 2550 175.7		O/C	0 0 24 Mar 2008			0 0
Engine										
750019 (750020)	No. 2 Engine - Low-Pressure Cooling AIR Outlet Tube - Removal / Installation X SN-UNKNOWN	HRS ENC MOS MSC		5452.4 2550 176.2		O/C	0 0 11 Mar 2008			0 0
Engine										
750021	No. 1 Engine - 7TH Stage Compressor AIR Duct - Removal / Installation - -	HRS ENC MOS MSC		882.2 304 24.4		O/C	4570.2 2246 04 Nov 2020			0 0
Engine										
750021 (750022)	No. 2 Engine - 7TH Stage Compressor AIR Duct - Removal / Installation N/A N/A	HRS ENC MOS MSC	TSN:4570.2 TSN:2246 TSN:152	882.2 304 24.1		O/C	4570.2 2246 13 Nov 2020			0 0
Engine										

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
Logbook Position	HW	SW									
	MM Ref										
	Ops Number(s)										
750023	No. 1 Engine - 12TH Stage Compressor AIR Duct - Removal / Installation		HRS		882.2			4570.2			0
			ENC		304			2246			0
	-	-	MOS		24.4			04 Nov 2020			
			MSC				O/C				
Engine											
750023 (750024)	No. 2 Engine - 12TH Stage Compressor AIR Duct - Removal / Installation		HRS		882.2			4570.2			0
			ENC		304			2246			0
	X	X	MOS		24.1			13 Nov 2020			
			MSC				O/C				
Engine											
750025	Valve, L Eng Mid Stage Check		HRS		5530.4			0			0
	3202908-1	SN-UNKNOWN	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			HONEYWELL ENGINES SYSTEMS & SERVICE
			MSC				O/C				
Airframe											
750026	Valve, R Eng Mid Stage Check		HRS		5530.4			0			0
	3202908-1	SN-UNKNOWN	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			HONEYWELL ENGINES SYSTEMS & SERVICE
			MSC				O/C				
Airframe											
76 - Engine Controls											
761001	Throttle Quadrant Assembly - Removal / Installation		HRS		957.2			4573.2			0
	1159SCF553-2	126569	AFL		362			2237			0
			MOS		29.1			12 Jun 2020			
			MSC				O/C				
Airframe											
762339	No. 1 Engine - Low-Pressure Turbine Fuel Shut-Off System - Detailed Inspection		HRS		2079			3373.4			0
			ENC		844			1706			0
			MOS		66.2		120	09 May 2017	09 May 2027		
Engine											

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
762339 (762340)	No. 2 Engine - Low-Pressure Turbine Fuel Shut-Off System - Detailed Inspection	HRS ENC MOS		2079 844 66.2		 120	3373.4 1706 09 May 2017	 09 May 2027		0 0
Engine										
77 - Engine Indicating										
771201	No. 1 Engine - Channel A Hp Speed Probe (No. 1) - Removal / Installation 889-3-13 8295	HRS ENC MOS MSC		5452.4 2550 175.7		 O/C	0 0 24 Mar 2008			0 0 ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
Engine										
771201 (771202)	No. 2 Engine - Channel A Hp Speed Probe (No. 1) - Removal / Installation 889-3-13 9698	HRS ENC MOS MSC		5452.4 2550 176.2		 O/C	0 0 11 Mar 2008			0 0 ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
Engine										
771203	No. 1 Engine - Channel B Hp Speed Probe (No. 2) - Removal / Installation 889-3-13 8296	HRS ENC MOS MSC		5452.4 2550 175.7		 O/C	0 0 24 Mar 2008			0 0 ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
Engine										
771203 (771204)	No. 2 Engine - Channel B Hp Speed Probe (No. 2) - Removal / Installation 889-3-13 9699	HRS ENC MOS MSC		5452.4 2550 176.2		 O/C	0 0 11 Mar 2008			0 0 ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
Engine										
771205	No. 1 Engine - Shared Hp Speed Probe (No. 3) - Removal / Installation 889-3-13 8297	HRS ENC MOS MSC		5452.4 2550 175.7		 O/C	0 0 24 Mar 2008			0 0 ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
Engine										

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Description: Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
771205 (771206)	No. 2 Engine - Shared Hp Speed Probe (No. 3) - Removal / Installation		HRS		5452.4			0			0
			ENC		2550			0			0
	889-3-13	9700	MOS		176.2			11 Mar 2008			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
			MSC				O/C				
Engine											
771207	No. 1 Engine - EVM / Idg Hp Speed Probe (No. 4) - Removal / Installation		HRS		5452.4			0			0
			ENC		2550			0			0
	889-3-13	8298	MOS		175.7			24 Mar 2008			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
			MSC				O/C				
Engine											
771207 (771208)	No. 2 Engine - EVM / Idg Hp Speed Probe (No. 4) - Removal / Installation		HRS		5452.4			0			0
			ENC		2550			0			0
	889-3-13	9701	MOS		176.2			11 Mar 2008			ROLLS- ROYCE DEUTSCHLAND LTD. & CO. KG
			MSC				O/C				
Engine											
772011	No. 1 Engine - Turbine Gas Temperature Thermocouple (No. 1) - Removal / Installation		HRS		5452.4			0			0
			ENC		2550			0			0
	1040-1-11	2422	MOS		175.7			24 Mar 2008			
			MSC				O/C				
Engine											
772011 (772012)	No. 2 Engine - Turbine Gas Temperature Thermocouple (No. 1) - Removal / Installation		HRS		5452.4			0			0
			ENC		2550			0			0
	1040-1-11	2602	MOS		176.2			11 Mar 2008			
			MSC				O/C				
Engine											
772013	No. 1 Engine - Turbine Gas Temperature Thermocouple (No. 2) - Removal / Installation		HRS		5452.4			0			0
			ENC		2550			0			0
	1040-1-11	2424	MOS		175.7			24 Mar 2008			
			MSC				O/C				
Engine											

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
Logbook Position	HW	SW									
	MM Ref										
	Ops Number(s)										
772013 (772014)	No. 2 Engine - Turbine Gas Temperature Thermocouple (No. 2) - Removal / Installation		HRS		5452.4			0			0
			ENC		2550			0			0
	1040-1-11	2603	MOS		176.2			11 Mar 2008			
			MSC				O/C				
Engine											
772015	No. 1 Engine - Turbine Gas Temperature Thermocouple (No. 3) - Removal / Installation		HRS		5452.4			0			0
			ENC		2550			0			0
	1040-1-11	2425	MOS		175.7			24 Mar 2008			
			MSC				O/C				
Engine											
772015 (772016)	No. 2 Engine - Turbine Gas Temperature Thermocouple (No. 3) - Removal / Installation		HRS		5452.4			0			0
			ENC		2550			0			0
	1040-1-11	2604	MOS		176.2			11 Mar 2008			
			MSC				O/C				
Engine											
772017	No. 1 Engine - Turbine Gas Temperature Thermocouple (No. 4) - Removal / Installation		HRS		5452.4			0			0
			ENC		2550			0			0
	1040-1-11	2426	MOS		175.7			24 Mar 2008			
			MSC				O/C				
Engine											
772017 (772018)	No. 2 Engine - Turbine Gas Temperature Thermocouple (No. 4) - Removal / Installation		HRS		5452.4			0			0
			ENC		2550			0			0
	1040-1-11	2606	MOS		176.2			11 Mar 2008			
			MSC				O/C				
Engine											
772019	No. 1 Engine - Turbine Gas Temperature Thermocouple (No. 5) - Removal / Installation		HRS		5452.4			0			0
			ENC		2550			0			0
	1040-1-11	2427	MOS		175.7			24 Mar 2008			
			MSC				O/C				
Engine											
772019 (772020)	No. 2 Engine - Turbine Gas Temperature Thermocouple (No. 5) - Removal / Installation		HRS		5452.4			0			0
			ENC		2550			0			0
	1040-1-11	2607	MOS		176.2			11 Mar 2008			
			MSC				O/C				
Engine											

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
772021	No. 1 Engine - Turbine Gas Temperature Thermocouple (No. 6) - Removal / Installation 1040-1-11 2428	HRS ENC MOS MSC		5452.4 2550 175.7		 O/C	0 0 24 Mar 2008			0 0
Engine										
772021 (772022)	No. 2 Engine - Turbine Gas Temperature Thermocouple (No. 6) - Removal / Installation 1040-1-11 2608	HRS ENC MOS MSC		5452.4 2550 176.2		 O/C	0 0 11 Mar 2008			0 0
Engine										
772023	No. 1 Engine - Turbine Gas Temperature Thermocouple (No. 7) - Removal / Installation 1040-1-11 2429	HRS ENC MOS MSC		5452.4 2550 175.7		 O/C	0 0 24 Mar 2008			0 0
Engine										
772023 (772024)	No. 2 Engine - Turbine Gas Temperature Thermocouple (No. 7) - Removal / Installation 1040-1-11 2609	HRS ENC MOS MSC		5452.4 2550 176.2		 O/C	0 0 11 Mar 2008			0 0
Engine										
772025	No. 1 Engine - Turbine Gas Temperature Thermocouple (No. 8) - Removal / Installation 1040-1-11 2430	HRS ENC MOS MSC		5452.4 2550 175.7		 O/C	0 0 24 Mar 2008			0 0
Engine										
772025 (772026)	No. 2 Engine - Turbine Gas Temperature Thermocouple (No. 8) - Removal / Installation 1040-1-11 2640	HRS ENC MOS MSC		5452.4 2550 176.2		 O/C	0 0 11 Mar 2008			0 0
Engine										
773001	Integrated Engine Vibration Monitor Card - Removal / Installation 241-304-003-022 AD08137	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 TAPIS CORP
Airframe										
Notes: VERFIED BY:PQ005										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
773005 Engine	No. 1 Engine - Engine Vibration Monitor Accelerometer (Forward) - Removal / Installation 144-151-000-301 AD00973	HRS ENC MOS MSC	TSN:3760.9 TSN:1882 TSN:124	1691.5 668 51.9		 O/C	3760.9 1882 19 Jul 2018			0 0 GULFSTREAM SAV PROD-IPT
773005 (773006) Engine	No. 2 Engine - Engine Vibration Monitor Accelerometer (Forward) - Removal / Installation 144-151-000-301 AD00975	HRS ENC MOS MSC	TSN:3760.9 TSN:1882 TSN:124	1691.5 668 51.9		 O/C	3760.9 1882 19 Jul 2018			0 0 GULFSTREAM SAV PROD-IPT
773007 Engine	No. 1 Engine - Engine Vibration Monitor Accelerometer (Aft) - Removal / Installation 144-151-000-301 AD00974	HRS ENC MOS MSC	TSN:3760.9 TSN:1882 TSN:124	1691.5 668 51.9		 O/C	3760.9 1882 19 Jul 2018			0 0 GULFSTREAM SAV PROD-IPT
773007 (773008) Engine	No. 2 Engine - Engine Vibration Monitor Accelerometer (Aft) - Removal / Installation 144-151-000-301 AD00976	HRS ENC MOS MSC	TSN:3760.9 TSN:1882 TSN:124	1691.5 668 51.9		 O/C	3760.9 1882 19 Jul 2018			0 0 GULFSTREAM SAV PROD-IPT
773101 Airframe	Engine Vibration Monitor System (Left) - Operational Test	HRS AFL MOS MSC		2653.1 1095 90.6		 O/C	2877.3 1504 29 Apr 2015			0 0
773102 Airframe	Engine Vibration Monitor System (Right) - Operational Test	HRS AFL MOS MSC		2643.1 1095 90.6		 O/C	2887.3 1504 29 Apr 2015			0 0
779998 Airframe	Availale Code 1040-1-11 2431	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
Logbook Position	HW	SW									
	MM Ref										
	Ops Number(s)										
779999	Availale Code		HRS		5530.4			0			0
	1040-1-11	2641	AFL		2599			0			0
			MOS		174.6			28 Apr 2008			
			MSC				O/C				
Airframe											
78 - Exhaust											
780005	Thrust Reverser / Exhaust Internal (Left) - Zonal Inspection		HRS		6.5	49.3	1000	5523.9	6573.2*	6623.2	0
			AFL		2			2597			0
			MOS		.2			11 Nov 2022			
			[HRS: +50/-50]								
Airframe	052000-2A,200102										
780006	Thrust Reverser / Exhaust Internal (Right) - Zonal Inspection		HRS		6.5	49.3	1000	5523.9	6573.2*	6623.2	0
			AFL		2			2597			0
			MOS		.2			11 Nov 2022			
			[HRS: +50/-50]								
Airframe	052000-2A,200102										
780009	Thrust Reverser System Bleed (Left) - Procedure		HRS		957.2			4573.2			0
			AFL		362			2237			0
			MOS		29.1			12 Jun 2020			
			MSC				O/C				
Airframe											
780010	Thrust Reverser System Bleed (Right) - Procedure		HRS		5530.4			0			0
			AFL		2599			0			0
			MOS		174.6			28 Apr 2008			
			MSC				O/C				
Airframe											
780015	Thrust Reverser Deactivation (Left) - Procedure		HRS		957.2			4573.2			0
			AFL		362			2237			0
			MOS		29.1			12 Jun 2020			
			MSC				O/C				
Airframe											
780020	Thrust Reverser Deactivation (Right) - Procedure		HRS		882.2			4648.2			0
			AFL		304			2295			0
			MOS		24.8			21 Oct 2020			
			MSC				O/C				
Airframe											

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
780025 Airframe	Thrust Reverser Activation (Left) - Procedure	HRS AFL MOS MSC		957.2 362 29.1		O/C	4573.2 2237 12 Jun 2020			0 0
780030 Airframe	Thrust Reverser Activation (Right) - Procedure	HRS AFL MOS MSC		957.2 362 29.1		O/C	4573.2 2237 12 Jun 2020			0 0
780031 Airframe	Thrust Reverser Ground Operation (Left) - Procedure	HRS AFL MOS MSC		957.2 362 29.1		O/C	4573.2 2237 12 Jun 2020			0 0
780032 Airframe	Thrust Reverser Ground Operation (Right) - Procedure	HRS AFL MOS MSC		957.2 362 29.1		O/C	4573.2 2237 12 Jun 2020			0 0
780033 Airframe	Thrust Reverser Return to Service (Left) - Procedure	HRS AFL MOS MSC		882.2 304 23.1		O/C	4648.2 2295 14 Dec 2020			0 0
780034 Airframe	Thrust Reverser Return to Service (Right) - Procedure	HRS AFL MOS MSC		882.2 304 23.1		O/C	4648.2 2295 14 Dec 2020			0 0
781103 Engine	No. 1 Engine - Turbine Exhaust Cone Assembly - Inspection / Check 052000-6A	HRS ENC MOS [HRS: +50/-50]		2562.5 1045 90.1		3000	2889.9 1505 12 May 2015	5889.9	5939.9	0 0
781103 (781104) Engine	No. 2 Engine - Turbine Exhaust Cone Assembly - Inspection / Check 052000-6A	HRS ENC MOS [HRS: +50/-50]		2562.5 1045 90.1		3000	2889.9 1505 12 May 2015	5889.9	5939.9	0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
781117 Airframe	Exhaust Mixer Assembly (Left) - Inspection / Check 052000-6A,200106	HRS AFL MOS [HRS: +50/-50]		2640.5 1094 90.1		3000	2889.9 1505 12 May 2015	5889.9	5939.9	0 0
781118 Airframe	Exhaust Mixer Assembly (Right) - Inspection / Check 052000-6A,200106	HRS AFL MOS [HRS: +50/-50]		2640.5 1094 90.1		3000	2889.9 1505 12 May 2015	5889.9	5939.9	0 0
781125 Engine	No. 1 Engine - Exhaust Collector Support (Warren Girders) - Detailed Inspection 052000-6A	HRS ENC MOS [HRS: +50/-50]		2562.5 1045 90.1		3000	2889.9 1505 12 May 2015	5889.9	5939.9	0 0
781125 (781126) Engine	No. 2 Engine - Exhaust Collector Support (Warren Girders) - Detailed Inspection 052000-6A	HRS ENC MOS [HRS: +50/-50]		2562.5 1045 90.1		3000	2889.9 1505 12 May 2015	5889.9	5939.9	0 0
783001 Airframe	Thrust Reverser (Left) - Removal / Installation 08ND78006-3 G40118LH	HRS AFL MOS MSC	TSN:3838.9 TSN:1931 TSN:123	1691.5 668 51.9		 O/C	3838.9 1931 19 Jul 2018			0 0 NORDAM GROUP MANUFACTURING DIVISION
783002 Airframe	Thrust Reverser (Right) - Removal / Installation 08ND78006-4 G40120RH	HRS AFL MOS MSC	TSN:3838.9 TSN:1931 TSN:123	1691.5 668 51.9		 O/C	3838.9 1931 20 Jul 2018			0 0 NORDAM GROUP MANUFACTURING DIVISION
783005 Airframe	Open / Close Thrust Reverser Doors (Manually) (Left)	HRS AFL MOS MSC		957.2 362 29.1		 O/C	4573.2 2237 12 Jun 2020			0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
783006	Open / Close Thrust Reverser Doors (Manually) (Right)	HRS		957.2			4573.2			0
		AFL		362			2237			0
		MOS		29.1			12 Jun 2020			
		MSC				O/C				
Airframe										
783007	Thrust Reverser (Left) - Adjustment / Test	HRS		5516.4			14			0
		AFL		2594			5			0
		MOS		171.2			09 Aug 2008			
		MSC				O/C				
Airframe										
783008	Thrust Reverser (Right) - Adjustment / Test	HRS		5516.4			14			0
		AFL		2594			5			0
		MOS		171.2			09 Aug 2008			
		MSC				O/C				
Airframe										
783031	Driver Link Assembly (Left) - Removal / Installation PN SN-UNKNOWN	HRS		5530.4			0			0
		AFL		2599			0			0
		MOS		174.6			28 Apr 2008			
		MSC				O/C				
Airframe										
783032	Driver Link Assembly (Right) - Removal / Installation PN SN-UNKNOWN	HRS		5530.4			0			0
		AFL		2599			0			0
		MOS		174.6			28 Apr 2008			
		MSC				O/C				
Airframe										
783039	Panel and Fairing Assembly (Left) - Removal / Installation PN SN-UNKNOWN	HRS		957.2			4573.2			0
		AFL		362			2237			0
		MOS		29.1			12 Jun 2020			
		MSC				O/C				
Airframe										
783040	Panel and Fairing Assembly (Right) - Removal / Installation PN SN-UNKNOWN	HRS		957.2			4573.2			0
		AFL		362			2237			0
		MOS		29.1			12 Jun 2020			
		MSC				O/C				
Airframe										
783101	Thrust Reverser Door (Left, Upper) - Removal / Installation 08ND78604-1 G40118-23	HRS		5530.4			0			0
		AFL		2599			0			0
		MOS		174.6			28 Apr 2008			NORDAM GROUP MANUFACTURING DIVISION
		MSC				O/C				
Airframe										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
783102	Thrust Reverser Door (Right, Upper) - Removal / Installation 08ND78602-6 G40120-24	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 NORDAM GROUP MANUFACTURING DIVISION
Airframe										
783103	Thrust Reverser Door (Left, Lower) - Removal / Installation 08ND78704-1 G40118LH	HRS AFL MOS MSC		4882.7 2421 149.6		 O/C	647.7 178 28 May 2010			0 0 NORDAM GROUP MANUFACTURING DIVISION
Airframe										
783104	Thrust Reverser Door (Right, Lower) - Removal / Installation 08ND78703-8 G40120-26	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 NORDAM GROUP MANUFACTURING DIVISION
Airframe										
783109	Thrust Reverser Door (Left) - Inspection / Check	HRS AFL MOS MSC		4882.7 2421 149.6		 O/C	647.7 178 29 May 2010			0 0
Airframe										
783110	Thrust Reverser Door (Right) - Inspection / Check	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										
783115	Door Fairing Seal Assembly (Left Upper Inboard) - Removal / Installation PN SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										
783116	Door Fairing Seal Assembly (Left Lower Ouboard) - Removal / Installation PN SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
783117	Door Fairing Seal Assembly (Left Lower Inboard) - Removal / Installation PN SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										
783118	Door Fairing Seal Assembly (Right Upper Inboard) - Removal / Installation PN SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										
783119	Door Fairing Seal Assembly (Right Lower Ouboard) - Removal / Installation PN SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										
783120	Door Fairing Seal Assembly (Right Lower Inboard) - Removal / Installation PN SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										
783121	Door Fairing Seal Assembly (Left Upper Outboard) - Removal / Installation PN SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										
783122	Door Fairing Seal Assembly (Right Upper Outboard) - Removal / Installation PN SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										
783127	Latch Hook Assembly (Left, Inboard) - Removal / Installation PN SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
783128 Airframe	Latch Hook Assembly (Right, Inboard) - Removal / Installation PN SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
783129 Airframe	Latch Hook Assembly (Left, Outboard) - Removal / Installation PN SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
783130 Airframe	Latch Hook Assembly (Right, Outboard) - Removal / Installation PN SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
783139 Airframe	Thrust Reverser System Adjustment (Rigging) (Left) - Procedure	HRS AFL MOS MSC		1691.5 668 51.8		 O/C	3838.9 1931 23 Jul 2018			0 0
783140 Airframe	Thrust Reverser System Adjustment (Rigging) (Right) - Procedure	HRS AFL MOS MSC		1691.5 668 51.7		 O/C	3838.9 1931 24 Jul 2018			0 0
783303 Airframe	Isolation Control Valve (Left) - Removal / Installation 08ND78235-9 0490A	HRS AFL MOS MSC	 TSN:114	957.2 362 29.1		 O/C	4573.2 2237 12 Jun 2020			0 0
783304 Airframe	Isolation Control Valve (Right) - Removal / Installation 08ND78235-9 0293A	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 NORDAM GROUP MANUFACTURING DIVISION

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
783305 Airframe	Main Actuator Assembly (Left Inboard) - Removal / Installation 08ND78401-3 0498	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
783306 Airframe	Main Actuator Assembly (Right Inboard) - Removal / Installation 08ND78401-3 0507	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
783309 Airframe	Main Actuator Assembly (Left Outboard) - Removal / Installation 08ND78401-3 0499	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
783310 Airframe	Main Actuator Assembly (Right Outboard) - Removal / Installation 08ND78401-3 0509	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
783311 Airframe	Main Actuator Assembly (Left) - Inspection / Check	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
783312 Airframe	Main Actuator Assembly (Right) - Inspection / Check	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
783317 Airframe	Unlatch Actuator Assembly (Left) - Adjustment / Test	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
783318 Airframe	Unlatch Actuator Assembly (Right) - Adjustment / Test	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
783321 Airframe	Actuator, Outboard Primary Lock (Left) - Removal / Installation 08ND78404-1 SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
783322 Airframe	Actuator, Outboard Primary Lock (Right) - Removal / Installation 08ND78404-1 SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
783328 Airframe	Thrust Reverser Components (Left) - Detailed Inspection	HRS AFL MOS		5530.4 174.6		 10000** 	0 28 Apr 2008	 10000 		0 0
783329 Airframe	Thrust Reverser Components (Right) - Detailed Inspection	HRS AFL MOS		5530.4 174.6		 10000** 	0 28 Apr 2008	 10000 		0 0
783331 Airframe	Hydraulic Control Unit (Left) - Removal / Installation 08ND78230-13 0305	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 NORDAM GROUP MANUFACTURING DIVISION
783332 Airframe	Hydraulic Control Unit (Right) - Removal / Installation 08ND78230-13 0308	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 NORDAM GROUP MANUFACTURING DIVISION

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
783421	Thrust Reverser Electronic Control Unit (Left) - Removal / Installation 08ND78305-9 00330AJ	HRS AFL MOS MSC		882.2 304 23.1		 O/C	4648.2 2295 14 Dec 2020			0 0
Airframe										
Notes: S/N REMOVED: 00339AJ										
783422	Thrust Reverser Electronic Control Unit (Right) - Removal / Installation 08ND78305-9 00520AJS	HRS AFL MOS MSC		882.2 304 23.1		 O/C	4648.2 2295 14 Dec 2020			0 0
Airframe										
Notes: S/N REMOVED: 00339AJ										
783423	Thrust Reverser Control Unit (Left) - Adjustment / Test	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										
783424	Thrust Reverser Control Unit (Right) - Adjustment / Test	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										
783439	Main Harness Assembly (Left) - Removal / Installation JCK02006 SN-UNKNOWN	HRS AFL MOS MSC		957.2 362 29.1		 O/C	4573.2 2237 12 Jun 2020			0 0
Airframe										
783448	Switch Harness Assembly, Outboard (Right) - Removal / Installation 08ND78352-5 G4525-028	HRS AFL MOS MSC		4003 1871 126.1		 O/C	1527.4 728 14 May 2012			0 0
Airframe										
Notes: P/N REMOVED: 08ND78352-7S/N REMOVED: G4525-252										
783505	Thrust Reverser Barrel and Door (Left) - Delamination Inspection	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe										

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
783510	Thrust Reverser Barrel and Door (Right) - Delamination Inspection		HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe											
79 - Oil											
790001	Oil Servicing Reservoir - Removal / Installation 1159SCP565-3	0374	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 TYEE AIRCRAFT INC
Airframe											
790002	Engine and APU Servicing Pump - Removal / Installation 1B5-17	6BC42	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 PARKER HANNIFIN CORPORATION
Airframe											
790004	Oil Replenishing System Selector Valve - Removal / Installation 1159SCP105-1	0538	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 CHASE WALTON ELASTOMERS
Airframe											
790006	Engine and APU Replenishing System - Operational Check		HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0
Airframe											
790011	No. 1 Engine - Magnetic Chip Detectors - Inspection / Check		HRS ENC MOS MSC		2562.5 1045 90.3		 O/C	2889.9 1505 08 May 2015			0 0
Engine											

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
790011 (790012)	No. 2 Engine - Magnetic Chip Detectors - Inspection / Check	HRS ENC MOS MSC		2562.5 1045 90.2		 O/C	2889.9 1505 11 May 2015			0 0
Engine										
790015	No. 1 Engine - Magnetic Chip Detector (External Gearbox Scavenge Line) - Removal / Installation VM1251002 NSN	HRS ENC MOS MSC		2562.5 1045 90.3		 O/C	2889.9 1505 08 May 2015			0 0
Engine										
790015 (790016)	No. 2 Engine - Magnetic Chip Detector (External Gearbox Scavenge Line) - Removal / Installation VM1251002 NSN	HRS ENC MOS MSC		2562.5 1045 90.2		 O/C	2889.9 1505 11 May 2015			0 0
Engine										
790027	No. 1 Engine - Oil Pump Scavenge Oil Strainer - Removal / Installation EU54259 NSN	HRS ENC MOS MSC		2562.5 1045 90.2		 O/C	2889.9 1505 11 May 2015			0 0
Engine										
790027 (790028)	No. 2 Engine - Oil Pump Scavenge Oil Strainer - Removal / Installation EU54259 NSN	HRS ENC MOS MSC		2562.5 1045 90		 O/C	2889.9 1505 15 May 2015			0 0
Engine										
790029	No. 1 Engine - Gearbox Scavenge Oil Strainer - Removal / Installation EU54259 NSN	HRS ENC MOS MSC		2562.5 1045 90.2		 O/C	2889.9 1505 11 May 2015			0 0
Engine										
790029 (790030)	No. 2 Engine - Gearbox Scavenge Oil Strainer - Removal / Installation EU54259 NSN	HRS ENC MOS MSC		2562.5 1045 90		 O/C	2889.9 1505 15 May 2015			0 0
Engine										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
790031 Logbook Position	No. 1 Engine - Oil Pump Scavenge Oil Strainers - Inspection / Check	HRS ENC MOS MSC		2562.5 1045 90.2		 O/C	2889.9 1505 11 May 2015			0 0
Engine										
790031 (790032)	No. 2 Engine - Oil Pump Scavenge Oil Strainers - Inspection / Check	HRS ENC MOS MSC		2562.5 1045 90		 O/C	2889.9 1505 15 May 2015			0 0
Engine										
790035	No. 1 Engine - Gearbox Scavenge Oil Strainers - Inspection / Check	HRS ENC MOS MSC		2562.5 1045 90.2		 O/C	2889.9 1505 11 May 2015			0 0
Engine										
790035 (790036)	No. 2 Engine - Gearbox Scavenge Oil Strainers - Inspection / Check	HRS ENC MOS MSC		2562.5 1045 90		 O/C	2889.9 1505 15 May 2015			0 0
Engine										
792101	No. 1 Engine - Oil Pressure Filter - Detailed Inspection / Cleaning	HRS ENC MOS		6.5 2 .2		1000 48	5445.9 2548 11 Nov 2022	6445.9 30 Nov 2026	6495.9 31 Dec 2026	0 0
Engine	[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50] 052000-2A,200098									
792101 (792102)	No. 2 Engine - Oil Pressure Filter - Detailed Inspection / Cleaning	HRS ENC MOS		6.5 2 .2		1000 48	5445.9 2548 11 Nov 2022	6445.9 30 Nov 2026	6495.9 31 Dec 2026	0 0
Engine	[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50] 052000-2A,200099									
792105	No. 1 Engine - Oil Filter Element - Removal / Installation MPA 30502 NSN	HRS ENC MOS MSC		882.2 304 26		 O/C	4570.2 2246 17 Sep 2020			0 0
Engine										
Notes: P/N REMOVED: MPA 30502										

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Description: Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
792105 (792106)	No. 2 Engine - Oil Filter Element - Removal / Installation		HRS		882.2			4570.2			0
	MPA 30502	NSN	ENC		304			2246			0
			MOS		25			15 Oct 2020			
			MSC				O/C				
Engine											
Notes: P/N REMOVED: MPA 30502											
792107	No. 1 Engine - Oil Tubes and Fittings - Cleaning		HRS		5452.4			0			0
			ENC		2550			0			0
			MOS		175.7			24 Mar 2008			
			MSC				O/C				
Engine											
792107 (792108)	No. 2 Engine - Oil Tubes and Fittings - Cleaning		HRS		5452.4			0			0
			ENC		2550			0			0
			MOS		176.2			11 Mar 2008			
			MSC				O/C				
Engine											
792109	No. 1 Engine - Core Oil Tubes / Fittings - Inspection / Check		HRS		5452.4			0			0
			ENC		2550			0			0
			MOS		175.7			24 Mar 2008			
			MSC				O/C				
Engine											
792109 (792110)	No. 2 Engine - Core Oil Tubes / Fittings - Inspection / Check		HRS		5452.4			0			0
			ENC		2550			0			0
			MOS		176.2			11 Mar 2008			
			MSC				O/C				
Engine											
792201	No. 1 Engine - Fuel Cooled Oil Cooler - Removal / Installation		HRS		5452.4			0			0
	47121-1092	FC28233	ENC		2550			0			0
			MOS		175.7			24 Mar 2008			
			MSC				O/C				
Engine											
792201 (792202)	No. 2 Engine - Fuel Cooled Oil Cooler - Removal / Installation		HRS		5452.4			0			0
	47121-1092	FC28241	ENC		2550			0			0
			MOS		176.2			11 Mar 2008			
			MSC				O/C				
Engine											

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
792303	No. 1 Engine - Remote Oil Fill Valve - Removal / Installation		HRS		5452.4			0			0
			ENC		2550			0			0
	237-0263-03	0314	MOS		175.7			24 Mar 2008			
			MSC				O/C				
Engine											
792303 (792304)	No. 2 Engine - Remote Oil Fill Valve - Removal / Installation		HRS		5452.4			0			0
			ENC		2550			0			0
	237-0263-03	0313	MOS		176.2			11 Mar 2008			
			MSC				O/C				
Engine											
793003	No. 1 Engine - Oil Filter Differential Pressure POP-Up Indicator - Inspection / Check		HRS		1691.5			3760.9			0
			ENC		668			1882			0
			MOS		51.7			24 Jul 2018			
			MSC				O/C				
Engine											
793003 (793004)	No. 2 Engine - Oil Filter Differential Pressure POP-Up Indicator - Inspection / Check		HRS		1691.5			3760.9			0
			ENC		668			1882			0
			MOS		51.7			24 Jul 2018			
			MSC				O/C				
Engine											
793005	No. 1 Engine - Oil Pressure Transducer (No. 1) - Removal / Installation		HRS		5452.4			0			0
			ENC		2550			0			0
	APT-12B-1500	K0298	MOS		175.7			24 Mar 2008			
			MSC				O/C				
Engine											
793005 (793006)	No. 2 Engine - Oil Pressure Transducer (No. 1) - Removal / Installation		HRS		5452.4			0			0
			ENC		2550			0			0
	APT-12B-1500	K0278	MOS		176.2			11 Mar 2008			
			MSC				O/C				
Engine											
793009	No. 1 Engine - Oil Quantity Transmitter - Removal / Installation		HRS		5452.4			0			0
			ENC		2550			0			0
	3-1579-300	00283	MOS		175.7			24 Mar 2008			GULFSTREAM DALLAS
			MSC				O/C				
Engine											

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
793009 (793010)	No. 2 Engine - Oil Quantity Transmitter - Removal / Installation 3-1579-300 00265	HRS ENC MOS MSC		5452.4 2550 176.2		 O/C	0 0 11 Mar 2008			0 0 GULFSTREAM DALLAS
Engine										
793021	Remote Oil Service Indicator 366-211-001 SN-UNKNOWN	HRS AFL MOS MSC		5530.4 2599 174.6		 O/C	0 0 28 Apr 2008			0 0 PARKER HANNIFIN CORPORATION
Airframe										
80 - Starting										
801001	No. 1 Engine - Engine Starter Turbine Assembly - Removal / Installation 383700-4 0208-0360	HRS ENC MOS MSC	TSN:4570.2 TSN:2246 TSN:153	882.2 304 23.3		 O/C	4570.2 2246 08 Dec 2020			0 0
Engine										
801001 (801002)	No. 2 Engine - Engine Starter Turbine Assembly - Removal / Installation 0383700-4 0208-0361	HRS ENC MOS MSC		882.2 304 25		 O/C	4570.2 2246 16 Oct 2020			0 0
Engine										
801003	No. 1 Engine - Assy, Engine Starter 383702-4 0208-360	HRS ENC MOS MSC		5452.4 2550 175.7		 O/C	0 0 24 Mar 2008			0 0 HONEYWELL ENGINES SYSTEMS & SERVICE
Engine										
801003 (801004)	No. 2 Engine - Assy, Engine Starter 383702-4 0208-0361	HRS ENC MOS MSC		5452.4 2550 176.2		 O/C	0 0 11 Mar 2008			0 0 HONEYWELL ENGINES SYSTEMS & SERVICE
Engine										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
801005	No. 1 Engine - Engine Starter Regulator Valve - Removal / Installation	HRS		1080.8			4371.6			0
	3215850-4 0608-0425	ENC		416			2134			0
		MOS		34.5			02 Jan 2020			
		MSC				O/C				
Engine										
801005 (801006)	No. 2 Engine - Engine Starter Regulator Valve - Removal / Installation	HRS		1080.8			4371.6			0
	3215850-4 1107-0357	ENC		416			2134			0
		MOS		34.5			02 Jan 2020			
		MSC				O/C				
Engine										
801009	No. 1 Engine - Engine Starter - Oil Change	HRS		6.5		1000	5445.9	6445.9	6495.9	0
		ENC		2			2548			0
		MOS		.2		48	11 Nov 2022	30 Nov 2026	31 Dec 2026	
Engine	[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50] 052000-2A,200098									
801009 (801010)	No. 2 Engine - Engine Starter - Oil Change	HRS		6.5		1000	5445.9	6445.9	6495.9	0
		ENC		2			2548			0
		MOS		.2		48	11 Nov 2022	30 Nov 2026	31 Dec 2026	
Engine	[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50] 052000-2A,200099									
801037	No. 1 Engine - Starter Duct - Removal / Installation	HRS		5452.4			0			0
	PN SN-UNKNOWN	ENC		2550			0			0
		MOS		175.7			24 Mar 2008			
		MSC				O/C				
Engine										
801037 (801038)	No. 2 Engine - Starter Duct - Removal / Installation	HRS		5452.4			0			0
	PN SN-UNKNOWN	ENC		2550			0			0
		MOS		176.2			11 Mar 2008			
		MSC				O/C				
Engine										
AD - Airworthiness Directives										
DGAC AD N-2006-04-13 R01 (B) (992621)	France AD N-2006-04-13 R1 (B) Gulfstream Cockpit Displays	HRS		5525.5			4.9			0
		AFL		2597			2			0
		MOS		171.5			31 Jul 2008			
		MSC				-				
Airframe										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
DGAC N-2007-12-25 (B) (992731) Airframe	France AD N-2007-12-25 (B) Gulfstream Water Drain/Supply Valves	HRS AFL MOS MSC		5525.5 2597 171.5		-	4.9 2 31 Jul 2008			0 0
EASA 2006-0268-E (992650) Engine	No. 1 Engine - 2006-0268-E - Engine Fuel and Control - Engine Electronic Controller (Eec) - Inspection/Replacement	HRS ENC MOS MSC		4639.7 2252 144.9		-	812.7 298 20 Oct 2010			0 0
Notes: N/A DUE TO INSTALLED EQUIP P/N										
EASA 2006-0268-E^{U} (992620) Airframe	2006-0268-E - Engine Fuel and Control - Engine Electronic Controller (Eec) - Inspection/Replacement	HRS AFL MOS MSC		4717.7 2301 144.9		-	812.7 298 20 Oct 2010			0 0
EASA 2006-0268-E (992651) (992650) Engine	No. 2 Engine - 2006-0268-E - Engine Fuel and Control - Engine Electronic Controller (Eec) - Inspection/Replacement	HRS ENC MOS MSC		4639.7 2252 144.9		-	812.7 298 20 Oct 2010			0 0
Notes: N/A DUE TO INSTALLED EQUIP P/N										
EASA 2006-0336 (992652) Engine	No. 1 Engine - EASA AD 2006-0336 - Engine - Hp Compressor Vanes Stages 4 to 11 -Introduction of A New Setting Procedure to Increasethe Minimum Vane Tip Clearance	HRS ENC MOS MSC		2532.4 1029 80.3		ESV**	2920 1521 08 Mar 2016			0 0
Notes: -N/A BY ENGINE S/N-TAY611-8C: ENGINE SERIAL NUMBERS PRIOR TO 85055										

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Description: Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
EASA 2006-0336 (992653) (992652) Engine	No. 2 Engine - EASA AD 2006-0336 - Engine - Hp Compressor Vanes Stages 4 to 11 -Introduction of A New Setting Procedure to Increasethe Minimum Vane Tip Clearance		HRS ENC MOS MSC		2532.4 1029 80.3		 ESV**	2920 1521 08 Mar 2016			0 0
Notes: -N/A BY ENGINE S/N-TAY611-8C: ENGINE SERIAL NUMBERS PRIOR TO 85055											
EASA 2007-0258 (992750) Engine	No. 1 Engine - EASA AD 2007-0258 Lp Compressor Case Assembly Ice Impact Panels-Inspect		HRS ENC MOS MSC		4639.7 2252 144.9		 -	812.7 298 20 Oct 2010			0 0
Notes: N/A DUE TO SB STATUS											
EASA 2007-0258 (992751) (992750) Engine	No. 2 Engine - EASA AD 2007-0258 Lp Compressor Case Assembly Ice Impact Panels-Inspect		HRS ENC MOS MSC		4639.7 2252 144.9		 -	812.7 298 20 Oct 2010			0 0
Notes: N/A DUE TO SB STATUS											
EASA 2009-0180 R01 (992959) Airframe	EASA AD 2009-0180-R1 APU Enclosure Inspection		HRS AFL MOS		2486.2 1025 78.6			3044.2 1574 28 Apr 2016			0 0
Notes: N/A DUE TO A/C SERIAL 4123											
EASA 2009-0180-E (992951) Airframe	EASA AD 2009-0180-E APU Enclosure Inspection		HRS AFL MOS MSC		4717.7 2301 144.9		 -	812.7 298 20 Oct 2010			0 0
Notes: N/A DUE TO A/C SERIAL 4123											

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
EASA 2009-0251-E (992956) Airframe	EASA Emergency AD 2009-0251-E - Portable Halon 1211 FIRE Extinguishers	HRS AFL MOS MSC		4717.7 2301 144.9		- -	812.7 298 20 Oct 2010			0 0
Notes: N/A DUE TO INSTALLED P/N										
EASA 2009-0262 R01 (992957) Airframe	EASA AD 2009-0262 R1 - Portable Halon 1211 FIRE Extinguishers	HRS AFL MOS MSC		4717.7 2301 144.9		- -	812.7 298 20 Oct 2010			0 0
Notes: N/A DUE TO INSTALLED P/N										
EASA 2010-0003 R02 (993059) Airframe	EASA AD 2010-0003R2 MODE S Transponder Aircraft Type MODE Strapping - Check / Modification	HRS AFL MOS MSC		2886.6 1245 97.2		- -	2643.8 1354 09 Oct 2014			0 0
Notes: N/A DUE TO INSTALLED EQUIPMENT / SJT/TAC										
EASA 2010-0062 (993050) Airframe	EASA AD 2010-0062 - FIRE Fighting Enterprises Limited Portable Halon 1211 FIRE Extinguishers	HRS AFL MOS MSC		4717.7 2301 144.9		- -	812.7 298 20 Oct 2010			0 0
Notes: PN: AS INDICATED BY ASB 26-116 SN: <NONE>. N/A DUE TO INSTALLED P/N										
EASA 2010-0062 R01 (993055) Airframe	EASA AD 2010-0062R1 - FIRE Fighting Enterprises Limited Portable Halon 1211 FIRE Extinguishers	HRS AFL MOS MSC		4717.7 2301 144.9		- -	812.7 298 20 Oct 2010			0 0
Notes: PN: AS INDICATED BY ASB 26-116 ISSUE B SN: <NONE>. N/A DUE TO INSTALLED P/N										
EASA 2010-0067 (993054) Airframe	EASA AD 2010-0067 Tdr-94 and Tdr-94D Transponders	HRS AFL MOS MSC		4852.4 2401 148.6		- -	678 198 29 Jun 2010			0 0
Notes: N/A BY CONFIGURATION (NO TDR-64 OR TDR-94D TRANSPONDERS INSTALLED).										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
EASA 2010-0152 (993056) Airframe	EASA AD 2010-0152 Intertechnique, Eros Oxygen Mask Regulator-MOD	HRS AFL MOS MSC		4782.4 2337 146.2		-	748 262 10 Sep 2010			0 0
Notes: N/A BY INSTALLED P/N"S										
EASA 2011-0090 R01 (993091) Airframe	EASA AD 2011-0090R1 Oxygen Mask Regulator Inflatable Harness - Identification / Replacement	HRS AFL MOS MSC		4216.4 1986 95.9		-	1314 613 18 Nov 2014			0 0
Notes: N/A BY MANUFACTURER DATE										
EASA 2012-0039 R01 (996002) Engine	No. 1 Engine - EASA AD 2012-0039 R1 Engine - Stage 2 High Pressure Turbine Disc Spanner Retaining Nut - Replacement	HRS ENC MOS MSC		3986.4 1842 128		-	1466 708 15 Mar 2012			0 0
Notes: N/A BY SERIAL NUMBER ENGINE										
EASA 2012-0039 R01 (996003) (996002) Engine	No. 2 Engine - EASA AD 2012-0039 R1 Engine - Stage 2 High Pressure Turbine Disc Spanner Retaining Nut - Replacement	HRS ENC MOS MSC		3986.4 1842 128		-	1466 708 15 Mar 2012			0 0
Notes: N/A BY SERIAL NUMBER ENGINE										
EASA 2012-0254 PARA (3) (993100) Airframe	EASA AD 2012-0254 Flight Crew Oxygen Regulator - Identification / Operational Procedure / Replacement	HRS AFL MOS MSC		 72.5		-	 31 Oct 2016			0 0
EASA 2012-0254 R01 PARA (3) (993101) Airframe	EASA AD 2012-0254R1 Flight Crew Oxygen Regulator - Identification / Operational Procedure / Replacement	HRS AFL MOS MSC		 72.5		-	 31 Oct 2016			0 0

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Description: Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
EASA 2013-0020	EASA AD 2013-0020 - Safety Belts / Torso Restraint Systems - Inspection / Replacement		HRS		5530.4			0			0
			AFL		2599			0			0
			MOS		116.1			14 Mar 2013			
(993102)			MSC				-				
Airframe											
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
EASA 2013-0020 R01	EASA AD 2013-0020R1 - Safety Belts / Torso Restraint Systems - Inspection / Replacement		HRS		5530.4			0			0
			AFL		2599			0			0
			MOS		112			15 Jul 2013			
(993107)			MSC				-				
Airframe											
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
EASA 2013-0020 R02	EASA AD 2013-0020R2 - Safety Belts / Torso Restraint Systems - Inspection / Replacement		HRS		3385.8			2144.6			0
			AFL		1502			1097			0
			MOS		111.8			23 Jul 2013			
(993110)			MSC				-				
Airframe											
Notes: NO SEATBELTS REPLACED UNTIL DATE, SJT/TAC.											
EASA 2013-0020 R03	EASA AD 2013-0020R3 - Safety Belt / Torso Restraint Systems - Inspection / Replacement		HRS		3385.4			2145			0
			AFL		1502			1097			0
			MOS		111.8			23 Jul 2013			
(993120)			MSC				-				
Airframe											
EASA 2013-0020 R04	EASA AD 2013-0020R4 - Safety Belt / Torso Restraint Systems - Inspection / Replacement		HRS		2958.4			2572			0
			AFL		1297			1302			0
			MOS		100.1			14 Jul 2014			
(993121)			MSC				-				
Airframe											
Notes: P/C/W											
EASA 2013-0106	EASA AD 2013-0106 Varnish on Veneered Panels - Inspection / Refurbishment		HRS		882.2			4648.2			0
			AFL		304			2295			0
			MOS		26.4			04 Sep 2020			
(993108)			MSC				-				
Airframe											

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
EASA 2014-0142 (993113) Airframe	EASA AD 2014-0142 - Oxygen Mask Regulator Inflatable Harness / Hose	HRS AFL MOS MSC		5530.4 2599 171.1		-	0 0 12 Aug 2008			0 0
EASA 2014-0142 R01 PARA (1) (993114) Airframe	EASA AD 2014-0142R1 - Oxygen Mask Regulator Inflatable Harness / Hose	HRS AFL MOS MSC		2367 954 73		-	3163.4 1645 17 Oct 2016			0 0
EASA 2014-0187 U (997187) Airframe	EASA AD 2014-0187 Type D1-02 and D1-03 Seat'S Belt Attachment Bolts	HRS AFL MOS MSC		2410.4 975 75.7		-	3120 1624 24 Jul 2016			0 0
EASA 2016-0044 PARA (1) (994025) Airframe	EASA AD 2016-0044 -Engine and Auxiliary Power Unit Automatic FIRE Extinguishers - Inspection/Overhaul	HRS AFL MOS MSC		2410.4 975 75.7		-	3120 1624 24 Jul 2016			0 0
EASA 2016-0167 R01[U] Airframe	Zodiac Seats France, Cabin Attendants Seats CAS536	HRS AFL MOS MSC [End Of Month Item]				-				0 0
EASA 2017-0192[U] Airframe	Recaro Aircraft Seating Gmbh & CO. Kg - Passenger Seats - Modification	HRS AFL MOS MSC [End Of Month Item]		60.8		-	22 Oct 2017			0 0
EASA 2017-0196[U] Airframe	TCAS Processor / Software Update / Replacement	HRS AFL MOS MSC [End Of Month Item]				-				0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
EASA 2017-0217[U]	No. 1 Engine - ATA 72 - Engine - Low Pressure Compressor Fan Blades - Identification / Replacement	HRS ENC MOS MSC				- -				0 0
Engine		[End Of Month Item]								
EASA 2017-0217[U]	No. 2 Engine - ATA 72 - Engine - Low Pressure Compressor Fan Blades - Identification / Replacement	HRS ENC MOS MSC				- -				0 0
Engine		[End Of Month Item]								
EASA 2017-0225[U]	Schroth Safety Products	HRS AFL MOS MSC				- -				0 0
Airframe		[End Of Month Item]								
EASA 2018-0013[U]	No. 1 Engine - ATA 72 - Engine - Low Pressure Compressor Fan Blades - Identification / Replacement	HRS ENC MOS MSC				- -				0 0
Engine		[End Of Month Item]								
EASA 2018-0013[U]	No. 2 Engine - ATA 72 - Engine - Low Pressure Compressor Fan Blades - Identification / Replacement	HRS ENC MOS MSC				- -				0 0
Engine		[End Of Month Item]								
EASA 2018-0055	No. 1 Engine - 2018-0055 - ATA 05 - Time Limits / Maintenance Checks - Time Limits Manual - Amendment	HRS ENC MOS MSC				- -				0 0
(994058) Engine										
EASA 2018-0055 (994059)	No. 2 Engine - 2018-0055 - ATA 05 - Time Limits / Maintenance Checks - Time Limits Manual - Amendment	HRS ENC MOS MSC				- -				0 0
(994058) Engine										

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
Logbook Position	HW	SW									
	MM Ref										
	Ops Number(s)										
EASA 2018-0079U	No. 1 Engine - ATA 72 - Engine - Low Pressure Compressor Fan Blades - Identification / Replacement		HRS ENC MOS MSC				- -				0 0
Engine			[End Of Month Item]								
EASA 2018-0079U	No. 2 Engine - ATA 72 - Engine - Low Pressure Compressor Fan Blades - Identification / Replacement		HRS ENC MOS MSC				- -				0 0
Engine			[End Of Month Item]								
EASA 2018-0195U	Anjou Aeronautique - Restraint Systems		HRS AFL MOS MSC				- -				0 0
Airframe			[End Of Month Item]								
EASA 2018-0223U	B/E Aerospace Fischer		HRS AFL MOS MSC				- -				0 0
Airframe			[End Of Month Item]								
EASA 2018-0247U	Trig Avionics Ltd - Transponder		HRS AFL MOS MSC				- -				0 0
Airframe			[End Of Month Item]								
EASA 2018-0262U	Ipeco Holding Ltd - Flight Crew Seats		HRS AFL MOS MSC				- -				0 0
Airframe			[End Of Month Item]								
EASA 2018-0264U	Avioninteriors S.P.A - Centaurus Passenger Seats		HRS AFL MOS MSC				- -				0 0
Airframe			[End Of Month Item]								

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
EASA 2018-0264 R01[U] Airframe	ATA 25 - Equipment / Furnishings - Life Vest Pouch - Inspection This AD Revises EASA AD 2018-0264 Dated 07 December 2018.	HRS AFL MOS MSC [End Of Month Item]		43		- -	17 Apr 2019			0 0
EASA 2019-0004[U] Airframe	Thales Receiver Topstar 200	HRS AFL MOS MSC [End Of Month Item]				- -				0 0
EASA 2019-0010[U] Airframe	Safran Life Jackets	HRS AFL MOS MSC [End Of Month Item]				- -				0 0
EASA 2019-0235 (994074) Airframe	EASA AD 2019-0235 ACR Electronics, Inc - C406 & G406 Emergency Locator Transmitters	HRS AFL MOS MSC				- -				0 0
EASA 2020-0272 Airframe	Appliance AD - Equipment / Furnishings - Buckle - Modification / Replacement	HRS AFL MOS MSC				- -				0 0
EASA 2020-0272 PARA (1) Airframe	Modify Each Affected Buckle or Replace the Affected Buckle With A Serviceable Buckle	HRS AFL MOS				- -				0 0
EASA 2020-0272 PARA (2) Airframe	Replace Each Affected Buckle With A Serviceable Buckle (IF Post-Modification and Pre-Replacement Per Para (1))	HRS AFL MOS				- -				0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
EASA 990024[U] (990024) Airframe	EASA AD 2016-0024 FIRE Protection - Optical and Ambient Smoke Detectors - Identification / Replacement	HRS AFL MOS MSC		2410.4 975 75.7		-	3120 1624 24 Jul 2016			0 0
EASA 990026[U] (990026) Airframe Notes: N/A BY MOD.	EASA AD 2013-0106 Equipment / Furnishings - Varnish on Veneered Panels - Inspection / RE-Furbishing	HRS AFL MOS MSC		1948.9 786 59.9		-	3581.5 1813 18 Nov 2017			0 0
EASA 990044[U] (990044) Airframe Notes: N/A BY P/N	EASA AD 2016-0044 FIRE Protection - Engine and Auxiliary Power Unit Automatic FIRE Extinguishers - Inspection/Overhaul	HRS AFL MOS MSC		1948.9 786 59.9		-	3581.5 1813 18 Nov 2017			0 0
EASA 990093[U] (990093) Airframe	EASA AD 2015-0093 Lcr-100 Attitude Heading Reference System	HRS AFL MOS MSC		2410.4 975 75.7		-	3120 1624 24 Jul 2016			0 0
EASA 997125[U] (997125) Airframe	EASA AD 2014-0125 Equipment / Furnishings - Crash Position Indicator System	HRS AFL MOS MSC		2410.4 975 75.7		-	3120 1624 24 Jul 2016			0 0
EASA AD 2014-0019[U] (999853) Airframe	EASA AD 2014-0019 Equipment / Furnishings - Crash Position Indicator - Modification Aircraft Flight Manual - Amendment	HRS AFL MOS MSC		2410.4 975 75.7		-	3120 1624 24 Jul 2016			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
EASA AD 2014-0088[U] (990025) Airframe	EASA AD 2014-0088 Communications - Cockpit Voice Recorder - Replacement	HRS AFL MOS MSC		2410.4 975 75.7		 -	3120 1624 24 Jul 2016			0 0
EASA AD 2014-0095R1[U] (997096) Airframe	EASA AD 2014-0095R1 Equipment / Furnishings - Crash Position Indicator	HRS AFL MOS MSC		2410.4 975 75.7		 -	3120 1624 24 Jul 2016			0 0
FAA 1974-08-09 R02 (997427) Airframe Notes: SUPERCEDED BY REV 3. REF CODE 994002	AD 74-08-09 R2 Lavatory MOD	HRS AFL MOS MSC		4593.3 2210 139.9		 -	937.1 389 19 Mar 2011			0 0
FAA 1974-08-09 R03 (994002) Airframe	AD 74-08-09 R3 Lavatory Paper and Linen Waste Receptacle Enclosure Access Door and Disposal Door Inspection	HRS AFL MOS		6.5 2 .2		1000	5523.9 2597 11 Nov 2022	6523.9		0 0
FAA 1998-25-10 R01 (999831) Airframe Notes: N/A BY P/N AND S/N	AD 98-25-10R1 Seat Belt Restraint	HRS AFL MOS MSC		 171.5		 -	 31 Jul 2008			0 0
FAA 2002-21-01[U] (998002) Airframe Notes: N/A BY P/N AND S/N.	AD 2002-21-01 Britex Sell Gmbh & CO, Ohg Water Boilers, Coffe Makers, and Berage Makers	HRS AFL MOS MSC		 171.5		 -	 31 Jul 2008			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
FAA 2003-26-14[U] (999958) Airframe	AD 2003-26-14 Hand Held Extinguishers	HRS AFL MOS MSC		171.5		-	31 Jul 2008			0 0
Notes: N/A BY S/N										
FAA 2005-07-27 (992506) Airframe	AD 2005-07-27 Aviointeriors Seats	HRS AFL MOS MSC	5525.5 2597 171.5			-	4.9 2 31 Jul 2008			0 0
Notes: N/A BY MANUFACTURE MODEL OF SEAT INSTALLED.										
FAA 2005-16-14 (992509) Airframe	AD 2005-16-14 Adel Wiggins Floor Heater - Deactivation	HRS AFL MOS MSC	5525.5 2597 171.5			-	4.9 2 31 Jul 2008			0 0
FAA 2005-20-26 (992513) Airframe	AD 2005-20-26 Aviointeriors Model 312 Seats	HRS AFL MOS MSC	5525.5 2597 171.5			-	4.9 2 31 Jul 2008			0 0
Notes: N/A BY MANUFACTURE OF SEATS INSTALLED.										
FAA 2006-04-13 (992602) Airframe	AD 2006-04-13 Afm Procedures, Cockpit Displays Malfunction	HRS AFL MOS MSC	5525.5 2597 171.5			-	4.9 2 31 Jul 2008			0 0
FAA 2006-04-13 R01 (992603) Airframe	AD 2006-04-13 R1 Afm Procedure, Ckpt Displays Malfunction	HRS AFL MOS MSC	5525.5 2597 171.5			-	4.9 2 31 Jul 2008			0 0
Notes: COMPLIED WITH PARA. (F) OF THIS AD.										
FAA 2006-18-08 (992608) Airframe	AD 2006-18-08 Goodyear Aviation Tires	HRS AFL MOS MSC	5525.5 2597 171.5			-	4.9 2 31 Jul 2008			0 0
Notes: FOUND TO BE PREVIOUSLY C/W IAW ALERT CB AND/OR GOODYEAR SB. NO FURTHER ACTION REQUIRED.										

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
FAA 2006-19-04 PARA (F) (992610) Airframe	AD 2006-19-04 Honeywell International (14 Day)		HRS AFL MOS MSC		5525.5 2597 171.5		-	4.9 2 31 Jul 2008			0 0
Notes: C/W WITH THIS AD IAW PARA. (C)(1)(2) AND FOUND TO BE N/A BY P/N INSTALLED.											
FAA 2006-19-04 PARA (G) (992611) Airframe	AD 2006-19-04 Honeywell International (18 Month)		HRS AFL MOS MSC		5525.5 2597 171.5		-	4.9 2 31 Jul 2008			0 0
Notes: C/W WITH THIS AD IAW PARA. (C)(1)(2) AND FOUND TO BE N/A BY P/N INSTALLED.											
FAA 2007-12-25 (992707) Airframe	AD 2007-12-25 Water Drain/Supply Valves		HRS AFL MOS MSC		5525.5 2597 171.5		-	4.9 2 31 Jul 2008			0 0
Notes: N/A BY VALVE P/N.											
FAA 2007-12-25 PARA (H) (992708) Airframe	AD 2007-12-25 Water Drain/Supply Valves (Terminating Action)		HRS AFL MOS MSC		5525.5 2597 171.5		-	4.9 2 31 Jul 2008			0 0
Notes: N/A BY VALVE P/N.											
FAA 2007-26-19 (992801) Engine	No. 1 Engine - 2007-26-19 - Engine - Ice-Impact Panels and Fillets In the Low Pressure (Lp) Compressor Case - Inspect / Replace		HRS ENC MOS MSC		5447.5 2548 171.5		-	4.9 2 31 Jul 2008			0 0
Notes: N/A BY ENGINE S/N.											
FAA 2007-26-19 (992802) (992801) Engine	No. 2 Engine - 2007-26-19 - Engine - Ice-Impact Panels and Fillets In the Low Pressure (Lp) Compressor Case - Inspect / Replace		HRS ENC MOS MSC		5447.5 2548 171.5		-	4.9 2 31 Jul 2008			0 0
Notes: N/A BY ENGINE S/N.											

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
FAA 2009-17-01 (992902) Airframe	AD 2009-17-01 Inspection for Sealant Applied to the Exterior of the Auxiliary Power Unit (APU) Enclosure	HRS AFL MOS MSC		5214.6 2493 158.5		-	315.8 106 02 Sep 2009			0 0
FAA 2009-21-10 (992903) Airframe	AD 2009-21-10 Avox Systems and B/E Aerospace Oxygen Cylinder Assemblies	HRS AFL MOS MSC		 153.4		-	 04 Feb 2010			0 0
FAA 2009-21-10 R01 (992904) Airframe Notes: P/N & S/N NOT ON AIRCRAFT	AD 2009-21-10 R1 Avox Systems and B/E Aerospace Oxygen Cylinder Assemblies	HRS AFL MOS MSC	5006.3	5006.3 2454 153		- -	524.1 145 16 Feb 2010			0 0
FAA 2010-01-03 (993001) Airframe Notes: PN: ANY SN: <NONE>. EXT NOT INSTALLED OR CARRIED.	AD 2010-01-03 FIRE Fighting Enterprises Limited Portable Halon 1211 FIRE Extinguishers	HRS AFL MOS MSC	5006.3	5006.3 2454 153		- -	524.1 145 16 Feb 2010			0 0
FAA 2010-07-02 (993004) Airframe Notes: N/A	AD 2010-07-02 Honeywell Primus Ii Rnz-850/-851	HRS AFL MOS	1948.9	1948.9 786 59.9			3581.5 1813 18 Nov 2017			0 0
FAA 2011-01-09 (993009) Airframe	AD 2011-01-09 B/E Aerospace Pbe (P/N) 119003-11	HRS AFL MOS MSC	4480	4480 2140 137		- -	1050.4 459 17 Jun 2011			0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
FAA 2012-02-08 (994001) Airframe	AD 2012-02-08 - Aviation Communication & Surveillance Systems, Llc	HRS AFL MOS MSC		3246.2 1432 107.9		-	2284.2 1167 18 Nov 2013			0 0
Notes: COMPLIED WITH VIA ALTERNATE MEANS. FAA 130L-12-80 & SB8008559-001										
FAA 2012-06-17 (994003) Engine	No. 1 Engine - 2012-06-17 - Engine - Stage 2 High Pressure Turbine Disc Spanner Retaining Nut - Replacement	HRS ENC MOS MSC		2532.4 1029 81.4		-	2920 1521 03 Feb 2016			0 0
Notes: PN: TAY 611-8C SN: 85245. N/A BY S/N										
FAA 2012-06-17 (994004) (994003) Engine	No. 2 Engine - 2012-06-17 - Engine - Stage 2 High Pressure Turbine Disc Spanner Retaining Nut - Replacement	HRS ENC MOS MSC		2532.4 1029 81.4		-	2920 1521 03 Feb 2016			0 0
Notes: PN: TAY 611-8C SN: 85244. N/A BY S/N										
FAA 2012-11-09 U (999934) Airframe	AD 2012-11-09 Oxygen Generators	HRS AFL MOS MSC		2486.2 1025 77.3		-	3044.2 1574 08 Jun 2016			0 0
Notes: NOT OPERATED UNDER 14 CFR PART 121 AND 14 CFR PART 129										
FAA 2012-11-09 R1 U (999935) Airframe	AD 2012-11-09 R1 Oxygen Generators	HRS AFL MOS MSC		2486.2 1025 77.3		-	3044.2 1574 08 Jun 2016			0 0
Notes: NOT OPERATED UNDER 14 CFR PART 121 AND 14 CFR PART 129										
FAA 2012-11-09 R1 U (999961) Airframe	AD 2012-11-09 R1 Honeywell FMS Posittion Deviations	HRS AFL MOS MSC		 171.5		-	 31 Jul 2008			0 0
Notes: C/W PART (F) OF THIS AD.										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
FAA 2012-13-12 PARA (G) (994008) Airframe	AD 2012-13-12 Flight Control Surface Paint Thickness - Afm Revision	HRS AFL MOS MSC		2640.5 1094 90.3		-	2889.9 1505 06 May 2015			0 0
FAA 2012-13-12 PARA (H)(1) (994009) Airframe	AD 2012-13-12 Flight Control Surface Paint Thickness - Measurement	HRS AFL MOS MSC		2640.5 1094 90.3		-	2889.9 1505 06 May 2015			0 0
FAA 2012-13-12 PARA (I)(1) (994010) Airframe	AD 2012-13-12 Flight Control Surface Paint Thickness - Corrective Action	HRS AFL MOS MSC		2640.5 1094 90.3		-	2889.9 1505 06 May 2015			0 0
FAA 2012-14-15[U] (999830) Airframe	AD 2012-14-15 Honeywell International, Inc. Global Navigation Satellite Sensor Units	HRS AFL MOS MSC		2410.4 975 75.7		-	3120 1624 24 Jul 2016			0 0
FAA 2012-16-15 R1[U] (999952) Airframe	AD 2012-16-15 R1 Honeywell International AIR Data Pressure Transducers	HRS AFL MOS MSC		2640.6 1094 89.3		-	2889.8 1505 06 Jun 2015			0 0
FAA 2012-25-07 (994014) Airframe	AD 2012-25-07 System Power-on SELF Test of Fsecu	HRS AFL MOS MSC		3639.9 1663 118.9		-	1890.5 936 18 Dec 2012			0 0
Notes: ACB-011 PREVIOUSLY C/W										
FAA 2012-26-15 (998000) Airframe	AD 2012-26-15 Honeywell International	HRS AFL MOS MSC		3629.4 1649 116.4		-	1901 950 05 Mar 2013			0 0
Notes: N/A DUE TO INSTALLED SERIALS										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
FAA 2012-26-15 R01 (998001) Airframe	AD 2012-26-15 R1 Honeywell International	HRS AFL MOS MSC		2640.5 1094 90.3		--	2889.9 1505 07 May 2015			0 0
Notes: SEE CUSTOM CODE 998001										
FAA 2014-18-01 (994015) Airframe	AD 2014-18-01 Rockwell Collins MODE S Transponders Tdr-94/Tdr-94D	HRS AFL MOS MSC		2640.5 1094 90.3		--	2889.9 1505 07 May 2015			0 0
Notes: N/A BY CONFIGURATION (NO TDR-94/TDR-94D INSTALLED)										
FAA 2015-08-07 (994018) Airframe	AD 2015-08-07 Zodiac Aerotechnics (Formerly Intertechnique Aircraft Systems) - Oxygen Mask Regulator Inflatable Harness - Identification / Replacement	HRS AFL MOS MSC		2157 893 66.2		--	3373.4 1706 09 May 2017			0 0
FAA 2015-16-04 (994019) Airframe	AD 2015-16-04 Kidde Graviner	HRS AFL MOS MSC		2623.3 1084 82.1		--	2907.1 1515 14 Jan 2016			0 0
Notes: NO KIDDE GRAVIENER WITH PN 56412-001, 56411-001, 56412-002 INSTALLED ON A/C.										
FAA 2015-23-09 PARA (G) (994021) Airframe	AD 2015-23-09 Zodiac Aerotechnics Flightcrew Oxygen Mask Regulators (Part 1 - Inspect)	HRS AFL MOS MSC		 72.5		--	 31 Oct 2016			0 0
Notes: N/A DUE TO P/N AND S/N.										
FAA 2015-23-09 PARA (I) (994022) Airframe	AD 2015-23-09 Zodiac Aerotechnics Flightcrew Oxygen Mask Regulators (Part 2 - Replace)	HRS AFL MOS MSC		2610.4 1078 81.5		--	2920 1521 31 Jan 2016			0 0
Notes: N/A DUE TO P/N AND S/N.										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
FAA 2016-11-20 (994026) Airframe	AD 2016-11-20 - B/E Aerospace Pbe P/N 119003-11	HRS AFL MOS MSC		2364.8 953 71.9		-	3165.6 1646 19 Nov 2016			0 0
FAA 2016-18-11 PARA (G) (994029) Airframe	AD 2016-18-11 Gulfstream Aerospace Corporation (MLG End CAP)	HRS AFL DATE		5530.4		9500**	0	9500		0 0
FAA 2017-09-09[U] Airframe	Zodiac Seats California Llc	HRS AFL MOS MSC [End Of Month Item]		60.8		-	22 Oct 2017			0 0
FAA 2017-11-11[U] Airframe	Navworx ADS-B Transceiver Units	HRS AFL MOS MSC [End Of Month Item]		60.8		-	22 Oct 2017			0 0
FAA 2017-16-01[U] Airframe	Ameriking CORP. ELT	HRS AFL MOS MSC [End Of Month Item]		60.8		-	22 Oct 2017			0 0
FAA 2017-18-12 PARA (I) & (J) (994042) Airframe	AD 2017-18-12 B/E Aerospace	HRS AFL MOS MSC		1769.5 717 54.8		-	3760.9 1882 23 Apr 2018			0 0
FAA 2017-19-05[U] Airframe	Siemens Smoke Detectors	HRS AFL MOS MSC [End Of Month Item]				-				0 0
FAA 2017-20-08 (994045) Airframe	AD 2017-20-08 - Gulfstream Aerospace - Gulfstream Afm Supplement Incorporation	HRS AFL MOS MSC		1936.8 780 59.5		-	3593.6 1819 02 Dec 2017			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
FAA 2017-22-14U Airframe	Rockwell Collins, Inc. Tssa- 4100 Field Loadable Software	HRS AFL MOS MSC [End Of Month Item]				- -				0 0
FAA 2017-26-05 (994053) Airframe	AD 2017-26-05 Gulfstream Aerospace Corporation: Amendment 39-19136	HRS AFL MOS MSC	1905.6 769 58.1			- -	3624.8 1830 12 Jan 2018			0 0
Notes: N/A BY S/N (4123 NOT AFFECTED), JANIS BLUMER										
FAA 2018-03-04U Airframe	Rosement Aerospace Model 851 Ak Pitot Probes	HRS AFL MOS MSC [End Of Month Item]				- -				0 0
FAA 2018-09-04 (994064) Airframe	AD 2018-09-04 Gulfstream Aerospace Corporation: Amendment 39-19260; Docket No. FAA-2017-1163; Product Identifier 2017-Ce-041-AD.	HRS AFL MOS MSC	51.6			- -	27 Jul 2018			0 0
Notes: N/A BY MOD STATUS (NO REPAIR ACCORDING DRAWING SE05732102), JANIS BLUMER										
FAA 2018-16-13U Airframe	Zodiac Seats	HRS AFL MOS MSC [End Of Month Item]				- -				0 0
FAA 2018-21-14 (994070) Airframe	AD 2018-21-14 Zodiac Aerotechnics (Formerly Intertechnique) - Oxygen Mask Regulator Harness Inflation Hose - Identification / Replacement	HRS AFL MOS MSC	882.2 304 24.5			- -	4648.2 2295 02 Nov 2020			0 0
FAA 2018-23-12U Airframe	Zodiac Aero Evac Systems	HRS AFL MOS MSC [End Of Month Item]				- -				0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
FAA 2019-01-02U Airframe	Aspen Avionics ADS-B	HRS AFL MOS MSC [End Of Month Item]				- -				0 0
FAA 2019-07-03U Airframe	Jasc Code 2500 Cabin Equipment/Furnishings Zodiac Seats France	HRS AFL MOS MSC [End Of Month Item]				- -				0 0
FAA 2019-07-10U Airframe	Northrop Grumman / Ahrs	HRS AFL MOS MSC [End Of Month Item]				- -				0 0
FAA 2019-08-01U Airframe	Recaro Aircraft Seating Gmbh & CO. Kg - Passenger Compartment Equipment	HRS AFL MOS MSC [End Of Month Item]	41.8			- -	23 May 2019			0 0
FAA 2019-13-03U Airframe	Trig Avionics Ltd - Transponder	HRS AFL MOS MSC [End Of Month Item]				- -				0 0
FAA 2019-14-05U Airframe	B/E Aerospace Fischer Gmbh / Common Seats	HRS AFL MOS MSC [End Of Month Item]				- -				0 0
FAA 2019-15-10U Airframe	Joint Aircraft System Component (Jasc) Code 2561, Life Jacket	HRS AFL MOS MSC [End Of Month Item]				- -				0 0
FAA 2019-20-03U Airframe	ATA 46 Information Systems (Lone STAR Aviation, CORP.	HRS AFL MOS MSC [End Of Month Item]				- -				0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
FAA 2019-20-08 (994075) Airframe	AD 2019-20-08 Incorporation of the Airworthiness Limitations Specified In Gulfstream Document No. Giv-Ger-0008	HRS AFL MOS MSC		882.3 304 30.6		-	4648.1 2295 28 Apr 2020			0 0
FAA 2019-21-06[U] Airframe	Ipeco Holding Ltd - Flight Crew Seats (Replaces AD FAA AD 2017-22-02 / EASA AD 2018-0262)	HRS AFL MOS MSC [End Of Month Item]		24.8		-	21 Oct 2020			0 0
FAA 2019-21-09[U] Airframe	AD 2019-21-09 Avionteriors S.P.A.	HRS AFL MOS MSC		26.4		-	03 Sep 2020			0 0
FAA 2020-08-02 Airframe	Appliance AD - Navigation - Thales AVS France SAS - Global Navigation Satellite System - Operational Limitations (Mandatory)	HRS AFL MOS MSC				-				0 0
FAA 2020-09-02 Airframe	Appliance AD - Equipment/Furnishings - Anjou Aeronautique - Restraint Systems Rotary Buckle Sub Assembly - Replacement (Mandatory)	HRS AFL MOS MSC				-				0 0
FAA 2020-09-02 PARA (G)(1) Airframe	Inspect Each Restraint System for Proper Release of the Straps from the Restraint System and, Depending IF the Straps Release, Placard the Seat as Inoperative and Remove and Replace the Rotary Buckle Sub-Assembly (for the Restraint Systems Listed In the Effectivity of Anjou Aero Sb 358SB-14-101 R01, Except for S/Ns 1038-1048 (Inclusive), 1050-1055 (Inclusive), and 1062-1073 (Inclusive)) (Mandatory)	HRS AFL MOS								0 0

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
FAA 2020-09-02 PARA (G)(2) Airframe	Inspect Each Restraint System for Proper Release of the Straps from the Restraint System and, Depending IF the Straps Release, Placard the Seat as Inoperative and Remove and Replace the Restraint System from Service (for Restraint Systems, P/N 358XX-Xxx-Yy-Zzz (Where 358XX-Xxx-Yy-Zzz Can Be Any Combination of Numbers and/or Letters), Having S/Ns 738-1619 (Inclusive)) (Mandatory)		HRS AFL MOS								0 0
FAA 2020-09-02 PARA (H) Airframe	Do Not Install on Any Aircraft an Anjou Aeronautique Restraint System, P/N 358XX-Xxx-Yy-Zzz, Having S/Ns 738-1619 (Inclusive), Even IF the Restraint System Is Labeled In Compliance With Anjou Aero Sb 358SB-14-101 R01, Dated December 12, 2014 (Mandatory)		HRS AFL MOS MSC				- -				0 0
FAA 2020-10-05 (992099) Airframe	Navigation - Rockwell Collins Pro Line 4 and Pro Line 21 Flight Management Systems (Mandatory)		HRS AFL MOS								0 0
FAA 2020-16-08 Airframe	Appliance AD - Aspen Avionics, Inc. - EFD1000 Flight Display Systems - Airplane Flight Manual - Revision (Mandatory)		HRS AFL MOS MSC				- -				0 0
FAA 2020-18-51 (992009) Airframe	Sandia Aerospace - Airplane Flight Manual - Section Limitations - Amendment (Mandatory)		HRS AFL MOS MSC				- -				0 0

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
Logbook Position	HW	SW									
	MM Ref										
	Ops Number(s)										
FAA 2020-18-51-E Airframe	Appliance/Emergency AD - Sandia Aerospace - Airplane Flight Manual - Section Limitations - Amendment (Mandatory)		HRS AFL MOS MSC				- -				0 0
FAA 2020-19-06 Airframe	Appliance AD - Propellers/Propulsors - Governor - Idler Gear Bearing "BA 59" - Replacement (Mandatory)		HRS AFL MOS MSC				- -				0 0
FAA 2020-21-02 Airframe	Appliance AD - FIRE Protection - Kidde Aerospace & Defense Cargo FIRE Extinguisher Halon Bottles - Replacement (Mandatory)		HRS AFL MOS MSC				- -				0 0
FAA 2020-21-02 PARA (H) & (I) Airframe	Do an Inspection to Determine the Part Number and Serial Number of the Cargo FIRE Extinguisher Halon Bottles Installed In the Cargo Compartment and Replace With A Serviceable Part as Required (Mandatory)		HRS AFL MOS MSC				- -				0 0
FAA 2020-21-02 PARA (J) Airframe	No Person May Install on Any Airplane an Affected Part as Identified In Paragraph (G)(3) of This AD unless that Part Has A Circled Letter “G” Stamped AT A Distance 8 of Approximately One Inch from the Left Edge of the Placard, Indicating that the Cargo FIRE Extinguisher Halon Bottle Has Been Tested and Refilled (Mandatory)		HRS AFL MOS MSC				- -				0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
FAA 2020-23-08 (992308) Engine	No. 1 Engine - Engine - LPC Rotor Blade Dry Film Lubrication (DFL) RE-Applications - Review / Replacement (Mandatory)	HRS ENC DATE MSC		882.2 304 709 d		-	4570.2 2246 07 Dec 2020			0 0
FAA 2020-23-08 (992308) Engine	No. 2 Engine - Engine - LPC Rotor Blade Dry Film Lubrication (DFL) RE-Applications - Review / Replacement (Mandatory)	HRS ENC DATE MSC		882.2 304 709 d		-	4570.2 2246 07 Dec 2020			0 0
FAA 2021-23-12 (992199) Airframe	Appliance AD - Indicating / Recording / Navigation - Radio (Radar) Altimeter - Afm Revision to Incorporate Limitations (Mandatory)	HRS AFL MOS MSC		381 133 10.4		-	5149.4 2466 03 Jan 2022			0 0
FAA 94-01-04 U (999954) Airframe Notes: N/A BY P/N	AD 94-01-04 Traffic Alert and Collision Avoidance System	HRS AFL MOS MSC		2610.4 1078 80.5		-	2920 1521 02 Mar 2016			0 0
FAA 94-01-05 U (999955) Airframe Notes: NA/ BY EXISTING SUFFIX	AD 94-01-05 Traffic Alert and Collision Avoidance System Ii Processors	HRS AFL MOS MSC		2610.4 1078 80.5		-	2920 1521 02 Mar 2016			0 0
FAA 98-24-27 U (999959) Airframe Notes: N/A BY P/N AND S/N	AD 98-24-27 Toilet FIRE Extinguishers	HRS AFL MOS MSC		171.5		-	31 Jul 2008			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
FAA 99-08-21 U (999960) Airframe	AD 99-08-21 Puritan-Bennett Passenger Oxygen Masks	HRS AFL MOS MSC		171.5		-	31 Jul 2008			0 0
Notes: N/A BY P/N AND S/N										
FAA 992520U (992520) Engine	No. 1 Engine - Lba- AD #D-2004-313R5 Lp Compressor Ice Panels	HRS ENC MOS MSC		5452.4 2550 174.6		-	0 0 28 Apr 2008			0 0
FAA 992521U (992521) Engine	No. 2 Engine - Lba- AD #D-2004-313R5 Lp Compressor Ice Panels	HRS ENC MOS MSC		5452.4 2550 174.6		-	0 0 28 Apr 2008			0 0
FAA 999950U (999950) Airframe	AD 99-08-01 Puritan Bennet Oxygen Masks	HRS AFL MOS		5530.4 2599 171.5			0 0 31 Jul 2008			0 0
Notes: N/A BY P/N AND S/N INSTALLED										
FAA 999951U (999951) Airframe	AD 2007-03-02 Rolls Royce Tay Lp Compressor Module	HRS AFL MOS		5530.4 2599 174.6			0 0 28 Apr 2008			0 0
Notes: N/A BY P/NS INSTALLED.										
FAA 999953U (999953) Airframe	AD 2014-15-01 Rockwell Collins MODE S Transponders Tdr-94 / Tdr-94D	HRS AFL MOS		2640.6 1094 89.3			2889.8 1505 06 Jun 2015			0 0
FAA 999956U (999956) Airframe	AD 2011-04-09 R1 - Oxygen	HRS AFL MOS		2610.4 1078 80			2920 1521 15 Mar 2016			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
FAA 999957U (999957) Airframe	AD 2011-04-09 - Oxygen	HRS AFL MOS		2610.4 1078 80.3			2920 1521 08 Mar 2016			0 0
Notes: PN: SUPERCEEDED BY AD 2012-11-09 SN: <NONE>. SUPERSEDED BY R1.										
FAA 999962U (999962) Engine	No. 1 Engine - AD 2007-03-02 Rolls Royce Tay Lp Compressor Module	HRS ENC MOS MSC		5452.4 2550 174.6		- -	0 0 28 Apr 2008			0 0
Notes: N/A BY P/NS INSTALLED.										
FAA 999963U (999963) Engine	No. 2 Engine - AD 2007-03-02 Rolls Royce Tay Lp Compressor Module	HRS ENC MOS MSC		5452.4 2550 174.6		- -	0 0 28 Apr 2008			0 0
Notes: N/A BY P/NS INSTALLED.										
FOCA HB-1994-079U Airframe	AD 94-01-05 Traffic Alert and Collision Avoidance System Ii Processors	HRS AFL MOS MSC [End Of Month Item]		 80.4		 -	 03 Mar 2016			0 0
FOCA HB-1996-343U Airframe	Lavatory MOD	HRS AFL MOS MSC [End Of Month Item]		 139.9		 -	 19 Mar 2011			0 0
FOCA HB-1997-078U Airframe	AD 94-01-04 Traffic Alert and Collision Avoidance System	HRS AFL MOS MSC [End Of Month Item]		 80.4		 -	 03 Mar 2016			0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
FOCA HB-1999-013[U]	Seat Belts - Aircraft Belts Inc.	HRS AFL MOS MSC		171.5		- -	31 Jul 2008			0 0
Airframe		[End Of Month Item]								
FOCA HB-1999-291[U]	Puritan Bennett Passenger Oxygen Mask	HRS AFL MOS MSC		171.5		- -	31 Jul 2008			0 0
Airframe		[End Of Month Item]								
FOCA HB-2005-379[U]	Adel Wiggins Floor Heater - Deactivation	HRS AFL MOS MSC		171.5		- -	31 Jul 2008			0 0
Airframe		[End Of Month Item]								
FOCA HB-2006-244[U]	Afm Procedure, Ckpt Displays Malfunction	HRS AFL MOS MSC		171.5		- -	31 Jul 2008			0 0
Airframe		[End Of Month Item]								
FOCA HB-2006-508[U]	Goodyear Aviation Tires	HRS AFL MOS MSC		171.5		- -	31 Jul 2008			0 0
Airframe		[End Of Month Item]								
FOCA HB-2006-509[U]	Honeywell RCZB30 & 85() Com Units & MODE S Transponders	HRS AFL MOS MSC		171.5		- -	31 Jul 2008			0 0
Airframe		[End Of Month Item]								
FOCA HB-2007-270[U]	Fwd Water Draon/Supplyvalves	HRS AFL MOS MSC		171.5		- -	31 Jul 2008			0 0
Airframe		[End Of Month Item]								

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
FOCA HB-2007-271U	Honeywell Int. / FMS Nz-2000	HRS								0
		AFL								0
		MOS		171.5			31 Jul 2008			
		MSC				-				
Airframe		[End Of Month Item]								
SIAC - Service Information/Bulletins										
231592U	Aircell Cabin Telecommunications Router Software Update	HRS		4593.3			937.1			0
		AFL		2210			389			0
		MOS		139.9			19 Mar 2011			
Airframe										
346026U	FMS Nav Data Update - Blue CD	HRS		2367			3163.4			0
		AFL		954			1645			0
		MOS		72.3			06 Nov 2016			
Airframe										
Notes: REFERENCE: G450 MAINTENANCE MANUAL 20-22-00 DATED FEBRUARY 29/16EXPIRATION DATE: 23 NOV. 2016										
9010001U	Cabin Interior STC - ST03579AT-D	HRS		5525.5			4.9			0
		AFL		2597			2			0
		MOS		171.5			01 Aug 2008			
		MSC				-				
Airframe										
Notes: REFERENCE ICA DOCUMENT GC42801A344 REV - FOR STC ST03579AT-D										
901022U	SDR Software Release MOD P (1.12.0).	HRS				0**				0
		AFL								0
		MOS								
Airframe										SERVICE
979201U	ASC 005A Placards and Markings (ATA 11) G450 Modifications	HRS		5525.5			4.9			0
		AFL		2597			2			0
		MOS		174.6			29 Apr 2008			
		MSC				-				
Airframe										
Notes: ACCOMPLISHED IN PRODUCTION ON 29 APRIL 2008 (MB)										
ACB007 (990070)	Acb 7 Modification-Tail Compartment Ladder	HRS		5419.4			111			0
		AFL		2568			31			0
		MOS		169.1			13 Oct 2008			
		MSC				-				
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
ACB008 (990080) Airframe	Acb 8 - Operational Limitations - Auxiliary Power Unit (APU)	HRS AFL MOS MSC		5264.1 2510 161.3		-	266.3 89 08 Jun 2009			0 0
ACB008A (990081) Airframe	Acb 8A Operational Limitations - Auxiliary Power Unit (APU)	HRS AFL MOS MSC		5217.2 2495 160.1		-	313.2 104 13 Jul 2009			0 0
Notes: ACCOMPLISHED ACB08A										
ACB009 (990090) Airframe	Acb 9 - Operational Limitations - Auxiliary Power Unit (APU) Enclosure With Thermal Barrier Coating	HRS AFL MOS		4204.3 1973 131.1			1326.1 626 12 Dec 2011			0 0
Notes: AFM SUPPLEMENT WAS NEVER REMOVED AFTER APU ENCLOSURE MOD. PHYSICAL INSPECTED AND FOUND STILL INSERTED. TAC										
ACB010 (990100) Airframe	Acb 10 Operational Limitations - Auxiliary Power Unit (APU) Enclosure With Thermal Barrier Coating - Expanded Effectivity	HRS AFL MOS MSC		1948.9 786 59.9		-	3581.5 1813 18 Nov 2017			0 0
Notes: N/A BY S/N										
ACB011 (990110) Airframe	Acb 11 Operational Instructions - Flap / Stab Electronic Control Unit - System Power - on SELF Test	HRS AFL MOS MSC		3653.4 1674 119.4		-	1877 925 05 Dec 2012			0 0
ASC001B (970013) Airframe	ASC 1B Digital Flight Data Recorder-Upgrade	HRS AFL MOS MSC		5525.5 2597 171.4		-	4.9 2 05 Aug 2008			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
ASC001C (970014) Airframe	ASC 001C Digital Flight Data Recorder System Upgrade	HRS AFL MOS MSC		3946.4 1833 125.2		-	1584 766 11 Jun 2012			0 0
Notes: PREVIOUSLY C/W ASC 001B.										
ASC001D (970015) Airframe	ASC 001D Digital Flight Data Recorder System Upgrade (88 Parameters) (Incorporation Temporarily Suspended)	HRS AFL MOS MSC		3922 1818 124.9		-	1608.4 781 18 Jun 2012			0 0
Notes: PREVIOUSLY C/W ASC 001B.										
ASC002A PART I (970021) Airframe	ASC 2A (Part 1) EASA / Jaa Cert - BASIC Requirements	HRS AFL MOS MSC		5525.5 2597 171.6		-	4.9 2 28 Jul 2008			0 0
Notes: ASC002 DE-MODIFIED WITH GULFSTREAM WO SC17300 06/06/2015										
ASC002A PART II (970022) Airframe	ASC 2A (Part 2) EASA / Jaa Cert - BASIC Requirements	HRS AFL MOS MSC		5525.5 2597 171.6		-	4.9 2 28 Jul 2008			0 0
Notes: ASC002 DE-MODIFIED WITH GULFSTREAM WO SC17300 06/06/2015										
ASC007A (970071) Airframe	ASC 007A - Maximum Landing Gross Weight - 58,500 Pounds Placard Installation	HRS AFL MOS MSC		5525.5 2597 171.4		-	4.9 2 05 Aug 2008			0 0
ASC007B (970072) Airframe	ASC 007B Maximum Landing Gross Weight - 58,500 Pounds - Category C - Provisions	HRS AFL MOS MSC		3963.7 1844 125.4		-	1566.7 755 05 Jun 2012			0 0
Notes: SUPERSEDED BY ASC 007C										

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ASC007C	ASC 007C Maximum Landing Gross Weight - 58,500 Pounds - Category C - Provisions		HRS		4003			1527.4			0
			AFL		1871			728			0
			MOS		126.1			14 May 2012			
(970073)			MSC				-				
Airframe											
ASC007D	ASC 7D Maximum Landing Gross Weight - 58,500 Pounds - Category C - Provisions		HRS		5530.4			0			0
			AFL		2599			0			0
			MOS		99.3			07 Aug 2014			
(970074)			MSC				-				
Airframe											
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
ASC007E	ASC 7E Placards and Markings - Mlgw 58,500 Pounds - Category C Provisions		HRS		1961.9			3568.5			0
			AFL		791			1808			0
			MOS		126.1			14 May 2012			
(970075)			MSC				-				
Airframe											
Notes: ASC7C C/W ON 14.05.214, REV. D IN P/C/W											
ASC008	ASC 8 Max Zero Fuel Gross Wei		HRS		5525.5			4.9			0
			AFL		2597			2			0
(970080)			MOS		174			16 May 2008			
Airframe			MSC				-				
ASC008A	ASC 008A Maximum Zero Fuel Gross Weight 48,000 Pounds - Placard Installation		HRS		2698.6			2831.8			0
			AFL		1124			1475			0
			MOS		92.2			10 Mar 2015			
(970081)			MSC				-				
Airframe											
Notes: PREVIOUSLY COMPLIED WITH BY ORIGINAL ASC-008 @ 16.05.2008											
ASC008B	ASC 008B Maximum Zero Fuel Gross Weight 48,000 Pounds - Placard Installation		HRS		1905.6			3624.8			0
			AFL		769			1830			0
			MOS		58.6			27 Dec 2017			
(970082)			MSC				-				
Airframe											
Notes: PREVIOUSLY COMPLIED WITH BY ORIGINAL ASC-008 @ 16.05.2008											

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
ASC016 (970160) Airframe	ASC 16 Maximum Take-Off Gross Weight (Mtogw) Increase	HRS AFL MOS MSC		5525.5 2597 171.6		- -	4.9 2 28 Jul 2008			0 0
ASC016A (970161) Airframe	ASC 016A Maximum Takeoff Gross Weight (Mtogw) Increase	HRS AFL MOS MSC		3804 1763 122.8		- -	1726.4 836 22 Aug 2012			0 0
ASC020 (970200) Airframe	ASC 20 Category Ii Annunciation-Activation	HRS AFL MOS MSC		4852.8 2401 148.5		- -	677.6 198 30 Jun 2010			0 0
ASC021 (970210) Airframe	ASC 21 Lightning Sensor System Installation	HRS AFL MOS MSC		5530.4 2599 87.4		- -	0 0 03 Aug 2015			0 0
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.										
ASC021 AM1 (970211) Airframe	ASC 21 AM1 Lightning Sensor System Installation	HRS AFL MOS MSC		5530.4 2599 87.4		- -	0 0 03 Aug 2015			0 0
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.										
ASC021A (970212) Airframe	ASC 21A - Lightning Sensor System Installation	HRS AFL DATE MSC		5530.4 2599		- -	0 0			0 0
ASC021B (970213) Airframe	Navigation (ATA 34) - Lightning Sensor System (Lss) - Installation, Aircraft Service Change (Optional)	HRS AFL DATE MSC				- -				0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
ASC025 (970250) Airframe	ASC 25 Cmf-ARINC Direct-Datalink Service Provider	HRS AFL MOS MSC		5530.4 2599 128.2		 -	0 0 09 Mar 2012			0 0
ASC025A (970251) Airframe	ASC 25A Planeview Communication Management Function (Cmf) - ARINC Direct - Datalink Service Provider	HRS AFL DATE MSC		5530.4 2599		 -	0 0			0 0
ASC037 (970370) Airframe	ASC 37 Synthetic Vision-Primary Flight Display (Sv-Pfd)	HRS AFL MOS MSC		3922 1818 124.9		 -	1608.4 781 18 Jun 2012			0 0
Notes: SUPERSEDED BY ASC 37B INSTALLED UNDER A TRAIL BASIS, NO LONGER VALID										
ASC037 AM1 (970371) Airframe	ASC 37 AM1- Synthetic Vision Primary Flight Display (Sv-Pf)	HRS AFL MOS MSC		3922 1818 124.9		 -	1608.4 781 18 Jun 2012			0 0
Notes: SUPERSEDED BY ASC 37B INSTALLED UNDER A TRAIL BASIS, NO LONGER VALID										
ASC037A (970372) Airframe	ASC 37A Synthetic Vision - Primary Flight Display (Sv-Pfd) Installation	HRS AFL MOS MSC		3922 1818 124.9		 -	1608.4 781 18 Jun 2012			0 0
Notes: SUPERSEDED BY ASC 37B INSTALLED UNDER A TRAIL BASIS, NO LONGER VALID										
ASC037A AM1 (970373) Airframe	ASC 37A AM1 Synthetic Vision - Primary Flight Display (Sv-Pfd) Installation	HRS AFL MOS MSC		3922 1818 124.9		 -	1608.4 781 18 Jun 2012			0 0
Notes: SUPERSEDED BY ASC 37B INSTALLED UNDER A TRAIL BASIS, NO LONGER VALID										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
ASC037B (970374) Airframe	ASC 37B Synthetic Vision - Primary Flight Display (Sv-Pfd) Installation	HRS AFL MOS MSC		866.2 299 22.5		- -	4664.2 2300 31 Dec 2020			0 0
Notes: INSTALLED UNDER A TRAIL BASIS, NO LONGER VALID										
ASC040A (970401) Airframe	ASC 40A Runway Awareness Advisory-Install	HRS AFL MOS MSC		4593.3 2210 139.9		- -	937.1 389 19 Mar 2011			0 0
ASC045 (970450) Airframe	ASC 45 Engine Electronic Controller - T5.1 Software Upgrade	HRS AFL MOS MSC		5214.6 2493 158.4		- -	315.8 106 03 Sep 2009			0 0
ASC046 (970460) Airframe	ASC 46 Micro Quick Access Recorder	HRS AFL MOS MSC		5525.5 2597 171.5		- -	4.9 2 31 Jul 2008			0 0
ASC047 (970470) Airframe	ASC 47 Vacuum Waste System - Heater Installation	HRS AFL MOS MSC		4882.7 2421 149.6		- -	647.7 178 27 May 2010			0 0
ASC047A (970471) Airframe	ASC 47A Vacuum Waste System - Heater Installation	HRS AFL MOS MSC		3922 1818 124.9		- -	1608.4 781 18 Jun 2012			0 0
Notes: PREVIOUSLY C/W ASC 047										
ASC048 (970480) Airframe	ASC 48 Medeco Door Locks Installation	HRS AFL DATE MSC		5530.4 2599		- -	0 0			0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
ASC049 (970490) Airframe	ASC 49 Nose Gear Uplock Hook Spring Replacement	HRS AFL MOS MSC		5517.4 2595 171.4		- -	13 4 05 Aug 2008			0 0
ASC049A (970491) Airframe	ASC 49A Nose Gear Uplock Hook Spring Replacement	HRS AFL MOS MSC		5411.4 2562 169.4		- -	119 37 05 Oct 2008			0 0
Notes: C/W IN GULFSTREAM SAVANNAH GEORGIA I.A.W CB 79										
ASC050 (970500) Airframe	ASC 50 Dual Brake Metering Valve Replacement	HRS AFL MOS MSC		5530.4 2599 160.1		- -	0 0 13 Jul 2009			0 0
ASC050A (970501) Airframe	ASC 50A Dual Brake Metering Valve Replacement	HRS AFL MOS MSC		4882.7 2421 149.6		- -	647.7 178 29 May 2010			0 0
Notes: DUE DATE SET PER CUSTOMER REQUEST.										
ASC055 (970550) Airframe	ASC 55 Stall Barrier System - Angle of Attack (AOA) Transducer - Replacement	HRS AFL MOS MSC		3963.7 1844 125.4		- -	1566.7 755 05 Jun 2012			0 0
Notes: SUPERSEDED BY ASC 55A										
ASC055A (970551) Airframe	ASC 55A Stall Barrier System - Angle of Attack (AOA) Transducer - Replacement	HRS AFL DATE MSC		5530.4 2599		- -	0 0			0 0
ASC057 (970570) Airframe	ASC 57 Tail Compartment Ladder - Hinge Pin and Placard	HRS AFL MOS MSC		5530.4 2599 164.6		- -	0 0 27 Feb 2009			0 0

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ASC057A	ASC 57A Tail Compartment Ladder - Hinge Pin and Placard		HRS AFL MOS MSC		5291.5 2524 164.1		-	238.9 75 12 Mar 2009			0 0
(970571)											
Airframe											
ASC057A AM1	ASC 57A AM1 Tail Compartment Ladder - Hinge Pin and Placard		HRS AFL MOS MSC		3963.7 1844 125.4		-	1566.7 755 05 Jun 2012			0 0
(970572)											
Airframe											
Notes: PREVIOUSLY COMPLIED WITH @ JET AVIATION W/O 52662 12 MARCH 2009											
ASC058	ASC 58 Planeview Avionics Enhancement (Cert Fox)		HRS AFL DATE MSC		5530.4 2599		-	0 0			0 0
(970580)											
Airframe											
ASC058A	ASC 58A Planeview Avionics Enhancement (Cert Fox)		HRS AFL MOS MSC		4593.3 2210 139.9		-	937.1 389 19 Mar 2011			0 0
(970581)											
Airframe											
ASC058B	ASC 58B Planeview Avionics Enhancement (Cert Fox)		HRS AFL MOS MSC		3963.7 1844 125.4		-	1566.7 755 05 Jun 2012			0 0
(970582)											
Airframe											
Notes: SUPERSEDED BY ASC 58C											
ASC058C	ASC 58C Planeview Avionics Enhancement		HRS AFL MOS MSC		4003 1871 126.2		-	1527.4 728 11 May 2012			0 0
(970583)											
Airframe											
ASC059	ASC 59 Enhanced Navigation		HRS AFL MOS MSC		3946.4 1833 125.2		-	1584 766 11 Jun 2012			0 0
(970590)											
Airframe											
Notes: SUPERSEDED BY ASC059											

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
ASC059A (970591) Airframe	ASC 59A Enhanced Navigation	HRS AFL MOS MSC		4593.3 2210 139.9		- - - -	937.1 389 19 Mar 2011			0 0
ASC059B (970592) Airframe	ASC 59B Enhanced Navigation	HRS AFL MOS MSC		3946.4 1833 125.1		- - - -	1584 766 14 Jun 2012			0 0
Notes: PREVIOUSLY C/W										
ASC059C (970593) Airframe	ASC 59C Enhanced Navigation	HRS AFL MOS MSC		5530.4 2599 72.9		- - - -	0 0 19 Oct 2016			0 0
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.										
ASC059D (970594) Airframe	ASC 59D Enhanced Navigation	HRS AFL MOS MSC		1553.9 610 46.1		- - - -	3976.5 1989 12 Jan 2019			0 0
Notes: ASC 059 P/C/W ON 11. JUN 2012										
ASC060 (970600) Airframe	ASC 60 Xm Weather Installation	HRS AFL DATE MSC		5530.4 2599		- - - -	0 0			0 0
ASC060A (970601) Airframe	ASC 60A Xm Weather Installation	HRS AFL MOS MSC		5530.4 2599 58.9		- - - -	0 0 18 Dec 2017			0 0
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.										
ASC060B (970602) Airframe	ASC 60B Xm Weather Installation	HRS AFL DATE MSC		5530.4 2599		- - - -	0 0			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
ASC060B-CN (970602) Airframe	ASC060B-Cn - Indicating / Recording - Xm Weather Installation (New Installations Discontinued See All Mol-22 -0016), Aircraft Service Change (Cancelled)	HRS AFL DATE MSC				- -				0 0
ASC061 (970610) Airframe	ASC 61 Canadian Certification Requirements	HRS AFL DATE MSC	5530.4 2599			- -	0 0			0 0
ASC063 (970630) Airframe	ASC 63 Flap and Stabilizer Electronic Control Unit (Fsecu) - Software Upgrade	HRS AFL MOS MSC	4882.7 2421 149.5			- - -	647.7 178 01 Jun 2010			0 0
ASC064 (970640) Airframe	ASC 064 Stage 4 Noise Standards - Certification	HRS AFL MOS MSC	3803.9 1763 123			- - -	1726.5 836 15 Aug 2012			0 0
ASC064A (970641) Airframe	ASC 064A Stage 4 Noise Standards - Certification	HRS AFL MOS MSC	958.6 365 32			- - -	4571.8 2234 16 Mar 2020			0 0
ASC065 (970650) Airframe	ASC 65 Auxiliary Power Unit (APU) Enclosure - Thermal Barrier Installation	HRS AFL MOS MSC	4593.3 2210 139.9			- - -	937.1 389 19 Mar 2011			0 0
ASC065 AM1 (970651) Airframe	ASC 065 AM1 Auxiliary Power Unit (APU) Enclosure - Thermal Barrier Installation	HRS AFL MOS MSC	4593.3 2210 139.9			- - -	937.1 389 19 Mar 2011			0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
ASC065A	ASC 065 A Auxiliary Power Unit (APU) Enclosure - Thermal Barrier Installation	HRS		3963.7			1566.7			0
		AFL		1844			755			0
		MOS		125.4			05 Jun 2012			
(970652)		MSC				-				
Airframe										
Notes: ASC 065 AM1 COMPLIED WITH, REV A NO FURTHER ACTION REQUIRED. SJT TAC										
ASC066	ASC 66 Communication Management Function (Cmf) - SATCOM Direct - Datalink Service Provider	HRS		4138.4			1392			0
		AFL		1939			660			0
		MOS		129.8			22 Jan 2012			
(970660)		MSC				-				
Airframe										
ASC067	ASC 67 Landing Gear Door Close - Restrictor Bypass Installation	HRS		4882.7			647.7			0
		AFL		2421			178			0
		MOS		149.6			28 May 2010			
(970670)		MSC				-				
Airframe										
ASC067A	ASC 67A Landing Gear Door Close - Restrictor Bypass Installation	HRS		5530.4			0			0
		AFL		2599			0			0
		DATE								
(970671)		MSC				-				
Airframe										
ASC069	ASC 069 Main Battery Power - Nickel Cadmium (Nicad) Battery - Installation	HRS		5530.4			0			0
		AFL		2599			0			0
		DATE								
(970690)		MSC				-				
Airframe										
ASC070B	ASC 070B - Planeview Avionics Enhancement	HRS		2698.6			2831.8			0
		AFL		1124			1475			0
(970702)		MOS		92.2			10 Mar 2015			
Airframe		MSC				-				
Notes: SUPERSEDED BY ASC-081/ASC-910										
ASC071	ASC 071 - CPDLC - FANS 1/A	HRS		2698.6			2831.8			0
		AFL		1124			1475			0
(970710)		MOS		92.2			10 Mar 2015			
Airframe		MSC				-				
Notes: PREVIOUSLY COMPLIED WITH BY ASC-059 @ 19.03.2011										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
ASC072B (970722) Airframe	ASC 072B - Data Link Recording	HRS AFL DATE MSC		5530.4 2599		--	0 0			0 0
ASC073 (970730) Airframe	ASC 73 FS 793 Bulkhead CAP Angle - Replacement	HRS AFL DATE MSC		5530.4 2599		--	0 0			0 0
ASC076 (970760) Airframe	ASC-076 - Engine Electronic Controller - T5.2 Software Upgrade	HRS AFL MOS MSC		2640.5 1094 89.6		--	2889.9 1505 29 May 2015			0 0
ASC077 (970770) Airframe	ASC 077 TCAS 7.1 Installation	HRS AFL MOS MSC		3246.2 1432 107.9		--	2284.2 1167 18 Nov 2013			0 0
ASC079 (970790) Airframe	ASC 079 - Automatic Dependent Surveillance - Broadcast (ADS-B) Out Installation	HRS AFL MOS MSC		3246.1 1432 107.6		--	2284.3 1167 29 Nov 2013			0 0
ASC079A (970791) Airframe Notes: PREVIOUSLY COMPLIED WITH BY ORIGINAL ASC-079 @ 29.11.2013	ASC 79A - Automatic Dependent Surveillance - Broadcast (ADS-B) Out Installation	HRS AFL MOS MSC		2698.6 1124 92.2		--	2831.8 1475 10 Mar 2015			0 0
ASC079B (970792) Airframe Notes: PREVIOUSLY COMPLIED WITH BY ORIGINAL ASC-079 @ 29.11.2013	ASC 79B - Automatic Dependent Surveillance - Broadcast (ADS-B) Out Installation	HRS AFL MOS MSC		958.6 365 32		--	4571.8 2234 16 Mar 2020			0 0

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
Logbook Position	HW	SW									
	MM Ref										
	Ops Number(s)										
ASC080	ASC 80 - Low Pressure Cooling AIR Outlet (Lpcao) - Seal Replacment		HRS AFL MOS MSC		2793.5 1211 95.3		-	2736.9 1388 08 Dec 2014			0 0
(970800) Airframe											
ASC081	ASC 081 - Planeview Avionics Enhancement		HRS AFL MOS MSC		3246.2 1432 107.6		-	2284.2 1167 28 Nov 2013			0 0
(970810) Airframe											
ASC082	ASC 82 Bleed AIR and AIR Conditioning Controllers - Upgrade		HRS AFL DATE MSC		5530.4 2599		-	0 0			0 0
(970820) Airframe											
ASC083	ASC 083 - APU Enclosure - Non-Compliant Sealant - Modification		HRS AFL DATE MSC		5530.4 2599		-	0 0			0 0
(970830) Airframe											
ASC084	ASC 084 - Mandates Package (CPDLC / ADS-B Out)		HRS AFL MOS MSC		5530.4 2599 99.6		-	0 0 29 Jul 2014			0 0
(970840) Airframe											
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
ASC084A	ASC 84A - Communication / Navigation (ATA 23 / 34) Mandates Package (CPDLC / ADS-B Out)		HRS AFL DATE MSC		5530.4 2599		-	0 0			0 0
(970841) Airframe											
ASC085	ASC 085 Nacelles and Pylons (ATA 54) Aft Pylon Rib Assembly - Drainage Rework		HRS AFL MOS MSC		3246.1 1432 107.9		-	2284.3 1167 19 Nov 2013			0 0
(970850) Airframe											

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
ASC086 (970860) Airframe	ASC 86 - Flap and Stabilizer Electronic Control Unit (Fsecu) - Software Upgrade	HRS AFL MOS MSC		2640.5 1094 89.6		-	2889.9 1505 29 May 2015			0 0
ASC088 (970880) Airframe	ASC 88 Cockpit Portable FIRE Extinguisher - Relocation	HRS AFL MOS MSC		5530.4 2599 109.5		-	0 0 02 Oct 2013			0 0
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.										
ASC088A PART I (970881) Airframe	ASC 88A (Part 1) Cockpit Portable FIRE Extinguisher / Pilot Seat Track Stop - Relocation	HRS AFL DATE MSC		5530.4 2599		-	0 0			0 0
ASC088A PART II (970882) Airframe	ASC 88A (Part 2) Cockpit Portable FIRE Extinguisher / Pilot Seat Track Stop - Relocation	HRS AFL MOS MSC		958.6 365 32		-	4571.8 2234 16 Mar 2020			0 0
Notes: N/A by S/N - RB										
ASC089 (970890) Airframe	ASC 89 Elevator Hardover Prevention System (Hops) - Improvement	HRS AFL MOS MSC		3021.1 1338 102.2		-	2509.3 1261 09 May 2014			0 0
ASC090 (970900) Airframe	ASC 90 - Planeview Avionics Enhancement	HRS AFL MOS MSC		5530.4 2599 97.9		-	0 0 18 Sep 2014			0 0
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.										
ASC090A (970901) Airframe	ASC 90A - Planeview Avionics Enhancement	HRS AFL MOS MSC		2640.5 1094 89.4		-	2889.9 1505 04 Jun 2015			0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
ASC094	ASC 094 - Nose Landing Gear (NLG) Harness - Installation	HRS		5530.4			0			0
		AFL		2599			0			0
		MOS		86			17 Sep 2015			
(970940)		MSC				-				
Airframe										
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.										
ASC094A	ASC 94A Nose Landing Gear (NLG) Harness - Installation	HRS		5530.4			0			0
		AFL		2599			0			0
(970941)		MOS		76.5			01 Jul 2016			
Airframe		MSC				-				
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.										
ASC094B	ASC 094B Nose Landing Gear (NLG) Harness - Installation	HRS		2367			3163.4			0
		AFL		954			1645			0
		MOS		72.6			27 Oct 2016			
(970942)		MSC				-				
Airframe										
Notes: TORQUE WRENCH # 554587 DUE CAL 07/17										
ASC094C	ASC 094C Nose Landing Gear (NLG) Harness - Installation	HRS		1764			3766.4			0
		AFL		716			1883			0
		MOS		54.1			14 May 2018			
(970943)		MSC				-				
Airframe										
Notes: ASC094 REV. B P/C/W ON 27 OCT 2016, REF CODE 970942 (MB)										
ASC095	ASC 95 Baggage Door Striker Plates - Replacement	HRS		5530.4			0			0
		AFL		2599			0			0
(970950)		DATE								
Airframe		MSC				-				
ASC097	ASC 97 - Integrated Drive Generator (Idg) Feeder Cable Clamp	HRS		2793.5			2736.9			0
		AFL		1211			1388			0
		MOS		95.3			08 Dec 2014			
(970970)		MSC				-				
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
ASC099 (970990) Airframe	ASC 099 Planeview Avionics Enhancement	HRS AFL MOS MSC		2367 954 73		--	3163.4 1645 16 Oct 2016			0 0
Notes: COMPLY WITH ASC99										
ASC099A (970991) Airframe	ASC 099A Planeview Avionics Enhancement	HRS AFL MOS MSC		5530.4 2599 42.1		--	0 0 14 May 2019			0 0
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.										
ASC099B (970992) Airframe	ASC 099B Planeview Avionics Enhancement	HRS AFL DATE MSC		5530.4 2599		--	0 0			0 0
ASC099C (970993) Airframe	ASC 099C Planeview Avionics Enhancement	HRS AFL MOS MSC		882.2 304 23.3		--	4648.2 2295 07 Dec 2020			0 0
ASC101 (971010) Airframe	ASC 101 Cargo Lights Replacement	HRS AFL DATE MSC		5530.4 2599		--	0 0			0 0
ASC102 (971020) Airframe	ASC 102 Led Navigation and Anticollision	HRS AFL DATE MSC		5530.4 2599		--	0 0			0 0
ASC103 (971030) Airframe	ASC 103 Flashlights - Replacement	HRS AFL MOS MSC		5530.4 2599 52.8		--	0 0 22 Jun 2018			0 0
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
ASC103A (971031) Airframe	ASC 103A Flashlights - Replacement	HRS AFL DATE MSC		5530.4 2599		-	0 0			0 0
ASC103B (971032) Airframe	Equipment and Furnishings (ATA 25) - Flashlights - Replacement, Aircraft Service Change (Optional)	HRS AFL DATE MSC				-				0 0
ASC104 (971040) Airframe	ASC 104 Junction Panel Relay Obsolescence Modification	HRS AFL MOS MSC		5530.4 2599 48.7		-	0 0 26 Oct 2018			0 0
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.										
ASC104A (971041) Airframe	ASC 104A Junction Panel Relay Obsolescence Modification	HRS AFL DATE MSC		5530.4 2599		-	0 0			0 0
ASC106 (971060) Airframe	ASC 106 8.8 KHZ Underwater Acoustic Beacon (Uab) Installation	HRS AFL DATE MSC		5530.4 2599		-	0 0			0 0
ASC106A PART 1 (971061) Airframe	ASC106A Part 1 - Equipment and Furnishings - 8.8 KHZ Underwater Acoustic Beacon (Uab) Installation - Modification Instructions (-1 Kit, Aft Equipment Bay Installation), Aircraft Service Change (Optional)	HRS AFL DATE MSC				-				0 0

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ASC106A PART 2	ASC106A Part 2 - Equipment and Furnishings - 8.8 KHZ Underwater Acoustic Beacon (Uab) Installation - Modification Instructions (-2 Kit, Baggage Compartment Installation), Aircraft Service Change (Optional)		HRS AFL DATE MSC				- -				0 0
(971062)											
Airframe											
ASC107	ASC 107 Auxiliary Hydraulic Pump - Grounding Installation		HRS AFL MOS MSC		1416.9 561 42.7		- -	4113.5 2038 26 Apr 2019			0 0
(971070)											
Airframe											
ASC108	Indicating / Recording (ATA 31) - High-Speed LAN Implementation, Aircraft Service Change (Optional)		HRS AFL DATE MSC				- -				0 0
(971080)											
Airframe											
ASC109	ASC 109 Wing to Body Fairings Av-Dec Gasket Installation		HRS AFL DATE MSC		5530.4 2599		- -	0 0			0 0
(971090)											
Airframe											
ASC908	ASC 908 Planeview Master Operating System Software Update (Cert Fox)		HRS AFL MOS MSC		3963.7 1844 125.4		- -	1566.7 755 05 Jun 2012			0 0
(979080)											
Airframe											
Notes: SUPERSEDED BY ASC 908A											
ASC908A	ASC 908A Planeview Master Operating System Software Update (Cert Fox)		HRS AFL MOS MSC		4593.3 2210 139.9		- -	937.1 389 19 Mar 2011			0 0
(979081)											
Airframe											

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
ASC908B	ASC 908B Planeview Master Operating System Software Update (Cert Fox)	HRS AFL MOS		3963.7 1844 125.4			1566.7 755 05 Jun 2012			0 0
(979082)		MSC				-				
Airframe										
Notes: SUPERSEDED BY ASC 908C										
ASC908C	ASC 908C Planeview Master Operating System Software Update	HRS AFL MOS		4003 1871 126.2			1527.4 728 11 May 2012			0 0
(979083)		MSC				-				
Airframe										
ASC909B	ASC 909B - Planeview Master Operating System Software Update	HRS AFL MOS		2698.6 1124 92.2			2831.8 1475 10 Mar 2015			0 0
(979092)		MSC				-				
Airframe										
Notes: SUPERSEDED BY ASC-910 ACCORDING EMAIL MERLISA.HARROD@GULFSTREAM.COM										
ASC910	ASC 910 - Planeview Master Operating System Software Update	HRS AFL MOS		3246.2 1432 107.6			2284.2 1167 28 Nov 2013			0 0
(979100)		MSC				-				
Airframe										
ASC911	ASC 911 - Planeview Master Operating System Software Update	HRS AFL MOS		5530.4 2599 97.9			0 0 18 Sep 2014			0 0
(979110)		MSC				-				
Airframe										
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.										
ASC911A	ASC 911A - Planeview Master Operating System Software Update	HRS AFL MOS		2640.5 1094 89.4			2889.9 1505 04 Jun 2015			0 0
(979111)		MSC				-				
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
ASC912 (979120) Airframe	ASC 912 Planeview Master Operating System Software Update	HRS AFL MOS MSC		2367 954 72.3		-	3163.4 1645 07 Nov 2016			0 0
Notes: COMPLY WITH ASC 912										
ASC912A (979121) Airframe	ASC 912A Planeview Master Operating System Software Update	HRS AFL MOS MSC		958.6 365 32		-	4571.8 2234 16 Mar 2020			0 0
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.										
ASC912B (979122) Airframe	ASC 912B Planeview Master Operating System Software Update	HRS AFL MOS MSC		1112.2 433 35.9		-	4418.2 2166 20 Nov 2019			0 0
ASC912C (979123) Airframe	ASC 912C Planeview Master Operating System Software Update	HRS AFL MOS MSC		882.2 304 23.3		-	4648.2 2295 07 Dec 2020			0 0
CB079 (980790) Airframe	Cb 79 MOD-Nose Gear Uplock Hook Spring (ASC 49)	HRS AFL MOS MSC		5525.5 2597 171.4		-	4.9 2 05 Aug 2008			0 0
CB089 (980890) Airframe	Cb 89 Inspection-Aircraft Security System Antenna Mount Fasteners	HRS AFL MOS MSC		4882.7 2421 149.8		-	647.7 178 21 May 2010			0 0
CB091 (980910) Airframe	Cb 91 - Replacement - Flight Spoiler Pushrod ROD End Assemblies, Pn 1150CM20263-1	HRS AFL MOS		4882.7 2421 149.6			647.7 178 28 May 2010			0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
CB093 (980930) Airframe	Cb 93 MOD - Tail Compartment Access Ladder (ASC 057)	HRS AFL MOS MSC		5530.4 2599 164.6		-	0 0 27 Feb 2009			0 0
CB093A (980931) Airframe	Cb 93A MOD - Tail Compartment Access Ladder (ASC 057A)	HRS AFL MOS MSC		5293.5 2527 164.1		-	236.9 72 12 Mar 2009			0 0
Notes: PERFORMED IAW ASC 057A ON 12/03/09 BY JET AVIATION DXB STAMP # JDXB 23										
CB094 (980940) Airframe	Cb 94 - Divan Seat Belt Anchor Installation	HRS AFL MOS MSC		5530.4 2599 165.1		-	0 0 13 Feb 2009			0 0
CB094A (980941) Airframe	Cb 94A - Divan Seat Belt Anchor Installation	HRS AFL MOS MSC		5291.5 2524 163.1		-	238.9 75 14 Apr 2009			0 0
CB095 (980950) Airframe	Cb 95 Modification - Engine (Eec) Software (ASC 045)	HRS AFL MOS MSC		4882.7 2421 149.9		-	647.7 178 19 May 2010			0 0
CB096 (980960) Airframe	Cb 96 MOD-Right Electronic Equipment Rack (Reer) Cb Panel Overlay	HRS AFL MOS MSC		5006.3 2454 153		-	524.1 145 16 Feb 2010			0 0
Notes: APU PWR BREAKER ID APU PWR #1, OVERLAY ID P/N 1159SB47972-5										
CB099 (980990) Airframe	Cb 99 Inspection - Electrical Wiring AT Fuselage Station 605 Below Floors	HRS AFL MOS MSC		5006.3 2454 153		-	524.1 145 16 Feb 2010			0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
CB100 (981000) Airframe	Cb 100 Inspection - Rudder Sector Assembly Fuselage Station 133	HRS AFL MOS MSC		4882.7 2421 149.8		-	647.7 178 21 May 2010			0 0
CB101 (981010) Airframe	Cb 101 Inspection - Engine Front Beam Seal	HRS AFL MOS MSC		4882.7 2421 149.9		-	647.7 178 18 May 2010			0 0
CB102 (981020) Airframe	Cb 102 Modification - Flap and Stabilizer Electronic Control Unit (Fsecu) - Software Upgrade (ASC 063)	HRS AFL MOS MSC		4882.7 2421 149.5		-	647.7 178 01 Jun 2010			0 0
CB103 (981030) Airframe	Cb 103 Modification - Sealing of Nose Wheel Steering Electrical Connectors	HRS AFL MOS MSC		4882.7 2421 149.5		-	647.7 178 01 Jun 2010			0 0
CB105 (981050) Airframe	Cb 105 Global Positioning System Cable Installation AT Fuselage Station 139	HRS AFL MOS MSC		4882.7 2421 149.5		-	647.7 178 01 Jun 2010			0 0
CB108 (981080) Airframe	Cb 108 Inspection - Winslow Life Raft	HRS AFL MOS MSC		4943.3 2436 152		-	587.1 163 15 Mar 2010			0 0
Notes: LIFE RAFT P/N AND S/N NOT INSTALLED										
CB109 (981090) Airframe	Cb 109 Modification - Nose Jack Point	HRS AFL MOS MSC		4882.7 2421 149.5		-	647.7 178 02 Jun 2010			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
CB110 (981100) Airframe	Cb 110 Modification - Pilot / Copilot Seat - Forward / Aft Adjustment Control Lever	HRS AFL MOS MSC		4882.7 2421 149.9		- 	647.7 178 19 May 2010			0 0
CB112 PART I (981120) Airframe	Cb 112 (Part I) Modification - Landing Gear Door Close - Restrictor Installation (ASC 067)	HRS AFL MOS MSC		4882.7 2421 149.5		- 	647.7 178 31 May 2010			0 0
CB112 PART II (981121) Airframe	Cb 112 (Part Ii) Modification - Landing Gear Door Close - Restrictor Installation (ASC 067)	HRS AFL MOS MSC		4882.7 2421 149.5		- 	647.7 178 31 May 2010			0 0
CB113 (981130) Airframe	Cb 113 Inspection - Waste Tank Bonding Strap Installation	HRS AFL MOS MSC		4593.3 2210 139.9		- 	937.1 389 19 Mar 2011			0 0
CB114 (981140) Airframe	Cb 114 Inspection - Weather Radar Antenna Wire Harness	HRS AFL MOS MSC		4882.7 2421 149.7		- 	647.7 178 26 May 2010			0 0
CB115 (981150) Airframe	Cb 115 Installation - Vacuum Waste System Thermal Heater (ASC 047)	HRS AFL MOS MSC		4882.7 2421 149.6		- 	647.7 178 27 May 2010			0 0
CB116 (981160) Airframe	Cb 116 Replacement - Emergency Brake Accumulator and Landing Gear Emergency Extension Nitrogen Blow-Down Bottle Charging Valves	HRS AFL MOS MSC		4882.7 2421 149.7		- 	647.7 178 26 May 2010			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
CB118 PART I (981180) Airframe	Cb 118 Part I - Inspection - Landing Light Leading Edge Skins	HRS AFL MOS MSC		4593.3 2210 139.9		-	937.1 389 19 Mar 2011			0 0
CB118 PART II (981181) Airframe	Cb 118 Part Ii - Inspection - Landing Light Leading Edge Skin	HRS AFL MOS MSC		4593.3 2210 139.9		-	937.1 389 19 Mar 2011			0 0
Notes: RESET TO 12 MONTHS AFTER PART ONE IF APPLICABLE										
CB119 (981190) Airframe	Cb 119 Inspection - Crew Seat Inertia Reels	HRS AFL MOS MSC		5530.4 2599 149.3		-	0 0 07 Jun 2010			0 0
CB119A (981191) Airframe	Cb 119A Inspection - Crew Seat Inertia Reels	HRS AFL MOS MSC		4593.3 2210 139.9		-	937.1 389 19 Mar 2011			0 0
CB122 (981220) Airframe	Cb 122 Modification - Emergency Battery Pack	HRS AFL MOS MSC		4003 1871 126.2		-	1527.4 728 09 May 2012			0 0
CB125 PART I (981250) Airframe	Cb 125 Part I Inspection - Aileron Actuator Hydraulic Line to Support Structure Contact	HRS AFL MOS MSC		5530.4 2599 139.9		-	0 0 18 Mar 2011			0 0
CB125 PART II (981251) Airframe	Cb 125 Part Ii Inspection - Aileron Actuator Hydraulic Line to Support Structure Contact	HRS AFL MOS MSC		5530.4 2599 139.9		-	0 0 18 Mar 2011			0 0

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CB125A PART I	Cb 125A Part I Inspection - Aileron Actuator Hydraulic Line to Support Structure Contact		HRS AFL MOS MSC		4238.4 2006 132.5		-	1292 593 01 Nov 2011			0 0
(981252)											
Airframe											
CB125A PART II	Cb 125A Part Ii Inspection - Aileron Actuator Hydraulic Line to Support Structure Contact		HRS AFL MOS MSC		4238.4 2006 132.5		-	1292 593 01 Nov 2011			0 0
(981253)											
Airframe											
CB126	Cb 126 Inspection - Nose Landing Gear Uplock Hydraulic Flow Regulator Decal		HRS AFL MOS MSC		4480 2140 137		-	1050.4 459 17 Jun 2011			0 0
(981260)											
Airframe											
CB127	Cb 127 Inspection - Aircraft Battery Charger Wire Harness to Rudder Trim Cable Contact		HRS AFL MOS MSC		4343.4 2048 134.5		-	1187 551 30 Aug 2011			0 0
(981270)											
Airframe											
CB128	Cb 128 Inspection - Enhanced Vision System (Evs) Radome Support Strut, P/N 1159SCAM561-1		HRS AFL MOS MSC		4343.4 2048 134.5		-	1187 551 30 Aug 2011			0 0
(981280)											
Airframe											
CB129	Cb 129 Modification - Tail Compartment Ladder Attach Fittings		HRS AFL MOS MSC		4003 1871 126.5		-	1527.4 728 01 May 2012			0 0
(981290)											
Airframe											
CB131	Cb 131 Non-Compliance - Stage 3 Noise Certification (ASC 007C)		HRS AFL MOS MSC		4003 1871 126.1		-	1527.4 728 14 May 2012			0 0
(981310)											
Airframe											

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
CB133	Cb 133 Inspection - Engine / Auxiliary Power Unit (APU) FIRE Bottle Thermal Relief Discharge Port	HRS AFL MOS MSC		4157.9 1948 130.1		-	1372.5 651 12 Jan 2012			0 0
(981330)										
Airframe										
CB134 PART I	Cb 134 Part I - Inspection - Auxiliary Power Unit (APU) AIR Intake Duct Slosh Coating	HRS AFL MOS MSC		3963.7 1844 125.4		-	1566.7 755 05 Jun 2012			0 0
(981340)										
Airframe										
Notes: SUPERSEDED BY CB 134A PART I										
CB134 PART II	Cb 134 Part Ii - Inspection - Auxiliary Power Unit (APU) AIR Intake Duct Slosh Coating	HRS AFL MOS MSC		3963.7 1844 125.4		-	1566.7 755 05 Jun 2012			0 0
(981341)										
Airframe										
Notes: SUPERSEDED BY CB 134A PART II										
CB134A PART I	Cb 134A - Part I Inspection - Auxiliary Power Unit (APU) AIR Intake Duct Slosh Coating	HRS AFL MOS MSC		4003 1871 126.1		-	1527.4 728 14 May 2012			0 0
(981342)										
Airframe										
CB134A PART II	Cb 134A - Part Ii Inspection - Auxiliary Power Unit (APU) AIR Intake Duct Slosh Coating	HRS AFL MOS MSC		3144.8 1378 104.7		-	2385.6 1221 25 Feb 2014			0 0
(981343)										
Airframe										
CB134B PART I	Cb 134B - Part I Inspection - Auxiliary Power Unit (APU) AIR Intake Duct Slosh Coating	HRS AFL MOS MSC		2918.4 1266 96.5		-	2612 1333 31 Oct 2014			0 0
(981344)										
Airframe										
Notes: P/C/W BY CB 134A										

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
Logbook Position	HW	SW									
	MM Ref										
	Ops Number(s)										
CB134B PART II	Cb 134B - Part Ii Inspection - Auxiliary Power Unit (APU) AIR Intake Duct Slosh Coating		HRS AFL MOS MSC		2849.4 1234 96.5		-	2681 1365 31 Oct 2014			0 0
(981345)											
Airframe											
Notes: P/C/W BY CB 134A											
CB134C PART I	Cb 134C - Part I Inspection - Auxiliary Power Unit (APU) AIR Intake Duct Slosh Coating		HRS AFL MOS MSC		2367 954 72.9		-	3163.4 1645 20 Oct 2016			0 0
(981346)											
Airframe											
Notes: PREVIOUSLY COMPLIED WITH REF CB134 PT I 01/MAY/2012											
CB134C PART II	Cb 134C - Part Ii Inspection - Auxiliary Power Unit (APU) AIR Intake Duct Slosh Coating		HRS AFL MOS MSC		2367 954 72.9		-	3163.4 1645 20 Oct 2016			0 0
(981347)											
Airframe											
Notes: PREVIOUSLY COMPLIED WITH REF CB134 PT I 24/FEB/2014											
CB137 PART I	Cb 137 Inspection (Part I) - Auxiliary Power Unit (APU) Enclosure Thermal Barrier Coating		HRS AFL MOS MSC		4003 1871 126.1		-	1527.4 728 14 May 2012			0 0
(981370)											
Airframe											
CB137 PART II	Cb 137 Inspection (Part Ii) - Auxiliary Power Unit (APU) Enclosure Thermal Barrier Coating		HRS AFL MOS MSC		3977.1 1851 125.5		-	1553.3 748 30 May 2012			0 0
(981371)											
Airframe											
Notes: SUPERSEEDED BY CB 137A											
CB137A PART I	Cb 137A Inspection (Part I) - Auxiliary Power Unit (APU) Enclosure Thermal Barrier Coating		HRS AFL MOS MSC		3977.1 1851 125.5		-	1553.3 748 30 May 2012			0 0
(981372)											
Airframe											
Notes: PREVIOUSLY COMPLIED WITH CB 137 WITH NO FINDINGS											

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
CB137A PART II (981373) Airframe	Cb 137A Inspection (Part Ii) - Auxiliary Power Unit (APU) Enclosure Thermal Barrier Coating	HRS AFL MOS MSC		3977.1 1851 125.5		-	1553.3 748 30 May 2012			0 0
Notes: CB137 PART II PREVIOUSLY COMPLIED WITH										
CB141 (981410) Airframe	Cb 141 Airplane Flight Manual (Afm) Supplement Update - Maximum Takeoff Gross Weight Increase (ASC 016A)	HRS AFL MOS MSC		3804 1763 122.8		-	1726.4 836 22 Aug 2012			0 0
CB142 (981420) Airframe	Cb 142 Inspection - Rudder Actuator Pressure Monitoring Port Plugs	HRS AFL MOS MSC		3804.1 1763 123		-	1726.3 836 15 Aug 2012			0 0
CB142A (981421) Airframe	Cb 142A Inspection - Rudder Actuator Pressure Monitoring Port Plugs	HRS AFL MOS MSC		3701.7 1705 120.8		-	1828.7 894 22 Oct 2012			0 0
CB143 (981430) Airframe	Cb 143 Inspection - Nose Landing Gear Downlock Connector Hardware	HRS AFL MOS MSC		3803.9 1763 123		-	1726.5 836 16 Aug 2012			0 0
CB144 (981440) Airframe	Cb 144 Replacement - Nose Wheel Steering Collar Hardware	HRS AFL MOS MSC		3803.9 1763 123		-	1726.5 836 16 Aug 2012			0 0
CB151 (981510) Airframe	Cb 151 Inspection - Inspection - Left Emergency Exit Light Wiring AT Fuselage Station 452	HRS AFL MOS MSC		3246.1 1432 107.9		-	2284.3 1167 19 Nov 2013			0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
CB152 PART I	Cb 152 Part 1 Inspection - Engine Ignition Harness Installation	HRS		5530.4			0			0
		AFL		2599			0			0
		MOS		114			16 May 2013			
(981520)		MSC				-				
Airframe										
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.										
CB152 PART II	Cb 152 Part Ii Inspection - Engine Ignition Harness Installation	HRS		5530.4			0			0
		AFL		2599			0			0
		MOS		114			16 May 2013			
(981521)		MSC				-				
Airframe										
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.										
CB152A PART I	Cb 152A - Part 1 Inspection - Engine Ignition Harness Installation	HRS		3246.1			2284.3			0
		AFL		1432			1167			0
		MOS		107.7			26 Nov 2013			
(981522)		MSC				-				
Airframe										
CB152A PART II	Cb 152A - Part Ii Inspection - Engine Ignition Harness Installation	HRS		3246.1			2284.3			0
		AFL		1432			1167			0
		MOS		107.6			27 Nov 2013			
(981523)		MSC				-				
Airframe										
CB153	Cb 153 - Inspection - SATCOM High Power Amplifier (Hpa) / Satellite Data Unit (Sdu) Fan Terminals	HRS		3246.1			2284.3			0
		AFL		1432			1167			0
		MOS		107.7			26 Nov 2013			
(981530)		MSC				-				
Airframe										
CB154	Cb 154 - Inspection - Tail Cone Anticollision Light - Fault Indicator Wiring	HRS		3246.1			2284.3			0
		AFL		1432			1167			0
		MOS		107.8			21 Nov 2013			
(981540)		MSC				-				
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
CB155 (981550) Airframe	Cb 155 - Modification - Thrust Reverser Main Actuator Bearings (Nordam Sb Giv-Xtr 78-12)	HRS AFL MOS MSC		3021.1 1338 102.1		-	2509.3 1261 14 May 2014			0 0
CB158 (981580) Airframe	Cb 158 - Replacement - Thrust Reverser Latch Hook Housing Springs	HRS AFL MOS MSC		3021.1 1338 102.2		-	2509.3 1261 09 May 2014			0 0
CB159 (981590) Airframe	Cb 159 - Modification - Pylon Aft Lower Panel Drain (ASC 085)	HRS AFL MOS MSC		3246.1 1432 107.9		-	2284.3 1167 19 Nov 2013			0 0
CB165 (981650) Airframe	Cb 165 - MOD - Elevator Hardover Prevention System (Hops) Improvement (ASC 89)	HRS AFL MOS MSC		3021.1 1338 102		-	2509.3 1261 15 May 2014			0 0
CB170 (981700) Airframe	Cb 170 - Modification - Flap and Stabilizer Electronic Control Unit (Fsecu) Software Upgrade (ASC 086)	HRS AFL MOS MSC		2640.5 1094 89.6		-	2889.9 1505 29 May 2015			0 0
CB171 (981710) Airframe	Cb 171 - Modification - Low Pressure Cooling AIR Outlet (Lpcao) Seal Replacement (ASC 080)	HRS AFL MOS MSC		2793.5 1211 95.3		-	2736.9 1388 08 Dec 2014			0 0
CB174 (981740) Airframe	Cb 174 - Inspection - Forward Cabin Pocket Door Bulkhead AT FS 193E	HRS AFL MOS MSC		2886.4 1245 97.3		-	2644 1354 07 Oct 2014			0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
CB175	Cb 175 - Inspection - Cockpit Overhead Circuit Breaker Panels	HRS		2698.6			2831.8			0
		AFL		1124			1475			0
		MOS		92.5			02 Mar 2015			
(981750)		MSC				-				
Airframe										
CB176	Cb 176 - Replacement - Integrated Drive Generator (Idg) Feeder Cable Clamps (ASC 097)	HRS		2793.5			2736.9			0
		AFL		1211			1388			0
		MOS		95.3			08 Dec 2014			
(981760)		MSC				-				
Airframe										
CB180	Cb 180 Inspection - Main Landing Gear Door Actuator	HRS		2698.6			2831.8			0
		AFL		1124			1475			0
(981800)		MOS		92.2			10 Mar 2015			
Airframe		MSC				-				
CB181	Cb 181 - Replacement - Main Landing Gear Door Actuator End CAP - Life Limit	HRS		2486.2			3044.2			0
		AFL		1025			1574			0
		MOS		78.4			03 May 2016			
(981810)		MSC				-				
Airframe										
CB183	Cb 183 Modification - Nose Landing Gear Electrical Harness Installation (ASC 094A)	HRS		2367			3163.4			0
		AFL		954			1645			0
		MOS		73.1			12 Oct 2016			
(981830)		MSC				-				
Airframe										
CB184	Cb 184 - Inspection - Wiring Harness Installation AT Fuselage Station 743	HRS		2367			3163.4			0
		AFL		954			1645			0
		MOS		73.4			04 Oct 2016			
(981840)										
Airframe										
CB185	Cb 185 Inspection - Wire Installation In Right Electrical Equipment Rack (Reer) Circuit Breaker (Cb) Panel	HRS		2367			3163.4			0
		AFL		954			1645			0
		MOS		73.4			04 Oct 2016			
(981850)		MSC				-				
Airframe										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
CB187	Cb 187 Inspection - Auxiliary Power Unit (APU) Fuel Shut-Off Valve	HRS		2367			3163.4			0
		AFL		954			1645			0
		MOS		73			17 Oct 2016			
(981870)		MSC				-				
Airframe										
CB187A	Cb 187A Inspection - Auxiliary Power Unit (APU) Fuel Shut-Off Valve	HRS		2126.6			3403.8			0
		AFL		875			1724			0
		MOS		65.3			07 Jun 2017			
(981871)		MSC				-				
Airframe										
Notes: CB 187 COMPLIED WITH										
CB191	Cb 191 Modification - Pedestal Assembly Edge Light Panel Upgrade	HRS		5530.4			0			0
		AFL		2599			0			0
		MOS		75.4			05 Aug 2016			
(981910)		MSC				-				
Airframe										
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.										
CB191A	Cb 191A Modification - Pedestal Assembly Edge Light Panel Upgrade	HRS		1769.5			3760.9			0
		AFL		717			1882			0
		MOS		54.9			18 Apr 2018			
(981911)		MSC				-				
Airframe										
CB192	Cb 192 Inspection - Repaired Main Landing Gear Side Brace Actuator Fittings for Continued Airworthiness	HRS		5530.4			0			0
		AFL		2599			0			0
		MOS		65			16 Jun 2017			
(981920)		MSC				-				
Airframe										
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.										
CB192A	Cb 192A Repaired Main Landing Gear Side Brace Actuator Fittings for Continued Airworthiness	HRS		1769.5			3760.9			0
		AFL		717			1882			0
		MOS		54.6			27 Apr 2018			
(981921)		MSC				-				
Airframe										
Notes: PER CB192A, PARA I.(B) NOTE, A/C NOT REPAIRED USING SE05732102 ARE NOT AFFECTED BY THIS REVISION, WHICH THIS A/C WAS NOT (MB)										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
CB194 (981940) Airframe	Cb 194 Inspection - Oxygen Bottle Installation	HRS AFL MOS MSC		2106.6 868 64.8		--	3423.8 1731 21 Jun 2017			0 0
CB199 (981990) Airframe	Cb 199 Inspection - Wire Routing In Right Electrical Equipment Rack, Fuselage Station 169	HRS AFL MOS MSC		1416.9 561 43		--	4113.5 2038 16 Apr 2019			0 0
CB201 (982010) Airframe	Cb 201 Modification - Main Landing Gear Doors, P/N 1159B42000 (Fokker Sb RP-Dgup-25.10.1532)	HRS AFL MOS MSC		5530.4 2599 55.3		--	0 0 06 Apr 2018			0 0
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.										
CB201A (982011) Airframe	Cb 201A Modification - Main Landing Gear Doors, P/N 1159B42000 (Fokker Sb RP-Dgup-25.10.1532)	HRS AFL MOS MSC		957.2 362 29.1		--	4573.2 2237 12 Jun 2020			0 0
CB201B (982012) Airframe	Landing Gear (ATA 32) - Modification - Main Landing Gear Doors, P/N 1159B42000 (Fokker Sb RP-Dgup-25.10.1532), Customer Bulletin (Mandatory)	HRS AFL MOS MSC		882.3 304 25.8		--	4648.1 2295 21 Sep 2020			0 0
CB202 (982020) Airframe	Cb 202 Modification - Auxiliary Hydraulic Pump Grounding Installation (ASC 107)	HRS AFL MOS MSC		1416.9 561 42.7		--	4113.5 2038 26 Apr 2019			0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
CB205	Cb 205 Inspection - Display Unit Tray Assembly, Ground Strap Plating Flaking	HRS AFL MOS MSC		1534 603 45.3		-	3996.4 1996 07 Feb 2019			0 0
(982050)										
Airframe										
Notes: N/A BY S/N, J. BLUMER										
CB206	Cb 206 Wings (ATA 57), Inspection - Wing Upper Surface AT Fuselage Station (FS) 355, Right Side, for Contact With Forward Lavatory Waste Tube	HRS AFL MOS MSC		957.2 362 29.1		-	4573.2 2237 12 Jun 2020			0 0
(982060)										
Airframe										
CB207	Flight Controls (ATA 27) - Inspection - Aileron Force Link Wiring Harness Installation, Customer Bulletin (Mandatory)	HRS AFL MOS MSC		882.2 304 24.7		-	4648.2 2295 26 Oct 2020			0 0
(982070)										
Airframe										
CB208	Flight Controls (ATA 27) - Inspection - Rudder Lower Hinge - Swivel #1 Assembly, Customer Bulletin (Mandatory)	HRS AFL MOS MSC				-				0 0
(982080)										
Airframe										
CB210	CB210 - Communications (ATA 23) Modification - Jetwave System BLV8.1 Software Release (Honeywell Sb Jetwave -23-0009), Customer Bulletin (Cancelled)	HRS AFL MOS MSC		439.3 157 12.1		-	5091.1 2442 12 Nov 2021			0 0
(982100)										
Airframe										
CB210A	CB210A - Communications (ATA 23) Modification - Jetwave System BLV8.1 Software Release (Honeywell Sb Jetwave-23-0009), Customer Bulletin (Mandatory)	HRS AFL DATE MSC				-				0 0
(982101)										
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
CB211 (982110) Airframe	CB211 - FIRE Protection (ATA 26) - Inspection - Engine FIRE Bottle Thermal Relief Discharge Port, Customer Bulletin (Mandatory)	HRS AFL MOS MSC		6.5 2 .2		--	5523.9 2597 11 Nov 2022			0 0
CSB016 (940160) Airframe	Advanced Cabin Server (Acs) (Gen 4) Cabinview Software Update V2.2.3, Cabin Service Bulletin (Optional)	HRS AFL MOS MSC				--				0 0
CSB018 (940180) Airframe	Gulfstream Cabin Management System (Gcms 1) Firmware Update V1.10.7, Cabin Service Bulletin (Optional)	HRS AFL MOS MSC				--				0 0
CSB019 (940190) Airframe	CSB019 - Ce-Csb-4019 - Cabin Systems - Advanced Cabin Server (Acs) (Gen 4) Cabin View Software Update, Cabin Service Bulletin (Recommended)	HRS AFL DATE MSC				--				0 0
GIV-XTR 78-15 R01 (785013) Airframe	Lh Exhaust - Thrust Reverser - Replace the Nozzle Seals, Service Bulletin (Optional)	HRS AFL MOS MSC				--				0 0
MP-17-4501 (949005) Airframe	Cmc Module Reliability Enhancement Program (Mp-17-4501)	HRS AFL DATE MSC		5530.4 2599		--	0 0			0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
ST03290AT-D (901031) Airframe	ST03290AT-D (Atg) Injection Molded Elec Window Shades	HRS AFL MOS MSC		5525.5 2597 171.5		O/C	4.9 2 01 Aug 2008			0 0
Notes: REFERENCE ICA DOCUMENT GC41506A002 REV - FOR STC ST03290AT-D										
STC ST02979AT-D (901002) Airframe	STC ST02979AT-D Crew/Pax Oxygen System	HRS AFL MOS MSC		5525.5 2597 171.5		O/C	4.9 2 01 Aug 2008			0 0
Notes: REFERENCE ICA DOCUMENT GC41453A000 REV A FOR STC ST02979AT-D										
STC ST02980AT-D (901003) Airframe	STC ST02980AT-D External Camera System	HRS AFL MOS MSC		5525.5 2597 171.5		O/C	4.9 2 01 Aug 2008			0 0
Notes: REFERENCE ICA DOCUMENT GC41505A005 REV - FOR STC ST02980AT-D										
STC ST02987AT-D (901004) Airframe	STC ST02987AT-D Interior Emergency Lights	HRS AFL MOS MSC		5525.5 2597 171.5		O/C	4.9 2 01 Aug 2008			0 0
Notes: REFERENCE ICA DOCUMENT GC41486A000 REV - FOR STC ST02987AT-D										
STC ST03027AT-D (901007) Airframe	STC ST03027AT-D Broadband Multi-Link Wireless LAN	HRS AFL MOS MSC		5525.5 2597 171.5		O/C	4.9 2 01 Aug 2008			0 0
Notes: REFERENCE ICA DOCUMENT GC41303A008 REV - FOR STC ST03027AT-D										
STC ST03047AT-D (901005) Airframe	STC ST03047AT-D Airshow 4000 Inflight Information System	HRS AFL MOS MSC		5525.5 2597 171.5		O/C	4.9 2 01 Aug 2008			0 0
Notes: REFERENCE ICA DOCUMENT GGC41504A001 REV - FOR STC ST03047AT-D										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
STC ST03238AT-D (901021) Airframe	STC ST03238AT-D - SATCOM High Speed Data (Hd-128) (MCS-7100)	HRS AFL MOS MSC		5525.5 2597 171.5		 O/C	4.9 2 01 Aug 2008			0 0
Notes: REFERENCE ICA DOCUMENT GC41303A006 REV A FOR STC ST03238AT-D										
STC ST03532AT-D (901034) Airframe	STC ST03532AT-D Iridum Satellite Phone, Aircell Axxess Ii	HRS AFL MOS MSC		5525.5 2597 171.5		 O/C	4.9 2 01 Aug 2008			0 0
Notes: REFERENCE ICA DOCUMENT GC41203A004 REV - FOR STC ST03532AT-D										
SIAE - APU/Engine Service Information/Bulletins										
2704458-49-2396 R03 APU	APU - 2704458-49-2396 R03 - Airborne Auxiliary Power - Starter Motor Assembly - Modification of the Starter Motor Assembly from Pn 2704458-1 Series 3 to Pn 2704458-2, Instructions Are for the Replacement of the Brush Assemblies, Service Bulletin (Recommended)	HRS APUS DATE MSC				 -				0 0
36-49-8116 (958116) APU	APU - Sb 36-49-8116 - Replace the Starter Motor, Pn 2704458-1WITH Pn 2704458-2	HRS APUS MOS MSC		5230.5 5452 54.1		 -	0 0 14 May 2018			0 0
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.										
36-49-8116 R01 (958117) APU	APU - Sb 36-49-8116R1 - Replace the Starter Motor, Pn 2704458-1 With Pn 2704458-2	HRS APUS DATE MSC		5230.5 5452		 -	0 0			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
36-49-8116 R02	APU - Sb 36-49-8116 R02 - Airborne Auxiliary Power - Gas Turbine Engine - Replace the Starter Motor, Pn 2704458-1 With Pn 2704458-2, Service Bulletin (Recommended)	HRS APUS DATE MSC				- 				0 0
APU										
36-49-8361 R02	APU - Sb 36-49-8361 R02 - Airborne Auxiliary Power - Gas Turbine Engine - Replace Rivet Pn M24243/6A401H With Rivet Pn 627-504-9209 on 36-150 Engine Models, Service Bulletin (Category 2)	HRS APUS DATE MSC				- 				0 0
APU										
36-49-8361 R03	APU - Sb 36-49-8361 R03 - Airborne Auxiliary Power - Gas Turbine Engine - Replace Rivet Pn M24243/6A401H With Rivet Pn 627-504-9209 on 36-150 Engine Models, Service Bulletin (Category 2)	HRS APUS DATE MSC				- 				0 0
APU										
49-7933	APU - SB49-7933 Airborne Auxiliary Power Unit (APU) Oil - General - Approved Oils	HRS APUS MOS MSC		5230.5 5452 98.4		- 	0 0 03 Sep 2014			0 0
(957933)										
APU										
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.										
49-7933 R04	APU - Sb 49-7933 R04 Airborne Auxiliary Power Unit (APU) Oil - General - Approved Oils	HRS APUS MOS MSC		5230.5 5452 96.3		- 	0 0 06 Nov 2014			0 0
(957934)										
APU										
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
49-7933 R05	APU - Sb 49-7933 R05 Airborne Auxiliary Power Unit (APU) Oil - General - Approved Oils	HRS APUS MOS MSC	5230.5 5452 81.6				0 0 29 Jan 2016			0 0
(957935) APU						-				
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.										
49-7933 R06	APU - Sb 49-7933 R06 Airborne Auxiliary Power Unit (APU) Oil - General - Approved Oils	HRS APUS MOS MSC	5230.5 5452 68.1				0 0 13 Mar 2017			0 0
(957936) APU						-				
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.										
49-7933 R08	APU - Sb 49-7933 R08 Airborne Auxiliary Power Unit (APU) Oil - General - Approved Oils	HRS APUS DATE MSC	5230.5 5452			DUE**	0 0			0 0
(957938) APU										
49-8252	APU - 49-8252 - Airborne - Auxiliary Power Unit (APU) - Approved Fuels for Honeywell Commercial Apus	HRS APUS DATE MSC	5230.5 5452			-	0 0			0 0
(958252) APU										
881699	No. 1 Engine - Sb Tay-72-1704 AIR Guide Tube Drive Shaft	HRS ENC DATE MSC	5452.4 2550			-	0 0			0 0
(881699) Engine										
881699 (891699)	No. 2 Engine - Sb Tay-72-1704 AIR Guide Tube Drive Shaft	HRS ENC DATE MSC	5452.4 2550			-	0 0			0 0
(881699) Engine										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
APU-49 R11 APU	APU - Implementation of the Honeywell Spectrometric Oil and Filter Analysis Program (Soap) for Honeywell Auxiliary Power Units (Apus), Service Information Letter (Recommended)	HRS APUS DATE MSC				- -				0 0
APU-49 R12 APU	APU - Sil APU-49 R12 - Implementation of the Honeywell Spectrometric Oil and Filter Analysis Program (Soap) for Honeywell Auxiliary Power Units (Apus), Service Information Letter (Recommended)	HRS APUS DATE MSC				- -				0 0
TAY-70-1050 R11 (887306) Engine	No. 1 Engine - Tay Life Management - Non-Airline Engines - Non-Modification Service Bulletin, Service Bulletin (Optional)	HRS ENC MOS MSC	957.2 362 29.1			- - -	4495.2 2188 12 Jun 2020			0 0
TAY-70-1050 R11 (887306) Engine	No. 2 Engine - Tay Life Management - Non-Airline Engines - Non-Modification Service Bulletin, Service Bulletin (Optional)	HRS ENC MOS MSC	957.2 362 29.1			- - -	4495.2 2188 12 Jun 2020			0 0
TAY-70-1050 R12 (887311) Engine	No. 1 Engine - Sb Tay-70-1050 R12 - Tay Life Management - Non-Airline Engines - Non-Modification Service Bulletin, Service Bulletin (Optional)	HRS ENC DATE MSC				- -				0 0
TAY-70-1050 R12 (887311) Engine	No. 2 Engine - Sb Tay-70-1050 R12 - Tay Life Management - Non-Airline Engines - Non-Modification Service Bulletin, Service Bulletin (Optional)	HRS ENC DATE MSC				- -				0 0

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
Logbook Position	HW	SW									
	MM Ref										
	Ops Number(s)										
TAY-70-1050 R13	No. 1 Engine - Sb Tay-70-1050 R13 - Tay Life Management - Non-Airline Engines - Non-Modification Service Bulletin, Service Bulletin (Optional)		HRS ENC DATE MSC				- -				0 0
(887314)											
Engine											
TAY-70-1050 R13	No. 2 Engine - Sb Tay-70-1050 R13 - Tay Life Management - Non-Airline Engines - Non-Modification Service Bulletin, Service Bulletin (Optional)		HRS ENC DATE MSC				- -				0 0
(887314)											
Engine											
TAY-70-1050 R14	No. 1 Engine - Sb Tay-70-1050 R14 - Tay Life Management - Non-Airline Engines - Non-Modification Service Bulletin, Service Bulletin (Optional)		HRS ENC DATE MSC				- -				0 0
(887315)											
Engine											
TAY-70-1050 R14	No. 2 Engine - Sb Tay-70-1050 R14 - Tay Life Management - Non-Airline Engines - Non-Modification Service Bulletin, Service Bulletin (Optional)		HRS ENC DATE MSC				- -				0 0
(887315)											
Engine											
TAY-70-1493 R05	No. 1 Engine - Sb Tay-70-1493 R05 - Introduction of Revised Maintenance Tasks - Non-Modification Service Bulletin, Service Bulletin (Optional)		HRS ENC DATE MSC				- -				0 0
(887310)											
Engine											
TAY-70-1493 R05	No. 2 Engine - Sb Tay-70-1493 R05 - Introduction of Revised Maintenance Tasks - Non-Modification Service Bulletin, Service Bulletin (Optional)		HRS ENC DATE MSC				- -				0 0
(887310)											
Engine											

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
TAY-70-1517 R05 (887309) Engine	No. 1 Engine - Sb Tay-70-1517 R05 - Introduction of Task Oriented Maintenance - Non-Modification Service Bulletin, Service Bulletin (Optional)	HRS ENC DATE MSC				- -				0 0
TAY-70-1517 R05 (887309) Engine	No. 2 Engine - Sb Tay-70-1517 R05 - Introduction of Task Oriented Maintenance - Non-Modification Service Bulletin, Service Bulletin (Optional)	HRS ENC DATE MSC				- -				0 0
TAY-70-1642 (881642) Engine	No. 1 Engine - Sb Tay-70-1642 Hard Time Maintenance Policy	HRS ENC MOS MSC	5447.5 2548 172.2			- -	4.9 2 11 Jul 2008			0 0
Notes: ENGINE DECLARED TASK ORIENTED										
TAY-70-1642 (891642) (881642) Engine	No. 2 Engine - Sb Tay-70-1642 Hard Time Maintenance Policy	HRS ENC MOS MSC	5447.5 2548 172.2			- -	4.9 2 11 Jul 2008			0 0
Notes: ENGINE DECLARED TASK ORIENTED										
TAY-70-1642 R02 (881644) Engine	No. 1 Engine - Sb Tay-70-1642 R2 Hard Time Maintenance Policy	HRS ENC MOS MSC	5452.4 2550 81.5			A/R	0 0 02 Feb 2016			0 0
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.										
TAY-70-1642 R02 (891644) (881644) Engine	No. 2 Engine - Sb Tay-70-1642 R2 Hard Time Maintenance Policy	HRS ENC MOS MSC	5452.4 2550 81.5			A/R	0 0 02 Feb 2016			0 0
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
TAY-70-1682 (881682) Engine	No. 1 Engine - Sb Tay-70-1682 Task Oriented Maintenance Policy	HRS ENC MOS MSC		5447.5 2548 172.2		-	4.9 2 11 Jul 2008			0 0
Notes: ENGINE DECLARED TASK ORIENTED										
TAY-70-1682 (891682) (881682) Engine	No. 2 Engine - Sb Tay-70-1682 Task Oriented Maintenance Policy	HRS ENC MOS MSC		5447.5 2548 172.2		-	4.9 2 11 Jul 2008			0 0
Notes: ENGINE DECLARED TASK ORIENTED										
TAY-72-1729 (881729) Engine	No. 1 Engine - Sb Tay-72-1729 Hp Comp Bleed Valve Assy	HRS ENC DATE MSC		5452.4 2550		-	0 0			0 0
TAY-72-1729 (891729) (881729) Engine	No. 2 Engine - Sb Tay-72-1729 Hp Comp Bleed Valve Assy	HRS ENC DATE MSC		5452.4 2550		-	0 0			0 0
TAY-72-1835 (881835) Engine	No. 1 Engine - Sb Tay-72-1835 - Low Pressure (Lp) Compressor (Fan) Blades - Dry Film Lubricant RE-Application Calculation Method	HRS ENC MOS MSC		1769.5 717 52.2		-	3682.9 1833 10 Jul 2018			0 0
TAY-72-1835 (891835) (881835) Engine	No. 2 Engine - Sb Tay-72-1835 - Low Pressure (Lp) Compressor (Fan) Blades - Dry Film Lubricant RE-Application Calculation Method	HRS ENC MOS MSC		1769.5 717 52.7		-	3682.9 1833 26 Jun 2018			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
TAY-72-1843 (887307) Engine	No. 1 Engine - High Pressure (Hp) Turbine Rotor - Hp Turbine Stage 2 Disc - Verification of Correct Hp Turbine Stage 2 Disc Serial Number - Non-Modification Service Bulletin, Service Bulletin (Recommended)	HRS ENC DATE MSC				- 				0 0
TAY-72-1843 (887307) Engine	No. 2 Engine - High Pressure (Hp) Turbine Rotor - Hp Turbine Stage 2 Disc - Verification of Correct Hp Turbine Stage 2 Disc Serial Number - Non-Modification Service Bulletin, Service Bulletin (Recommended)	HRS ENC DATE MSC				- 				0 0
TAY-73-1453 R02 (881453) Engine	No. 1 Engine - Sb Tay-73-1453 R02 - Engine Fuel and Control - Fuel Tubes and Manifolds - Removal of the Inlet Filter from the Engine Drains Tank Ejector Pump Unit on Service Engines - MOD.73-1453	HRS ENC MOS MSC	3561.9 1614 118.8			- 	1890.5 936 21 Dec 2012			0 0
Notes: ENGINE EPR FILTER REMOVED IAW RR SB 73-1453. FILTERS CLEANED AND INSTALLED. EPR FUEL LINES REINSTALLED ON THE ENGINE AND FOUND SATIS.										
TAY-73-1453 R02 (891453) (881453) Engine	No. 2 Engine - Sb Tay-73-1453 R02 - Engine Fuel and Control - Fuel Tubes and Manifolds - Removal of the Inlet Filter from the Engine Drains Tank Ejector Pump Unit on Service Engines - MOD.73-1453	HRS ENC MOS MSC	3561.9 1614 118.9			- 	1890.5 936 18 Dec 2012			0 0
Notes: NEW EJP INSTALLED.										
TAY-73-1738 (881738) Engine	No. 1 Engine - Sb Tay-73-1738 - Engine Fuel and Control - Engine Electronic Controller (Eec) and Data Entry Plug - Introduction of an Eec With T5.1 Software Standard	HRS ENC MOS MSC	5136.6 2444 156.4			- 	315.8 106 03 Nov 2009			0 0

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
TAY-73-1738 (891738) (881738) Engine	No. 2 Engine - Sb Tay-73-1738 - Engine Fuel and Control - Engine Electronic Controller (Eec) and Data Entry Plug - Introduction of an Eec With T5.1 Software Standard		HRS ENC MOS MSC		5136.6 2444 156.4		- -	315.8 106 03 Nov 2009			0 0
TAY-73-1842 (887305) Engine	No. 1 Engine - Engine Fuel and Control - Fuel System Tubes and Fittings-External-Neutral - Introduction of Different Standard Seal Rings and Three Modified Clip Positions for the Low Pressure (Lp) Fuel Tubes, Service Bulletin (Optional)		HRS ENC MOS MSC				- -				0 0
TAY-73-1842 (897305) (887305) Engine	No. 2 Engine - Engine Fuel and Control - Fuel System Tubes and Fittings-External-Neutral - Introduction of Different Standard Seal Rings and Three Modified Clip Positions for the Low Pressure (Lp) Fuel Tubes, Service Bulletin (Optional)		HRS ENC MOS MSC				- -				0 0
TAY-79-1816 (887304) Engine	No. 1 Engine - Sb Tay-79-1816 - Introduction of Shorter Bolts on the Oil Filter Housing		HRS ENC DATE MSC		5452.4 2550		- -	0 0			0 0
TAY-79-1816 (897304) (887304) Engine	No. 2 Engine - Sb Tay-79-1816 - Introduction of Shorter Bolts on the Oil Filter Housing		HRS ENC DATE MSC		5452.4 2550		- -	0 0			0 0