

PRODUCT DATA SHEET

PT-573 FILLER/SANDING EPOXY PRIMER PTI PRIMER SERIES

DESCRIPTION

PT-573 Filler/ Sanding Epoxy Primer is a two component epoxy based primer. **PT-573** is capable of filling small holes and imperfections before top coating. **PT-573** provides a smooth, sandable base coat that improves the adhesion and appearance of the top coat. Because of **PT-573's** unique formula, this primer also provides excellent rust and corrosion protection.

This sandable primer is compatible with PTI's epoxy (**PT-426F series**) and Polyurethane (**PT-785 and PT-799 series**) top coats.

COLORS

This coating can be provided light gray.

COATING PROPERTIES & CHARACTERISTICS

Mix Ratio, by volume	1 part Base to 1 part Catalyst by volume
Reducer	No thinning required
Recommended Dry Film Thickness	1 – 2 mils
Admixed Weight per Gallon	11.5 lbs.
Theoretical Coverage	500 sq. ft. ² /gal.
Pot Life	8 hours
Lubricating Oil Resistance	di-2-ethyl-hexyl sebacate (95%) & trieresyl phosphate (5%) at 250°F for 4 hours
MEK Resistant	50 Passes
MIL-L-23699 Lubricating Oil	24 hours at 120°C
MIL-H-8382 Hydraulic Fluid	24 hours at 150°F
DS2 Resistance	Pass
Coatings VOC	Below 340 g/L

SHELF LIFE

Shelf life is only applicable for materials stored in unopened and undamaged original factory filled containers. 1 year when stored between 50°-85° Fahrenheit.

SURFACE PREPARATION INSTRUCTIONS

This primer can be applied directly to metal that has been prepared according to a recognized cleaning method such as Federal Test Method Standard, #141 and Method 2013. It is recommended that all parts be pretreated with PTI's Acid Etching Wash Primer, PT-402 which meets MIL-C-8514. However, parts can also be pretreated with chemical conversion coating materials or alodine.

- Scuff the surface with scotch bright pads.
- Dust off the surface with an air hose and wand.
- Wipe of the substrate with IPA, Acetone or PTC-2002 to remove grime and oils
- Remove all remaining dust and debris by lightly wiping the substrate with a tack or "cheese" cloth
- For additional protection apply PTI's Acid Etch Primer prior to the Epoxy Primer

MIXING INSTRUCTIONS

Shake component A in a paint shaker for 5 – 10 minutes for optimal results.

Admix by volume:

1. Stir or shake both component “A” and “B” well before mixing
2. Add 1 parts of Component “A” to 1 part of Component “B” by volume and stir thoroughly. Stir each well before mixing.
3. Mix only an amount that can be used in one day.

APPLICATION

This product can be applied using conventional air spray equipment, HVLP spray system. Please consult with a PTI representative for specific equipment recommendations and settings.

1. Make sure pots, guns, and lines are purged and cleaned.
2. Mix both base and catalyst thoroughly and filter/strain before spray application.
3. HVLP Spray Pressure: 7-10psi. Conventional spray equipment 25-40 psi
4. Always air-blow and tack wipe the surfaces to be painted. Aircraft should be grounded to prevent static.
5. Best application results: apply 1 fog/tack coat at 0.5 mil thickness followed by a heavy coat that can be up to 1.5 mils. This product is intended for high build film thickness, apply additional coats if necessary.

NOTE: Application of PTI products requires the use of all OSHA approved safety equipment, including proper ventilation. Additionally, PTI products require the recommended temperature/humidity conditions and film thickness ranges for optimal performance. The material, hangar, and aircraft skin temperatures should be no lower than 75° F / 25° C before, during and after application.

DRYING & CURING SCHEDULE

Dry times are based on the dry film thickness of 1 to 1.5 mils.

Air Dry:

- Set to touch in 1 hour.
- Dry hard in 2 hours.
- Dry to apply 2nd or more coats at ½ hour intervals.
- Dry to topcoat in 2 hours.
- Dry to sand in 8 hours or overnight.

Force Dry Times: MUST AIR DRY FOR AT LEAST 15 MINUTES.

- **Dry hard:** 2 hours at 150°F.
- **Full chemical:** After “dry hard” 2 hours at 225°F



PRODUCT DATA SHEET

EQUIPMENT CLEANUP

Use clean Acetone, IPA or MEK solvent. Do not allow material to dry or cure inside any equipment.

HEALTH, SAFETY, & STORAGE REQUIREMENTS

Refer to each individual material SDS (Safety Data Sheet) for specific requirements on the health, safety, storage and handling requirements. Follow all local, state, and national regulations during surface preparation, material application and cleanup.

PRODUCT INFORMATION & DISCLAIMER

Product Data Sheets are periodically updated to reflect new information. It is important to use the latest and most recent revision for the product being used. The foregoing information is accurate to the best of our knowledge. However, due to differences in customer handling, use and method of application which are not known and are beyond our control, Products Techniques, Inc. makes no warranties as to the end result.