


Main parts needed to mount the extrusion



Aluminum profile (A)



End cap (B)



End cap with hole (C)



Cover (D)



LED strip(E)



screw(F)

Tools needed for mounting:


screwdriver

NOTE! All LED strips must be connected to a 12V or 24V power supply.


IMPORTANT: The manual presents the simplest mounting procedure.

More mounting procedures and related accessories can be consulted from Lucretia lighting.


1. Mount the end caps (B) and (C), then mount the aluminum profile (A) on the wall and ceiling.



2. Apply a layer of plaster to the profile and the ceiling and wall, and then paint the surface to finish.



3. Mount the LED strip (E), insert the cover (D). Lead out the power cable.



4. Run the cable to the power source. Connect power.

