

SIGNS & DECALS



Designed to visually enhance your safety procedures and guarding protocols, these signs and decals can be fastened to existing guards in order to warn of potential dangers and remind workers to stay safe. Signs are digitally printed on 3mm laminated PVC for maximum durability. Vinyl decals are laminated to resist damage and increase lifespan.



SIGNS & DECALS			
SIGNS - 7" X 10"		DECALS - 5" X 7"	
ITEM NAME	PART NUMBER	ITEM NAME	PART NUMBER
Danger - Lock Out	31912S	Danger - Lock Out	31912D
Danger - Do Not Operate	31915S	Danger - Do Not Operate	31915D
Danger - Stay Clear	31916S	Danger - Stay Clear	31916D
Danger - Keep Clear	31917S	Danger - Keep Clear	31917D
Danger - Exposed Conveyors	31918S	Danger - Exposed Conveyors	31918D
Think - Zero Injuries	31914S	Think - Zero Injuries	31914D
Think - Before You Act	31913S	Think - Before You Act	31913D
Danger - Lock Out, Tag Out, Try Out	31924S	Danger - Lock Out, Tag Out, Try Out	31924D
Remember - Cable Ties	31929S	Remember - Cable Ties	31929D

THESE SIGNS WERE DESIGNED BASED ON THE FOLLOWING ANSI STANDARDS:

ANSI Z535.2-2011
Environmental and Facility Safety Signs

ANSI Z535.3-2011
Criteria for Safety Symbols



BELT CONVEYOR GUARDING
Proven Safety Guarding Solutions

1-866-300-6668 | safety@conveyorguarding.com
www.conveyorguarding.com