

RFA Engineering Ltd

Powered Access Specialists

CERTIFICATE OF THOROUGH EXAMINATION

In accordance with Regulations, section 9, LOLER Lifting Operations and Lifting Equipment Regulations


Carried out to recommendation / ref	Reason for examination
Te/sc1	SIX MONTHLY
Make and model	Serial N.o
Skyjack sj9250	50002355

Fleet N.o	Hour reading	Last exam date
9250-05a	1922.8	Unknown
Next due	Build year	S.W.L
06/01/22	2018	681kg

Defects and observations	Rectify within	Sign when rectified
Upper lift cylinders weeping (not dropping) Slight play in steer linkage Debris under power extension decks (causing it to jam)	Advise Advise Advise	

Address where carried out	Registered keeper
TANKERSLEY LANE HOYLAND BARNESLEY S74 0DS	United power access

I certify that on **07/07/21** I thoroughly examined the item described in this report.

Engineer print	Engineer signature	Cap N.o
R FLAVELL		00593

Customer print	Customer signature	Ref N.o
		2293