

RFA Engineering Ltd

Powered Access Specialists

CERTIFICATE OF THOROUGH EXAMINATION

In accordance with Regulations, section 9, LOLER Lifting Operations and Lifting Equipment Regulations

Carried out to recommendation / ref	Reason for examination
TE/SC1	SIX MONTHLY
Make and model	Serial N.o
LGMG 1623	LWJAS160EM0730008

Fleet N.o	Hour reading	Last exam date
11	156	12/05/21
Next due	Build year	S.W.L
09/05/22	2021	680KG

Defects and observations	Rectify within	Sign when rectified
Ground controls canopy door damaged	Observation	<i>[Signature]</i>
Rear right main deck hand rail damaged and welds split	Before use	<i>[Signature]</i>
2 x 3/8 rail lock pins missing	Before use	<i>[Signature]</i>

Address where carried out	Registered keeper
PLOT 1 DORDON TAMWORTH B78 1TX	NORTH WEST MEWPS

I certify that on **10/11/21** I thoroughly examined the item described in this report.

Engineer print	Engineer signature	Cap N.o
J SHARP	<i>[Signature]</i>	00921

Customer print	Customer signature	Ref N.o
		2487